

INSURANCE

INS. CASE OWNER:

CC 4/AIG190 10283, Ak63-9

LKK:
IDAC:

Surveyor:

Adnan

DOI:

ASSIGNMENT

10/6/19

Date / Time:

10/6/19

Registered in Merimen:

11/6/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SDU 7300E

Name of Insured:

OW YONG SUE LIONG

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

2/6/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TIH AH LIONG

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

004561070864

Policy No.:

700394659

Make / Model:

MERCEDES

Place of Accident:

411 AME AVE 10 UP

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SUB 32094



INSRS:
WSP:
Tel:
Liability:
RMKS:

MIAP
KONH



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SCAMPER - 1 32094 - 1

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

45 \$5 2, 300

(4 days) Reduction:

56 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

\$5

Loss of Rental (LOR):

\$5

(days)

Loss of Use (LOU):

\$5

(5 x days)

Loss of Income (LOI):

\$5

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search:

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost:

\$5

Total:

\$5

Global Sum \$5:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

WP

3) Survey fee:

\$250

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

Name 1:

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5


Name 3:

arian

ASSIGNMENT

TC: _____ Date: _____
mainrd Cost: _____
/TF/WS/TP RES/OD RES/EVA/INV/MV
Inspect Vehicle No: _____
Workshop m/s: _____
ured: _____
icy No: _____
lms No: _____
m Insured: _____ Excess: _____
Client's Record) _____
ike of Veh: _____

Police Condition) _____
mark: The veh had commenced its
repair at the time of inspection.



il. or Market Value: _____
AC Accident Rpt: _____ Consistent? : Yes or No
IA / IPR Seen: _____ Consistent? : Yes or No
st. Repairs: 4 days Res: Yes or No
rm Sum: 20 % 3 Val: Yes or No
A / REV / REP. / 24 HRS
ate: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLB3269U Yr Regn: 2006, May
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Honda Civic c.c 1799
Colour Red A/C: Insured / Std / NI / NA
Sp. Reading 183723 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: JHMF716306S208027
Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/55H6
R: 205/55R16

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal.	<u>06</u> mm	R/Bal.	<u>06</u> mm
L/Bal.	<u>06</u> mm	L/Bal.	<u>06</u> mm
D.O.A.	_____	D.O.I.	<u>10/06/19</u>
Survey held at: <u>Hiep Hong</u>			
Des. of Damages: <u>Frnt</u> / Rear / O/S / <u>N/S</u> / U/C / Rooftop or			

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TPA 16.</u>
	<u>COE Expiry: 10/05/26.</u>
	<u>C/L \$ 2,300 / Rod \$ 2,917 / 56 /)</u>
	<u>MV: 40k</u>
	<u>PV: 31.9k</u>
	<u>Nett: 8.1k</u>

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:	Survey Fee:	Date:
1) _____	2) _____	IN _____	Basic & Add. _____	
3) _____	4) _____	OUT _____	S + RS. _____ SI	
5) _____	6) _____		Photos _____	
			Others _____	
Prefi. Report:			TOTAL _____	
Final Report:				

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/06/2019 16:00
Date Of Accident	02/06/2019 08:00
Exact Location Of Accident	ANG MO KIO HDB C/P NEAR BLK 408
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB3269U
Insured/Policyholder	
Name Of Registered Owner	WONG GUOYIN
NRIC No	S8743259I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96606112
Alternative Phone No	OFFICE-96606112

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC 1.8L A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5090748221-02 (TP)
Cover Note Number	

Driver

Name of Driver	WONG WAI YIN
NRIC No	S1106827H
Date Of Birth	01/06/1955
Occupation	INDOOR
Date Of Driving Pass	16/08/1973
Driving Experience	45 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96606112
Fax Number	
Contact Number	
Email Address	WWAIYIN@YMAIL.COM

TPA 16. SLB32694.
 Khanchana. Honda Civic
 JHMF D16306S208027

Front Number Plate	Bent	30(SW) ✓
Front Number Plate Garnish	Debond	66.80 ✓
Front Bumper	Debond	63.8 ✓
Front Bumper Clips	new	30 ✓
Front Bumper Side Holder x 02	new	$24.5 \times 2 = 49$ ✓
Front Bumper Reinforcement.	Bent	218.80 ✓
Front Bumper Fog Lamp x 02	RH Can't d	$303.8 \times 2 = 607.60$ ^{303.8} 607.60
Front Bumper Fog Lamp Covers x 02	new	$65.2 \times 2 = 130.40$ X
Front Grille	Cracked	282.50 ✓
Front Grille Chrome Moulding	at	185.30 ✓
Front Grille Logo	Xlec	30.20 ✓
Front Grille Clips	new	15 ✓
Headlamp x 02	RH cracked	$912.3 \times 2 = 1824.60$ ^{912.30} 1824.60
Headlamp Lower Bracket x 02	RH Bent	$29.4 \times 2 = 58.80$ 58.80 29.40
		2734.4
		2187.52

SLB3269U

Panel Beating

Spray Painting

Wiring

~~500~~ 400

~~500~~ 300

~~50~~ 30

730

total 2917.52

H/s: 231K

04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary parts must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Information	
Owner ID Type:	Singapore NRIC
Owner ID:	3259I
Vehicle Details	
Vehicle No.:	SLB3269U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.8L A
Primary Colour:	Red
Manufacturing Year:	2006
Engine No.:	R18A11027025
Chassis No.:	JHMFD163065208027
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$20,907.00
Original Registration Date:	11 May 2006
First Registration Date:	11 May 2006
Transfer Count:	4
Actual ARF Paid:	\$22,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 May 2026
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$46,048.00
COE Rebate Amount:	\$31,849.00
Total Rebate Amount:	\$31,849.00

The information contained herein is correct as at 10 Jun 2019

OK

Khanchna (LKK Auto)

From: Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>
Sent: Wednesday, 31 July 2019 11:26 AM
To: CS A Team
Subject: AIG REF:0045600708SG-003 [received LOD from TP solicitor]

Importance: High

Dear Team,

Pls submit WP report urgently as we have received LOD from TP lawyer.

Also, do confirm if insured has been engaged on liability assessment.

Thank you

Kind Regards,
Saliha

Saliha Syed Yusoff
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16, Singapore 079120
Tel +(65) 6419 1917 |
www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Transaction ref 20160523094207109567

The owner and vehicle particulars for Vehicle No. SLB3269U as at 23 May 2016 are as follows:

1. Name	: WONG GUOYIN
2. Identification No. Type	: Singapore NRIC
3. Identification No.	: S8743259I
4. Place Of Passport Issue	: -
5. Vehicle No.	: SLB3269U
6. Previous Vehicle No.	: -
7. Effective Date of Ownership	: 23 May 2016
8. Original Registration Date	: 11 May 2006
9. First Registration Date	: 11 May 2006
10. Vehicle Type	: P10 - Passenger Motor Car
11. Vehicle Scheme	: Normal
12. Attachment 1	: No Attachment
13. Attachment 2	: -
14. Attachment 3	: -
15. Vehicle Make	: HONDA
16. Vehicle Model	: CIVIC 1.8L A
17. Year of Manufacture	: 2006
18. Primary Colour	: Red
19. Secondary Colour	: -
20. Passenger Capacity	: 4
21. Chassis/Trailer Chassis No.	: JHMFD16306S208027 / -
22. Propellant	: Petrol
23. Engine No./Motor No.	: R18A11027025 / -
24. Engine Capacity(cc)/Power Rating(kW)	: 1799 / -
25. Maximum Power Output(kW/bhp)	: 103.0 / 138
26. Unladen Weight(kg)	: 1219



Reclinable Bucket Seat x 2, EK9 Header / FD2R Cat / Invidia Catback LTA Approve With Cert, DC2 Rear Seat, Type R Shifter, Linkage Varia, CF Bonnet, Original Nardi Steering Wheel, Original Koyo Radiato...

Posted: 06-Jun-2019 Tags: 2000 Honda Civic, 2000 Honda Civic, Honda Civic, Honda Civic, Honda Civic, Honda Civic, Honda Civic, Honda Civic



☐ Honda Civic 1.6A VTI (CQE till 09/2020)	\$10,800	\$8,420 /yr	21-Sep-2005	1,590 cc	-	Sedan	Available
--	----------	-------------	-------------	----------	---	-------	-----------

Full Loan Available At \$900 Plus, We Can Help To Convert To Z10 Usage If Needed, In House Loan Or Bank Loan Available! Balloon Scheme Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart...

88 Motor Trading



☐ Honda Civic 1.8A VTI-S (COE till 01/2021)	\$19,800	\$12,020 /yr	22-Feb-2006	1,799 cc	165,000 km	Sedan	Available
--	----------	--------------	-------------	----------	------------	-------	-----------

Consignment Unit. Viewing By Appointment Only!

Car Search

Received 13 May 2019 Accepted 2008 Honda Civic, 2000 Honda Civic, Honda Civic, Honda Civic, Honda Civic, Civic, Civic, Used Honda



☐ Honda Civic 1.8A VTI-S (COE till 05/2026)	\$42,800	\$6,130 /yr	01-Jun-2006	1,799 cc	-	Sedan	Available
--	----------	-------------	-------------	----------	---	-------	-----------

Full Loan Monthly \$700 Plus, We Are sgCarMart Premium Dealer! Buy With No Worries! No Hidden Costs! Car In Original Condition! Low Mileage! Accident Free! In House Loan Or Bank Loan Available! No Need...

BB: Master Trading

Save this search criteria, to get email alerts whenever a match is found.



Make ▼ Model ▼ Price ▼ Depreciation ▼ Reg Date ▼ Eng Cap ▼ Mileage ▼ Veh Type ▼ Status ▼

[For old advertisements, view Expired ads](#)

[← Back \(1 2 3 4 5 6 7 8 \) Next →](#)

20 results/page

[Home](#) [New Cars](#) [Used Cars](#) [Sell My Car](#) [Directory](#) [Products](#) [Insurance](#) [Article](#) [Forum](#) [Resources](#)

Follow sgCarMart.com



[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 soCarMart. All rights reserved.

CONTENTS • A

PRE-REPAIR INSPECTION REQUEST – SLB3269U vs SDU7300E (OI) on D.O.A.: 02/06/2019

From: Hor, Yinnul

To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)

Cc: Fong, Andy-SY, Fan, Winnie-LW, Kaur, Baljit, Abu Kassim, Noor Marissa, Azlan, Syazairina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Te

Sent: 6/10/2019 2:34:06 PM

Attachments:       

Hi,

Please refer to the enclosed request from **Tng Soon Chye & Co.**

Claim no : 0045600708SG003

Cash Owner : Wan Nur Salihah Binte Syed Yusoff

If you have any queries/concerns, please let us know.

Kindly assist to assign **Adrian Ling** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yinnul (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Yinnul.Hor@aig.com | [654348137](tel:654348137)

From: Tng Soon Chye [<mailto:tsclx@singnet.com.sg>]

Sent: Monday, June 10, 2019 12:37 PM

To: Hor, Yinnul

Subject: [EXTERNAL] PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDU7300E AND SLB3269U ON 02/06/2019

This message is from an external sender; be cautious with links and attachments.

IMMEDIATE ATTENTION

Dear Sirs,

We refer to your without prejudice email dated 10th June 2019 to us.

Our client instructs that he agrees to the appointment of Adrian Ling of M/s LKK Auto Consultants Pte Ltd as a single joint expert for the pre-repair inspection of the vehicle **SLB3269U** at the workshop, Hiap Hong Motor Repair, situated at **2 Kaki Bukit Avenue 2 #02-13 Auto Hub Singapore 417921 (tel: 6745 9633)**.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you. Our client's rights are hereby expressly reserved.

Thank You & Best Regards,

M/s Tng Soon Chye & Co
150 South Bridge Road
#02-19
Fook Hai Building
Singapore 058727

Confidentiality: This e-mail and its attachments are intended for the above named only and may be confidential. If they have come to you in error you must take no action based on them, nor must you copy or show them to anyone; please reply to this e-mail and highlight the error. The firm reserves the right to monitor all incoming and outgoing e-mail.

Security Warning: Please note that this e-mail has been created in the knowledge that Internet e-mail is not a 100% secure communications medium. We advise that you understand and observe this lack of security when e-mailing us.

Viruses: Although we have taken steps to ensure that this e-mail and attachments are free from any virus, we advise that in keeping with good computing practice the recipient should ensure they are actually virus free

From: Yinnul.Hor@aig.com

To: tsclx@singnet.com.sg

Cc: Andy-SY.Fong@aig.com, Winnie-LW.Fan@aig.com, Baljit.Kaur@aig.com, NoorMarissa.AbuKassim@aig.com, Syazairina.Azlan@aig.com, YokeShi.Chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Divyashni.Subramaniam@aig.com, Wahxin.Tong@aig.com

Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDU7300E AND SLB3269U ON 02/06/2019

Date: Mon, 10 Jun 2019 02:11:02 +0000

Without Prejudice

Your Reference : TSC.SLB3269U.Accid.2019(HH)-ak

Our Reference : 0045600708SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services

Veh Lu - Adrian

Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rui (Viviane)

AJG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Yinui.Hor@sga.com | www.sga.sg

湯 順 才 律 師 樓
TNG SOON CHYE & CO.

ADVOCATES & SOLICITORS
NOTARY PUBLIC
COMMISSIONER FOR OATHS
UEN NO: 53131141D

150 South Bridge Road #02-19 Fook Hai Building Singapore 058727

Tel: 6438 3133 • Fax: 6438 6066

(Service of Court documents via fax is not acceptable)

Our Ref: TSC.SLB3269U.Accid.2019(HH)-ak
Your Ref: SDU7300E

7th June 2019

M/s **AIG ASIA PACIFIC INSURANCE PTE LTD**
Motor Claims Department
78 Shenton Way
#08-16
Singapore 079120
(Insurer of Vehicle No. SDU7300E)

URGENT ATTENTION
By Fax/Certificate of Posting
(Fax: 6835 7417)

cc. to:

OW YONG SWEE CHONG
73 Sunrise Drive
Singapore 806576
(Owner of vehicle no. SDU7300E)

URGENT ATTENTION
By Certificate of Posting

Dear Sirs,

ACCIDENT ON 2ND JUNE 2019 @ 08:00 HRS INVOLVING MOTOR-VEHICLES NOS. SLB3269U & SDU7300E ALONG ANG MO KIO HDB C/P NEAR BLK 408

We are instructed by Mdm Wong GuoYin to notify you of a road traffic accident on 2nd June 2019 at about 08:00 hrs along Ang Mo Kio HDB C/P near Blk 408 involving our client's vehicle registration number SLB3269U and vehicle registration number SDU7300E driven by your insured's driver at the material time. A copy of the Singapore accident statement is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle at 2 Kaki Bukit Avenue 2 #02-13 Auto Hub Singapore 417921.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you. Our client's rights are hereby expressly reserved.

Yours faithfully,

Tng Soon Chye

enc

cc. client – via fax: 6747 8602 only
(ref: SLB3269U)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jun 2019 Edit Reg		10 Jun 2019 00:00 Edit Adj Rpt	S\$2,300.00 Edit Estimates	S\$2,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	OW YONG SWEE CHONG , ID: S1283225G								
Main Claimant:	WONG GUOYIN , ID: S8743259I								
Vehicle Reg. No.:	SLB3269U	Date of Loss:	02/06/2019 08:00 - :59 [156 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0045600708SG	Policy/Cover Note No.:	(Comprehensive) Coverage: 03/12/2018 - 02/12/2019						
Vehicle Reg. No. (Insured):	SDU7300E	Policy No. (Claimant):	5090748221-02						
		Excess:							
Repairer:	Hiap Hong Motor Repair () 2 Kaki Bukit Avenue 2, #02-13, 417921 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 20/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLB3269U (0045600708SG)
[SDU7300E]
TP
WONG GUOYIN
Jun 2 2019 8:00AM
[OW YONG SWEE CHONG]
Hiap Hong Motor Repair

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	04/07/19 16:32	General View														Load JPG	☒			
2	04/07/19 16:32	General View														Load JPG	☒			
3	04/07/19 16:32	General View														Load JPG	☒			
4	04/07/19 16:32	General View														Load JPG	☒			
5	04/07/19 16:32	General View														Load JPG	☒			
6	04/07/19 16:32	General View														Load JPG	☒			
7	04/07/19 16:32	General View														Load JPG	☒			
8	04/07/19 16:32	General View														Load JPG	☒			
9	04/07/19 16:32	General View														Load JPG	☒			
10	04/07/19 16:32	General View														Load JPG	☒			
11	04/07/19 16:32	General View														Load JPG	☒			
12	04/07/19 16:32	General View														Load JPG	☒			
13	04/07/19 16:32	General View														Load JPG	☒			
14	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
15	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
16	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
17	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
18	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
19	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
20	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
21	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
22	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
23	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
24	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
25	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
26	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
27	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
28	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
29	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
30	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
31	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
32	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
33	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
34	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
35	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
36	04/07/19 16:33	Reinspection Photo														Load JPG	☒			
37	04/07/19 16:33	Reinspection Photo														Load JPG	☒			

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	04/07/19 16:33	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/06/19 16:35	EMAIL FROM AIG DD 10062019	 Load PDF	
2	11/06/19 16:35	NOTICE & GIA REPORT	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/06/19 12:03	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19010283/AKB3Q2

Date: 31/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLB3269U

Insured Vehicle No : SDU7300E

Date of Loss: 02/06/2019

Nature of Claim: TP

Claim No: 0045600708SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB3269U**

Make & Model: HONDA CIVIC, 1.8 L (A)

Engine No: R18A11027025

Reg. Date: 11/05/2006 (Man. Year: 2006)

Chassis No: JHMF16306S208027

Colour: Red

Odometer: 183723 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,167.00	2,238.88	1,928.12	46.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	730.00	320.00	30.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,217.00	2,968.88	2,248.12	43.09
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	5,217.00	2,300.00	2,917.00	55.91
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 10/06/2019

Date Inspected: 10/06/2019 Inspected At:

Hiap Hong Motor Repair
2 Kaki Bykit Avenue 2, #02-13
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
2	1		*FRONT NUMBER PLATE GARNISH	Deformed	66.80 F	*66.80 FL
3	1		*FRONT BUMPER	Deformed	638.00 F	*638.00 FL
4	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
5	2		*FRONT BUMPER SIDE HOLDER	Necessary	49.00 F	*49.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	218.80 F	*218.80 FL
7	1		*FRONT BUMPER FOG LAMP	O/S Cracked	607.60 F	*303.80 FL
8	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	130.40 F	*- FL
9	1		*FRONT GRILLE	Cracked	282.50 F	*282.50 FL
10	1		*FRONT GRILLE CHROME MOULDING	Cut	185.30 F	*185.30 FL
11	1		*FRONT GRILLE LOGO	Necessary	30.20 F	*30.20 FL
12	1		*FRONT GRILLE CLIPS	Necessary	15.00 F	*15.00 FL
13	1		*HEADLAMP	O/S Cracked	1,824.60 F	*912.30 FL
14	1		*HEADLAMP LOWER BRACKET	O/S Bent	58.80 F	*29.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	4,167.00	2,791.10
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	552.22
Total Parts (\$\$)	4,167.00	2,238.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	500.00	400.00
2	SPRAY PAINTING	New	500.00	300.00
3	WIRING	New	50.00	30.00
Gross Labour Cost (S\$)			1,050.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >