

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SJR195H

No.	Qty	List Items	
1	1	Rear RH door wheel arch garnish	\$ <i>nd/m</i> 325.00 ✓
2	1	Rear RH fender wheel arch garnish (Rear)	\$ <i>in</i> 159.00 X
3	1 set	Rear RH fender wheel arch garnish clips	\$ <i>nn</i> 60.00 X
4	1	Rear RH shock absorber	\$ <i>By</i> 300.00 ✓
5	1	Rear RH upper arm	\$ <i>di</i> 195.00 ✓
6	1	Rear RH trailing arm	\$ <i>By</i> 453.10 ✓
7	1	Rear RH knuckle arm	\$ <i>By</i> 325.00 ✓
8	1	Rear RH wheel hub & bearing	\$ <i>nn</i> 387.10 ✓
9	1	Rear stabilizer bar	\$ <i>nn</i> 200.00 X
10	1	Rear stabilizer bar RH link rod	\$ <i>di</i> 85.90 ✓
11	1	Rear RH sports rims	\$ <i>By</i> 956.00 ✓
12	1	Front RH door garnish	\$ <i>nd/m</i> 225.00 ✓
			\$ 3,671.10
Less 20%			\$ 734.22
Total :			\$ 2,936.88
<u>Special Nett Items</u>			
13	1	Rear RH tyre	\$ <i>Per</i> 300.00 <i>409m 1205m</i>
<u>Labour</u>			
1		Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 500.00 <i>300</i>
2		To putty and spray Spray Paintings charges.	\$ <i>nn</i> 600.00 X
3		To remove, refit rear RH under carriage damages.	\$ 280.00 <i>200</i>
4		To conduct computerise wheel alignment test.	\$ 80.00 <i>60</i>
5		To supply and apply anti rust treatment	\$ <i>nn</i> 50.00 X
Total :			\$ 1,510.00
Total Parts and Labour :			\$ 4,746.88

Not withain
11 By 82600h
Putty After Paint
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: