

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SJR195H

No.	Qty	List Items	
1	1	Rear RH door wheel arch garnish	\$ <i>nd/bn</i> 325.00 ✓
2	1	Rear RH fender wheel arch garnish (Rear)	\$ <i>sn</i> 159.00 X
3	1 set	Rear RH fender wheel arech garnish clips	\$ <i>sn</i> 60.00 X
4	1	Rear RH shock absorber	\$ 300.00 ?
5	1	Rear RH upper arm	\$ 195.00 ?
6	1	Rear RH trailing arm	\$ 453.10 ?
7	1	Rear RH knuckle arm	\$ <i>Bz</i> 325.00 ✓
8	1	Rear RH wheel hub & bearing	\$ <i>sn</i> 387.10 ✓
9	1	Rear stabilizer bar	\$ <i>sn</i> 200.00 X
10	1	Rear stabilizer bar RH link rod	\$ 85.90 ?
11	1	Rear RH sports rims	\$ <i>Bz</i> 956.00 ✓
12	1	Front RH door garnish	\$ <i>nd/bn</i> 225.00 ✓
			\$ 3,671.10
Less 20%			\$ 734.22
Total :			\$ 2,936.88

Special Nett Items			
13	1	Rear RH tyre	\$ <i>Per</i> 300.00 <i>409/20</i>

<u>Labour</u>			
1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	500.00 <i>300</i>
2	To putty and spray Spray Paintings charges.	\$ <i>nn</i>	600.00 X
3	To remove, refit rear RH under carriage damages.	\$	280.00 <i>2000</i>
4	To conduct computerise wheel alignment test.	\$	80.00 <i>60</i>
5	To supply and apply anti rust treatment	\$ <i>nn</i>	50.00 X
Total :		\$	<u>1,510.00</u>

Total Parts and Labour : \$ 4,746.88

Not Withash
1/1 Day 8?
Putty After Paint
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: