

ASS. REC. BY:

REF:

CS/FCI 19010365/USD3

Special Instruction:

Supervisor:

Marcus

CWS

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time:

11/6/19 @ 5:34pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBH 442SR

Insured:

SHB 4038K

at Workshop m/s

Bun Hock Hin

Tel:

62816520

of

No. 6 Defu Lane 4

Policy No:

Claim No:

D19063509MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/5/2019

(Client's Record)

CA / PWV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

10:17am @ 12/6/19

Person Contacted:

Raymond

Vehicle IN / OUT

Date/Time

Action/Instruction

Raymond

13/06/19 @ 15:01 pm revised PA to Eileen via email.

(08/11/13) wef

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBH 4425R

Yr Regn:

6 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Vamche Jupiter MX c.c 134

Colour:

red

A/C: Insured / Std / NI / NA

Sp. Reading

34721

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MH350C003DK564819

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

70-90-17

R:

80-90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Diamond.

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

25/5/19

D.O.I.

11/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt, 115 body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

net 3633

22/8/19 L/S \$1250 Confirmed with Raymond.
 (\$1,132.00 Red - 48%)

RECEIVED 22 AUG 2019

Date/Time, File Pass to?

22/08/19

1) Type: 54

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$

) \$ + RS, SI



: Interview (\$

) Photos



: Tech. Invs (\$

) Others



: Weekend (\$

)

Report Format:

Lump Sum / I.B.I. (\$ 1,250/- L/S)

TOTAL

110

50

50

78

288

MOTOR SURVEY ASSIGNMENT

Date	28-05-2019	Our Ref No. D19003509MFSH
Accident Date	25-05-2019	Claim Type. Third Party
Insured Vehicle	SHB4038K	Third Party Vehicle. FBH4425R
Survey Location	NO. 6 DEFU LANE 4	
Contact Person.	RAYMOND	
Contact No.	62816520/ 0	Fax No. 62842969
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	BAN HOCK HIN CO. PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Enquire Transfer Fee

Enquire Transfer Fee			
Vehicle Details			
Vehicle No.:	FBH4425R		
Vehicle Type:	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Normal		
Vehicle Make:	YAMAHA		
Vehicle Model:	JUPITER MX (HC)		
Chassis No.:	MH350C003DK564819		
Propellant:	Petrol		
Engine No.:	50C564905		
Engine Capacity:	134 cc		
Maximum Power Output:	-		
Maximum Laden Weight:	242 kg		
Unladen Weight:	116 kg		
Year Of Manufacture:	2013		
Original Registration Date:	17 Jun 2013		
Lifespan Expiry Date:	-		
COE Category:	D - Motorcycle		
Quota Premium:	\$1,663.00		
COE Expiry Date:	16 Jun 2023		
Road Tax Expiry Date:	16 Jun 2020		
Inspection Due Date:	16 Jun 2020		
Intended Transfer Date:	11 Jun 2019		
CO2 Emission:	-		
CO Emission:	-		
HC Emission:	-		
NOx Emission:	-		
PM Emission:	-		
Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	9280B

Vehicle Details

Vehicle No.:	FBH4425R
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jun 2019
Vehicle Make:	YAMAHA
Vehicle Model:	JUPITER MX (HC)
Primary Colour:	Purple
Manufacturing Year:	2013
Engine No.:	50C564905
Chassis No.:	MH350C003DK564819
Maximum Power Output:	-
Open Market Value:	\$1,802.00
Original Registration Date:	17 Jun 2013
First Registration Date:	17 Jun 2013
Transfer Count:	2
Actual ARF Paid:	\$271.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	16 Jun 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,663.00
COE Rebate Amount:	\$667.00
Total Rebate Amount:	\$667.00

The information contained herein is correct as at 11 Jun 2019

OK

Brand	Yamaha (/listing/usedbike/brand/yamaha/)
Model	Yamaha Jupiter MX135 (/listing/usedbike/model/yamaha-jupiter-mx135/)
Engine Capacity	134cc
Classification	Class 2B (/listing/usedbike/model/motorcycle-for-sale/class/class-2b/)
Registration Date	17/01/2013
COE Expiry Date	16/01/2023 (3 years 7 months left)
Mileage	-
No. of owners	1
Type of Vehicle	Cubs (/listing/usedbike/model/motorcycle-for-sale/cubs/)

Price: ^{SGD}\$4300

DETAILS

Many other brand new and used motorcycles available. Come visit us at Ban Hon Brothers (Agencies) Pte Ltd. Block 5022, Ang Mo Kio Industrial Park 2 #01-19 Singapore 569525.

SIMILAR BIKES

[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](#)



Yamaha Jupiter MX135

[\(/listing/usedbike/yamaha-yamaha-jupiter-mx135/12930/\)](/listing/usedbike/yamaha-yamaha-jupiter-mx135/12930/)



Yamaha Jupiter MX135

[\(/listing/usedbike/yamaha-yamaha-jupiter-mx135/12881/\)](/listing/usedbike/yamaha-yamaha-jupiter-mx135/12881/)



Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 13 June 2019 3:01 PM
To: 'Eileen Lee'; 'CWS Motor Claims'
Cc: assignments; SUR
Subject: RE: SURVEY ASSESSMENT - D19003509MFSH/1
Attachments: FBH 4425R - Preli Advise .pdf

Dear Eileen,

Enclosed preliminary revised of vehicle FBH 4425R.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 12 June 2019 12:12 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003509MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 11 June 2019 5:34 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003509MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003509MFSH

Date: 13 June 2019

Our Ref: CS/FCI19010365/Usd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. FBH 4425R .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/06/2019 at the premises of M/s Ban Hock Hin Co Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 2,275.00 .
Revised Estimate Amount	: S\$ 1,861.00 .
"Check" Items Amount	: S\$ 212.00 .
Total	: S\$.
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:

The vehicle sustained damages at the front portion & n/s body.



Comments/ Present Status:

Damages Consistent.
Repair days: 4 days

Yours faithfully,
Marcus Chua
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/05/2019 15:42
Date Of Accident	25/05/2019 20:50
Exact Location Of Accident	ALONG AYE TOWARDS CHANGI AIRPORT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBH4425R
Insured/Policyholder	
Name Of Registered Owner	LAU CHUN SIANG
NRIC No	S8089280B
Email Address	CHUNSIANG1980@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98075555
Alternative Phone No	OFFICE-98075555

Vehicle Particulars

Manufacturer	YAMAHA
Model	JUPITER MX (HC)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5109009266
Cover Note Number	

Driver

Name of Driver	LAU CHUN SIANG
NRIC No	S8089280B
Date Of Birth	01/03/1980
Occupation	INDOOR
Date Of Driving Pass	17/04/2014
Driving Experience	5 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98075555
Fax Number	
Contact Number	OFFICE-98075555
EEmail Address	CHUNSIANG1980@HOTMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	CLEMENTI NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20190526/2019 LODGED AT CLEMENTI NPC. ON 25/05/2019 AT ABOUT 2050HRS, I WAS RIDING MY MOTORCYCLE BEARING THE REGISTRATION NUMBER FBH4425R ALONG AYE TOWARDS CHANGI AIRPORT DIRECTION WHEN AN UNKNOWN BLUE-COLOURED TAXI SIDE-SWIPE ME NEAR TOLL ROAD ENTRANCE TO THE AYE. I WAS TRAVELLING ALONG LANE 2 OF THE EXPRESSWAY WHEN THE TAXI APPEARED SUDDENLY ON THE LEFT SIDE OF MY MOTORCYCLE AND SIDE SWIPED ME. I DO NOT KNOW WHY THE TAXI SUDDENLY FILTER TO LANE 2 FROM LANE 3. DUE TO THE IMPACT, I LOST FELL FROM MY MOTORCYCLE. I IMMEDIATELY STOOD UP AS I FEARED THAT ARE VEHICLES BEHIND MY MOTORCYCLE AND I QUICKLY RAN TOWARDS THE ROAD SHOULDER. I THEN SAT DOWN AS I HAD SUFFERED SOME INJURIES ON BOTH MY HANDS AND LEGS. THE TAXI DRIVER STOPPED HIS VEHICLE AND WENT TO ME TO ASK FOR MY WELL-BEING. THE TAXI DRIVER IS ONE MALE CHINESE AGED ABOUT 50S. THE TAXI DRIVER DID NOT EXCHANGED HIS PARTICULARS DURING THE INCIDENT. DUE TO ME TRAUMATIZED FROM THE ACCIDENT, I WAS UNABLE TO GET THE TAXI REGISTRATION NUMBER. I WAS CONVEYED TO NUH A&E AND I WAS GIVEN 4 DAYS MC. (REF TO NUH19143797).. THERE WAS A POLICE CAR ATTENDED TO MY INCIDENT BUT I WAS NOT GIVEN A CASE CARD OR REPORT NUMBER FOR REFERENCE. I DO NOT KNOW THE DAMAGE/S TO MY MOTORCYCLE AND I DO NOT KNOW THE WHEREABOUTS OF MY MOTORCYCLE AS I WAS CONVEYED TO NUH IMMEDIATELY AFTER THE INCIDENT. I HAVE REPORTED THE ACCIDENT TO NTUC FOR THEIR RECORDS THROUGH THEIR HOTLINE. I AM LODGING THIS REPORT FOR MU INSURANCE CLAIM (NTUC) FOR MY MEDICAL EXPENSES AND REPAIR FOR MY MOTORCYCLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB4038K
Vehicle Make/Model/Colour	HYUNDAI I40 1.7L CRDI AT ABS AIRBAG 4DR / BLUE
Details Of Properties	

Vehicle Category	TAXI
Name of Driver	UNKNOWN DRIVER
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	LAU CHUN SIANG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBH4425R
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 28/05/2019

1634hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Traffic Accident Report No. T|20190526|2019 attached.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 28/05/2019

GIARMC SketchPlanForm_V3

Driver's Signature _____

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Police Report Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190526/2019

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

1 of 3

Report No. T/20190526/2019

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/05/2019 09:01		Vide Report No.:		Station Diary No.: 14	
Informant's Particulars					
Name of Informant: LAU CHUN SIANG			Address: 5 JLN NUSARIA 4/9G TMN NUSANTARA 81550 GELANG PATAH JB M'SIA		
ID Type / ID No.: NRIC NO / S8089280B			Contact No.: Home/Office: 60127299292 Mobile: 98075555		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 39	Date of Birth: 01/03/1980	Type of Informant: Rider		
Race: Chinese			Language:		Institution / School Name:
Occupation: TECHNICIAN			Driving Licence Information: Class: 2B,2A,2,3C Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 25/05/2019 20:50	Type of Location: Straight Road
Location: Along Road 1 AYER RAJAH EXPRESSWAY Along AYE towards Changi Airport near TUAS Checkpoint Viaduct. Near one Toll Road.				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 80 Km/h
Traffic Flow: One Way		Traffic Control:		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No	Type	Make	Model	Color	Condition	No. of Passenger
FBH4425R	Motorcycle				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20190526/2019

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

2 of 3

Report No. T/20190526/2019

CONTINUATION OF REPORT

Brief Details.

On 25/05/2019 at about 2050hrs, I was riding my motorcycle bearing the registration number FBH4425R along AYE towards Changi Airport direction when an unknown blue-coloured taxi side-swiped me near Toll Road entrance to the AYE. I was travelling along lane 2 of the expressway when the taxi appeared suddenly on the left side of my motorcycle and side swiped me. I do not know why the taxi suddenly filter to Lane 2 from Lane 3.

Due to the impact, I lost fell from my motorcycle. I immediately stood up as I feared that are vehicles behind my motorcycle and I quickly ran towards the road shoulder. I then sat down as I had suffered some injuries on both my hands and legs.

The taxi driver stopped his vehicle and went to me to ask for my well-being.

The taxi driver is one male Chinese aged about 50s. The taxi driver did not exchanged his particulars during the incident. Due to me traumatized from the accident, I was unable to get the taxi registration number.

I was conveyed to NUH A&E and I was given 4 days MC. (Ref to NUH19143797)..

There was a police car attended to my incident but I was not given a case card or report number for reference.

I do not know the damage/s to my motorcycle and I do not know the whereabouts of my motorcycle as I was conveyed to NUH immediately after the incident.

I have reported the accident to NTUC for their records through their hotline.

I am lodging this report for my insurance claim (NTUC) for my medical expenses and repair for my motorcycle.



**SINGAPORE
POLICE FORCE**



T/20190526/2019

Police Station Of Origin:
Clementi N.P.C.
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

3 of 3

Report No. T/20190526/2019

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: D / SI IMRAN BIN MOHAMMAD HAJAR	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 26/05/2019 09:01
Officer In Charge Of Case: TP / GIT / SI ONG CHEE HIEN Contact No.: 65476437	Classification Of Case:

Authentication Stamp
NP168

	SINGAPORE POLICE FORCE	SN 37
SIGNATURE		



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

FIRST CAPITAL INSURANCE LTD
06 RAFFLES QUAY #21-00
SINGAPORE 048580

NO. : 34251

DATE : 07/06/2019
CLAIM NO. : 11354
POLICY NO. :
FROM : RAYMOND

VEHICLE NO. : FBH4425R
MAKE/MODEL : YAM / JUPITER MX (HC)

*not Afford
LH
2/5 \$1250
4 day.
11/6/19
Theophile Adhoge.*

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER HANDLE P/N: 51527	REPLACE	1.00	\$9.00	9.00
2	BEARING RIM FRONT	REPLACE	2.00	\$14.00	28.00
3	BRACKET FOOTREST REAR LH	REPLACE	1.00	\$66.00	66.00
4	BUSH P/N: 51495	REPLACE	2.00	\$10.50	21.00
5	COVER FOOTREST P/N: 51505	REPLACE	1.00	\$9.00	9.00
6	COVER HANDLE UPPER P/N: 51542	REPLACE	1.00	\$58.00	58.00
7	COVER SIDE FRONT LOWER LH	REPLACE	1.00	\$24.00	24.00
8	COVER SPROCKET FRONT	REPLACE	1.00	\$20.00	20.00
9	COVER TAIL LH (RED)	REPLACE	1.00	\$55.00	55.00
10	FOOTREST P/N: 51522	REPLACE	1.00	\$84.00	84.00
11	FOOTREST REAR LH	REPLACE	1.00	\$9.00	9.00
12	HANDLE P/N: 51524	REPLACE	1.00	\$62.00	62.00
13	HEADLIGHT ASSY	REPLACE	1.00	\$112.00	112.00
14	LABOUR P/N: 06766	Supply/Install	10.00	\$35.00	350.00



bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0383
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
15	LEVER CLUTCH	REPLACE	1.00	\$26.00	scr 26.00
16	METER IU (12V) NEW MODEL P/N: 34351	REPLACE	1.00	\$200.00	SVC 200.00 X
17	MIRROR LH	REPLACE	1.00	\$20.00	cut 20.00
18	MOLE 1 P/N: 51543	REPLACE	1.00	\$66.00	cut 66.00
19	MUDGUARD FRONT (RED) P/N: 55804	REPLACE	1.00	\$104.00	cut 104.00
20	NUT WHEEL	REPLACE	1.00	\$5.00	rec 5.00
21	PEDAL GEAR	REPLACE	1.00	\$26.00	scr 26.00
22	RIM SPORT FRONT	REPLACE	1.00	\$423.00	cut 423.00
23	ROD SHIFT PEDAL GEAR	REPLACE	1.00	\$5.00	scr 5.00
24	RUBBER PEDAL GEAR	REPLACE	1.00	\$2.00	rec 2.00
25	SEAT HANDLE	REPLACE	1.00	\$104.00	cut 104.00
26	STICKER BODY SET (RED)	REPLACE	1.00	\$68.00	rec 68.00 S.N
27	STOPPER FOOTREST REAR LH	REPLACE	1.00	\$2.00	70.00 2.00
28	SWING ARM	REPLACE	1.00	\$136.00	SVC 136.00 X
29	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD P/N: 45833	Supply/Install	1.00	\$55.00	35 55.00
30	TUBE OUTER LH	REPLACE	1.00	\$56.00	SVC 56.00 X
31	TUBE OUTER RH	REPLACE	1.00	\$56.00	SVC 56.00 X
32	WHEEL AXLE P/N: 51499	REPLACE	1.00	\$14.00	scr 14.00

SUB TOTAL

2382 \$2,275.00

GST @ 7 %

\$159.25

GRAND TOTAL

\$2,434.25

50% deposit required before ordering of parts.

Validity: 30 days



Acknowledged by Repairer

Signature:

bizSAFE₃CERT NO.: 2002-140363
ISO 9001: 2015

S/N DescriptionActionQtyUnit PriceAmount

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO : 2002-1-0383
ISO 9001 : 2015



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

FIRST CAPITAL INSURANCE LTD
06 RAFFLES QUAY #21-00
SINGAPORE 048580

NO. : 34610

Supplementary 1 To QTN: 34251

DATE : 20/08/2019

CLAIM NO. : 11354

POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBH4425R
MAKE/MODEL : YAM / JUPITER MX (HC)

S/N	Description	Action	Qty	Unit Price	Amount
1	COVER LEG SHIELD LH (RED) P/N: 63734	Replace	1.00	\$51.00	51.00
2	GASKET COVER CRANKCASE 2 P/N: 51518	Replace	1.00	\$9.00	9.00
3	GEAR SHAFT P/N: 63047	Replace	1.00	\$47.00	47.00
SUB TOTAL					\$107.00
GST @ 7 %					\$7.49
GRAND TOTAL					\$114.49

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0363
ISO 1001 2:16



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 34251

- Rev. 1

FIRST CAPITAL INSURANCE LTD
06 RAFFLES QUAY #21-00
SINGAPORE 048580

DATE : 07/06/2019
CLAIM NO. : 11354
POLICY NO. :
FROM : RAYMOND

VEHICLE NO. : FBH4425R
MAKE/MODEL : YAM / JUPITER MX (HC)

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER HANDLE P/N: 51527	REPLACE	1.00	\$9.00 Disc %: 10.00	8.10
2	BEARING RIM FRONT	REPLACE	2.00	\$14.00 Disc %: 10.00	25.20
3	BUSH P/N: 51495	REPLACE	2.00	\$10.50 Disc %: 10.00	18.90
4	COVER FOOTREST P/N: 51505	REPLACE	1.00	\$9.00 Disc %: 10.00	8.10
5	COVER HANDLE UPPER P/N: 51542	REPLACE	1.00	\$58.00 Disc %: 10.00	52.20
6	COVER SIDE FRONT LOWER LH	REPLACE	1.00	\$24.00 Disc %: 10.00	21.60
7	COVER TAIL LH (RED)	REPLACE	1.00	\$55.00 Disc %: 10.00	49.50
8	FOOTREST P/N: 51522	REPLACE	1.00	\$84.00 Disc %: 10.00	75.60
9	FOOTREST REAR LH	REPLACE	1.00	\$9.00 Disc %: 10.00	8.10
10	HANDLE P/N: 51524	REPLACE	1.00	\$62.00 Disc %: 10.00	55.80
11	HEADLIGHT ASSY	REPLACE	1.00	\$112.00 Disc %: 10.00	100.80
12	LABOUR P/N: 06766	Supply/Install	1.00	\$250.00	250.00
13	LEVER CLUTCH	REPLACE	1.00	\$26.00 Disc %: 10.00	23.40
14	MIRROR LH	REPLACE	1.00	\$20.00 Disc %: 10.00	18.00



bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO : 2002-1-0383
ISO 9001:2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
15	MOLE 1 P/N: 51543	REPLACE	1.00	\$66.00 Disc %: 10.00	59.40
16	MUDGUARD FRONT (RED) P/N: 55804	REPLACE	1.00	\$104.00 Disc %: 10.00	93.60
17	NUT WHEEL	REPLACE	1.00	\$5.00 Disc %: 10.00	4.50
18	PEDAL GEAR	REPLACE	1.00	\$26.00 Disc %: 10.00	23.40
19	RIM SPORT FRONT	REPLACE	1.00	\$423.00 Disc %: 10.00	380.70
20	ROD SHIFT PEDAL GEAR	REPLACE	1.00	\$5.00 Disc %: 10.00	4.50
21	RUBBER PEDAL GEAR	REPLACE	1.00	\$2.00 Disc %: 10.00	1.80
22	SEAT HANDLE	REPLACE	1.00	\$104.00 Disc %: 10.00	93.60
23	STICKER BODY SET (RED)	REPLACE	1.00	\$68.00	68.00
24	STOPPER FOOTREST REAR LH	REPLACE	1.00	\$2.00 Disc %: 10.00	1.80
25	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD P/N: 45833	Supply/Install	1.00	\$35.00	35.00
26	WHEEL AXLE P/N: 51499	REPLACE	1.00	\$14.00 Disc %: 10.00	12.60
27	COVER LEG SHIELD LH (RED) P/N: 63734	Replace	1.00	\$51.00 Disc %: 10.00	45.90
28	GASKET COVER CRANKCASE 2 P/N: 51518	Replace	1.00	\$9.00 Disc %: 10.00	8.10
29	GEAR SHAFT P/N: 63047	Replace	1.00	\$47.00 Disc %: 10.00	42.30
SUB TOTAL					\$1,590.50
GST @ 7 %					\$111.34
GRAND TOTAL					\$1,701.84

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND



Acknowledge & Accepted By

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-14383
ISO 9001: 2015



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19010365/Usd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4038K	Veh. Inspected	FBH 4425R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003509MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	11/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA JUPITER MX	c.c	134	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	MH350C003DK564819	Colour	RED	
Odometer	34721	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	70-90-17	DIAMONDS	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	80-90-17	DIAMONDS	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/05/2019	Inspection Date	11/06/2019	
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 4425R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BALANCER HANDLE	SCRATCHED	9.00	9.00
2	BEARING RIM FRONT @\$14.00	NECESSARY	28.00	28.00
1	BRACKET FOOTREST REAR LH	TO REPAIR SEE LABOUR	66.00	-
2	BUSH @\$10.50	NECESSARY	21.00	21.00
1	COVER FOOTREST	DAMAGED	9.00	9.00
1	COVER HANDLE UPPER	CUT	58.00	58.00
1	COVER SIDE FRONT LOWER LH	CUT	24.00	24.00
1	COVER SPROCKET FRONT	NOT NECESSARY	20.00	-
1	COVER TAIL LH (RED)	CUT	55.00	55.00
1	FOOTREST	BENT	84.00	84.00
1	FOOTREST REAR LH	CUT	9.00	9.00
1	HANDLE	BENT	62.00	62.00
1	HEADLIGHT ASSY	SCRATCHED	112.00	112.00
1	LEVER CLUTCH	SCRATCHED	26.00	26.00
1	METER IU (12V) NEW MODEL	SERVICEABLE	200.00	-
1	MIRROR LH	CUT	20.00	20.00
1	MOLE 1	CRACKED	66.00	66.00
1	MUDGUARD FRONT (RED)	CUT	104.00	104.00
1	NUT WHEEL	NECESSARY	5.00	5.00
1	PEDAL GEAR	BENT	26.00	26.00
1	RIM SPORT FRONT	CUT	423.00	423.00
1	ROD SHIFT PEDAL GEAR	BENT	5.00	5.00
1	RUBBER PEDAL GEAR	NECESSARY	2.00	2.00
1	SEAT HANDLE	CUT	104.00	104.00
1	STOPPER FOOTREST REAR LH	TORN	2.00	2.00
1	SWING ARM	SERVICEABLE	136.00	-
1	TUBE OUTER LH	SERVICEABLE	56.00	-
1	TUBE OUTER RH	SERVICEABLE	56.00	-
1	WHEELAXLE	BENT	14.00	14.00
1	COVER LEG SHIELD LH (RED) (ADDITIONAL)	TORN	51.00	51.00

Report Ref No. CS/FCI19010365/Usd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GASKET COVER CRANKCASE 2 (ADDITIONAL)	NECESSARY	9.00	9.00
1	GEAR SHAFT (ADDITIONAL)	BENT	47.00	47.00
	LESS 10% DISCOUNT		-	-137.50
			1,909.00	1,237.50
	<u>SPECIAL NETT ITEMS</u>			
1	SET STICKER BODY (RED) (SN)	NECESSARY	68.00	68.00
			68.00	68.00
	<u>LABOUR</u>			
	LABOUR. INCLUSIVE OF THE REPAIR OF BRACKET FOOTREST REAR LH.		350.00	250.00
	TRANSPORT CHARGES (MOTORCYCLE / SCOOTER).		55.00	35.00
			405.00	285.00
GRAND TOTAL			2,382.00	1,590.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,250.00

Report Ref No. CS/FCI19010365/Usd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.