

7/15/2010

INS. CASE OWNER

CC 4/EGI1901 0409, U k639

LKK:

IDAC:

Surveyor:

MARCUS (CKS)

DOI:

ASSIGNMENT

12/6/14

Date / Time:

11/6/14

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUR 6944

Name of Insured:

ANG SIEW GEOR

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

20/11/14

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

DMPG 1800 NBT

TUGOIN

CIE EXIT OUTRAM

If NO. Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT: YES NO : TP GIA REPORT: YES NO

Insured Liability: % Final? Yes / No

FBL 9895M

INSRS:
WSP:
Tel:
Liability:
RMKS:

BHT

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

3/11/14 11:30am
phorchen

FBL 9895M - 8 SUR 6944 - 1

- called OI twice, no answer.

- OI called in. Informed OI on TP claim, agreed to settle.

5/11/14
phorchen

File pass to shu rei to close

STAGE

DATE / PIC

Non-Reporting 1st (1st):

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call OI:

After call 1st to OI:

2/11/14
e-mail to shu rei

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P

SS

847.60

(3 days)

Reduction:

11 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

Repair Cost:

C/L (451)

SS

906.93

Loss of Rental (LOR):

SS

-

(- days)

Loss of Use (LOU):

SS

60

(5 20 x 3 days)

Loss of Income (LOI):

SS

-

(5 - x - days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

2.06

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

966.93

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

966.93

Name 1:

BAN HOCK HIN CO PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

08/11/12 wel
ASS. REG. BY: MARUS

REF:

221

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

GA / PR Seen

Est. Repairs:

3

days

Res:

Yes or No

Lum Sum:

110

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

LYA 4869

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

FBL 9895M

Yr Regn:

6.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BAJAJ PULSAR c.c 200

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

17023

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MD2A36F25GCA25793

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110-70-17

R:

140/70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

2

mm

Rear

R/Bal.

2

mm

L/Bal.

30/5/19

mm

L/Bal.

12/6/19

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

(P/P \$ 847.60 / Red \$ 106.40 / 11%)

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

* Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

\$ + RS \$

) Photos

) Others

TOTAL



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 18700250K

MOTORCYCLE ACCESSORIES / SERVICE CENTRE
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

QUOTATION

Customer :

ERGO INSURANCE PTE LTD
302 ORCHARD ROAD
#09-01 TIONG BUILDING
SINGAPORE 238862

ERGO INSURANCE PTE LTD

VEHICLE NO : FBL5895M
MAKE/MODEL : BAJAJ / PULSAR 200 NS M

NO. : 34256

DATE : 11/06/2019

CLAIM NO. : 11349

POLICY NO. :

FROM : RAYMOND

*not added
new
2/12/18 847.60
327.
1/16/19
2/1/19 111-117*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	ASLY HUGGER REAR	REPLACE	1.00	\$35.00	35.00
2	BALANCER L/RH P/N: 62564	REPLACE	1.00	\$28.00	28.00
3	BOX REAR (GIVI) E33N W/O LIGHT-BLACK P/N: 44275	REPLACE	1.00	\$155.00	155.00
4	BRACKET REFLECTOR MTG P/N: 62557	REPLACE	1.00	\$9.00	9.00
5	FOG LIGHT	REPLACE	1.00	\$150.00	150.00
6	FOOT BRAKE PEDAL P/N: 62565	REPLACE	1.00	\$42.00	42.00
7	GUARD LEG RH	REPLACE	1.00	\$25.00	25.00
8	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED	*	1.00	\$190.00	190.00
9	LEVER BRAKE	REPLACE	1.00	\$18.00	18.00
10	LOCK PLATE RH	REPLACE	1.00	\$3.00	3.00
11	MIRROR RH P/N: 62560	REPLACE	1.00	\$28.00	28.00
12	REAR BOX BRACKET (KAPPA)	REPLACE	1.00	\$138.00	138.00
13	REFLECTOR	REPLACE	1.00	\$7.00	7.00



bizSAFE



S/N	Description	Action	Qty	Unit Price	Amount
14	STEP HOLDER PILLION RH	REPLACE	1.00	\$55.00	CU 1 55.00 ?
15	STEP PILLION ASSY COMP	REPLACE	1.00	\$18.00	CU 7 18.00 ?
16	STICKER P PLATE P/N: 29128	REPLACE	1.00	\$18.00	mm 18.00
17	TUBE REAR HUGGER MTG	REPLACE	1.00	\$35.00	mm 35.00 ?
SUB TOTAL					\$954.00
GST @ 7 %					\$66.78
GRAND TOTAL					\$1,020.78

~~Quotation is valid for 30 days from the date of issue.~~

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

P-764
P47.60

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

\$ 764.00
76.40

\$ 687.60
160.00

\$ 847.60



bizSAFE₃





BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000286K
MOTORCYCLE ACCESSORIES / SERVICE CENTRE
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

QUOTATION

Customer :

NO. : 34256

ERGO INSURANCE PTE LTD
302 ORCHARD ROAD
#09-01 TIONG BUILDING
SINGAPORE 238862

DATE : 11/06/2019
CLAIM NO. : 11349
POLICY NO. :

ERGO INSURANCE PTE LTD

FROM : RAYMOND

VEHICLE NO. : FBL9895M
MAKE/MODEL : BAJAJ / PULSAR 200 NS M

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	ASLY HUGGER REAR	REPLACE	1.00	\$35.00	35.00
2	BALANCER LH/RH P/N: 62564	REPLACE	1.00	\$28.00	28.00
3	BOX REAR (GIVI) E33N W/O LIGHT-BLACK P/N: 44275	REPLACE	1.00	\$155.00	155.00
4	BRACKET REFLECTOR MTG P/N: 62557	REPLACE	1.00	\$9.00	9.00
5	FOG LIGHT	REPLACE	1.00	\$150.00	150.00
6	FOOT BRAKE PEDAL P/N: 62565	REPLACE	1.00	\$42.00	42.00
7	GUARD LEG RH	REPLACE	1.00	\$25.00	25.00
8	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED		1.00	\$190.00	190.00
9	LEVER BRAKE	REPLACE	1.00	\$18.00	18.00
10	LOCK PLATE RH	REPLACE	1.00	\$3.00	3.00
11	MIRROR RH P/N: 62560	REPLACE	1.00	\$28.00	28.00
12	REAR BOX BRACKET (KAPPA)	REPLACE	1.00	\$138.00	138.00
13	REFLECTOR	REPLACE	1.00	\$7.00	7.00



bizSAFE₃



Address: No. 6, Delu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERTIFIED 200 HMM
20181121

S/N	Description	Action	Qty	Unit Price	Amount
14	STEP HOLDER PILLION RH	REPLACE	1.00	\$55.00	55.00
15	STEP PILLION ASSY COMP	REPLACE	1.00	\$18.00	18.00
16	STICKER P PLATE P/N: 29128	REPLACE	1.00	\$18.00	18.00
17	TUBE REAR HUGGER MTG	REPLACE	1.00	\$35.00	35.00
SUB TOTAL					\$954.00
GST @ 7 %					\$66.78
GRAND TOTAL					\$1,020.78

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

bizSAFE₃CERT NO. 29044002
ISO 9001:2015

Nivitha (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 11 June 2019 6:04 PM
To: assignments
Subject: FW: Accident Involving FBL9895M & SLR2694Y on 30/05/2019
Attachments: 11349_Claim File.pdf; SLR2694Y.PDF

12.55pm @ 12/6/19
person @ Raymond
vehicle in
SUR @ Mams.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ERGO Insurance Pte. Ltd. (Claims Department) [mailto:claims@ergo.com.sg]

Sent: Tuesday, 11 June 2019 4:33 PM

To: Admin A (admin-a@lkkauto.com) <admin-a@lkkauto.com>; SUR (sur@lkkauto.com) <sur@lkkauto.com>

Subject: FW: Accident Involving FBL9895M & SLR2694Y on 30/05/2019

Hi,

Please survey vehicle for direct settlement.

Thank you.

Warmest Regards,

Phoebe Jay Xie

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five

Singapore 038985

DID.: +65 6829 9191

phoebe.xie@ergo.com.sg

From: ERGO Insurance Pte. Ltd. (Claims Department)

Sent: Tuesday, 11 June, 2019 3:23 PM

To: raymond@bhh.com.sg

Cc: ERGO Insurance Pte. Ltd. (Claims Department)

Subject: FW: Accident Involving FBL9895M & SLR2694Y on 30/05/2019

Dear Sir,

We acknowledged receipt of your email for the PRS request as below.

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below.

- | | | |
|---|-----|--|
| 1 | AIS | Automobile Inspection Services Pte Ltd |
| 2 | FTA | FormTeam Consultancy Pte Ltd |
| 3 | IAS | Infiniti Appraisal Service |
| 4 | JPk | JP Knights Pte Ltd |

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBL9895M		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	BAJAJ		
Vehicle Model :	PULSAR 200 NS FI		
Chassis No. :	MD2A36FZ5GCA25793		
Propellant :	Petrol		
Engine No. :	JLZCGA30679		
Engine Capacity :	200 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	299 kg		
Unladen Weight :	145 kg		
Year Of Manufacture :	2016		
Original Registration Date :	06 Jun 2017		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$6,101.00		
COE Expiry Date :	05 Jun 2027		
Road Tax Expiry Date :	05 Jun 2020		
Inspection Due Date :	05 Jun 2020		
Intended Transfer Date :	12 Jun 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

shirleyloo@ajaxmars.com

From: Judy Ang <judyang8@singnet.com.sg>
Sent: Friday, 31 May 2019 12:19 PM
To: shirleyloo@ajaxmars.com
Cc: group@ajaxmars.com
Subject: ***SPAM*** Re: SLR2694Y-30052019-GIA REPORT (AMENDED)

Dear Shirley

As spoken to Elizabeth earlier, please amend the report as I will be claiming my own insurance. The report Should be amend to yes instead of No.

Please amend the report and resend to me.

Thank you.

Best regards
Judy Ang

Sent from my iPhone, please excuse typos and short responses

On 30 May 2019, at 10:07 PM, <shirleyloo@ajaxmars.com> <shirleyloo@ajaxmars.com> wrote:

Dear Sir/Madam,

Please find attached file, the GIA Accident Report for your perusal.

Should you wish to reply to this email, kindly click "Reply All"

If you require any further clarification on the matter, please do not hesitate to contact us at 6333 2222.

Thank You.

Mobile Accident Response Service (MARS)
Tel: 6333 2222



Virus-free. www.avast.com

<SLR2694Y-30052019-GIA REPORT (AMENDED).pdf>



e-Services (/content/policehubhome/homepage.html)

Log in

Status of Driving Licence

Qualified Driving Licence

Qualified Driving Licence Number

S1580078Z

Status of Qualified Driving Licence

Valid

Class(es) of Qualified Driving Licence

3

Expiry Date

Lifetime unless revoked, suspended or disqualified

Provisional Driving Licence

You are not a valid Provisional Driving Licence Holder.

HOME (<https://www.police.gov.sg/>)

ABOUT US (<https://www.police.gov.sg/about-us>)

SGSECURE (<https://www.police.gov.sg/sgsecure>)

I-WITNESS (<https://www.police.gov.sg/iwitness>)

COMMUNITY PROGRAMMES (<https://www.police.gov.sg/community-programme>)

RESOURCES (<https://www.police.gov.sg/resources>)

NEWS & PUBLICATIONS (<https://www.police.gov.sg/news-and-publications>)

JOIN US (<https://www.police.gov.sg/join-us>)

FAQS (<https://va.ecitizen.gov.sg/cfp/CustomerPages/SPF/explorefaq.aspx>)

CONTACT US (<https://www.police.gov.sg/content/contact-us>)

E-FEEDBACK (/content/policehubfeedback/efeedback.html)

SITEMAP (<https://www.police.gov.sg/sitemap>)

Privacy Statement (<https://www.police.gov.sg/content/privacy-statement>) | Terms of Use

(<https://www.police.gov.sg/content/terms-of-use>) | Rate this Service

(<https://fdm.gov.sg/forms/spf/5b90934f64567e000fb2d9a6>) . © 2019 Singapore Police Force. A Member of The Home Team (<https://www.mha.gov.sg>).

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 3 July 2019 11:38 AM
To: JUDYANG8@SINGNET.COM.SG
Cc: Admin A
Subject: ACCIDENT INVOLVING SLR 2694Y & FBL9895M ALONG ON 30/05/2019

Tracking:	Recipient	Delivery
	JUDYANG8@SINGNET.COM.SG	
	Admin A	
	shupei@lkkauto.com	Delivered: 3/7/2019 11:38 AM
	olivialau@lkkauto.com	Delivered: 3/7/2019 11:38 AM
	Meikwan@lkkauto.com	Delivered: 3/7/2019 11:38 AM

Our Ref: CC4/EG19010409/Ukb3
Your Ref: SLR 2694Y

ANG SIEW GEOK
APT BLK 422
SERANGOON CENTRAL
#04-368
SINGAPORE 550422

Dear Sir/Madam,

ACCIDENT INVOLVING SLR 2694Y [ERGO] & FBL9895M ALONG ON 30/05/2019

We refer to the above subject matter.

We write to inform you that we are the loss adjuster appointed by your motor insurer, **ERGO Insurance Company Limited** to deal with the third party claim against your policy.

We have received a claim from FBL9895M against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 8 October 2019 11:28 AM
To: Raymond
Cc: Admin A
Subject: RE: Accident Involving FBL9895M & SLR2694Y on 30/05/2019 *** LKK REF: CC4/EGI19010409/Ukb3

Tracking:	Recipient	Delivery
	Raymond	
	Admin A	
	olivialau@lkkauto.com	Delivered: 8/10/2019 11:29 AM
	Meikwan@lkkauto.com	Delivered: 8/10/2019 11:29 AM
	shupei@lkkauto.com	Delivered: 8/10/2019 11:29 AM

WITHOUT PREJUDICE

Dear Raymond,

The above matter and your e-mail below refers.

We confirm settlement at **\$968.93(all in)** as per your LOD dated 18/7/2019.

We will be proceeding to submit our report to process for your payment.

Please note that for M/s ERGO Insurance cases, quantum below \$20k do not require DV.

Thank you.

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Raymond <raymond@bhh.com.sg>
Sent: Tuesday, 8 October 2019 11:03 AM
To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Accident Involving FBL9895M & SLR2694Y on 30/05/2019 *** LKK REF: CC4/EGI19010409/Ukb3

Dear Khanchna,

Please refer to our Letter of Demand dated 18/07/2019.

We are still pending to receive the DV for the above direct settlement.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s ERGO INSURANCE PTE LTD

Date: 15/11/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SLR 2694Y (Insd Veh)	Your Ref. No. : DMPG18002287
	FBL 9895M (TP Veh)	Our Ref. No. : CC4/EGI19010409/Ukb3q2
Date of Accident	30/5/2019	

Liability	100%	
Final Repair Cost	: \$ 906.93	
Loss of Use	: \$ 60.00	3 days
Rental (If any)	: \$	days
Others:	: \$ 2.00	
	: \$	
	968.93	
Final Settlement Sum	: \$ 968.93	
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	BAN HOCK HIN CO.PTE LTD	: \$ 968.93
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CC4/EGI19010409/Ukb3q2

5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 15-11-2019



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLR 2694Y	Veh. Inspected	FBL 9895M
Policy No.	DMPG18002287	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	PHOEBE	Assign Date	11/06/2019

2. Vehicle Particulars & Condition

Make & Model	BAJAJ PULSAR	c.c	200
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MD2A36FZ5GCA25793	Colour	BLACK
Odometer	17023	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	110-70-17	PIRELLI	8 mm
L/H Front Tyre			mm
R/H Rear Tyre	140-70-17	PIRELLI	8 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/05/2019	Inspection Date	12/06/2019
Survey held at	BAN HOCK HIN CO,PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 9895M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	ASLY HUGGER REAR	DEFORMED	35.00	35.00
1	BALANCER RH	SCRATCHED	28.00	28.00
1	BOX REAR (GIVI) E33N W/O LIGHT -BLACK	CUT	155.00	155.00
1	BRACKET REFLECTOR MTG	NECESSARY	9.00	9.00
1	FOOT BRAKE PEDAL	BENT	42.00	42.00
1	GUARD LEG RH	NECESSARY	25.00	25.00
1	LEVER BRAKE	SCRATCHED	18.00	18.00
1	LOCK PLATE RH	NECESSARY	3.00	3.00
1	MIRROR RH	CUT	28.00	28.00
1	REAR BOX BRACKET (KAPPA)	BENT	138.00	138.00
1	REFLECTOR	MISSING	7.00	7.00
1	STEP HOLDER PILLION RH	CUT	55.00	55.00
1	STEP PILLION ASSY COMP	CUT	18.00	18.00
1	STICKER P PLATE	NECESSARY	18.00	18.00
1	TUBE REAR HUGGER MTG	NECESSARY	35.00	35.00
1	FOG LIGHT	DAMAGED	150.00	150.00
	LESS 10% DISCOUNT		-	-76.40
			764.00	687.60
	LABOUR			
	LABOUR -FOR DISMANTLE AND ASSEMBLING OF PARTS QUOTED.		190.00	160.00
			190.00	160.00
	GRAND TOTAL		954.00	847.60
RECOMMENDED COST OF REPAIRS				847.60

Report Ref No. CC4/EG19010409/Ukb3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.