



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

ERGO INSURANCE PTE LTD
302 ORCHARD ROAD
#09-01 TIONG BUILDING
SINGAPORE 238862

ERGO INSURANCE PTE LTD

VEHICLE NO. : FBL9895M
MAKE/MODEL : BAJAJ / PULSAR 200 NS M

NO. : 34256

DATE : 11/06/2019
CLAIM NO. : 11349
POLICY NO. :

FROM : RAYMOND

*not Afford
nhan
2/12/19
3027.
11/6/19
24h/24h AM-12p*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	ASLY HUGGER REAR	REPLACE	1.00	\$35.00	35.00
2	BALANCER L/RH P/N: 62564	REPLACE	1.00	\$28.00	28.00
3	BOX REAR (GIVI) E33N W/O LIGHT-BLACK P/N: 44275	REPLACE	1.00	\$155.00	155.00
4	BRACKET REFLECTOR MTG P/N: 62557	REPLACE	1.00	\$9.00	9.00
5	FOG LIGHT	REPLACE	1.00	\$150.00	150.00
6	FOOT BRAKE PEDAL P/N: 62565	REPLACE	1.00	\$42.00	42.00
7	GUARD LEG RH	REPLACE	1.00	\$25.00	25.00
8	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED		1.00	\$190.00	190.00
9	LEVER BRAKE	REPLACE	1.00	\$18.00	18.00
10	LOCK PLATE RH	REPLACE	1.00	\$3.00	3.00
11	MIRROR RH P/N: 62560	REPLACE	1.00	\$28.00	28.00
12	REAR BOX BRACKET (KAPPA)	REPLACE	1.00	\$138.00	138.00
13	REFLECTOR	REPLACE	1.00	\$7.00	7.00



bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0383
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
14	STEP HOLDER PILLION RH	REPLACE	1.00	\$55.00	55.00 ?
15	STEP PILLION ASSY COMP	REPLACE	1.00	\$18.00	18.00 ?
16	STICKER P PLATE P/N: 29128	REPLACE	1.00	\$18.00	18.00 <i>me</i>
17	TUBE REAR HUGGER MTG	REPLACE	1.00	\$35.00	35.00 ?

SUB TOTAL

\$954.00

GST @ 7 %

\$66.78

GRAND TOTAL

\$1,020.78

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

Let Auto Components hence notify the Repairer of the following:

- To resolve before any painting
- To replace damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

bizSAFE₃