



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。
Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Attn: The Motor Claims Department

QBE INS INT'L LTD

No.60 Anson Road

#11-01 Mapletree Anson

Singapore 079914

WITHOUT PREJUDICE

(By Email Only)

DID: 65 6477 1186

Email: joyce.foo@qbe.com

Tel : 6477 1225

jttoh@qbe.com

Fax: 65 6534 5356

Date : 11/06/2019

Estimate Cost Repair Bill To Nissan Sunny SGG 3306 D & SLU 7290 E on 09/06/2019 @08:30:00

To Supply :-

1pc	Rear boot cover <i>Reated</i>		\$ 674.60	nett	✓
1pc	Rear boot cover sunny plate		\$ 105.20	nett	✓
1pc	Rear boot cover EX saloon plate	<i>3</i>	\$ 89.00	nett	✓
1pc	Rear boot cover CVTL plate		\$ 89.00	nett	✓
1pc	Rear lamp RH <i>cracked</i>		\$ 360.20	nett	✓
1pc	Rear lamp panel RH <i>Repaired</i>	<i>2448.10</i>	\$ 152.90	nett	+
1pc	Rear panel <i>Reated</i>	<i>2203.29</i>	\$ 334.00	nett	✓
2pcs	Rear boot cover hinge <i>new</i>	<i>86</i>	\$ 172.00	nett	+
1pc	Rear bumper <i>Disbled</i>		\$ 452.50	nett	✓
2pcs	Rear bumper bracket <i>RH Reated</i>	<i>95.2</i>	\$ 190.40	nett	<i>95.20</i>
2pcs	Rear bumper side bracket <i>new</i>	<i>36.6</i>	\$ 73.20	nett	✓
1pc	Rear bumper center moulding <i>new</i>	<i>175.2</i>	\$ 175.20	nett	✓
1pc	Rear boot inner rubber <i>new</i>		\$ 88.40	nett	+
			\$ 2,956.60		
less			10%	\$ 295.66	
				\$ 2,660.94	

1pc Rear reverse sersor *Damaged* *200* \$ ~~350.00~~ s/nett *200*

To dismanlte & replace damage parts,panel beat where necessaey.

\$ ~~820.00~~ *700*

To putty,apply primer & spray paint on the affecte portion

\$ ~~880.00~~ *800*

To check wiring functions

\$ ~~80.00~~ *30*

To remove reverse sensor

\$ ~~50.00~~ ✓

\$ 4,840.94

LKK Auto Consultants hence notify the Repairer of the following:
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3983.29

4/5: 3150

Admin King
4/5 12/06/19
06Days