

[illegible]

		SUBTOTAL		\$	6,321.90	\$	-
		10%		\$	632.19	\$	-
		PARTS TOTAL		\$	5,689.71	\$	-
SPECIAL NETT		QTY	PRICE	PRICE			
1	TAIL GATE STICKER (NISSAN) <i>per</i>	1	\$	180.00	120		
2	TAIL GATE STICKER (70KM/H) <i>per</i>	1	\$	40.00	10		
3	TAIL GATE STICKER (13 PAX) <i>per</i>	1	\$	40.00	10		
4	REFLECTIVE STICKER (YELLOW AND RED) <i>per</i>	1	\$	350.00	100		
5	REAR NUMBER PLATE <i>per</i> 440	1	\$	80.00	X		
6	REVERSE SENSOR <i>per</i>	1SET	\$	250.00	200		
		SPECIAL NETT 1	\$	940.00	\$	-	
LABOUR		QTY	PRICE	PRICE			
1	TO KNOCK, STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA	1	\$	1,200.00	200		
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1	\$	1,400.00	250		
3	TO RUST PROOF ACCIDENT AFFECTED AREA 520	1	\$	120.00	X		
4	TO CHECK REVERSE SENSOR AND WIRING	1	\$	120.00	70		
		LABOUR TOTAL	\$	2,840.00	\$	-	
		GRAND TOTAL COST	\$	9,469.71	\$	-	

PAGE 2 OF 2

total : 1108.
4/5: 880
02 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: