

cc4, 111 190 10445, Agaz 9

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A.:

Nature of Accident:

(VA YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES NO ; TP GIA REPORT: YES NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Advain

Repair Cost:

S\$ 6000.00

(7

days)

Reduction: \$6626.06 % 52

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

(W/loss) S\$ 6420.00

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ 880.00

(\$ 80 x 11 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$ 7.95

Medical:

S\$ -

Disbursement:

S\$ -

(e.g Tow/Independent)

Legal Cost

S\$ -

Total:

S\$ 7307.45

Global Sum S\$:

7300.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 7300.00

Name 1:

H-51 Automotive Pte Ltd

Payee 2: (Strike if N/A)

S\$ -

Name 2:

Payee 3: (Strike if N/A)

S\$ -

Name 3:

COPY SENT
3/3/2020

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$400/-

Accident

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OO / TP / WS / TP RES / OO RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop m/s N51
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 7 days Res.: Yes or No
Lum Sum: 70 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Vehicle: IN / OUT
Person Contacted: _____

Veh No: XD3612J Yr Regn: 2009, June
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Mit Fuso c.c 12882
Colour: Gold A/C: Insured / Std / Nil / NA
Sp. Reading 578168 T/Radio: Insured / Std / Nil / NA
Eng/No: _____
C/No: FV5IJJA00525
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: (Nil) / S/Rim / STD A/Rim or
Tyre Size: F: 295/80 R22.5
R: 295/80 R22.5
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Firemax
Front: _____ Rear: _____
R/Bal. 06 mm R/Bal. 06 mm
L/Bal. 06 mm L/Bal. 06 mm
D.O.A. _____ D.O.I. 11/06/19
Survey held at N51
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front O/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP 111</u>
	<u>COE Expiry: 10/06/24.</u>
	<u>45 @ 1000/- (Red = \$6626.06 / 57%)</u>
	<u>MV: 12560K (Depreciation 12k)</u>
	<u>PV: 14.1K</u>
	<u>Nett: 45.9K</u>
	<u>7 repair days + 1 Sunday + 2 TRS + 1 cat = 11 days</u>

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:	Survey Fee:	Date:
1)	2)	IN	Basic & Add.	
3)	4)	OUT	S + RS, SI	
5)	6)		Photos	
Prel. Report:			Others	
Final Report:			TOTAL	



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LEY CHOON CONSTRUCTIONS AND
 ENGINEERING PTE LTD
 3 SUNGEI KADUT DRIVE KRANJI
 INDUSTRIAL ESTATE
 SINGAPORE 729556

Contact : 92479045

TP 111
 Cecilia

ESTIMATE

Repair Code : CLM15288

Date in : 10/06/2019

Vehicle Num. : XD3612J

Model : MITSUBISHI FV51JJD4RDEA

Chassis/Eng# : FV51JJA00525/6M70429876

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Delivered.</i>	1	2517.38	2517.38 ✓
FRONT BUMPER RH FOGLAMP <i>cracked.</i>	1	293.24	293.24 ✓
FRONT RH ARCH GARNISH <i>cracked</i>	1	532.00	532.00 ✓
FRONT RH ARCH GARNISH MOULDING <i>new</i>	1	211.00	211.00 ✓
FRONT RH CENTER STEP GARNISH <i>discontinued</i>	1	430.66	430.66 ✓
FRONT RH CORNER GARNISH <i>cracked</i>	1	1086.57	1086.57 ✓
FRONT RH CORNER GARNISH SIGNAL LAMP <i>new</i>	1	238.00	238.00 ✓
FRONT RH DOOR LAMP <i>new</i>	1	145.00	145.00 ✓
FRONT RH HEADLAMP <i>cut</i>	1	1286.44	1,286.44 ✓
FRONT RH HEADLAMP BRACKET <i>cracked</i>	1	729.60	729.60 ✓
FRONT RH HEADLAMP GARNISH <i>new</i>	1	257.49	257.49 ✓
FRONT RH LOWER STEP GARNISH <i>cracked.</i>	1	157.00	157.00 ✓
FRONT RH LOWER STEP PANEL <i>cracked.</i>	1	310.57	310.57 ✓
FRONT RH LOWER STEP PANEL LOWER COVER <i>cracked</i>	1	103.10	103.10 ✓
FRONT RH STEP PANEL BRACKET (FRONT) <i>Best</i>	1	191.00	191.00 ✓
FRONT RH STEP PANEL BRACKET (REAR) <i>Best</i>	1	205.00	205.00 ✓
FRONT RH UPPER STEP GARNISH <i>cracked.</i>	1	468.78	468.78 ✓
FRONT RH UPPER STEP PANEL <i>new</i>	1	310.57	310.57 ✓

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

LEY CHOON CONSTRUCTIONS AND
ENGINEERING PTE LTD
3 SUNGEI KADUT DRIVE KRANJI
INDUSTRIAL ESTATE
SINGAPORE 729556

Contact : 92479045

ESTIMATE

Repair Code : CLM15288

Date in : 10/06/2019

Vehicle Num. : XD3612J

Model : MITSUBISHI FV51JJD4RDEA

Chassis/Eng# : FV51JJA00525/6M70429876

		Subtotal before discount	9,473.40
Percentage discount	10%		947.34
		Sub-total 1	8,526.06
FRONT PARKING SENSOR	HE NEW	1	250.00 X
FRONT RH ARCH GARNISH CLIPS - SET	NEW	1	40.00 20
FRONT RH CORNER GARNISH CLIPS - SET	NEW	1	40.00 20
FRONT RH CORNER GARNISH SENSOR	NEW	1	250.00 +
FRONT RH DOOR ART STICKER	NEW	1	180.00 X
		Subtotal before discount	760.00
Percentage discount	0%		0.00
		Sub-total 2	760.00
		Parts-total	9,286.06

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall window glass. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

3,340.00

Parts & Labour Total

12,626.06

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from LKK Auto Consultants

Acknowledged by Repairer

Signature:

Date:

total 7492.29
H/S 6K
070up
0727

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner/Leasor

Owner ID Type:	Company
Owner ID:	4441H

Vehicle Details

Vehicle No.:	XD3612J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	11 Jun 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	FV51JJD4RDEA
Primary Colour:	Gold
Manufacturing Year:	2008
Engine No.:	6M70429876
Chassis No.:	FV51JJA00525
Maximum Power Output:	-
Open Market Value:	\$99,435.00
Original Registration Date:	11 Jun 2009
First Registration Date:	11 Jun 2009
Transfer Count:	0
Actual ARF Paid:	\$4,972.00

Intended PARF Rebate Amount

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	10 Jun 2024
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$14,132.00
COE Rebate Amount:	\$14,126.00
Total Rebate Amount:	\$14,126.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 11 Jun 2019

OK



☐	Mitsubishi Fuso Super Great FV513 (New 10-yr COE)	\$139,800	\$13,970 /yr	29-Dec-2009	12,882 cc	-	Truck	Available
Fuel Type: Diesel								
1 Owner, 10 Wheeler Mitsubishi FV513 With Palfinger PK42502 Crane, 5 Booms. Very Well Maintained, Service And Parts Replaced Regularly! Crane Maintenance By Agent Only, Come With Remote Control And Sp...								
Car (S) Pte Ltd								
☆ Posted: 10-Jun-2019 Target: 2009 Mitsubishi Fuso, 2009 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi								

PREMIUM



☐	Mitsubishi Fuso Super Great FV513	\$88,800	\$25,600 /yr	26-Nov-2012	12,882 cc	-	Truck	Available
Fuel Type: Diesel								
Condition Like New. Will Immediate Transfer Ownership So Buy With Worries Free. Flexible Loan Options Available, Call Now.								
Grande Auto Credit								
☆ Posted: 22-Apr-2019 Target: 2012 Mitsubishi Fuso, 2012 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi								



☐	Mitsubishi Fuso Super Great FV513	\$100,900	\$22,970 /yr	01-Nov-2013	12,882 cc	-	Truck	Available
Fuel Type: Diesel								
☆ Posted: 23-May-2019 Target: 2013 Mitsubishi Fuso, 2013 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi								



☐	Mitsubishi Fuso Super Great FV51S	\$72,888	\$14,790 /yr	15-May-2014	11,967 cc	-	Truck	Available
Fuel Type: Diesel								
☆ Posted: 16-Jun-2019 Target: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi								

DIRECT OWNER



Save up to 25% on petrol

Compare the latest petrol discount credit cards on sgCarMart. Enjoy discounts as high as 25% on your petrol bills.

[Find out more!](#)



☐	Mitsubishi Fuso Super Great FV51S	\$88,000	\$17,200 /yr	22-Jul-2014	11,967 cc	-	Truck	Available
Fuel Type: Diesel								
Mitsubishi FV51 Prime Mover 10 Wheeler, Vehicle Is In Superb Condition. View To Believe. Call In For Viewing And Test Drive Now.								
Bell Auto Pte Ltd								
☆ Posted: 17-Jun-2019 Target: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi								



☐	Mitsubishi Fuso Super Great FV51S	\$88,800	\$17,350 /yr	23-Jul-2014	11,967 cc	-	Truck	Available
Fuel Type: Diesel								
Very Powerful & Reliable FV51S 80Ton Prime Mover. Vehicle 5 Years Old, But In Superb Condition. New Spray Work. 100% Loan Available. Easy Approval. High Value Trade In For Your Vehicle, View To Believe...								
Bell Auto Pte Ltd								
☆ Posted: 06-Jun-2019 Target: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi								



☐	Mitsubishi Fuso Super Great FV51S	\$88,800	\$17,350 /yr	23-Jul-2014	11,967 cc	-	Truck	Available
Fuel Type: Diesel								
Most Popular 10 Wheelers Prime Mover In Singapore! With New Paintwork, Fully Repaired By Goldbell Authorised Workshop With New Servicing Done. Welcome This Superb Prime Mover To Your Existing Fleet! E...								
Bell Auto Pte Ltd								
☆ Posted: 21-May-2019 Target: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi								



☐	Mitsubishi Fuso Super Great FV51S	\$208,000	\$39,940 /yr	25-Aug-2014	11,967 cc	-	Truck	Available
Fuel Type: Diesel								
10 Wheels Crane Lorry, Fassi F455 Crane, In House Finance And Competitive Insurance Is Available, High Trade-In, Company Logo Available. Any Enquire Or Request Do Not Hesitate To Give Us A Call. View T...								
Convince Auto								
☆ Posted: 08-Jun-2019 Target: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi								



☐	Mitsubishi Fuso Super Great FV51S	\$181,800	\$26,850 /yr	28-Sep-2015	11,967 cc	12,000 km	Truck	Available
Fuel Type: Diesel								
10 Wheel Truck With Palfinger Crane PK33002. Low Mileage. 3 x 4 Boom. In Superb Condition. Well-Maintained By Previous Owner. Fast And Flexible In-House Loan And Insurance Available. High Value For Yo...								
ABWIN (1994) Pte Ltd								
☆ Posted: 06-Jun-2019 Target: 2015 Mitsubishi Fuso, 2015 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi								

EXCLUDED HISTORY

Compare

Print Received Message

This mail is associated with :

***XD3612J (MCT19040554)**
[SH7794D]

TP

LEY CHOON CONSTRUCTIONS AND ENGINEERING PTE LTD

Apr 20 2019 10:00AM

[COMFORT TRANSPORTATION PTE LTD]

N-51 Automotive Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 21/02/2020 08:30 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$7527.45) - XD3612J - Claim Handler: Pool Chin Han Daniel

Approved:7527.45:We agree on liability, please revert on quantum

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Dec 2019 Edit Reg		11 Jun 2019 00:00 Edit Adj Rpt	S\$6,000.00 Edit Estimates	S\$6,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	LEY CHOON CONSTRUCTIONS AND ENGINEERING PTE LTD, Co. Reg. No.: 199004441H		
Vehicle Reg. No.:	XD3612J	Date of Loss:	20/04/2019 10:00 - :59 [118 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT19040554	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	SH7794D	Policy No. (Claimant):	5075626144-03
	Excess:		
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pool Chin Han Daniel]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/06/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- III_SG (21/02/2020): Alert - Adj Mandate Approved (S\$7527.45) - XD3612J - Claim Handler: Pool Chin Ha...
- III_SG (31/12/2019): Alert - Adj Mandate Approved (S\$0.00) - XD3612J - Claim Handler: Pool Chin Han D...

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XD3612J (MCT19040554)

[SH7794D]

TP

LEY CHOON CONSTRUCTIONS AND ENGINEERING PTE LTD

Apr 20 2019 10:00AM

[COMFORT TRANSPORTATION PTE LTD]

N-51 Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Video									1 per page		☒
No	Finalized On	India International Insurance Pte Ltd (HQ)							Thumbnail	Print	
1	31/12/19 11:06	Video - Accident TP							Load MP4		
2	31/12/19 11:08	Video - Accident IV							Load MP4		
Photos/Images									3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	11/11/19 09:04	General View							Load JPG	☒	
2	11/11/19 09:04	General View							Load JPG	☒	
3	11/11/19 09:04	General View							Load JPG	☒	
4	11/11/19 09:04	General View							Load JPG	☒	
5	11/11/19 09:04	General View							Load JPG	☒	
6	11/11/19 09:04	General View							Load JPG	☒	
7	11/11/19 09:04	General View							Load JPG	☒	
8	11/11/19 09:04	General View							Load JPG	☒	
9	11/11/19 09:04	General View							Load JPG	☒	
10	11/11/19 09:04	General View							Load JPG	☒	
11	11/11/19 09:04	General View							Load JPG	☒	
12	11/11/19 09:04	General View							Load JPG	☒	
13	11/11/19 09:04	General View							Load JPG	☒	
14	11/11/19 09:04	General View							Load JPG	☒	
15	11/11/19 09:04	General View							Load JPG	☒	
16	11/11/19 09:04	General View							Load JPG	☒	
17	11/11/19 09:04	General View							Load JPG	☒	
18	11/11/19 09:04	General View							Load JPG	☒	
19	11/11/19 09:04	General View							Load JPG	☒	
20	11/11/19 09:06	Reinspection Photo							Load JPG	☒	
21	11/11/19 09:06	Reinspection Photo							Load JPG	☒	
22	11/11/19 09:06	Reinspection Photo							Load JPG	☒	
23	11/11/19 09:06	Reinspection Photo							Load JPG	☒	
24	11/11/19 09:06	Reinspection Photo							Load JPG	☒	
25	11/11/19 09:06	Reinspection Photo							Load JPG	☒	
26	11/11/19 09:06	Reinspection Photo							Load JPG	☒	
27	11/11/19 09:06	Reinspection Photo							Load JPG	☒	
28	11/11/19 09:06	Reinspection Photo							Load JPG	☒	
29	11/11/19 09:06	Reinspection Photo							Load JPG	☒	
30	11/11/19 09:06	Reinspection Photo							Load JPG	☒	
31	11/11/19 09:06	Reinspection Photo							Load JPG	☒	
32	11/11/19 09:06	Reinspection Photo							Load JPG	☒	
33	11/11/19 09:06	Reinspection Photo							Load JPG	☒	
34	11/11/19 09:06	Reinspection Photo							Load JPG	☒	
35	11/11/19 09:06	Reinspection Photo							Load JPG	☒	
36	11/11/19 09:06	Reinspection Photo							Load JPG	☒	
37	11/11/19 09:06	Reinspection Photo							Load JPG	☒	
38	11/11/19 09:06	Reinspection Photo							Load JPG	☒	
39	11/11/19 09:06	Reinspection Photo							Load JPG	☒	

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
40	11/11/19 09:06	Reinspection Photo		☒
41	11/11/19 09:06	Reinspection Photo		☒
42	11/11/19 09:06	Reinspection Photo		☒
43	11/11/19 09:06	Reinspection Photo		☒
44	11/11/19 09:06	Reinspection Photo		☒
45	11/11/19 09:06	Reinspection Photo		☒
46	11/11/19 09:06	Reinspection Photo		☒
47	11/11/19 09:06	Reinspection Photo		☒
48	11/11/19 09:06	Reinspection Photo		☒
49	11/11/19 09:06	Reinspection Photo		☒
50	11/11/19 09:06	Reinspection Photo		☒
51	11/11/19 09:06	Reinspection Photo		☒
52	11/11/19 09:06	Reinspection Photo		☒
53	11/11/19 09:06	Reinspection Photo		☒
54	11/11/19 09:06	Reinspection Photo		☒
55	11/11/19 09:06	Reinspection Photo		☒
56	11/11/19 09:06	Reinspection Photo		☒
57	11/11/19 09:06	Reinspection Photo		☒
58	11/11/19 09:06	Reinspection Photo		☒
59	11/11/19 09:06	Reinspection Photo		☒
60	11/11/19 09:06	Reinspection Photo		☒
61	11/11/19 09:06	Reinspection Photo		☒
62	11/11/19 09:06	Reinspection Photo		☒
63	11/11/19 09:06	Reinspection Photo		☒
64	11/11/19 09:06	Reinspection Photo		☒
65	11/11/19 09:06	Reinspection Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/06/19 08:56	NOTIFICATION FROM WORKSHOP		
2	13/06/19 08:56	NOTIFICATION FROM WORKSHOP + TP GIA REPORT		
3	13/06/19 08:56	ACKNOWLEDGEMENT EMAIL TO III DD 11.06.2019		
4	15/01/20 18:13	LOD AND OTHER DOCUMENTS		
5	05/02/20 15:23	WORKSHOP INVOICE		
6	05/02/20 15:23	LTA SEARCH		
7	05/02/20 15:23	LOD		
8	09/03/20 09:34	AUTHORISATION TO ACT FORM		
9	09/03/20 09:34	DISCHARGE VOUCHER		
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	13/06/19 08:41	Singapore Accident Statement IV		
2	31/12/19 11:10	Singapore Accident Statement TP XD3612J		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19010445/AGA3Q2

Date: 09/03/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant: XD3612J Insured Vehicle No: SH7794D
 Date of Loss: 20/04/2019 Nature of Claim: TP Claim No: MCT19040554

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD3612J
 Make & Model: MITSUBISHI FV51JJD4RDEA, 12.9 D (M) Engine No: 6M70429876
 Reg. Date: 11/06/2009 (Man. Year: 2008) Chassis No: FV51JJA00525
 Colour: Gold Odometer: 578168 km
 Engine Capacity: 12882 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5
 Front Left Side: Firemax 6 mm Rear Left Side: Firemax 6 mm
 Front Right Side: Firemax 6 mm Rear Right Side: Firemax 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,286.06	5,962.29	3,323.77	35.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,340.00	1,530.00	1,810.00	54.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,626.06	7,492.29	5,133.77	40.66
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	12,626.06	6,000.00	6,626.06	52.48
+ GST 7.00/7.00% (S\$)	883.82	420.00	463.82	52.48
Nett Amount (S\$)	13,509.88	6,420.00	7,089.88	52.48
+ Loss of Use (11.0 x S\$80.00/day) (S\$)		880.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,307.45		
Global Sum Settlement (S\$)		7,300.00		

INSPECTION

Date of Assignment: 11/06/2019
 Date Inspected: 11/06/2019 Inspected At: N-51 Automotive Pte Ltd (HQ)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI
 BUKIT AUTOHUB
 Singapore 417921
 Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Jan 2020)	
Parts:	N/A	MITSUBISHI FV51JJD4RDEA 12.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD3612J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	2,517.38 FL	*2,200.00 FL
2	1	*FRONT BUMPER RH FOGLAMP	Cracked	293.24 FL	*293.24 FL
3	1	*FRONT RH ARCH GARNISH	Deformed	532.00 FL	*532.00 FL
4	1	*FRONT RH ARCH GARNISH MOULDING	Not Necessary	211.00 FL	*- FL
5	1	*FRONT RH CENTER STEP GARNISH	Distorted	430.66 FL	*430.66 FL
6	1	*FRONT RH CORNER GARNISH	Cracked	1,086.57 FL	*989.00 FL
7	1	*FRONT RH CORNER GARNISH SIGNAL LAMP	Not Necessary	238.00 FL	*- FL
8	1	*FRONT RH DOOR LAMP	Not Necessary	145.00 FL	*- FL
9	1	*FRONT RH HEADLAMP	Cut	1,286.44 FL	*1,286.44 FL
10	1	*FRONT RH HEADLAMP BRACKET	Cracked	729.60 FL	*729.60 FL
11	1	*FRONT RH HEADLAMP GARNISH	Not Necessary	257.49 FL	*- FL
12	1	*FRONT RH LOWER STEP GARNISH	Cracked	157.00 FL	*157.00 FL
13	1	*FRONT RH LOWER STEP PANEL	Cracked	310.57 FL	*310.57 FL
14	1	*FRONT RH LOWER STEP PANEL LOWER COVER	Distorted	103.10 FL	*103.10 FL
15	1	*FRONT RH STEP PANEL BRACKET (FRONT)	Bent	191.00 FL	*191.00 FL
16	1	*FRONT RH STEP PANEL BRACKET (REAR)	Bent	205.00 FL	*205.00 FL
17	1	*FRONT RH UPPER STEP GARNISH	Cracked	468.78 FL	*468.78 FL
18	1	*FRONT RH UPPER STEP PANEL	Not Necessary	310.57 FL	*- FL
19	1	*FRONT PARKING SENSOR	Not Necessary	250.00 FS	*- FS
20	1	*SET FRONT RH ARCH GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
21	1	*SET FRONT RH CORNER GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
22	1	*FRONT RH CORNER GARNISH SENSOR	Not Necessary	250.00 FS	*- FS
23	1	*FRONT RH DOOR ART STICKER	Not Necessary	180.00 FS	*- FS
				Sub Total (\$\$)	10,233.40 7,936.39
				- List Item Discount on L Items 10.00/25.00% (\$\$)	947.34 1,974.10
				Total Parts (\$\$)	9,286.06 5,962.29

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.	New	80.00	30.00
2	TO REMOVE, REINSTALL WINDOW GLASS. (TO FR)	New	80.00	0.00
3	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.	New	1,500.00	800.00
4	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	1,600.00	650.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	New	80.00	50.00
Gross Labour Cost (S\$)			3,340.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >