

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Pauline Soh Li Ping

Date: 25 Nov 2019

## **Preliminary Advice**

Vehicle No	: SJX183K	Accident Date	: 05/06/2019
Make	: VOLKSWAGEN SHARAN	Policy No.	: 29091670AVW
Assignment Date	: 14/06/2019	Excess	: S\$1,500.00
Date of Inspection	: 13/06/2019	Est. Duration of Repair	: 11 days
Inspection At	: Volkswagen Centre Singapore (Alexandra) 247 Alexandra Road Singapore 159934		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion, n/s body, o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,304.10 (inclusive supp1 & 2)
Revised Amount	:S\$	12,044.82 (inclusive supp1 & 2)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	12,044.82
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	150,000.00
COE / PARF Rebate	:S\$	60,844.00
Salvage Value	:S\$	
Margin for Repair	:S\$	89,156.00

### **Remarks**

( X ) The vehicle is economical for repair. We have received supplementary 2 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Supplementary 2 amount is \$ 22.17.

( ) The above survey was conducted on a 'without prejudice' basis.