

Not Withstand
 11/12/19
 Resurvey After Paint
 5 days



ESTIMATE TO REPAIR

VEHICLE NO. : SKN 3549 K
 MAKE : TOYOTA
 MODEL : COROLLA ALTIS 1.6L CVT
 YEAR : 2014
 CHASSIS NO : MR053REH104509548

SURVEYOR NAME :	Kenneth (LKK)
DATE OF SURVEY :	17.06.2019
TIME OF SURVEY :	10.30am

DATE : 10-Jun-19
 DATE OF ACCIDENT : 8-Jun-19
 THIRD PARTY REF : SKA 3353 B / AIG

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ R1 486.50
2 pcs	Rear Bumper Retainer		\$ 88.50		\$ D11 177.00
2 pcs	Rear Bumper Bracket		\$ 56.30		\$ 112.60
1 pc	Rear End Panel				\$ R1 789.70
1 pc	Rear End Panel Garnish				\$ 189.20
1 pc	Rear Boot				\$ R1 784.60
1 pc	Rear Boot Lock				\$ 458.70
1 pc	Rear Boot Rubber				\$ 85.64
1 pc	Rear Boot Centre Emblem				\$ M 58.70
1 pc	Rear Boot COROLLA Emblem				\$ M c 88.50
1 pc	Rear Boot ALTIS Emblem				\$ M 85.90
2 pcs	Taillamps		\$ 381.90		\$ 763.80
1 pc	Rear Spare Tyre Top Cover				\$ Rn 324.11
	Less 25%				\$ 4,404.95
					\$ 1,101.24
					\$ 3,303.71
1 set	Rear Bumper Sensor	S.Nett			\$ Sham 200.00
1 pc	Rear Number Plate	S.Nett			\$ Rn 40.00
	To putty and spray painting				\$ F201 800.00
	To anti-rust				\$ 601 80.00
	Labour charges				\$ 601 650.00
TG/RA-	Total				\$ 5,073.71

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd