	22/13/2002 ASS. REC. BY: REF: (5)	FCI 19010492 RIG d3 Special Instruction:
	Surveyor Rasu) As	SSIGNMENT (Office)
(WS	From (Person): Hunny Kao of	PCL Date/Time: 13.6.19 2.56 p.m
	Estimated Cost:	Bill to:
	OD / TP / WS / TP RES / OD RES / EVA / IP To respect Vehicle No: SM 1 4714E	Insured: SH (07477
	at Workshop m/s Eurokars Habitat of 27A Tanjong Penjuru	Tel: 63310682
	Policy No:	Claim No: D19 00383) MFSH
	Sum Insured:	Excess:
	Make of Veh:(Client's Record)	D.O.A. 11.6.19
	CA / REV / REP. / REV 24 HRS	
	Date/Time Action/Instruction (√)	Estimate
	SM1 4114E-X	
	SH(0747-X	
	17/6/19@ 1149an versed to t	lenny kao by emuil.
	24/6/19@1-34m Confirmed	with Jessica fine By \$ 2344.70, 2 days.
	(Red \$ 70, 30/2)	71 11



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D19003832MFSH

Date: 17 June 2019

Our Ref: CS/FCI19010492/R1qd3

The Motor Claims Department MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SML 4714E .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/06/2019 at the premises of M/s EUROKARS HABITAT PTE LTD. and have the following to report:-

Workshop Estimate Amount	: <u>S\$</u>	2,414.70	
Revised Estimate Amount	: <u>S\$</u>	2,344.70	<u> </u>
"Check" Items Amount	: <u>S</u> \$	-	
Market Value	: <u>S\$</u>	-	
LTA Reimbursement Value	: <u>S</u> \$	-	
Nett Value	: <u>S\$</u>	-	

Description of Damage:

The vehicle sustained damages at the n/s rear portion.



Yours faithfully

Rasul Automotive Assessor



MS First Capital Insurance Limited Co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849

www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

12-06-2019

Our Ref No. D19003832MFSH

Accident Date

11-06-2019

Claim Type. Third Party

Insured Vehicle

SHC0747T

Third Party Vehicle. SML4714E

Survey Location

27A TANJONG PENJURU

Contact Person.

JOBI THOMAS

Contact No.

63310680/63310682

Fax No. 63310690

Survey Type

DIRECT SETTLEMENT:

Appointed

LKK AUTO CONSULTANTS PTE LTD

Surveyor Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

EUROKARS HABITAT

Attention, NIL

Cc : TP Solicitor

PTE LTD

NA

TP Solicitor Fax No. NA

Officer Incharge

HENRY KAO

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Monday, 24 June 2019 1:34 PM

To:

jessicahs@eurokars.com.sg

Cc:

jobithomas@eurokars.com.sg; sarah.candida@eurokars.com.sg; SUR

Subject:

RE: FINALIZATION FIRST CAP TP - SML4714E.xlsx

Dear Jessica,

WITHOUT PREJUDICE

Confirm final fig \$2,344.70 before GST and 2 repair days.

Kindly send the relevant documents to MS First Capital Insurance.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)

Sent: Monday, 24 June 2019 11:17 AM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Subject: FW: FINALIZATION FIRST CAP TP - SML4714E.xlsx

CS/FCI19010492/R1qd3

From: jessicahs@eurokars.com.sg <jessicahs@eurokars.com.sg>

Sent: Monday, 24 June, 2019 10:59 AM

To: Rasul (LKKAuto) < Rasul@lkkauto.com >; Admin A < admin-a@lkkauto.com >

Cc: sarah.candida@eurokars.com.sg; jobithomas@eurokars.com.sg

Subject: FINALIZATION FIRST CAP TP - SML4714E.xlsx

Dear Rasul,

Please find our computation attached for your agreement.

COR: \$2,344.70 before GST

2 repair days (not including preparation of estimate, wait for liability/wait for survey/authorization/spare parts, Sat/Sun/PH)

Appreciate your confirmation for this case urgently.

Thank you very much.

Regards,
Jessica Shastri
Admin Executive – Insurance Claims
27A, Tanjong Penjuru

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Monday, 17 June 2019 11:49 AM

To:

'CWS Motor Claims'; assignments; SUR

Cc:

'Henry Kao Cai Jie'

Subject:

RE: SURVEY ASSESSMENT - D19003832MFSH/1

Attachments:

CSFCI19010492R1qd3.pdf

Dear Henry,

Enclosed herewith preliminary advice of SML 4714E.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 13 June 2019 3:33 PM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR

<sur@lkkauto.com>

Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg> Subject: RE: SURVEY ASSESSMENT - D19003832MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Thursday, 13 June, 2019 2:56 PM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims < cwsmotorclaims@msfirstcapital.com.sg >; Henry Kao Cai Jie

<HenryKao@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19003832MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



CERTIFICATE OF INSURANCE

MINI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

: Yang Hao

Period of Insurance

: 23 May 2019 To 22 May 2021

Engine No.

: F930K073B38A15A

Chassis No.

: WMWXU72070TR62168

Vehicle No.

: SML4714E : 1900100884

Policy No.

Endorsement No. **Issued Date**

: 30 May 2019

ABOUT THE COVER

Make/Model

: MINI COOPER F55

Engine Capacity/Tonnage: 1,499.00 CC

Sum Insured : Market Value

First Year of Registration : 2019

Insuring with COE/PARF : Yes

: NA Driver Restriction Person or Classes of Persons Entitled to Drive*:

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience

Off Peak Car : No

Age Condition

: All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

· Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

Yang Hao - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Eurokars Habitat Pte Ltd. Add: Eurokars Centre. 12 Sungei Kadut Ave. Singapore 729648 63633003

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HL Bank

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0503599140

ARF (AP) PTE LTD - MINI

7 MAXWELL ROAD #01-100 ANNEX B MND COMPLEX


Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE











EUROKARS HABITAT PTE LTD 27A TANJONG PENJURU, SINGAPORE 609042



ESTIMATE COST OF REPAIRS

MS First Capita	al Insurance Ltd	NAME:			WIP:		28490	
6 Raffles Quay, #	21-00	ADDRESS: 11 Mount Sophia		EXCESS:				
Singapore 04858	30		#03-34 Sophia H	ills	DATE:	12	.06.2019	
			Singapore 22846	51				
ATTN.:	MOTOR CLAIMS	TEL:	852243	575				
FAX :				1000				
VEH NO :	SML4714E	DATE IN:		CONTACT PERSON :	JOBI THOM	1AS 633	310682	
CHASSIS NO :	WMWXU72070TR62168	MILEAGE :		TYPE OF CLAIM:		TP		
MODEL :	F55	DATE REG.:	23.05.2019	POLICY NO. :				
		Wi-	NATURE OF WO	ORKS .				1
s/NO		Pa	arts Description					1
			QTY		REVISED	1 8	PRIÇES	1
1 REAR WH	EEL ARCH 800		1	M51.77.7.329.031		\$	106.47	1
2 CLIP	re/		9	M07.14.2.754.954		\$	14.67	1
3 WHEEL RI	m cutr		1	M36.11.6.855.112		\$	1,093.56	1
	•	7.1						
				TOTAL PARTS		\$	1,214.70	
						\$		1
				TOTAL PARTS COST		\$	1,214.70	
								1
		Labour Descrip	tion					
1 TO REPLA	CE REAR DOOR WHEEL ARCH.					\$ 4	U 420.00	1
2 TO MOUI	NT 1 PC SPORT RIM AND CONDU	ICT WHEEL BALA	NCING.		NETT	\$	120.00	1
- Marie Carlotte								1
3 TO CHECK	K STEERING GEOMETRY & COND	UCT FULL WHEEL	ALIGNMENT.	(a)	NETT	\$	560.00	
		_	B	Mire			_ /	
4 SUNDRIE	s. Nec	KASUL		1 Hill	NETT	\$ 5	0 102.00	
		4090	010018	Wal				4
		" "		TOTAL LABOUR	\$ -	\$	1,200.00	4
		2 0	lauro	TOTAL PARTS	\$ -	\$	1,214.70	4
		20	lays 19@1630	TOTAL	\$ -	\$	2,414.70	
		14/1	1,4@1120	LESS EXCESS	\$ -	\$		
		14/20/	1761620	TOTAL AFTER EXCESS	\$ -			-
	C) ,	,	GST 7%	\$ -	\$	5	4
	*	con be	me .	GRAND TOTAL Auto Consu	itants bance notify	\$	-	

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED INSTITUTE. IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



EUROKARS HABITAT PTE LTD 27A TANJONG PENJURU, SINGAPORE 609042 FINALIZATION COST OF REPAIRS



28490 WIP: MS First Capital Insurance Ltd NAME: **EXCESS:** 6 Raffles Quay, #21-00 ADDRESS : 11 Mount Sophia 12.06.2019 DATE: #03-34 Sophia Hills Singapore 048580 Singapore 228461 TEL: MOTOR CLAIMS ATTN.: FAX: JOBI THOMAS 63310682 CONTACT PERSON: DATE IN: SML4714E VEH NO: TYPE OF CLAIM: TP WMWXU72070TR62168 MILEAGE : CHASSIS NO: POLICY NO. : 23.05.2019 DATE REG.: F55 MODEL: NATURE OF WORKS **Parts Description** S/NO **PRICES** REVISED QTY 106.47 \$ 106.47 \$ 1 M51.77.7.329.031 REAR WHEEL ARCH M07.14.2.754.954 \$ 14.67 14.67 9 CLIP 2 1,093.56 1,093.56 M36.11.6.855.112 1 WHEEL RIM \$ 1,214.70 TOTAL PARTS 1,214.70 1,214.70 \$ 1,214.70 \$ TOTAL PARTS COST **Labour Description** 400.00 420.00 TO REPLACE REAR DOOR WHEEL ARCH. 120.00 \$ 120.00 \$ TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING. 2 560.00 \$ 560.00 \$ TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT. 3 \$ 100.00 50.00 SUNDRIES. 4 TOTAL LABOUR \$ 1,130.00 \$ 1,200.00 1,214.70 \$ 1,214.70 TOTAL PARTS \$ 2,344.70 2,414.70 \$ \$ TOTAL \$ \$ LESS EXCESS TOTAL AFTER EXCESS Ś 2,344.70 \$ 164.13 GST 7% \$ \$ 2,508.83 **GRAND TOTAL**

NUMBER OF DAYS:2 WORKING DAYS (EXCLUDE WAITING FOR SURVEY, AUTHORIZATION, PARTS, SAT, SUN & PH)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

40 FIDOT OADITAL		Ref : CS/FCI1901049	
MS FIRST CAPITAL	INSURANCE LTD	Rei : C3/FC/1901048	22/K Iquonz
36 ROBINSON ROAL #16-01 CITY HOUSE	SINGAPORE 068877	Date: 27-06-2019 Code: FCI2	
1.	Policy Particula	rs :- THIRD PARTY CLAI	M
Insured Veh.	SHC 747T	Veh. Inspected	SML 4714E
Policy No.		Coverage (\$)	0.00
Claim No.	D19003832MFSH	Excess (\$)	0.00
Assign From	HENRY KAO	Assign Date	13/06/2019
2.	Vehicle Pa	rticulars & Condition	DESCRIPTION OF THE PARTY OF THE
Make & Model	MINI COOPER 5DR	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	WMWXU72070TR62168	Colour	RED
Odometer	977	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3.	Con	ditions of Tyres	ather to be 2
	Size	Make	Balance
R/H Front Tyre	205/45 R17	DUNLOP	6 mm
L/H Front Tyre	205/45 R17	DUNLOP	6 mm
R/H Rear Tyre	205/45 R17	DUNLOP	6 mm
L/H Rear Tyre	205/45 R17	DUNLOP	6 mm
4.	Descri	ption of Damages	
THE VEHICLE S	USTAINED DAMAGES AT THE	N/S REAR PORTION.	
DAMAGES SEE	DETAILS.		
5.	Gen	eral Information	
Accident Date	11/06/2019	Inspection Date	14/06/2019
Survey held at	EUROKARS HABITAT PTE I	LTD	
	NO.12 SUNGEI KADUT AVE SINGAPORE 729648		
5a.		Remarks	
B)THE INSPECT	DNSISTENT TO ACCIDENT REF TON WAS CONDUCTED ON A" NCE TO YOUR INSTRUCTIONS	WITHOUT PREJUDICE" BAS	
5b.		ate Days of Repair	
	RMAL PERIOD FOR REPAIR:	2 Working Day	rs.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 4714E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WHEEL ARCH (SN)	SCRATCHED	106.47	106.47
9	CLIP (SN)	NECESSARY	14.67	14.67
1	WHEEL RIM (SN)	CUT	1,093.56	1,093.56
- 1	SUNDRIES (SN)	NECESSARY	100.00	50.00
			1,314.70	1,264.70
	LABOUR			
	TO REPLACE REAR DOOR WHEEL ARCH.		420.00	400.00
	TO MOUNT 1PC SPORT RIM AND CONDUCT WHEEL BALANCING.		120.00	120.00
	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.		560.00	560.00
			1,100.00	1,080.00
	GRAND TOTAL		2,414.70	2,344.70

RECOMMENDED COST OF REPAIRS	2,344.70

Report Ref No. CS/FCI19010492/R1qd3n2

MKB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

St.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No.liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.