


Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg


INS TAX INVOICE

Page 1 15:43

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85014249 Date : 16/09/2019 Order : SKF8533P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120		
Regn No: SKF8533P (V 40521) Model: A4 SEDAN 2.0 TFSI 8W2ADG	Regn Date: 27/12/2018 Chassis: WAUZZZF42KN000967	Mileage: 35070 Engine: CVK 072225	WIP No.: 56469 Dept: U		
You have been assisted by :- UB-Siti Marsilla (137)					
		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1600.00	1.00	-1,600.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.	360.00	1.00	360.00
S	BODYWORK	M: TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	600.00	1.00	600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGE	280.00	1.00	280.00
S	BODYWORK	M: TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	1400.00	1.00	1,400.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIM, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	1400.00	1.00	1,400.00
S	BODYWORK	M: TO DISMANTLE REAR BUMPER, REAR LID AND LHS REAR DOOR. CUT OUT AND WELD LHS REAR FENDER AND LHS REAR INNER SIDE PANEL. RENEW LHS REAR DOOR. REORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	3500.00	1.00	3,500.00
S	BODYWORK	M: TO RESPRAY LHS REAR FENDER, LHS REAR DOOR, LHS SILL PANEL, ROOF CHANNEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORK	2750.00	1.00	2,750.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 15:43

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014249	Account: A0006 (T 0)
	Date : 16/09/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
	Order : SKF8533P	
	Term : 30	

Regn No: SKF8533P (V 40521)	Regn Date: 27/12/2018	Mileage: 35070	WIP No.: 56469
Model: A4 SEDAN 2.0 TFSI 8W2ADG	Chassis: WAUZZZF42KN000967	Engine: CVK 072225	Dept: U
You have been assisted by :- UB-Siti Marsilla (137)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO SUPPLY ACRYLIC SEALANT,CAVITY WAX,STONE CHIP,METAL FILLER POWDER,REAR WINDSCREEN SEALANT AND 1/4 GLASS SEALANT	1080.00	1.00	1,080.00
X	A8W5809837	SUBPART (LAST) Less 020%	1.00	2443.00	1,954.40
X	A8W5845297D NVE	SIDE WINDO (LAST) Less 020%	1.00	560.50	448.40
X	A8W5833051C	(SK) DOOR (LAST) Less 020%	1.00	2152.00	1,721.60
X	A8W5845501B NVE	REARWINDOW (LAST) Less 020%	1.00	1049.00	839.20
X	A8K9805673C	SPEED NUT Less 020%	1.00	1.20	0.96
X	A8W5839911A	(SK) SEAL Less 020%	1.00	184.50	147.60
X	AN 91233601	NUT Less 020%	2.00	1.00	1.60
X	AWHT005180	BOLT Less 020%	1.00	8.30	6.64

Parts 5,120.40
Labour 0.00
Sublet 11,562.00
Menus 0.00
Lubricant 0.00

Sub-Total 15,082.40

7% GST 1,055.77

Grand Total 16,138.17



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKF 8533 P

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0742/2019/SM
1ST JULY 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 2.0 TFSI
Vehicle Chassis No. : WAUZZZF42KN000967
Vehicle Regn No. : **SKF 8533 P**
Vehicle Mileage : 3500 KM
Vehicle Owner : Mr.Allaudeen S/O Ham eed
Certificate No : 1800150379
Own Damage Excess : \$1712.00 (Inclusive 7%GST)
Accident Date : 11th June 2019
Place : MINAMAR HOTEL CAR-PARK
Repair Cost : \$ 16,138.17
WIP No. : 56469
Repairer’s Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer’s charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : _____
Date : _____