

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

13 JUN 2019

E S T I M A T E

Estimate No.	: b1 51547	Page No. : 1 of 5
Date Estimated	: 13/06/2019	
Prepared By	: Gary Poh Chai Hoon	

- ESTIMATE REPAIR FOR - Lim Soh Hoon @ Florence Lim 18 Hythe Road Singapore 557499	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP1159E	D335085	15/08/2014	520ia	0

DESCRIPTION	VALUE
To replace front bumper, right front fender and attachment include knocking cause by the accident.	1700 2,550.00
Painting front bumper and right front fender.	1730 1,923.00
To carry out body cavity preservation. (Per panel).	X 118.00
To replace right headlight.	at 481.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
Sundries.	? 150.00
Total Labour 1:	5,399.00

DESCRIPTION	QTY	PRIC	VALUE
FRT RH FENDER	1	888.85	Rx 888.85
SET MOUNTS PDC SENSOR FRT (PDC)	1	58.60	? 58.60
FRT BUMPER CARRIER	1	715.90	X 715.90
FRT BUMPER BOTTOM MOUNT	1	164.65	? 164.65
RH GRILLE AIR INLET PARTLY CLOSED	1	68.65	not 68.65
FRT SHOCK ABSORBER	1	50.65	? 50.65
FRT BUMPER RH PROTECTIVE RUBBER STR	1	23.30	? 23.30
FRT BUMPER PANEL PRIMED (PDC)	1	1,335.40	del 1,335.40
RH COVERING PRIMEND	1	47.60	? 47.60
EMBLEM GROMMET	2	0.80	na 1.60
BMW EMBLEM	1	71.25	del 71.25
HOSE LINE HEADLIGHT CLEANING SYSTEM	1	48.70	X 48.70
RH HIGH PRESSURE NOZZLE	1	183.80	X 183.80
RH HEADLIGHT LED TECHNOLOGY	1	4,203.70	at 4,203.70
RH FOG LIGHT LED	1	441.95	? 441.95
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	na 20.20
BUMPER PDC SENSOR (A90 SOPHISTOGRAU	2	368.80	? 737.60

Performance Motors Limited

A Sime Darby Motors Company

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**Estimate No. : **b1 51547**
Date Estimated : **13/06/2019**
Prepared By : **Gary Poh Chai Hoon**Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP1159E	D335085	15/08/2014	520iA	0

Total Parts : **9,062.40**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct SettlementRegn No. 0171192130 Claim No. _____Date&Time 01/7/19 @ 1030 Excess S\$ _____Surveyor's Name Tanphu Sign [Signature]Surveyor's Tel 97495749 Authorised Yes / No _____Authorised Date WP Time _____RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____Surveyor's E-mail tanphu@lkkauto.comEst. of Working Days Recommend 4-5 days

Labour 1	:	5,399.00
Parts	:	9,062.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,012.30
Grand Total	:	15,473.70

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **