



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/06/2019

User ID : CatherineLee

Cecilia

U/S \$10800/- 5days.

Section A - Accident Details

Registration Number	SG1030U
Case Reference Number	BUS/06/19/1028
Registration Date	15/8/2016
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC530
Name of Driver	Tan Siok Lay
Type of Accident	Head To Side
Accident Date and Time	10/6/2019 9:43 PM
Accident Reported Date and Time	11/6/2019 5:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101968
Special Instruction to ARC, if any	SG1030U - FRONT PORTION SJL2666J (TP) - INSURED WITH AXA
Prepared Date and Time	12/6/2019 1:35 PM
Chassis Number	WEB62808323130284
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,650.00	\$2,385.00
Total Spray Cost	\$616.00	\$524.00
Total Spare Part Cost	\$9,851.71	\$7,881.37
Total Other Cost	\$200.00	\$0.00
TOTAL COST	\$13,317.71	\$10,790.37
Lump Sum Total	\$0.00	\$10,800.00
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Boon Chew Tay	Hwee jie
ARC / Surveyor Sign Off Date	12/06/2019 2:16 PM	13/06/2019 3:31 PM
Signature		LKK
Remarks		P/P REPAIR. PHOTO BEFORE PAINT

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/06/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$2,650.00	\$2,385.00
Total Labour	\$2,650.00	\$2,385.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$616.00	\$524.00
Total Spray Painting & Panel Beating	\$616.00	\$524.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$200.00	\$0.00
Total Other Costs	\$200.00	\$0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6012457			WIPER ARM COVER	1.00	\$19.50	10.00	\$17.55	Replace	Replace
			FRONT NUMBER PLATE	1.00	\$75.00	0.00	\$75.00	Replace	Replace
			STICKER IU	1.00	\$35.00	0.00	\$35.00	Replace	Replace
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	Replace
6009895	GLASS	6286712210	WINDSCREEN:FRONT.F OR MB CITARO O530	1.00	\$3,887.85	10.00	\$3,499.07	Replace	Replace
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	Replace
4006314	CONSUMABLE	Sikaflex-265	ADHESIVE:DIRECT GLAZING	10.00	\$37.00	0.00	\$370.00	Replace	Replace
4006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	Replace
6009901	Body	6283850401	BUMPER:FRONT,CENT RE, FOR MB CITARO O530	1.00	\$1,663.80	10.00	\$1,497.42	Replace	Replace
6009904	Body	6288850526	FLAP:FRONT,CENTRE.F OR MB CITARO O530	1.00	\$1,513.05	10.00	\$1,361.74	Replace	Replace
6010189	Body	0007501250	LOCK:FRT BUMPER, FOR MB CITARO BUS	2.00	\$66.00	10.00	\$118.80	Replace	Replace
6010339	BODY RH	6288210244	ARM,WIPER:RH, FOR MB O530 CITARO BUS	1.00	\$567.00	10.00	\$510.30	Replace	Replace
6010340	BODY LH	6288210144	ARM,WIPER:LH, FOR MB O530 CITARO BUS	1.00	\$567.00	10.00	\$510.30	Replace	Replace
6010341	Body		WIPER ARM ASSEMBLY:FOR MB O530 CITARO BUS	1.00	\$1,029.00	10.00	\$926.10	Replace	Replace
6010541	Body		BLADE,WIPER:FOR MB CITARO O530	2.00	\$113.80	10.00	\$204.84	Replace	Replace
6010399			COVERING :W/SCREEN EDGE,BOTTOM (CITARO)	1.00	\$545.10	10.00	\$490.59	Replace	Replace
Total					\$10,354.10		\$9,851.71		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									