



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: JHMGK3850HX200216
License No: SMH3445J
Mileage: 18083
Engine No: L13B11020136

Document No: SVO19038214
Printed By: ANIKKALAI
Order Date: 17. June 2019
Order Time: 1:53:41 PM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: HASLINDA BINTI ABDULLAH OWNER INSURER: CHINA TAIPING ACC DATE: 08/06/2019 SURVEYED BY: HWEE JIE / LKK DATE: 17/06/2019 REF NO: TP INSURER: MS FIRST CAPITAL TP VEH: SHC2698M						
68100-T5A-U10ZZ	TAIL GATE COMP <i>BUC -</i>	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIPTAILGATE <i>CUT -</i>	1	92.30	25	69.22	4.85	74.07
74801-T5A-013	LOCK ASSYTAILGATE <i>Ins -</i>	1	176.70	25	132.52	9.28	141.80
75722-T5L-T01	EMBLEMRR. <i>nec -</i>	1	10.90	25	8.17	0.57	8.74
74890-T5A-A11	GARNISH ASSY,RR LICENCE <i>DEF -</i>	1	105.50	25	79.12	5.54	84.66
75701-T5A-000	EMBLEMH <i>nec -</i>	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM <i>nec -</i>	2	2.10	25	3.15	0.22	3.37
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>nec -</i>	2	60.00		120.00	8.40	128.40
04715-T5A-000ZZ	FACERR.BUMPER <i>DEF -</i>	1	492.70	25	369.52	25.87	395.39
71593-T5A-000	SPACERR.RR.BUMPER <i>nec -</i>	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER <i>nec -</i>	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER <i>nec -</i>	10	2.30	25	17.25	1.21	18.46
66100-TAR-T00ZZ	PANEL COMPRR. <i>DD -</i>	1	320.40	25	240.30	16.82	257.12
84550-T5L-Q00	BOX ASSYCARGO FLOOR <i>DEF -</i>	1	80.00	25	60.00	4.20	64.20
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>shunted -</i>	1	320.00		320.00	22.40	342.40
73127-TY0-000	A RUBBER CWINDSHIELD DAMPER <i>nec -</i>	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	A RUBBERWINDSHIELD DAMPER <i>nec -</i>	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	A DAMPERSTD 5X5 <i>nec -</i>	1	8.50	25	6.37	0.45	6.82
	SUM PARTS:				2,017.13	141.21	2,158.34
BOSUN		1	40.00	✓	40.00	2.80	42.80
	SUNDRIES						
BOJSE	1718	1	80.00	✓	80.00	5.60	85.60
	BODY JOINT SEALANT <i>Tailgate</i>						
BOJSE	1718	1	80.00	✓	80.00	5.60	85.60
	BODY JOINT SEALANT. <i>End panel</i>						
BA02R	1466	1	120.00	✓	120.00	8.40	128.40
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BC012R		1	280.00	✓	280.00	19.60	299.60
	RESET VEHICLE SMART ENTRY SYSTEM						
BC011R	1466	1	280.00	✓	280.00	19.60	299.60
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA						
BG02R	1438	1	560.00	✓	560.00	39.20	599.20
	REPLACE RR. WINDSCREEN.(N)						
BKTG02R	1466	1	320.00	✓	320.00	22.40	342.40
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)						