

INS. CASE OWNER:

cc 4, MG 190 10562, KK.93

LKK:
IDAC:

Surveyor:

KSL

DOI:

ASSIGNMENT

20/6/2019

Date / Time:

13/6/19

Registered in Merimen:

14/6/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMK 2207X

Name of Insured:

JIAO ZHAO YU

Insured Tel No.:

HP:

Excess See II :SS

D.O.A: 11/6/2019

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SKS 6656M



INSRS:

WSP:

Tel:

Liability:

RMKS:

chung hwe



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P 11 SS 3,178.57, 5 days) Reduction: 17 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 11/19

Confirm with: Jure

Email ☒ Call ☐

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.: 21

If NO or B 28, Ass. Lia:

Repair Cost: (4148T)

SS 3,400.86

(01 REAR ENO TPVH)

Loss of Rental (LOR):

SS - (- days)

Loss of Use (LOU):

SS - (5 - x days)

Loss of Income (LOI):

SS 600 (S 100 x 6 days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

SS 8.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS 4005.86

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Phase 1:

SS 4,005.86

Name 1:

CHENG HOE MOTOR PTE LTD

Phase 2 (Strike if N/A):

SS

Name 2:

Phase 3 (Strike if N/A):

SS

Name 3:

ASS. REC. BY:

REF:

1161

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

1-B-1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 File pass to

C/P/P \$ 3,178.37 / Red \$ 651.42 / 17%

5 days + 1 Sunday = 6 days

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + R.S. \$

: Fuel

: Others

TOTAL

Veh No:

SKS 6656M

Yr Regn:

01, 19

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Ty Vios

c.c

1496

Colour:

M Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

16829

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR 2B 231-3501156656

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

R:

185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

11/6/19

D.O.I.

20/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Cheng Hoe Motor Pte Ltd

BK 1019, Yishun Industrial Park A #01-174/182, Singapore 768764
TEL: 67556142 (VIB) FAX: 67557719 (VIB) Email: chenghoe@chenghoe.com.sg
GST 2010011592 RCB NO 201001154E

SKS 6656M

7/1/16

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

Estimate No: ES1991639
Date: 19 Jun 2019
Policy No:
Veh Reg No: SKS6656M
Make/Model: TOYOTA TOYOTA
VIOS 1.5E AUTO
Chassis No: MR2B23F3501156656
Engine No: 2NR5295405
Reg. Date: 11/01/2019

WS Ref: TP AIG
Claim Type: Third Party
Accident Date: 11/06/2019
TP Veh Reg No: SMK2207X

Not Withheld

Repair by paint

20/6/19 5 days

8317837

Estimate Repair Cost to Vehicle No :SKS6656M

Description	U/Price	Quantity	List Price	Amount
List Price			SS	SS
1 REAR BOOT EMBLEM - VIOS	39.80	1 PC	39.80	—
2 REAR BUMPER	452.00	1 PC	452.00	—
3 REAR BUMPER SIDE RETAINER LH	133.90	1 PC	133.90	—
4 REAR BUMPER REFLECTOR LH	100.30	1 PC	100.30	—
5 REAR BUMPER CLIP	3.50	6 PCS	21.00	—
6 REAR BUMPER REINFORCEMENT	301.60	1 PC	301.60	—
7 REAR BOOT	684.80	1 PC	684.80	—
8 REAR BOOT INNER LOCK	360.42	1 PC	360.42	—
9 REAR BOOT LOGO	50.20	1 PC	50.20	—
10 REAR BOOT EMBLEM - E	34.00	1 PC	34.00	—
11 REAR PANEL	601.90	1 PC	601.90	—
12 REAR PANEL INNER GARNISH	179.80	1 PC	179.80	—
			2,959.72	—
	Less 23%		739.93	2,219.79
Special Net				
13 REVERSE SENSOR	200.00	1 PC	200.00	—
14 REAR BOOT BODY STICKER	30.00	1 PC	30.00	—
			230.00	230.00
Labour				
15 TO REMOVE AND REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT & ATTACHMENT, KNOCK AND REPAIR REAR PANEL, REAR RH FENDER AND RE-ALIGN TO PUTTY AND RESPRAY ON REAR PANEL, REAR BOOT, REAR BUMPER	600.00	1 LA	600.00	500
16 TO PUTTY AND RESPRAY ON REAR PANEL, REAR BOOT, REAR BUMPER	700.00	1 LA	700.00	600
17 RUSTPROOFING	30.00	1 LA	30.00	—
18 TO REMOVE AND REFIX REVERSE CAMERA AND RESET SYSTEM	50.00	1 LA	50.00	—
			1,380.00	1,380.00

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total: SS 3,829.79
Add GST @ 7%: 268.09
Total Amount Payable: SS 4,097.88

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

10R
7/1/16
571X100-600
L711-8

Cheng Hoe Motor Pte Ltd

Bldg 1019, Vishnu Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST: 201001158E RCB NO: 201001158E

SKS 6656M
 70/1/16

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP AIG

Claim Type: Third Party

Accident Date: 11/06/2019

TP Veh Reg No: SMK2207X

Not Notified
Recovery By claim
20/6/19 5 days

Estimate No: ES1991639

Date: 19 Jun 2019

Policy No:

Veh Reg No: SKS6656M

Make/Model: TOYOTA TOYOTA

VIOS 1.5E AUTO

Chassis No: MR2B23F3501156656

Engine No: 2NR5295405

Reg. Date: 11/01/2019

Estimate Repair Cost to Vehicle No :SKS6656M

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BOOT EMBLEM - VIOS	39.80	1 PC	<i>na</i> 39.80	—
2 REAR BUMPER	452.00	1 PC	<i>bu</i> 452.00	—
3 REAR BUMPER SIDE RETAINER LH	133.90	1 PC	<i>dit</i> 133.90	—
4 REAR BUMPER REFLECTOR LH	100.30	1 PC	<i>cm</i> 100.30	—
5 REAR BUMPER CLIP	3.50	6 PCS	<i>na</i> 21.00	—
6 REAR BUMPER REINFORCEMENT	301.60	1 PC	<i>na</i> 301.60	?
7 REAR BOOT	684.80	1 PC	<i>bu</i> 684.80	?
8 REAR BOOT INNER LOCK	360.42	1 PC	<i>na</i> 360.42	?
9 REAR BOOT LOGO	50.20	1 PC	<i>na</i> 50.20	—
10 REAR BOOT EMBLEM - E	34.00	1 PC	<i>na</i> 34.00	—
11 REAR PANEL	601.90	1 PC	<i>na</i> 601.90	?
12 REAR PANEL INNER GARNISH	179.80	1 PC	<i>mg</i> 179.80	?
			2,959.72	
		Less 25%	739.93	2,219.79
Special Net				
13 REVERSE SENSOR	200.00	1 PC	<i>shot</i> 200.00	—
14 REAR BOOT BODY STICKER	30.00	1 PC	<i>na</i> 30.00	—
			230.00	230.00
Labour				
15 TO REMOVE AND REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT & ATTACHMENT; KNOCK AND REPAIR REAR PANEL, REAR RH FENDER AND RE-ALIGN TO REAR BUMPER	600.00	1 LA	600.00	?
16 TO PUTTY AND RESPRAY ON REAR PANEL, REAR BOOT, REAR BUMPER	700.00	1 LA	700.00	<i>600</i>
17 RUSTPROOFING	30.00	1 LA	30.00	—
18 TO REMOVE AND REFIX REVERSE CAMERA AND RESET SYSTEM	50.00	1 LA	50.00	—
			1,380.00	1,380.00

Total S\$ 3,829.79

Add GST @ 7% 268.09

Total Amount Payable S\$ 4,097.88

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4932A

Vehicle Details

Vehicle No.: SKS6656M
Vehicle to be Exported: No
Intended Deregistration Date: 12 Jun 2019
Vehicle Make: TOYOTA
Vehicle Model: VIOS 1.5 E (AUTO)
Primary Colour: Silver
Manufacturing Year: 2018
Engine No.: 2NR5295405
Chassis No.: MR2B23F3501156656
Maximum Power Output: 79.0 kW (105 bhp)
Open Market Value: \$13,781.00
Original Registration Date: 11 Jan 2019
First Registration Date: 11 Jan 2019
Transfer Count: 0
Actual ARF Paid: \$13,781.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 10 Jan 2029
PARF Rebate Amount: \$10,335.00

Intended COE Rebate Details

COE Expiry Date: 10 Jan 2029
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$28,457.00
COE Rebate Amount: \$27,255.00
Total Rebate Amount: \$37,590.00

The information contained herein is correct as at 12 Jun 2019

OK

PRE-REPAIR INSPECTION REQUEST – SKS6656M vs SMK2207X (OI) on D.O.A.: 11/06/2019

From: Hor, Yinnul
To: "assignments@lkkauto.com", Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim; Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tor
Sent: 6/13/2019 1:57:44 PM
Attachments: SKS6656M.pdf

Hi,

Please refer to the enclosed request from **Cheng Hoe Motor Pte Ltd**.

Claim no : 6336735214SG003
Case Owner : Bernard Ler Ji Qian

If you have any queries/concerns, please let us know.
Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yinnul (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Yinnul.Hor@aig.com | www.aig.as

2.02pm @ 13/6/19
VNI
Effreda

From: chmotor@singnet.com.sg [mailto:chmotor@singnet.com.sg]
Sent: Thursday, June 13, 2019 1:39 PM
To: Abu Kassim, Noor Mariesa
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin; Hor, Yinnul; chmotor@singnet.com.sg
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMK2207X AND SKS6656M ON 11/06/2019

Dear Sir,

Our selection as below:-

Kenneth Kong LKK Auto Consultants Pte Ltd

Pls assist to arrange for survey asap.

Thanks
Rgds
June
Cheng Hoe Motor Pte Ltd
Tel : 67556142
Fax : 67557719

From: Abu Kassim, Noor Mariesa
Sent: Wed, 12 Jun 2019 06:16:55 +0000
To: Cheng Hoe Motor Pte Ltd (Yishun-June)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin; Hor, Yinnul
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMK2207X AND SKS6656M ON 11/06/2019

Without Prejudice

Your Reference : SKS6656M
Our Reference : 6336735214SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd

Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Mariesa Abu Kassim (Mariesa)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

NoorMariesa.AbuKassim@aig.com | www.aig.com

From: Cheng Hoe Motor Pte Ltd (Yishun-June) (<mailto:chmotor@singnet.com.sg>)

Sent: Wednesday, June 12, 2019 12:42 PM

To: imran.ishak@aig.com; Chin, Lee-Ying; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina

Subject: [EXTERNAL] Repair Survey (Single Joint Expert) - SKS6656M

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

OUR CLIENT – SKS6656M

DOA – 11.6.19 @11.50am

YOU

R INSURED : SMK2207X

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards

June

Cheng Hoe Motor Pte Ltd

Tel : 67556142

Fax : 67557719

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 23 October 2019 3:38 PM
To: zhaoyu jiao
Cc: Admin A
Subject: RE: ACCIDENT INVOLVING SKS 6656M & SMK 2207X ON 11/06/2019 ALONG UPPER PAYA LEBAR TURNING LEFT TO AIRPORT ROAD

Tracking:	Recipient	Delivery
	zhaoyu jiao	
	Admin A	
	olivialau@lkkauto.com	Delivered: 23/10/2019 3:38 PM
	Meikwan@lkkauto.com	Delivered: 23/10/2019 3:38 PM
	shupei@lkkauto.com	Delivered: 23/10/2019 3:38 PM

Dear Mr. Jiao Zhaoyu,

We have taken note of your e-mail below.

We were provided with all the documents, GIA report and accident video that you have submitted to AIG Insurance.

Based on the accident statements and accident video, we maintain our view that liability is not in your favour as it is a front to rear collision.

We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Thank you.

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: zhaoyu jiao <jiaozhaoyu@gmail.com>

Sent: Tuesday, 8 October 2019 9:31 AM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: Re: ACCIDENT INVOLVING SKS 6656M & SMK 2207X ON 11/06/2019 ALONG UPPER PAYA LEBAR TURNING LEFT TO AIRPORT ROAD

Hi Khanchna,

Thank you for your email, I have provided all the information ,images and video to AIG hours after the accident.

If you have any doubt, please let me know. I am contactable via this email and 81868697.

SKS6656M was driven by the learner but not the instructor, and it was an unnecessary stop.

Regards

Jiao Zhaoyu

On Wed, Oct 2, 2019 at 3:14 PM Khanchna (LKK Auto) <khanchna@lkkauto.com> wrote:

Our Ref: CC4/AIG19010562/Kka3

JIAO ZHAOYU

[POLICY HOLDER]

Dear Sir/Madam,

ACCIDENT INVOLVING SKS 6656M & SMK 2207X ON 11/06/2019 ALONG UPPER PAYA LEBAR TURNING LEFT TO AIRPORT ROAD

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, **AIG Asia Pacific Insurance Pte Ltd** to deal with the third party claim against your policy.

We have received a claim from SKS 6656M against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Thursday, 7 November 2019 8:58 AM
To: junephua@singnet.com.sg
Cc: Admin A
Subject: OFFER - ACCIDENT INVOLVING SKS 6656M & SMK 2207X [AIG] ON 11/06/2019

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We confirm settlement as per your LOD for **\$4,008.86(all in)**.

PAYMENT ADVICE

Your Ref : _____
Third party Vehicle No. : SMK2207X
Claimant Vehicle No. : SKS6656M

Accident on 11/06/2019 involving vehicle/s no. SKS6656M & SMK2207X
along/at FILTER LANE TOWARDS AIRPORT ROAD

BREAKDOWN OF PAYMENT/S

1) Repair cost	<u>S\$ 3400.86</u>	Payable to <u>Cheng Hoe Motor Pte Ltd</u>
2) Loss of Income (Tuition car)	<u>S\$ 600.00</u> (5 days)	Payable to <u>Cheng Hoe Motor Pte Ltd</u>
3) Hire of Vehicle	<u>S\$ 0.00</u>	Payable to <u>Cheng Hoe Motor Pte Ltd</u>
4) LTA Search	<u>S\$ 8.00</u>	Payable to <u>Cheng Hoe Motor Pte Ltd</u>
Total	<u>S\$ 4008.86</u>	

Service Adviser : LKK
Contact No. : 62563561

We will proceed to do the necessary.

Thank you.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna| Case Handler
LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SKS6656M
Vehicle Type:	L10 - For Instruction Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5 E (AUTO)
Chassis No.:	MR2B23F3501156656
Propellant:	Petrol
Engine No.:	2NR5295405
Engine Capacity:	1496 cc
Maximum Power Output:	79.0 kW (105 bhp)
Maximum Laden Weight:	1550 kg
Unladen Weight:	1085 kg
Year Of Manufacture:	2018
Original Registration Date:	11 Jan 2019
Lifespan Expiry Date:	-
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium:	\$28,457.00
COE Expiry Date:	10 Jan 2029
Road Tax Expiry Date:	10 Jan 2020
PARF Eligibility Expiry Date:	10 Jan 2029
Inspection Due Date:	10 Jan 2020
Intended Transfer Date:	12 Jun 2019
CO2 Emission:	131.00 (g/km)
CEV/VES Rebate Utilised Amount:	-
CO Emission:	0.200620 (g/km)
HC Emission:	0.019860 (g/km)
NOx Emission:	0.022360 (g/km)
PM Emission:	0.199000 (mg/km)

Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Additional Levy:			
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jun 2019 Edit Reg		13 Jun 2019 00:00 Edit Adj Rpt	S\$3,178.36 Edit Estimates	S\$3,178.36 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	JIAO ZHAOYU, ID: S8581367Z		
Main Claimant:	NG CHIANG KWEE, ID: S0104932A		
Vehicle Reg. No.:	SKS6656M	Date of Loss:	11/06/2019 11:00 - :59 [5 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / 6336735214SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SMK2207X	Policy No. (Claimant):	5106893891
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 25/06/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKS6656M (6336735214SG)
[SMK2207X]
TP
NG CHIANG KWEE
Jun 11 2019 11:00AM
[JIAO ZHAOYU]
Cheng Hoe Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser v	
Video			1 per page v ☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	22/10/19 08:59	Video - Accident	Load AVI	
2	22/10/19 08:59	Video - Accident	Load AVI	
Letters/Correspondences			1 per page v ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	
Photos/Images			3 per page v ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/11/19 18:01	General View	Load JPG	☒
2	19/11/19 18:01	General View	Load JPG	☒
3	19/11/19 18:01	General View	Load JPG	☒
4	19/11/19 18:01	General View	Load JPG	☒
5	19/11/19 18:01	General View	Load JPG	☒
6	19/11/19 18:01	General View	Load JPG	☒
7	19/11/19 18:01	General View	Load JPG	☒
8	19/11/19 18:01	General View	Load JPG	☒
9	19/11/19 18:01	General View	Load JPG	☒
10	19/11/19 18:01	General View	Load JPG	☒
11	19/11/19 18:01	General View	Load JPG	☒
12	19/11/19 18:01	General View	Load JPG	☒
13	19/11/19 18:01	General View	Load JPG	☒
14	19/11/19 18:01	General View	Load JPG	☒
15	19/11/19 18:01	General View	Load JPG	☒
16	19/11/19 18:01	General View	Load JPG	☒
17	19/11/19 18:01	General View	Load JPG	☒
18	19/11/19 18:01	General View	Load JPG	☒
19	19/11/19 18:01	General View	Load JPG	☒
20	19/11/19 18:01	General View	Load JPG	☒
21	19/11/19 18:01	General View	Load JPG	☒
22	19/11/19 18:01	General View	Load JPG	☒
23	19/11/19 18:01	General View	Load JPG	☒
24	19/11/19 18:01	General View	Load JPG	☒
25	19/11/19 18:01	General View	Load JPG	☒
26	19/11/19 18:01	General View	Load JPG	☒
27	19/11/19 18:01	General View	Load JPG	☒
Documentation			1 per page v ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/06/19 14:32	ACKNOWLEDGEMENT EMAIL TO AIG DD 13.06.2019	Load PDF	
2	14/06/19 14:32	EMAIL FROM AIG DD 13.06.2019	Load PDF	
3	14/06/19 14:32	TP GIA REPORT	Load PDF	
4	25/06/19 09:56	TP ESTIMATE - MARKED	Load PDF	
5	02/10/19 15:15	EMAIL TO OI	Load PDF	
6	27/11/19 09:49	WORKSHOP INVOICE	Load PDF	
7	27/11/19 09:49	AUTHORISATION TO ACT FORM	Load PDF	

Video			1 per page	☒
No	Finalized On		Thumbnail	Print
8	27/11/19 09:49	AIG Asia Pacific Insurance Pte. Ltd. (SG) Release Voucher		Load PDF
9	27/11/19 09:49	LTA SEARCH		Load PDF
10	27/11/19 09:49	LOD		Load PDF
No	Finalized On		Thumbnail	Print
1	17/06/19 09:53	AIG Asia Pacific Insurance Pte. Ltd. (SG) OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMK2207X (Insd veh)	Model:	TOYOTA VIOS 1.5 E (A)
	SKS6656M (TP veh)		
Date of Accident:	11/06/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	4,097.88
Final Repair Cost	:	\$	3,400.86
Loss of Use	:	\$	600.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	8.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,008.86
Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____(%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No- BOLA Scenario No: _____	
BOLA Liability: _____100_____(%)		Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Cheng Hoe Motor Pte Ltd	:	\$ 4,008.86
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

27 Nov
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19010562/KKA3Q2

Date: 27/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SKS6656M

Insured Vehicle No : SMK2207X

Date of Loss: 11/06/2019

Nature of Claim: TP

Claim No: 6336735214SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKS6656M

Make & Model: TOYOTA VIOS, 1.5 E (A)

Engine No: 2NR5295405

Reg. Date: 11/01/2019 (Man. Year: 2018)

Chassis No: MR2B23F3501156656

Colour: Metallic Silver

Odometer: 16629 km

Engine Capacity: 1496 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Dunlop 8 mm

Rear Left Side: Dunlop 8 mm

Front Right Side: Dunlop 8 mm

Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,449.79	1,998.36	451.43	18.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	1,180.00	200.00	14.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,829.79	3,178.36	651.43	17.01
+ GST 7.00/7.00% (S\$)	268.09	222.49	45.60	17.01
Nett Amount (S\$)	4,097.88	3,400.85	697.03	17.01
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		4,008.85		

INSPECTION

Date of Assignment: 13/06/2019

Date Inspected: 20/06/2019 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT EMBLEM -VIO5	Necessary	39.80 FL	*39.80 FL
2	1		*REAR BUMPER	Buckled	452.00 FL	*452.00 FL
3	1		*REAR BUMPER SIDE RETAINER LH	Distorted	133.90 FL	*133.90 FL
4	1		*REAR BUMPER REFLECTOR LH	Cracked	100.30 FL	*100.30 FL
5	6		*REAR BUMPER CLIP	Necessary	21.00 FL	*21.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	301.60 FL	*301.60 FL
7	1		*REAR BOOT	Buckled	684.80 FL	*684.80 FL
8	1		*REAR BOOT INNER LOCK	Dented	360.42 FL	*360.42 FL
9	1		*REAR BOOT LOGO	Necessary	50.20 FL	*50.20 FL
10	1		*REAR BOOT EMBLEM -E	Necessary	34.00 FL	*34.00 FL
11	1		*REAR PANEL	Repair	601.90 FL	*- FL
12	1		*REAR PANEL INNER GARNISH	Mtg Distorted	179.80 FL	*179.80 FL
13	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
14	1		*REAR BOOT BODY STICKER	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,189.72	2,587.82
- List Item Discount on L Items 25.00/25.00% (S\$)	739.93	589.46
Total Parts (S\$)	2,449.79	1,998.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIX REAR BUMPER ASSY ,TAILLAMPS ,REAR BOOT & ATTACHMENT ,KNOCK AND REPAIR REAR PANEL,REAR RH FENDER AND RE-ALIGN TO	New	600.00	500.00
2	TO PUTTY AND RESPRAY ON REAR PANEL,REAR BOOT,REAR BUMPER	New	700.00	600.00
3	RUSTPROOFING	New	30.00	30.00
4	TO REMOVE AND REFIX REVERSE CAMERA AND RESET SYSTEM	New	50.00	50.00
Gross Labour Cost (S\$)			1,380.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >