

ASS. REC. BY:

REF: CS/CTI19010642/Uvd302

Special Instruction:

Investor: Marcus

ASSIGNMENT (Office)

From (Person): Meikmen Chong Boon Sen

of CTI

Date/Time: 17/6/19 @ 9.08am

Estimated Cost:

Bill to:

OD / TP / PWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLZ 7638K

Insured:

CB2555G

at Workshop m/s

Kah Motor

Tel:

81006306

of

15 ubi Road #

Policy No:

DMB18N17585518011

Claim No:

SNM19D20259102

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12/06/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9.58am 17/6/19

Person Contacted:

Any

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimated ✓

SLZ 7638K - X

CB 2555G - X

19/8/19

Any with check

20/11/19 @ 1.29pm

Any with check. & email.

ASS. REC. BY:

REF: CTF

ASSIGNMENT

From: _____ Date: 2/12/19

Estimated Cost: _____

OD / P / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLZ 7638K

at Workshop m/s: Kah Motor

of: 15 Ubi Road 4

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 100cm
Any

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^(up)

Date: _____ Person Contacted: _____

N/S	O/S

Veh No: SLZ 7638K Yr Regn: 5118

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Honda Civic c.c 1597

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 25362 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRHFC560JT0006R

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____
R: 215/55-R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front	6	Rear	6
R/Bal.	mm	R/Bal.	mm
L/Bal.	6	L/Bal.	6
L/Bal.	mm	L/Bal.	mm

D.O.A. 12/6/19 D.O.I. 2/12/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/5 Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	have video. TRA 47574
27/12/19	contact Paul by 1560 with Any Cred 8549.21, 8410

RECEIVED 27 DEC 2019

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? 27/12 - typist

Days Of Repair: 3

Resurvey No. of Trip: -

Report Format: menmen

Lump Sum / U.C. (\$) 1560/-

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:	220
Transportation:	
S+RS, SI	
Photos	
Others	
TOTAL	220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Jun 2019		17 Jun 2019 09:08 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:									
Main Claimant: TAN WEI WEI , ID: S7513654D									
Vehicle Reg. No.: SLZ7638K		Date of Loss: 12/06/2019 08:00 - :59							
Claim Type: TP / SNM19D202591C02		Policy/Cover Note No.: DMB1SN17585518011							
Vehicle Reg. No. (Insured): CB2555G		Policy No. (Claimant): SD18V04847/VPC2/R00							
		Excess: S\$0.00							
Repairer: Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/06/2019]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 17 June 2019 9:06 AM
To: Ary Chua
Cc: Liew Thye Wui; Faeaz; 'assignments'
Subject: RE: TPDS: SLZ7638K (L) & CB2555G (CT) DOA: 12-06-2019@08.30AM / our ref: snm19d202591

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Ary Chua [mailto:arychua@honda.com.sg]
Sent: Friday, 14 June, 2019 10:06 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>
Subject: RE: TPDS: SLZ7638K (L) & CB2555G (CT) DOA: 12-06-2019@08.30AM / our ref: snm19d202591

Dear Mr. Chong BS,
We Choose Marcus Chua from LKK-Auto to Survey Our Client Vehicle

Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor **Kah Motor Co.Sdn.Bhd.** Address:15 Ubi Road 4 Singapore 408610
E-mail: arychua@honda.com.sg H/P:81006306 DID:68465673 Fax: 67480770

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 13 June, 2019 5:45 PM
To: Ary Chua <arychua@honda.com.sg>
Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>
Subject: RE: TPDS: SLZ7638K (L) & CB2555G (CT) DOA: 12-06-2019@08.30AM / our ref: snm19d202591

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Thursday, 13 June, 2019 4:21 PM

To: Ary Chua <arychua@honda.com.sg>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>; Angie Foo <angie.foo@sg.cntaiping.com>

Subject: RE: TPDS: SLZ7638K (L) & CB2555G (CT) DOA: 12-06-2019@08.30AM

Dear Boon Sen,

Please conduct PRS – TP: SLZ7638K (SNM19D202591) soonest possible.

File with OIC – Boon Sen - 63896171

From: Ary Chua [<mailto:arychua@honda.com.sg>]

Sent: Thursday, 13 June 2019 4:04 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>

Subject: TPDS: SLZ7638K (L) & CB2555G (CT) DOA: 12-06-2019@08.30AM

Hi OIC-CT,

Kindly Establish this case Liability Issue Before Arrange for Car Survey. Car Not In Ubi Bodyshop.
Our Client got Front & Rear Video Footage.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor **Kah Motor Co.Sdn.Bhd.** Address:15 Ubi Road 4 Singapore 408610

E-mail: arychua@honda.com.sg H/P:81006306 DID:68465673 Fax: 67480770



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	654D
Vehicle Details	
Vehicle No.:	SLZ7638K
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	Maroon
Manufacturing Year:	2018
Engine No.:	R16B25500737
Chassis No.:	MRHFC5650JT000685
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$19,662.00
Original Registration Date:	17 May 2018
First Registration Date:	17 May 2018
Transfer Count:	0
Actual ARF Paid:	\$19,662.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 May 2028
PARF Rebate Amount:	\$14,746.00
Intended COE Rebate Details	
COE Expiry Date:	16 May 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,830.00
COE Rebate Amount:	\$32,828.00
Total Rebate Amount:	\$47,574.00

The information contained herein is correct as at 02 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/06/2019 15:17
Date Of Accident	12/06/2019 08:30
Exact Location Of Accident	PASIR RIS DRIVE 3 (L/P 9) NEAR BUS STOP B01
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ7638K
Insured/Policyholder	
Name Of Registered Owner	TAN WEI WEI
NRIC No	S7513654D
Email Address	ESTELLETANWW@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96853505
Alternative Phone No	OFFICE-96853505

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.6 L (A)
Exact Purpose for which vehicle was being used at time of accident	P/USED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V04847/VPC2/R00
Cover Note Number	

Driver

Name of Driver	VINCENT CHEW JOON JEE
NRIC No	S7615700F
Date Of Birth	27/05/1976
Occupation	INDOOR
Date Of Driving Pass	22/10/2015
Driving Experience	3 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91993127
Fax Number	
Contact Number	
EMail Address	CHEVINCENT76@GMAIL.COM

Address	BLK 135 BEDOK NORTH ST 2 #08-131
Postcode	S460135
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

NOBODY INJURY DURING THE ACCIDENT & REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	CB2555G
Vehicle Make/Model/Colour	TOYOTA/MINI BUS/WHITE
Details Of Properties	
Vehicle Category	BUS
Name of Driver	KUA
NRIC/Passport Number	
Contact Number	98225856
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

Vehicle Number: SLK 7638/K

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:
 12/6/19



 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:
 12/6/19

14:14pm
 13 JUN 2019



 Reporting Centre Personnel's Signature
 Name: ARY CHUA
 NRIC/FIN No.:

Sketch Plan Pg. 2

Vehicle Number: SLZ7638K

Sheng Siang Loyang Point

SKETCH PLAN



A = SLZ7638K
B = CB2555G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 12th June 2019 morning around 8:25am, driver of CB2555G whom was planning to cut into lane 2 along Pasir Ris Drive 3, signal late and failing to allow ample distance before checking lane my vehicle SLZ7638K was already on his left. His intention is to keep left and turn left into Pasir Ris Drive 2. I did tried to warn him but the minibus CB2555G continue to swing left into my vehicle resulting scratches on right hand side of car and right side mirror.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time:

11/6/19

[Signature]

Driver's Signature

(if driver is not the policyholder)

Date & Time:

12/6/19

14:14pm
13 JUN 2019

[Signature]

Reporting Centre Personnel's Signature

Name: ARY CHUA

NRIC/FIN No.:

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate No SD18V04847 /NPC2 /R00
 Form MX1
 Date of Issue 18-MAY-2018
 1. Index Mark and Registration No. of Vehicle: SLZ7638K
 2. Chassis number of Vehicle: MRHFC5650JT000685
 3. Name of Policyholder: TAN WEI WEI (CHEN WEIWEI)
 4. Effective date of Commencement of Insurance
 for the purposes of the Act: 17-MAY-2018 00:00 AM
 5. Date of Expiry of Insurance: 16-MAY-2020 23:59 PM

6. Persons or Classes of Persons entitled to
 drive:

- A) The Policyholder.
 B) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation to that behalf from driving the Motor Vehicle.
 And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

7. Limitations as to use*:

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

8. The Policy does not cover:

- A) Use for hire or reward.
 B) Use for racing, pace-making, reliability trials or speed-testing.
 C) Use for the carriage of goods (other than samples) in connection with any trade or business.
 D) Use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

For and on behalf of
LIBERTY INSURANCE PTE LTD
 Approved Insurers



Authorised Signature

For information only:

COVERAGE:

Comprehensive, Unlimited Windscreen, NCD Protection

SUM INSURED:

MARKET VALUE AT THE TIME OF LOSS

EXCESS:

Section 1 S\$600, Additional Excess For Young & Inexperienced Drivers S\$3000, Windscreen Excess S\$100

FINANCE COMPANY:

OVERSEA-CHINESE BANKING CORPORATION LTD

PRODUCER NAME:

KAH MOTOR COMPANY SDN BERHAD



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Document No.	: SQT19002599	Page	1
Registration No	: SLZ7638K	Date	: 13. Jun 2019	Customer No.	: WZC008
Chassis No	: MRHFC5650JT000685	Svc Advisor	: ARY CHUA WAI NGENE	Engine No	: R16B25500737
Model	: CIVIC 1.6 VTI YM2018	Date Time	: 13. Jun 2019 2:18:12 PM	Surveyor Name	: DID : +65 6846 5673
Owner's Name	: TAN WEI WEI	Survey Date	: HP : +65 8100 6306	Authorisation Date	: Email : arychua@honda.com.sg
Ins Policy No.	: SD18V04847/VPC2/R00				
Date of Accident	: 12/6/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TAN WEI WEI OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 12-06-2019@08.30AM ACC: PASIR RIS DRIVE 3 (L/P 9) NEAR BUS STOP B01 SURVEYED BY: <i>Marcus Chua @ 11:11am</i> REF NO: TP INSURER: CHINA TAIPING INSURANCE (S'PORE) PTE L TP VEH: CB2555G - TOYOTA/MINI BUS/WHITE						
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	11 2	60.00	X	120.00	8.40	128.40
33500-TEA-T01	TAILLIGHT ASSYR.	11 1	261.40	X	248.33	17.38	265.71
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	11 1	617.20	X	586.34	41.04	627.38
91505-TM8-003	CLIP,BUMPER	11 8	2.30	X	17.48	1.22	18.70
71593-TEA-T01	SPACERR.RR BUMPER SIDE	11 1	11.50	X	10.92	0.76	11.68
04636-TEA-T00ZZ	PANEL SETR.RR.OUTSIDE	11 1	711.60	X	676.02	47.32	723.34
63321-TEA-T00ZZ	GUTTERR.RR.UPPER	11 1	29.40	X	27.93	1.96	29.89
73500-TEA-T02	GLASS ASSYR.QUARTER WINDSHIELD	11 1	138.00	X	131.10	9.18	140.28
67510-TEA-T00ZZ	PANELR.RR.DOOR	11 1	717.50	X	681.62	47.71	729.33
72925-TEA-T01	MOLDING ASSY,R.RR.DRINNER	11 1	29.20	X	27.74	1.94	29.68
72910-TEA-T01	MOLDING ASSYR.RR.DOOR	11 1	25.20	X	23.94	1.68	25.62
72930-TEA-T01	GARNISH ASSYR.RR.DOOR SASH	11 1	28.30	X	26.88	1.88	28.76
73227-TEA-003	RUBBER CWINDSHIELD DAM	11 1	17.20	X	16.34	1.14	17.48
73525-SYY-000	RUBBERRR QTR W/SHIELD	11 3	9.70	X	27.64	1.93	29.57
91501-S70-003	FASTENER BW/SHIELD	11 2	5.30	X	10.07	0.70	10.77
91536-SS0-J01	FASTENER AW/SHIELD	11 2	3.80	X	7.22	0.51	7.73
91568-TF0-003	CLIP,WINDSHIELD UPPER	11 2	2.90	X	5.51	0.39	5.90
73125-SR3-000	RUBBER, W/SHIELD	11 1	12.60	X	11.97	0.84	12.81
73126-SR3-000	RUBBER, W/SHIELD	11 1	14.40	X	13.68	0.96	14.64

☆ Photos taken for Marcus Chua Before Paint & After Repair.

Printed on 13/6/2019 3:41:41 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Document No.	: SQT19002599	Page	2
Registration No	: SLZ7638K	Date	: 13. Jun 2019	Customer No.	: WZC008
Chassis No	: MRHFC5650JT000685	Svc Advisor	: ARY CHUA WAI NGEN	Engine No	: R16B25500737
Model	: CIVIC 1.6 VTI YM2018	Date Time	: 13. Jun 2019 2:18:12 PM	Surveyor Name	:
Owner's Name	: TAN WEI WEI	Survey Date	:	Authorisation Date	:
Ins Policy No.	: SD18V04847VPC2/R00				
Date of Accident	: 12/6/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
76208-TEA-T02	MIRROR ASSY,R.	11	254.30	5	241.58	16.91	258.49
76201-TBA-A11ZN	CAP,R.SKULL	1	59.90	5	56.90	3.98	60.88
Sum Item					2969.21	207.83	3,177.04
BOSUN	SUNDRIES	1	40.00	20	40.00	2.80	42.80
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	140.00	80	140.00	9.80	149.80
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	160.00	X	160.00	11.20	171.20
BG02R	REMOVE & INSTALL RHF WING MIRROR FOLD SET	1	250.00	X	250.00	17.50	267.50
BG52D	REMOVE & INSTALL RR. R QTR GLASS.(N)	1	250.00	X	250.00	17.50	267.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	350.00	X	350.00	24.50	374.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	350.00	X	350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00	X	450.00	31.50	481.50
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	550.00	X	550.00	38.50	588.50
BKRP22S	STRAIGHTEN ALIGN RR PANEL RR R FENDER INCLUDING	1	1800.00	560	1800.00	126.00	1926.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2800.00	900	2800.00	196.00	2996.00
Sum Labor					7140.00	499.80	7,639.80

Survey By: Marcus Hui

Date & Time: 2/12/19 @ 11am.

Excess: _____

Status: Work done after repair

Signature: [Signature]

Total Amount 10,109.21 707.63 10,816.84

Total (Inclusive of GST) 10,816.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 13/6/2019 3:41:41 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	CU0099131 / CHINA TAIPING	Document No:	SVO19077227
Chassis No:	MRHFC5650JT000685	Printed By:	ARYCHUA
License No:	SLZ7638K	Order Date:	2. December 2019
Mileage:	25362	Order Time:	2:18:12 PM
Engine No:	R16B25500737	Service Advisor:	ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	OWNER: TAN WEI WEI OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 12-06-2019@08.30AM ACC: PASIR RIS DRIVE 3 (L/P 9) NEAR BUS STOP B01 SURVEYED BY: MARCUS CHUA(LKKAUTO)02/12/2019@11.11A REF NO: SNM19D202591 TP INSURER: CHINA TAIPING INSURANCE (S) PTE LTD TP VEH: CB2555G - TOYOTA/MINI BUS/WHITE						
BOSUN	0760	1	20.00		20.00	1.40	21.40
BML02I	SUNDRIES EXT-YJ	1	80.00		80.00	5.60	85.60
BKRP22S	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N) EXT-YJ	1	560.00		560.00	39.20	599.20
BP02R	STRAIGHTEN ALIGN RR PANEL RR R FENDER INCLUDING FITTING ON ATTACHMENT ITEMS. EXT-YBH	1	900.00		900.00	63.00	963.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(2P)						
			SUM LABOUR:		1,560.00	109.20	1,669.20
			TOTAL SGD		1,560.00	109.20	1,669.20
			Total Payable (SGD)				1,669.20

WD = 3

GST Amount is calculated from individual line(s)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 27 December 2019 10:06 AM
To: Ary Chua; Marcus Chua (LKKAuto); Admin A; SUR
Cc: Liew Thye Wui; Faeaz
Subject: RE: Photos Taken After Completed Spray Paint: Finalize TPDS-CT: SLZ7638K DOA: 12/06/2019@08.30AM

Dear Ary,

WITHOUT PREJUDICE

Confirmed amount \$1560 before GST @ 3 working days.

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ary Chua <arychua@honda.com.sg>
Sent: Friday, 6 December 2019 9:26 AM
To: Marcus Chua (LKKAuto) <MarcusChua@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>
Subject: Photos Taken After Completed Spray Paint: Finalize TPDS-CT: SLZ7638K DOA: 12/06/2019@08.30AM

Dear Marcus Chua,
Kindly refer to attachment Photos taken & close this Finalize.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Kah Motor Co. SDN BHD 15 Ubi Road 4 Singapore 408610

Phone: 6846 5673 Fax: 6748 0770 H/P: 81006306

Email Address : arychua@honda.com.sg

From: Ary Chua
Sent: Wednesday, 4 December 2019 5:37 PM
To: Marcus Chua (LKKAuto) <MarcusChua@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Ashley Chong (LKK Auto) <admin-d@lkkauto.com>
Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>
Subject: Finalize TPDS-CT: SLZ7638K DOA: 12/06/2019@08.30AM

Dear Marcus Chua,
Kindly Finalize TPDS-CT: SLZ7638K DOA: 12/06/2019@08.30AM

Final Repair Costs (include GST)	\$1,560.00 + (\$109.20) = \$1,669.20
Repair Period* (Working Day)	03

Please examine the above information carefully. If no discrepancy is reported within 7 days (*Exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Kah Motor Co. SDN BHD 15 Ubi Road 4 Singapore 408610

Phone: 6846 5673 Fax: 6748 0770 H/P: 81006306

Email Address : arychua@honda.com.sg



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Jun 2019		17 Jun 2019 09:08 Edit Adj Rpt	S\$1,560.00 Edit Estimates	S\$1,560.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	TAN WEI WEI, ID: S7513654D								
Vehicle Reg. No.:	SLZ7638K	Date of Loss:	12/06/2019 08:00 - :59 [12 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202591C02	Policy/Cover Note No.:	DMB1SN17585518011						
Vehicle Reg. No. (Insured):	CB2555G	Policy No. (Claimant):	SD18V04847/VPC2/R00						
		Excess:	S\$0.00						
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 26/06/2019]								
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail						
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All	Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLZ7638K (SNM19D202591C02)
[CB2555G]
TP
TAN WEI WEI
Jun 12 2019 8:00AM
[-]
Kah Motor Co Sdn Bhd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser	
Video						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print		
1	13/06/19 15:29	Video - Accident [Linked Accident Report Documents]		Load MP4	<input type="checkbox"/>		
2	13/06/19 15:29	Video - Accident [Linked Accident Report Documents]		Load MP4	<input type="checkbox"/>		
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print		
1	13/06/19 15:30	Accident Statement		Load HTM	<input type="checkbox"/>		
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print		
1	13/06/19 15:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>		
2	13/06/19 15:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>		
3	13/06/19 15:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>		
4	13/06/19 15:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>		
5	13/06/19 15:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>		
6	13/06/19 15:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>		
7	13/06/19 15:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>		
8	13/06/19 15:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	27/12/19 09:55	General View		Load PDF	<input type="checkbox"/>		
Documentation						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print		
1	17/06/19 09:10	pri contact		Load PDF	<input type="checkbox"/>		
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print		
1	13/06/19 15:29	Sketch Plan [Linked Accident Report Documents]		Load TIF	<input type="checkbox"/>		

Linked Accident Report Documents

						View View in Browser	
Video						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print		
1	13/06/19 15:29	Video - Accident		Load MP4	<input type="checkbox"/>		
2	13/06/19 15:29	Video - Accident		Load MP4	<input type="checkbox"/>		
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print		
1	04/09/19 01:16	Accident Statement		Load HTM	<input type="checkbox"/>		
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print		
1	13/06/19 15:30	Accident Photo		Load JPG	<input checked="" type="checkbox"/>		
2	13/06/19 15:30	Accident Photo		Load JPG	<input checked="" type="checkbox"/>		
3	13/06/19 15:30	Accident Photo		Load JPG	<input checked="" type="checkbox"/>		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
4	13/06/19 15:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	13/06/19 15:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	13/06/19 15:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	13/06/19 15:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	13/06/19 15:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	13/06/19 15:29	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CT119010642/UVD3E2**Date:** 30/12/2019REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN17585518011
Claimant Vehicle No : SLZ7638K **Insured Vehicle No :** CB2555G
 Date of Loss: 12/06/2019 Nature of Claim: TP **Claim No:** SNM19D202591C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ7638K**
 Make & Model: HONDA CIVIC, 1.6 L (A) Engine No: R16B25500737
 Reg. Date: 17/05/2018 (Man. Year: 2018) Chassis No: MRHFC5650JT000685
 Colour: Black Odometer: 25362 km
 Engine Capacity: 1597 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R16 Rear Tyre Size: 215/55 R16
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,009.21	20.00	2,989.21	99.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,100.00	1,540.00	5,560.00	78.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,109.21	1,560.00	8,549.21	84.57
+ GST 7.00/7.00% (S\$)	707.64	109.20	598.44	84.57
Nett Amount (S\$)	10,816.85	1,669.20	9,147.65	84.57

INSPECTION

Date of Assignment: 17/06/2019
 Date Inspected: 02/12/2019 Inspected At: Kah Motor Co Sdn Bhd (Ubi)
 15 Ubi Road 4
 Singapore 408610
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2019)
Parts: 143	HONDA CIVIC 1.6 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLZ7638K)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
2	1		*TAILLIGHT ASSYR.	Not Necessary	248.33 FS	*- FS
3	1		*FACE ASSY,RR.BUMPER	Not Necessary	586.34 FS	*- FS
4	8		*CLIP, BUMPER	Not Necessary	17.48 FS	*- FS
5	1		*SPACERR.RR.BUMPER SIDE	Not Necessary	10.92 FS	*- FS
6	1		*PANEL SETR.RR.OUTSIDE	Not Necessary	676.02 FS	*- FS
7	1		*GUTTERR.RR.UPPER	Not Necessary	27.93 FS	*- FS
8	1		*GLASS ASSYR.QUARTER WINDSHIELD	Not Necessary	131.10 FS	*- FS
9	1		*PANELR.RR.DOOR	Repair	681.62 FS	*- FS
10	1		*MOLDING ASSY,R.RR.DRINNER	Not Necessary	27.74 FS	*- FS
11	1		*MOLDING ASSYR.RR.DOOR	Not Necessary	23.94 FS	*- FS
12	1		*GARNISH ASSYR.RR.DOOR SASH	Not Necessary	26.88 FS	*- FS
13	1		*RUBBER CWINDSHIELD DAM	Not Necessary	16.34 FS	*- FS
14	3		*RUBBERRR QTR W/SHIELD	Not Necessary	27.64 FS	*- FS
15	2		*FASTENER BW/SHIELD	Not Necessary	10.07 FS	*- FS
16	2		*FASTENER AW/SHIELD	Not Necessary	7.22 FS	*- FS
17	2		*CLIP, WINDSHIELD UPPER	Not Necessary	5.51 FS	*- FS
18	1		*RUBBER, W/SHIELD	Not Necessary	11.97 FS	*- FS
19	1		*RUBBER, W/SHIELD	Not Necessary	13.68 FS	*- FS
20	1		*MIRROR ASSY,R.	Not Necessary	241.58 FS	*- FS
21	1		*CAP,R.SKULL	Not Necessary	56.90 FS	*- FS
22	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS
Total Parts (\$\$)					3,009.21	20.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	140.00	80.00
2	REMOVE & INSTALL RHF WING MIRROR FOLD SET	New	250.00	0.00
3	REMOVE & INSTALL RR. R QTR GLASS	New	250.00	0.00
4	REMOVE & INSTALL RR.WINDSCREEN	New	350.00	0.00
5	RESET VEHICLE SMART ENTRY SYSTEM	New	350.00	0.00
6	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	450.00	0.00
7	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	New	550.00	0.00
8	STRAIGHTEN ALIGN RR PANEL RR R FENDER INCLUDING FITTING ON ATTACHMENT ITEMS	New	1,800.00	560.00
9	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (5P)	New	2,800.00	900.00
10	REMOVE & INSTALL REVERSE SENSORS - 4 PCS	New	160.00	0.00
Gross Labour Cost (\$\$)			7,100.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >