

12/20/2008

ASS. REC. BY:

REF: CSICIL19010687 / U + d37

Special Instruction:

Envelope: Marcus

**ASSIGNMENT (Office)**

From (Person): Chong Boon Sen of CTI Date/Time: 17.6.19 3:55 p.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.: GRE 8041D Insured: GBF 1522A

at Workshop m/s Liu's Brother Tel: 67411730

of NO 1 KATI BUKH AVE 6 #01-01

Policy No: 19093298MFCV Claim No: SMM19D 202153

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 13.5.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS <sup>mp</sup> H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 17.6.19 4:06 p.m Person Contacted: Jasmine Vehicle: IN/OUT

Date/Time	Action/Instruction	Estimate	(✓)
	GRE 8041D - X		
	GBF 1522A - AA / INC 17/06/2019 3:55 / 1:5		POA - 13/05/2019

ASSIGNMENT

From: Date: 18.6.2019

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBE 8041D at Workshop n/s LIA'S Brothers Auto of MD1 Kaki Bukit Ave 6 #01-01

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 48

IDAC Accident Rpt: Consistent? : Yes or No

CA / PR Seen: 2 Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

" W / LTA30520

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBE 8041D Yr Regn: 3.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CM /

Make: Toyota hiace c.c 2982

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 74828 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTFHT02P100193979

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modl: M / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Austone

Front R/Bal: 6 mm Rear R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 13/5/19 D.O.I. 18/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
25/6/19	contact n/s @ 4500 with Susan. (Red: 7439; 62%)

RECEIVED 1 JUL 2019

Date/Time, File Pass to?  : Preli. Report  : Final Report

1) 117 Typst Date/Time, File Return to? 2)

Days Of Repair: 5

Resurvey No. of Trip:

Report Format: TP Lump Sum / I.B.I: (\$ 4500)

Add Fee:  Site Insp (\$ )  Interview (\$ )  Tech. Invs (\$ )  Weekend (\$ )

Survey Fee:	
Transportation:	
G + RS, SI	
Photos	
Others	
TOTAL	

## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Monday, 17 June 2019 3:55 PM  
**To:** Jasmine Low  
**Cc:** assignments  
**Subject:** RE: OUR REF : SNM19D202153 - Request for 3rd party survey GBE8041D Claims against GBF1582A

### WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

### Chong Boon Sen

Claims Executive  
Department

### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Jasmine Low [mailto:liusbrojasmine@yahoo.com]  
**Sent:** Monday, 17 June, 2019 3:54 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** Re: OUR REF : SNM19D202153 - Request for 3rd party survey GBE8041D Claims against GBF1582A

Hi,

We like to choose Marcus Chua.

Thank You.

On Monday, 17 June 2019, 15:41, Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)> wrote:

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**From:** Lim Shu Min

**Sent:** Monday, 17 June, 2019 3:03 PM

**To:** liusbrosjasmine@yahoo.com; Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>

**Subject:** OUR REF : SNM19D202153 - Request for 3rd party survey GBE8041D Claims against GBF1582A

Dear Boon Sen,

Please conduct PRS - GBE8041D soonest possible.

File with Officer-In-Charge – Chong Boon Sen - 63896171

Thank you

**Lim Shu Min**

Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 63896156 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Jasmine Low [mailto:[liusbrojasmine@yahoo.com](mailto:liusbrojasmine@yahoo.com)]  
**Sent:** Monday, 17 June, 2019 2:26 PM  
**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>  
**Cc:** Susan Low <[liusbro@ymail.com](mailto:liusbro@ymail.com)>  
**Subject:** Request for 3rd party survey GBE8041D Claims against GBF1582A

Accident on 13/05/2019 Along AYE TOWARDS JURONG

Involving GBE8041D and GBF1528A

We refer to the above accident and 3rd party claims.

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop at No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883 as soon as possible.

Kindly arrange.

Thank you.

Best Regard!

Jasmine Low

M/s Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01  
AutoBay @ Kaki Bukit

Singapore 417883 ☎: [6741 1730](tel:67411730) 📠: [6744 5746](tel:67445746)

Date of Survey:- \_\_\_\_\_

Name of Authorise Surveyor:- \_\_\_\_\_

Surveyor Email: \_\_\_\_\_

Remark 2

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

> **Back to OneMotoring**

**Enquire PARF/COE Rebate for Registered Vehicle**

**Vehicle Owner Particulars**

Owner ID Type: Company  
 Owner ID: 1196N

**Vehicle Details**

Vehicle No.: GBE8041D  
 Vehicle to be Exported: No  
 Intended Deregistration Date: 17 Jun 2019  
 Vehicle Make: TOYOTA  
 Vehicle Model: TOYOTA HIACE VAN TURBO 5 DR MANUAL  
 Primary Colour: White  
 Manufacturing Year: 2016  
 Engine No.: 1KD2599255  
 Chassis No.: JTFHT02P100193979  
 Maximum Power Output: -  
 Open Market Value: \$27,741.00  
 Original Registration Date: 28 Mar 2016  
 First Registration Date: 28 Mar 2016  
 Transfer Count: 1  
 Actual ARF Paid: \$1,388.00

**Intended PARF Rebate Details**

PARF Eligibility: No  
 PARF Eligibility Expiry Date: -  
 PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 27 Mar 2026  
 COE Category: C - Goods Vehicle & Bus  
 COE Period(Years): 10  
 QP Paid: \$45,036.00  
 COE Rebate Amount: \$30,520.00  
**Total Rebate Amount: \$30,520.00**

The information contained herein is correct as at 17 Jun 2019

OK

CHEAPEST CAR  
INSURANCE RENEWAL



Compare 10+ Insurers

GET A CHEAPER QUOTE NOW!

Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

High loan can be arrange upon request.



Li model, mileage only  
36,000km, 1 Owner, pristine  
condition.  
StarAd

- Free VICOM evaluation
- Free grooming and 6 months maintenance
- In-house workshop ensures quality service
- Member of SFTA and hire purchase association
- 100% deposit refund for unapproved loan

**YONG LEE SENG MOTOR PTE LTD**

Post an Ad Advertiser Login Ways of Selling

Browse by Category

« Back ( 1 2 ) Next »

Sort by Date Posted 20 results/page

30 vehicles

HIACE

Advanced Search Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
HIACE		Any	Any	2016	Any	Any	Any	Available



**Toyota Hiace 3.0A Super GL** \$70,800 \$10,130 /yr 13-Jun-2016 2,982 cc - Bus Available

**Fuel Type:** Diesel  
Special Promo! Price Reduced! Z20 Toyota Hiace Super GL Mid Roof! 14 Seater Bus! Lower Overall Height Than Hi-Roof To Accommodate Height Constraints Area! Cheaper Than Brand New Unit! Handover Anytime...

Car (S) Pte Ltd  
Posted: 18-Jun-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



**Toyota Hiace 3.0M DX** \$55,800 \$7,880 /yr 18-Jul-2016 2,982 cc 72,235 km Van Available

**Fuel Type:** Diesel  
Toyota Hiace Manual Rear Aircon, 3 Days Delivery, Super Low Miles, No Need Repairs. \$0 Drive Away, Cash Rebate, High Loan With Lowest Interest Rate Available, Super High Trade In, Call Now!

ABWIN Bus Pte Ltd  
Posted: 18-Jun-2019 Tags: 2016 Toyota hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



**Toyota Hiace 3.0A** \$51,800 \$7,610 /yr 06-Apr-2016 2,982 cc - Van Available

**Fuel Type:** Diesel  
In-house Loan Available. Call To View Now. Please Note, This Is Van,not Bus.

Prime Motor & Leasing  
Posted: 17-Jun-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



**Toyota Hiace 3.0M** \$55,800 \$7,740 /yr 01-Sep-2016 2,982 cc - Van Available

**Fuel Type:** Diesel  
\$3500 Drive Away! 100% Loan No Gemnick With Low Interest. High Trade In Private /commercial Vehicle. Monthly At \$852 Only. Comes With Warranty And Wear And Tear Done. Make A Appointment To View And Te...

Car (S) Pte Ltd  
Posted: 17-Jun-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

\$2233E Bidded Carplates For Sale



**Toyota Hiace 3.0M DX** \$56,800 \$7,620 /yr 28-Nov-2016 2,982 cc 45,000 km Van Available

**Fuel Type:** Diesel  
Guaranteed Cheapest In Market! All Business Owners Look Here! It Is A Special Offer Not To Be Missed! High Loan Options Available! Cheapest In Market! Cheaper Than New! New Paintwork! Monthly Installm...

Car (S) Pte Ltd  
Posted: 15-Jun-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



**Toyota Hiace 3.0M** \$54,800 \$7,610 /yr 30-Aug-2016 2,982 cc - Van Available

**Fuel Type:** Diesel  
As Good As New, Accident Free! One Owner! Guaranteed Cheapest In Market! Monthly Installment As Low As \$600 Plus! Why Lease When You Can Own Your Vehicle Today With Monthly Installments! Call Us To Vi...



**GENERAL  
INSURANCE  
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

### Third Party Insurer Enquiry

Our Ref No: GR-19-095912  
Date of Request: 17/06/2019

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP  
1 Kaki Bukit Ave 6 #01-01  
Auto Bay@Kaki Bukit  
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 17/06/2019  
Enquiry By: Jasmine Low Lay Hong  
TP Vehicle No.: GBF1582A  
Accident Date: 13/05/2019

#### Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBF1582A	China Taiping Insurance (Singapore) Pte. Ltd.	08/07/2018-07/07/2019	6389 6111
GBF1582A	China Taiping Insurance (Singapore) Pte. Ltd.	08/07/2018-07/07/2019	6389 6111

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/05/2019 19:19
Date Of Accident	13/05/2019 07:50
Exact Location Of Accident	AYE TOWARDS JURONG
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE8041D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Co Reg No	199001196N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64942897

### Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE VAN TURBO 5 DR MANUAL
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	19093298MFCV
Cover Note Number	N.A

### Driver

Name of Driver	RAHMAT BIN KASMIN
NRIC No	S1424883H
Date Of Birth	19/10/1960
Occupation	OUTDOOR
Date Of Driving Pass	16/06/1989
Driving Experience	29 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82884883
Fax Number	
Contact Number	
EMail Address	RAHMAT.KASMIN@TRANE.COM

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS  
REPORTING OFFICER  
MOHAMED SHARIL  
BIN SATAR

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan





**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**  
 No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883  
 ROB No: 53291793 | Tel: 6741-1730 / 731 | Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBE8041D190513

**Estimate**

**Customer** \_\_\_\_\_

Name: China Taiping Insurance (Singapore) Pte Ltd 17/6/2019  
 Address: Motor Claims Department GBE8041D  
3 Anson Road #16-00 Toyota  
Springleaf Tower Singapore 079909

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>Body 2D 192610</i>	\$ 2,051.60	
2	Tailgate Lock <i>twi/shld</i>	\$ 359.00	
3	Tailgate Weatherstrip <i>twi</i>	\$ 395.10	
4	Tailgate Inner Board <i>11</i>	\$ 165.30	X
5	Tailgate Toyota Sticker <i>nu 68.50</i>	\$ 70.50	
6	Tailgate 'Hiace' Emblem <i>nu</i>	\$ 75.00	
7	Tailgate '70Km/H' Sticker <i>nu</i>	\$ 15.00	
8	Tail-Lamp (Rh,Lh) @\$365.10 x 2 <i>one/cut</i>	\$ 730.20	
9	No Plate Lamp Outer Garnish <i>scr</i>	\$ 346.50	
10	No Plate <i>scr</i>	\$ 30.00	X
11	Windscreen Glass <i>11</i>	\$ 1,311.30	X
12	Reverse Camera <i>11</i>	\$ 450.00	SN X
13	Corner Panel (Lh) <i>11</i>	\$ 166.00	
14	Bumper <i>2D/Bead</i>	\$ 465.00	
15	Bumper Bracket (Rh,Lh) @\$39.10 x 2 <i>11/scr</i>	\$ 78.20	IPC
16	Bumper Clip (1 Set) <i>nu</i>	\$ 48.00	
17	Reverse Sensor <i>shld</i>	\$ 220.00	
18	End Panel 'Outer' <i>Body 2D</i>	\$ 566.10	
19	End Panel 'Inner' <i>nu</i>	\$ 936.20	
20	Floor Panel Beam <i>11</i>	\$ 260.00	X
21	Plywood <i>11</i>	\$ 450.00	SN X
22	"Corporate" Advertisement Sticker <i>nu</i>	\$ 350.00	
	To check all wiring & electrical component for proper function	\$ 200.00	30
	To apply Rust Proofing , reseal tuff-coating treatment on accident	\$ 80.00	60
	Remove & reinstall Windscreen Glass to facilitate repairs & perform	\$ 120.00	100 \$1390
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Et	\$ 1,200.00	600
	To putty & spray painting & including touch up paint on accident	\$ 800.00	600

*P#5183-60*  
*- \$1295.91*  
*\$3887.70*  
*SN \$360*

Total Parts & Labour of estimate for damaged vehicle \$ 11,939.00

Total amount in Lump Sum Basis for repaired vehicle \_\_\_\_\_

**SDLS:**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No financial recalculation is allowed
- Supplementary items must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_



M/s Liu's Brother Auto Engrg Wks

*not allowed*  
*2/3 @ 4500*  
*5 day*  
*Luqman Ahsan*  
*18/6/19*

*P-5183-60*  
*247*  
*3887.70*  
*5677.70*  
*4410*

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jul 2019 10:20		25 Jun 2019 16:59 <a href="#">Edit Adj Rpt</a>	<b>S\$4,500.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;"><a href="#">[Created by insurer]</a></span>									
Insured:	0, Co. Reg. No.: 0								
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N								
Vehicle Reg. No.:	GBE8041D	Date of Loss:	13/05/2019 07:00 - :59 [37 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	GBF1582A	Policy No. (Claimant):	19093298MFCV						
		Excess:	S\$0.00						
Repairer:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 04/07/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GBE8041D  
 [GBF1582A]  
 TP  
**GOLDBELL LEASING PTE LTD**  
 May 13 2019 7:00AM  
 [0]  
**Liu's Brother Auto Engineering Workshop**

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
<b>Assessment Reports</b>									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)				Thumbnail		Print		
1	13/05/19 19:26	<b>Accident Statement</b>					Load HTM			
<b>Photos/Images</b>									3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)				Thumbnail		Print		
1	13/05/19 19:23	<b>Accident Photo</b> [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>		
2	13/05/19 19:23	<b>Accident Photo</b> [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>		
3	13/05/19 19:23	<b>Accident Photo</b> [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>		
4	13/05/19 19:23	<b>Accident Photo</b> [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>		
5	13/05/19 19:23	<b>Accident Photo</b> [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>		
6	13/05/19 19:23	<b>Accident Photo</b> [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>		
7	13/05/19 19:23	<b>Accident Photo</b> [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>		
8	13/05/19 19:23	<b>Accident Photo</b> [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>		
9	13/05/19 19:23	<b>Accident Photo</b> [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>		
10	13/05/19 19:23	<b>Accident Photo</b> [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>		
11	13/05/19 19:23	<b>Driving License</b> [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>		
12	13/05/19 19:23	<b>Driving License</b> [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print		
1	01/07/19 10:08	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>		
2	01/07/19 10:08	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>		
3	01/07/19 10:08	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>		
4	01/07/19 10:08	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>		
5	01/07/19 10:08	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>		
6	01/07/19 10:08	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>		
7	01/07/19 10:08	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>		
8	01/07/19 10:08	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>		
9	01/07/19 10:08	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>		
10	01/07/19 10:08	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>		
11	01/07/19 10:08	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>		
12	01/07/19 10:08	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>		
13	01/07/19 10:08	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>		
14	01/07/19 10:08	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>		
15	01/07/19 10:08	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>		
16	01/07/19 10:08	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>		
17	01/07/19 10:08	<b>General View</b>					Load JPG			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
				<input checked="" type="checkbox"/>
18	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
19	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
20	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
21	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
22	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
23	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
24	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
25	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
26	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
27	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
28	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
29	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
30	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
31	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
32	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
33	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
34	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
35	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
36	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
37	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
38	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
39	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
40	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
41	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
42	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
43	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
44	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
45	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
46	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
47	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
48	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
49	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
50	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
51	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
52	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
53	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
54	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
55	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
56	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
57	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
58	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
59	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
60	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
61	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
62	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
63	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
64	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
65	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
66	01/07/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
67	01/07/19 10:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
68	01/07/19 10:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
69	01/07/19 10:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
70	01/07/19 10:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
71	01/07/19 10:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
72	01/07/19 10:08	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
73	01/07/19 10:08	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
74	01/07/19 10:08	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
75	01/07/19 10:08	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
76	01/07/19 10:08	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
77	01/07/19 10:08	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/06/19 17:00	<b>pri contact</b>	 Load PDF	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	13/05/19 19:22	<b>Sketch Plan</b> <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
2	13/05/19 19:22	<b>Common Statement</b> <small>[Linked Accident Report Documents]</small>	 Load TIFF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	13/05/19 19:26	<b>Accident Statement</b>	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	13/05/19 19:23	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
2	13/05/19 19:23	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
3	13/05/19 19:23	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
4	13/05/19 19:23	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
5	13/05/19 19:23	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
6	13/05/19 19:23	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
7	13/05/19 19:23	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
8	13/05/19 19:23	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
9	13/05/19 19:23	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
10	13/05/19 19:23	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
11	13/05/19 19:23	<b>Driving License</b>	 Load JPG	<input checked="" type="checkbox"/>
12	13/05/19 19:23	<b>Driving License</b>	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	13/05/19 19:22	<b>Sketch Plan</b>	 Load JPG	<input checked="" type="checkbox"/>
2	13/05/19 19:22	<b>Common Statement</b>	 Load TIFF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sun@lkkauto.com](mailto:sun@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CT119010687/UTD3Q2  
**Date:** 04/07/2019

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

**Claimant Vehicle No :** GBE8041D

**Insured Vehicle No :** GBF1582A

Date of Loss: 13/05/2019

Nature of Claim: TP Claim No: N/A

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBE8041D</b>	Engine No:	1KD2599255
Make & Model:	TOYOTA HIACE, 2.0 (M)	Chassis No:	JTFHT02P100193979
Reg. Date:	28/03/2016 (Man. Year: 2016)	Odometer:	74828 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,539.00	4,247.70	5,291.30	55.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,390.00	1,010.00	42.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,939.00</b>	<b>5,637.70</b>	<b>6,301.30</b>	<b>52.78</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,939.00</b>	<b>4,500.00</b>	<b>7,439.00</b>	<b>62.31</b>

#### INSPECTION

Date of Assignment: 25/06/2019

Date Inspected: 18/06/2019 Inspected At:

Liu's Brother Auto Engineering Workshop  
(HQ)  
BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO  
BAY @ KAKI BUKIT  
Singapore 417883

Estimated Period of Repair: 5.0 days

**Adjuster:** MARCUS CHUA

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 04 Jul 2019)	
<b>Parts:</b>	N/A	TOYOTA HIACE 2.0 (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBE8041D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	2,051.60 F	*1,925.10 FL
2	1		*REAR TAILGATE LOCK	Twisted/Shorted	359.00 F	*359.00 FL
3	1		*REAR TAILGATE WEATHERSTRIP	Twisted	395.10 F	*395.10 FL
4	1		*REAR TAILGATE INNER BOARD	Not Necessary	165.30 F	*- FL
5	1		*REAR TAILGATE TOYOTA STICKER	Necessary	70.50 F	*68.50 FL
6	1		*REAR TAILGATE HIACE EMBLEM	Necessary	75.00 F	*75.00 FL
7	2		*REAR TAIL-LAMP (RH,LH)	Cracked/Cut	730.20 F	*730.20 FL
8	1		*REAR NO PLATE LAMP OUTER GARNISH	Scratched	346.50 F	*346.50 FL
9	1		*REAR NO PLATE	Serviceable	30.00 F	*- FL
10	1		*REAR WINDSCREEN GLASS	Not Necessary	1,311.30 F	*- FL
11	1		*REAR GARNISH CORNER PANEL (LH)	Deformed	166.00 F	*166.00 FL
12	1		*REAR BUMPER	Dented/Bent	465.00 F	*465.00 FL
13	1		*REAR BUMPER BRACKET (RH,LH)	N/s Cracked	78.20 F	*39.10 FL
14	1		*SET REAR BUMPER CLIP	Necessary	48.00 F	*48.00 FL
15	1		*REAR END PANEL OUTER	Badly Dented	566.10 F	*566.10 FL
16	1		*REAR END PANEL INNER	Repair	936.20 F	*- FL
17	1		*REAR FLOOR PANEL BEAM	No such part	260.00 F	*- FL
18	1		*REAR PLYWOOD	Not Necessary	450.00 FS	*- FS
19	1		*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
20	1		*REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
21	1		*SET REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
22	1		*SET CORPORATE ADVERTISEMENT STICKER	Necessary	350.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,539.00</b>	<b>5,543.60</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	<b>0.00</b>	<b>1,295.90</b>
<b>Total Parts (\$\$)</b>	<b>9,539.00</b>	<b>4,247.70</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	200.00	30.00
2	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT	New	80.00	60.00
3	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS & PERFORM	New	120.00	100.00
4	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETC	New	1,200.00	600.00
5	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT	New	800.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>2,400.00</b>	<b>1,390.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >