



Cecilia

Email : darren@completevms.com.sg ( )  
lily@completevms.com.sg ( )  
lihui@completevms.com.sg ( )

CHYE THIAM MAINTENANCE PTE LTD  
14 TAMPINES INDUSTRIAL DRIVE  
SINGAPORE 528530

Attention : THE OWNER

Contact : 64819588 83518839

Estimate : ES006704

Date : 17/06/2019  
Vehicle Num. : XE320R  
Make/Model : NISSAN CWB45CLPHNB-2008  
Chassis/Eng# : CWB4CLP00098/GE13334373B  
Accident Date : 17/06/2019  
Claim No. :  
Reference :  
Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

LABOUR :  
TO SUPPLY AND INSTALL VERDEGRO US-100K (TMA'S) TRUCK  
MOUNTED ATTENUATORS (PASS NCHRP350 STS LEVER 3 ) C/W  
HYDRAULIC LIFT UP  
TO DISMANTLE CARRIAGE KNOCK AND STRAIGHTEN REAR CHASSIS  
FRAME, RE-ALIGN BODY AND RUST PROOFING

Labour Total S\$ :

price?  
42000  
59,800.00  
1000 2,800.00  
62,600.00

Rasul  
Hp 90010068  
5 days

43000

P/P

17/06/19 @ 1430

Ready new parts

Lik-Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SingDollars : Sixty Two Thousand Six Hundred Only

Total S\$ : 62,600.00

COMPLETE VMS PTE LTD

This is only an estimate based on our preliminary inspection and does not cover additional parts and labour time which  
may be required after the work has begun



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre  
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721  
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

NOT A VALID RECEIPT UNTIL IT IS SIGNED BY THE CUSTOMER

Email : darren@completevms.com.sg ( )  
lily@completevms.com.sg ( )  
lihul@completevms.com.sg ( )

CHYE THIAM MAINTENANCE PTE LTD  
14 TAMPINES INDUSTRIAL DRIVE  
SINGAPORE 528530

Attention : THE OWNER

Contact : 64819588 83518839

### Supplementary Estimate : ES006708

Date : 17/06/2019  
Vehicle Num. : XE320R  
Make/Model : NISSAN CWB45CLPHNB-2008  
Chassis/Eng# : CWB4CLP00098/GE133343738  
Accident Date : 15/06/2019  
Claim No. :  
Reference :  
Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|    |   |                                            |  |          |
|----|---|--------------------------------------------|--|----------|
| 1. | 1 | SPECIAL NETT ITEMS :                       |  |          |
| 2. | 1 | REAR BUMPER <i>repair</i>                  |  | 1,520.00 |
| 3. | 1 | REAR FENDER (REAR) L/H <i>repair</i>       |  | 325.00   |
|    |   | REAR FENDER MUDFLAP L/H <i>Don't X SWL</i> |  | 185.00   |

Special Nett Total S\$ : 2,031.00

#### LABOUR :

TO CHANGE REAR BUMPER, REAR FENDER L/H AND MUDFLAPS *(labour included in revised estimate)* 250.00 *X Am*

Labour Total S\$ :

250.00

SingDollars : Two Thousand Two Hundred Eighty-One Only

Total S\$ : 2,281.00

COMPLETE VMS PTE LTD

This is only an estimate based on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun