

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

**VEHICLE REPAIR ESTIMATE**

Insurance Company: AIG ASIA PACIFIC INSURANCE PTE LTD

Address: 78, SHENTON WAY, #07-16  
S(079120)

Telephone: 64193000

Fax: 68357416

Email: shenyang.lim@aig.com  
noormarries.abukassim@aig.com

Make/ Model : HYUNDAI AVANTE

Date: 24.06.2019

Chassis No : KMHD841CMKU880859

Vehicle No: SMK6459J

Date/Time of Accident: 23.04.2019/ 1930

Date of reg: 18.04.2019

**Materials Cost/ Spare Parts Cost****TO BE COMPLETED BY SERVICE ADVISOR**

| ITEMS                        | PARTS DESCRIPTION               | QTY | LIST PRICE<br>\$ | FINAL PRICE<br>\$  |
|------------------------------|---------------------------------|-----|------------------|--------------------|
| 1                            | BOOTLID                         | 1   | \$ 1,853.70      | \$ 1,853.70        |
| 2                            | REAR BUMPER                     | 1   | \$ 654.30        | \$ 654.30          |
| 3                            | REAR BUMPER LOWER (GLOSS BLACK) | 1   | \$ 496.30        | \$ 351.80          |
| 4                            | REAR BUMPER SIDE RETAINERS      | 2   | \$ 85.90         | \$ 171.80          |
| 5                            | REAR BUMPER REFLECTOR RH        | 1   | \$ 305.70        | \$ 201.50          |
| <b>Total List Price Cost</b> |                                 |     |                  | <b>\$ 3,481.80</b> |
| <b>PARTS DISCOUNT 20%</b>    |                                 |     |                  | <b>\$ 2,785.44</b> |

| SPECIAL NETT ITEM               | PARTS DESCRIPTION             | QTY   | PRICE \$  | FINAL PRICE<br>\$ |
|---------------------------------|-------------------------------|-------|-----------|-------------------|
| 1                               | REAR NUMBER PLATE WITH CASING | 1 SET | \$ 50.00  | \$ 50.00          |
| 2                               | REAR BUMPER CLIPS             | 1 SET | \$ 30.00  | \$ 30.00          |
| 3                               | REAR SENSORS                  | 1 SET | \$ 280.00 | \$ 280.00         |
| <b>Total Special Nett Items</b> |                               |       |           | <b>\$ 360.00</b>  |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants**

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

| Labour Works/ Panel Beating Related Works                      |                         |
|----------------------------------------------------------------|-------------------------|
| Job Scope                                                      | Quotation               |
| TO RENEW DAMAGED PARTS, REPLACE,BEAT ,WELD , REALIGN AND ALIGN | \$ 1,000.00 250         |
| Spray Painting                                                 |                         |
| Job Scope                                                      | Quotation               |
| TO RESPRAY AFFECTED AREAS                                      | \$ 1,000.00 300<br>300. |
| Others Cost (Accident Repair Related Expenses)                 |                         |
| Job Scope                                                      | Quotation               |
| TO TUFFCOAT AFFECTED AREA                                      | \$ 200.00 x 11          |
| TO REMOVE/ REFIT WIRING CHECKS                                 | \$ 120.00 30.           |
| TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTLING       | \$ 150.00 30.           |
| Total Others Cost                                              | \$ 470.00               |
| <b>GRAND TOTAL</b>                                             | <b>\$ 5,615.44 610</b>  |

**CAS GARAGE PTE LTD**  
 UEN 201828067M  
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,  
 SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan  
 Direct Contact: +65 8782 7171  
 Email: allangoh.cas@gmail.com  
 Fax: +65 6509 9501

972.48  
 275  
 610  
 1857.48  
 4/5 \$1500  
 02 day #

67418434.  
 Taufik 97495749  
 'wp'  
 24/6/19 @ 3pm  
 Repair after repair  
 2 days  
 Sure/Maintenance