

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: AIG ASIA PACIFIC INSURANCE PTE LTD

Address: 78, SHENTON WAY, #07-16
S(079120)

Telephone: 64193000

Fax: 68357416

Email: shenyang.lim@aig.com
noormarries.abukassim@aig.com

Make/ Model : HYUNDAI AVANTE

Date: 24.06.2019

Chassis No : KMHD841CMKU880859

Vehicle No: SMK6459J

Date/Time of Accident: 23.04.2019/ 1930

Date of reg: 18.04.2019

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	FINAL PRICE \$
1	BOOTLID	1	\$ 1,853.70	\$ 1,853.70
2	REAR BUMPER	1	\$ 654.30	\$ 654.30
3	REAR BUMPER LOWER (GLOSS BLACK)	1	\$ 496.30	\$ 496.30
4	REAR BUMPER SIDE RETAINERS	2	\$ 85.90	\$ 171.80
5	REAR BUMPER REFLECTOR RH	1	\$ 305.70	\$ 305.70
Total List Price Cost				\$ 3,481.80
PARTS DISCOUNT 20%				\$ 2,785.44

SPECIAL NETT ITEM	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR NUMBER PLATE WITH CASING	1SET	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS	1 SET	\$ 30.00	\$ 30.00
3	REAR SENSORS	1 SET	\$ 280.00	\$ 280.00
Total Special Nett Items				\$ 360.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE,BEAT ,WELD , REALIGN AND ALIGN	\$ 1,000.00 250.
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,000.00 300. 200.
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 200.00 x
TO REMOVE/ REFIT WIRING CHECKS	\$ 120.00 30.
TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTLING	\$ 150.00 30.
Total Others Cost	\$ 470.00
GRAND TOTAL	
	\$ 5,615.44

CAS GARAGE PTE LTD
 UEN 201828067M
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
 SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
 Direct Contact: +65 8782 7171
 Email: allangoh.cas@gmail.com
 Fax: +65 6509 9501

67418434.
 Tanjilun 97495749
 'wp'
 24/6/19 @ 3pm
 Repair after repair
 2 days
 Sure/Maintenance