

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Soh Li Ping

Date: 19 Jun 2019

Preliminary Advice

Vehicle No	: SKT1233C	Accident Date	: 16/06/2019
Make	: VOLKSWAGEN JETTA GP	Policy No.	: A80431314AVW
Assignment Date	: 18/06/2019	Excess	: S\$500.00
Date of Inspection	: 18/06/2019	Est. Duration of Repair	: 7 days
Inspection At	: Volkswagen Group Singapore (HQ) 17 Tuas Ave 9 Singapore 639197		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,312.09
Revised Amount	:S\$	6,016.55
Check Items (Estimated)	:S\$	440.86
Total	:S\$	6,457.41

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	55,000.00
COE / PARF Rebate	:S\$	47,769.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,231.00

Remarks

(X) The vehicle is economical for repair. Repairer able to undertake the repair limit not exceeding \$ 7,000.00 on part by part basis.

() The above survey was conducted on a 'without prejudice' basis.