

ASS. REC. BY:

REF:

CS/CT119010778/R19d3/112

Special Instructions

Surveyor: RusuASSIGNMENT (Office)From (Person): Chong Boon gen

of

CT1Date/Time: 18/6/19 11:48am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU 2902G

Insured:

GBG 4121 Y

at Workshop info

Pegasus

Tel:

65137748

of

74 Kien Teek Road

Policy No:

DMLCVSN1752618011

Claim No:

SNM19D202098 cov

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

8/5/2019

CA / REV / REP. / REV 24 HRS

1up19/6/19

H.O.D. Endorsement:

Date/Time:

12:18pm @ 18/6/19

Person Contacted:

Mee key

Vehicle IN/OUT

☒

Date/Time

Action/Instruction

18/6/19SLU 2902G - XGBG 4121 - XRasuul finalised final Ag \$2054, 2 days.
(Red \$3989.20, 66%).

Director

REF:

72009

ASSIGNMENT

From: Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLU 29029

at Workshop m/s Pegasus

of 74, KIM TEEK ROAD

Insured: CTI

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLU 29029 Yr Regn: 2017 / MSV

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDA 3 SEDAN 1.5 AT c.c. 1496

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 127117 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM 6BN 22ABH 015 7598

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TRIANGLE

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 08/05/19 D.O.I. 19/06/19

Survey held at Pegasus

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 27 SEP 2019

Date/Time. File Pass to?

☐ : Preli. Report

1) 27/9/2019

☐ : Final Report

Date/Time. File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

220

Report Format:

Lump Sum I.B.I. (\$) 2056

MER-TP

2056

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 18 June 2019 11:48 AM
To: Meekey Yap
Cc: Pegasus Engineering; assignments
Subject: RE: ARRANGE SURVEY - OUR REF: SNM19D202098 -accident involving- Grab: SLU2902G Your Insured: GBG4121Y DOA: 8/05/2019

WITHOUT PREJUDICE SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK.

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Meekey Yap [mailto:meekey.pegasusengrg@gmail.com]
Sent: Tuesday, 18 June, 2019 11:34 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: Pegasus Engineering <ar_claims@pegasusengrg.com.sg>
Subject: Re: ARRANGE SURVEY - OUR REF: SNM19D202098 -accident involving- Grab: SLU2902G Your Insured: GBG4121Y DOA: 8/05/2019

Dear Boon Sen,

Pls advise survey arrangement on tomorrow 19/6
Infinity Edward Choo...my selection.

Thank You.

Best Regards,
Mee Key

Pegasus Engineering & Trading Pte Ltd
74 Kian Teck Road S628800
Email: meekey.pegasusengrg@gmail.com
Office: 6513 7748
Fax: 6251 3161

On Fri, 14 Jun 2019 at 18:55, Meekey Yap <meekey.pegasusengrg@gmail.com> wrote:

Your Vehicle : GBG 4121Y

Our Vehicle : SLU 2902G

DOA: 08.05.2019

Without Prejudice

Dear All,

We refer to the above matter.

We enclose the following documents for your attention:-

a. Copy of our client's SAS report and damaged photos;

Pursuant to paragraph 2.3 of Pre-Action Protocol for NIMA Cases, please let us have **a list of 10 motor surveyors** for our selection and please let us know within **2 working days** whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

In the event that you request for post repair inspection pursuant to paragraph 4.1 under the NIMA Protocol, you must compensate our client for the loss of use of his/her vehicle for the day that the inspection is conducted.

In addition, please confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

Vehicle will be ground on 19/ 06/ 2019

Please arrange to survey our client's vehicle at 74 Kian Teck Road S628800.

Thank You.

Best Regards,
Mee Key
Pegasus Engineering & Trading Pte Ltd
74 Kian Teck Road S628800
Email: meekey.pegasusengrg@gmail.com
Office: 6513 7748
Fax: 6251 3161

On Thu, 13 Jun 2019 at 13:58, Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sir,

We are prepared to direct settle subject to estimate.

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Meekey Yap [mailto:meekey.pegasusengrg@gmail.com]

Sent: Wednesday, 29 May, 2019 12:45 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Cc: Pegasus Engineering <ar_claims@pegasusengrg.com.sg>

Subject: Re: CHECK LIABILITY - OUR REF: SNM19D202098 -accident involving- Grab: SLU2902G Your Insured: GBG4121Y DOA: 10/05/2019

Dear Boon Seng,

Pls advise updated status for the incident. Check and advise liability.

Your Reference: GBG 4121Y

Our Reference: SLU 2902G

DOA: 10/ 05/ 2019,

my client advise TP already lodged Insurance report.

Thank You.

Best Regards,

Mee Key

Pegasus Engineering & Trading Pte Ltd

74 Kian Teck Road S628800

Email: meekey.pegasusengrg@gmail.com

Office: 6513 7748

Fax: 6251 3161

On Wed, 22 May 2019 at 17:01, Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Dear Sir,

Insured yet to report.

Unable to advise at this juncture.

We will follow up as usual.

You may wish to ask your client to claim OD.

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3
Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Meekey Yap [mailto:meekey.pegasusengrg@gmail.com]

Sent: Wednesday, 22 May, 2019 4:37 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Cc: Chee So Chow <sochow.chee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Pegasus Engineering <car_claims@pegasusengrg.com.sg>

Subject: CHECK LIABILITY - OUR REF: SNM19D202098 -accident involving- Grab: SLU2902G Your Insured: GBG4121Y DOA: 10/05/2019

Dear Boon Sen,

Kindly check and advise liability.

GRAB: SLU 2902G

TP : GBG 4121Y

DOA: 08/05/2019

Thank You.

Best Regards.

Mee Key

Pegasus Engineering & Trading Pte Ltd

74 Kian Teck Road S628800

Email: meekey.pegasusengrg@gmail.com

Office: 6513 7748

Fax: 6251 3161

On Mon, 13 May 2019 at 18:03, Claims Dept of CTI <claimsdept@sg.cntaiping.com> wrote:

Dear Boon Sen,

Please conduct PR5 –SLU2902G soonest possible

File with OIC-Chong Boon Sen -6389 6171

Regards

Angie Foo

From: Meekey Yap [<mailto:meekey.pegasusengrg@gmail.com>]

Sent: Monday, May 13, 2019 4:34 PM

To: Claims Dept of CTI; Chong Boon Sen

Cc: Pegasus Engineering

Subject: ARRANGE SURVEY Grab: SLU2902G Your Insured: GBG4121Y DOA: 10/05/2019

Your Vehicle : GBG 4121Y

Our Vehicle : SLU 2902G

DOA: 10.05.2019

Without Prejudice

Dear All,

We refer to the above matter.

We enclose the following documents for your attention:-

a. Copy of our client's SAS report and damaged photos;

Pursuant to paragraph 2.3 of Pre-Action Protocol for NIMA Cases, please let us have a **list of 10 motor surveyors** for our selection and please let us know within **2 working days** whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

In the event that you request for post repair inspection pursuant to paragraph 4.1 under the NIMA Protocol, you must compensate our client for the loss of use of his/her vehicle for the day that the inspection is conducted.

In addition, please confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

Vehicle will be grounded at our workshop on 15/05/2019

Please arrange to survey our client's vehicle at 74 Kian Teck Road S628800.

Thank You.

Best Regards,

Mee Key

Pegasus Engineering & Trading Pte Ltd

74 Kian Teck Road S628800

Email: meekey.pegasusengrq@gmail.com

Office: 6513 7748

Fax: 6251 3161

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Shiau Chan (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Friday, 13 September 2019 6:05 PM
To: Vivian Tan
Cc: Shiau Chan (LKKAUTO)
Subject: RE: Finalise For SLU2902G (DOA 08/05/2019)

Hi Vivian,

Finalised amount confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Vivian Tan [mailto:vivian.pegasusengrg@gmail.com]
Sent: Thursday, 12 September, 2019 10:45 AM
To: Rasul (LKKAUTO)
Cc: Admin A; CS A Team; ar_claims@pegasusengrg.com.sg
Subject: RE: Finalise For SLU2902G (DOA 08/05/2019)

WITHOUT PREJUDICE

Dear Mr. Rasul,

Finalise amount @ Part By Part \$2,054.00 @ 02 working days.

Parts - \$1,344.00

SN - \$200.00

Labour - \$510.00

Total - \$2,054.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/05/2019 15:07
Date Of Accident	08/05/2019 17:00
Exact Location Of Accident	BALESTIER ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU2902G
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82431133
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29114756MKF
Cover Note Number	

Driver

Name of Driver	YEO CIN DEE
NRIC No	S7673703G
Date Of Birth	23/12/1976
Occupation	OUTDOOR
Date Of Driving Pass	14/07/2003
Driving Experience	15 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-82431133
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	176 BOON LAY DRIVE #07-364
Postcode	640176
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 08 MAY 2019, AT ABOUT 1700HRS, I WAS DRIVING MY VEHICLE, SLU2902G ALONG BALESTIER ROAD TOWARDS CTE. AS TRAFFIC WAS HEAVY, MY VEHICLE WAS STATIONARY WHEN SUDDENLY THERE WAS A LOUD THUD FROM THE REAR PORTION OF MY VEHICLE. NOBODY WAS INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG4121Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LAI WAI KIONG

NRIC/Passport Number

Contact Number

+6597864185

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

1348115
10/5/19

Reporting Centre Personnel's Signature
Name: Zgini
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 08/05/19, at about 1200hrs, I was driving my vehicle, SUV 2902G along Salisbury Road towards CTE. As traffic was heavy, my vehicle was stationary, when suddenly there was a loud bang from the rear portion of my vehicle. Nobody was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Wini
NIC/ID No.:

1545hrs
10/5/19



PEGASUS ENGINEERING & TRADING PTE LTD.

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : YAP MEE KEY Tel : Email :	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO19/05-1152	Quotation Date : 15/05/2019	Terms : 30 DAYS
Vehicle No. : SLU2902G	Chassis No. : JM6BN22A8H0157598	Third Party Insurer : CHINA TAIPING
Model : MAZDA 3	Date of Accident : 08/05/2019	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER <i>de</i>	1	1,075.0000	1,075.00
2	REAR BUMPER SIDE RETAINER <i>X su</i>	2	55.0000	110.00
3	REAR BUMPER CLIPS <i>new /</i>	10	4.0000	40.00
4	REAR BUMPER RIVET <i>ne /</i>	4	5.0000	20.00
5	REAR BUMPER TOW COVER <i>X su</i>	2	35.0000	70.00
6	REAR BUMPER REFLECTOR <i>X su</i>	2	115.0000	230.00
7	REAR BUMPER INNER CENTER BRACKET <i>X su</i>	1	35.0000	35.00
8	REAR REINFORCEMENT <i>? bt /</i>	1	545.0000	545.00
9	REAR END PANEL <i>X su</i>	1	615.0000	615.00
10	REAR END PANEL TOP GARNISH <i>X su</i>	1	125.0000	125.00
11	REAR END PANEL TOP GARNISH CLIPS <i>X su</i>	6	4.0000	24.00
12	REAR WEATHERSTRIPS <i>X su</i>	1	155.0000	155.00
13	REAR BOOTLID COVER <i>X su</i>	1	965.0000	965.00
14	REAR BOOTLID 'MAZDA' EMBLEM <i>X</i>	1	75.0000	75.00
15	REAR BOOTLID 'SKYACTIV' BADGE <i>X } an</i>	1	65.0000	65.00
16	REAR BOOTLID 'MAZDA 3' BADGE <i>X</i>	1	55.0000	55.00
17	LESS 20%	1	-840.8000	-840.80
18	REAR BUMPER REVERSE SENSOR @ 1 SET <i>? an /</i>	1	280.0000	200 280.00
19	REAR NUMBER PLATE WITH CASING <i>X su</i>	1	60.0000	60.00

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : YAP MEE KEY Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No :
-----------------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------

Quotation No. : QO19/05-1152	Quotation Date : 15/05/2019	Terms : 30 DAYS
Vehicle No. : SLU2902G	Chassis No. : JM6BN22A8H0157598	Third Party Insurer : CHINA TAIPING
Model : MAZDA 3	Date of Accident : 08/05/2019	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
20	TO REMOVE & REPLACED REAR REVERSE SENSOR	1	120.0000	60 120.00
21	TO REMOVE & REARRANGE REAR TAILLAMP & REFLECTOR WIRING SYSTEM	1	100.0000	100 100.00
22	TO APPLY RUST PROOFING & TUFFCOATING TREATMENT	1	120.0000	120 120.00
23	TO PANEL BEATING	1	1,000.0000	250 1,000.00
24	TO PUTTY & SPRAY PAINTING ON THE AFFECTED AREAS.	1	1,000.0000	200 1,000.00

Rasul
Hp 90010068 19/6/19
2 days
P/P
19/06/19 @ 1155
Resey before paint

LBT Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

 Acknowledged by Repairer
 Signature:
 Date:

Sub Total 6,043.20
 GST(7.00%) 423.02
 Total (SGD) 6,466.22

Please conduct the survey at
 Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

**PEGASUS****ENGINEERING & TRADING PTE LTD**

GST / ROC COMPANY NO : 201101753C

19/6 China Taipei
Survey & Ground
TP100**Quotation**

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : YAP MEE KEY Tel : Email :	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO19/05-1152	Quotation Date : 15/05/2019	Terms : 30 DAYS
Vehicle No. : SLU2902G	Chassis No. : JM6BN22A8H0157598	Third Party Insurer : CHINA TAIPING
Model : MAZDA 3	Date of Accident : 08/05/2019	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER <i>de</i>	1	1,075.0000	1,075.00
2	REAR BUMPER SIDE RETAINER <i>X 2</i>	2	55.0000	110.00
3	REAR BUMPER CLIPS <i>new</i>	10	4.0000	40.00
4	REAR BUMPER RIVET <i>new</i>	4	5.0000	20.00
5	REAR BUMPER TOW COVER <i>X 2</i>	2	35.0000	70.00
6	REAR BUMPER REFLECTOR <i>X 2</i>	2	115.0000	230.00
7	REAR BUMPER INNER CENTER BRACKET <i>X 1</i>	1	35.0000	35.00
8	REAR REINFORCEMENT <i>? / 64</i>	1	545.0000	545.00
9	REAR END PANEL <i>X 1</i>	1	615.0000	615.00
10	REAR END PANEL TOP GARNISH <i>X 1</i>	1	125.0000	125.00
11	REAR END PANEL TOP GARNISH CLIPS <i>X 6</i>	6	4.0000	24.00
12	REAR WEATHERSTRIPS <i>X 1</i>	1	155.0000	155.00
13	REAR BOOTLID COVER <i>X 1</i>	1	965.0000	965.00
14	REAR BOOTLID 'MAZDA' EMBLEM <i>X 1</i>	1	75.0000	75.00
15	REAR BOOTLID 'SKYACTIV' BADGE <i>X 1</i>	1	65.0000	65.00
16	REAR BOOTLID 'MAZDA 3' BADGE <i>X 1</i>	1	55.0000	55.00
17	LESS 20%	1	-840.8000	-840.80
18	REAR BUMPER REVERSE SENSOR @ 1 SET <i>? new / 760</i>	1	280.0000	280.00
19	REAR NUMBER PLATE WITH CASING <i>X 1</i>	1	60.0000	60.00

C/F 0.00

Page 1 of 2



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
74 KIAN TECK ROAD
SINGAPORE 628800

Officer in Charge : YAP MEE KEY
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax No. :

Quotation No. : QO19/05-1152	Quotation Date : 15/05/2019	Terms : 30 DAYS
Vehicle No. : SLU2902G	Chassis No. : JM6BN22A8H0157598	Third Party Insurer : CHINA TAIPING
Model : MAZDA 3		Date of Accident : 08/05/2019
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00

20	TO REMOVE & REPLACED REAR REVERSE SENSOR	1	120.0000	120.00
21	TO REMOVE & REARRANGE REAR TAILLAMP & REFLECTOR WIRING SYSTEM	1	100.0000	100.00
22	TO APPLY RUST PROOFING & TUFFCOATING TREATMENT	1	120.0000	120.00
23	TO PANEL BEATING	1	1,000.0000	1,000.00
24	TO PUTTY & SPRAY PAINTING ON THE AFFECTED AREAS.	1	1,000.0000	1,000.00

P - \$ 1346.00 W
SW - \$ 200.00 W
C - \$ 510.00 W
7 - \$ 2,057.00 W P/P.

Resul
Hp 90010078

2 days

P/P

19/06/19 @ 1155

Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sub Total 8,043.20
GST(7.00%) 423.02
Total (SGD) 8,466.22

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119010778/R1QD3N2

Date: 01/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN17522618011	
Claimant Vehicle No :	SLU2902G	Insured Vehicle No :	GBG4121Y	
Date of Loss:	08/05/2019	Nature of Claim:	TP	Claim No: SNM19D202098C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU2902G	Engine No:	P520450338
Make & Model:	MAZDA 3, 1.5 SEDAN EU6 (A)	Chassis No:	JM6BN22A8H0157598
Reg. Date:	28/11/2017 (Man. Year: 2017)	Odometer:	127117 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,703.20	1,544.00	2,159.20	58.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	510.00	1,830.00	78.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,043.20	2,054.00	3,989.20	66.01
+ GST 7.00/7.00% (\$\$)	423.02	143.78	279.24	66.01
Nett Amount (\$\$)	6,466.22	2,197.78	4,268.44	66.01

INSPECTION

Date of Assignment:	27/09/2019	
Date Inspected:	19/06/2019	Inspected At: Pegasus Engineering & Trading Pte Ltd (Kian Teck) 74 Kian Teck Road Singapore 628800
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Oct 2019)
Parts: 143	MAZDA 3 1.5 SEDAN EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU2902G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,075.00 FL	*1,075.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Serviceable	110.00 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
4	4		*REAR BUMPER RIVET	Necessary	20.00 FL	*20.00 FL
5	2		*REAR BUMPER TOW COVER	Serviceable	70.00 FL	*- FL
6	2		*REAR BUMPER REFLECTOR	Serviceable	230.00 FL	*- FL
7	1		*REAR BUMPER INNER CENTER BRACKET	Serviceable	35.00 FL	*- FL
8	1		*REAR REINFORCEMENT	Bent	545.00 FL	*545.00 FL
9	1		*REAR END PANEL	Serviceable	615.00 FL	*- FL
10	1		*REAR END PANEL TOP GARNISH	Serviceable	125.00 FL	*- FL
11	6		*REAR END PANEL TOP GARNISH CLIPS	Serviceable	24.00 FL	*- FL
12	1		*REAR WEATHERSTRIPS	Serviceable	155.00 FL	*- FL
13	1		*REAR BOOTLID COVER	Not Necessary	965.00 FL	*- FL
14	1		*REAR BOOTLID MAZDA EMBLEM	Not Necessary	75.00 FL	*- FL
15	1		*REAR BOOTLID SKYACTIV BADGE	Not Necessary	65.00 FL	*- FL
16	1		*REAR BOOTLID MAZDA 3 BADGE	Not Necessary	55.00 FL	*- FL
17	1		*SET REAR BUMPER REVERSE SENSOR	Not Working	280.00 FS	*200.00 FS
18	1		*REAR NUMBER PLATE WITH CASING	Serviceable	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,544.00	1,880.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	840.80	336.00
Total Parts (\$\$)	3,703.20	1,544.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACED REAR REVERSE SENSOR	New	120.00	60.00
2	TO REMOVE & REARRANGE REAR TAILLAMP & REFLECTOR WIRING SYSTEM	New	100.00	0.00
3	TO APPLY RUST PROOFING & TUFFCOATING TREATMENT	New	120.00	0.00
4	TO PANEL BEATING	New	1,000.00	250.00
5	TO PUTTY & SPRAY PAINTING ON THE AFFECTED AREAS	New	1,000.00	200.00
Gross Labour Cost (S\$)			2,340.00	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >