來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity 160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722 Tel: 64538110 Fax: 64596267 UEN: 199407592C

Your Ref: SLM 1202S

Our Ref: S 2988CD - 2019/JL

4 September 2019

ERGO Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attention: Motor Claims

WITHOUT PREJUDICE

Dear Sirs

ACCIDENT INVOLVING VEHICLE NOS. S 2988CD AND SLM 1202S ON 14/06/2019 AT HOLLAND ROAD

We refer to the above matter wherein your insured's vehicle no. SLM 1202S was involved in an accident with our client's vehicle no. S 2988CD.

As the accident was caused by your insured's negligence, our client is now claiming for the following losses:

Repair cost:

\$11,265.39 (include of GST)

Rental cost:

\$ 2,100.00 (14 days x \$150 per day)

Total:

\$13<u>,365.39</u>

Relevant documents in support of our client's claim are enclosed for your reference.

Please do not hestitate to contact Jenny Lim at telephone 64533757 or email jenny.lim@laihuat.com.sg should you need any additional information.

Meanwhile, we look forward to receiving your affirmative response soon enough.

Thank you.

Yours faithfully,

LAI HUAT (MENG KEE) MOTOR PTE LTD

encs

来發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267 GST No: M2-0128609-3 UEN: 199407592C

TAX INVOICE

EST No.: EST0022485

Andri Gunawan

Attn:

Your ref. TP-SLM 1202S ERGO

Payment

Date 4/9/2019

Vehicle No ...: S 2988CD

Vehicle Model: Mercedes Benz E200

Accident on ...: 14/6/2019

Quantity	Unit	Description	Unit price E	Unit price Disc. pct.	
		Supply of Parts - Nett item:			
1.00	Pc	Rear bumper inner part LH	52.00	10.00	46.80
1.00	Pc	Rear bumper inner part RH	52.00	10.00	46.80
1.00	Pc	Rear bumper chrome moulding LH	137.00	10.00	123.30
1.00	Pc	Rear bumper chrome mouliding RH	137.00	10.00	123.30
1.00	Pc	Rear bumper	1,698.00	10.00	1,528.20
1.00	Pc	Rear bumper lower garnish	245.00	10.00	220.50
1.00	Pc	Rear bumper inner part (centre)	260.00	10.00	234.00
1.00	Pc	Rear parking sensor inner LH	188.00	10.00	169.20
1.00	P¢	Rear tail lamp LH	718.00	10.00	646.20
1.00	Pc	Rear tail lamp RH	718.00	10.00	646.20
1.00	Pc	Rear bumper lower bracket LH	28.00	10.00	25.20
1.00	Ρ¢	Rear bumper lower bracket RH	28.00	10.00	25.20
1.00	Pc	Rear end panel	1,925.00	10.00	1,732.50
1.00	Pc	Rear end panel trim garnish	135.00	10.00	121.50
1.00	Pc	Rear boot lid	2,850.00	10.00	2,565.00
1.00	Рc	Rear boot lid chrome moulding	120.00	10.00	108.00
1.00		Rear boot lid E200 emblem	85.00	10.00	76.50
1.00	Pc	Rear boot lid Mercedes logo emblem	50.00	10.00	45.00
1.00	Pc	Rear boot lid 7G Tronic emblem	50.00	10.00	45.00

Special nett item:

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外,还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICC Deluxe oven heater for re-spraying all motor vehicles."

来發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267 GST No: M2-0128609-3 UEN: 199407592C

TAX INVOICE

EST No.: EST0022485

Andri Gunawan

GST Reg No M2-0128609-3

Your ref. TP-SLM 1202S ERGO

Payment

Date 4/9/2019

Attn:

Vehicle No ...: S 2988CD

Vehicle Model: Mercedes Benz E200

Accident on ...: 14/6/2019

Quantity Uni	t Description	Unit price Disc. pct.	Amount
1.00 Pc	Rear number plate	40.00	40.00
	Labour & Misc:		
1.00	To check/erase fault code	120.00	120.00
1.00	To apply underbody undercoating	60.00	60.00
1.00	To transfer reversing camera + cable, etc	80.00	80.00
1.00	To straighten rear body including cutting and welding, to knock dents on tail lamp panel LH & RH and renew of parts	800.00	800.00
1.00	To spray paint	900.00	900.00

 Sub-Total
 10,528.40

 GST 7.00%
 736.99

 Total
 \$\$ 11,265.39

本公司拥有最先进的 CAROLINER MARK IV 机械,可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外,还有先进的 SAICO Deluxe 喷漆供炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICC Deluxe oven heater for re-spraying all motor vehicles."

37A Bartley Road Singapore 539777 UEN: 200102894H

HIRING AGREEMENT CUM TAX INVOICE NUMBER:

1004438

(Please quote this number in all payments and correspondence)

Vehicle number

: SLU 5749M

Make & model

: Mercedes Benz C230

HIRER'S PARTICULARS

Hirer

: ANDRI GUNAWAN

NRIC No: G1914241N

Address

: 51 MT SINAI DRIVE, RIDGEWOOD #04-04

SINGAPORE 277107

Contact Number

Off:

H/p: 81843400

Res:

Nationality

: SINGAPOREAN

Licence Number: AS NRIC NO

Date Of Birth

Licence Expiry : NEW PHOTO LIC.

: 03.08.1975

Driver Address : AS ABOVE

NRIC No: AS ABOVE

Contact Number

: AS ABOVE

Off:

H/p: AS ABOVE

Res:

Nationality

: SINGAPOREAN

Licence Number: AS NRIC NO

Date Of Birth

: AS ABOVE

Licence Expiry: NEW PHOTO LIC.

RENTAL PRICING

Daily Rental Rate

: \$

150.00

Date Out : 14.06.2019

Days On Rental

14 /Day

Time Out : 3.35 pm

Date Return: 28.6.2019

TOTAL

:\$ 2100.00

Time Return: 5.30pm

***RENTER'S Liability for Vehicle Damage EXCESS is \$\$1,500.00 ON ALL CLAIMS.

***Applicable to driver below 23YRS old and above 70YRS old OR with less than 2YRS driving experience

EXCESS is S\$5,000.00

REMARK - Vehicle no: S 2988 CD

Job No:

70599

HIRER DECLARATION

I agree to the terms and conditions above and as set out overteaf. If I opt to pay by credit/charge chard, my signature here is deemed to have been made on the application credit card charge slip.

Authorised Signatory and Company Stamp

Date:

1 4 JUN 2019

APEX Car Rental Pte Ltd

Date:

1 4 JUN 2019

LETTER OF AUTHORITY

To:

Lai Huat (Meng Kee) Motor Pte Ltd 160 Sin Ming Drive #04-01, #04-02 & #07-03 Sin Ming Autocity Singapore 575722

NRIC No:

G1914241N

Dear Sirs					
ACCIDENT IN	VOLVING VEHICLE NOS	: S 2988 CD	& <u>SLM 1</u>	202S C	ON <u>14/06/2019</u>
AT HOLLAN	ID ROAD		. . – – – – – – – – – – – – – – – – – –		
	irm that on <u>14/06/2019</u> which was damaged in			to repair my	/ our vehicle no.
expenses and the above acc	on of your agreement to to defer demanding for pa ident, I / We hereby auth e and settle the acciden ed accident.	syment of the costs orise you and/or y	of repair whic our solicitors	ch was damaç as my / our i	ged as a result of representative to
/ our vehicle recost of repairs	undertake to co-operate we-inspected and being a value to my and the loss of use to my communication received	witness at trial) tha / our vehicle. T/W	nt may be ned le further unde	essary for your crtake to keep	ou to recover the you informed at
any payment.	confirm that by signing the last sent to me cepting any payment.				
unsuccessful for	of my / our claim agains or any reason whatsoevel otor Pte Ltd either by cash	r, I / We shall bear	the repair / ex	cess cost pa	yable to Lai Huat
	authorise the payment of e made directly to my				
the claim prod Motor Pte Ltd	ne personal and vehicle in tess (including by way of may use, disclose and p all activities related to my	recordings), I ago process my persor	ee and conse	ent that Lai H	Huat (Meng Kee)
Yours faithfully	′				
Signature:	-				
Name:	Andri Gunawan				