

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0022485
Andri Gunawan

Page 1 of 2
Your ref. TP-SLM 1202S ERGO
Job No. 70599
Our ref. 19.06.20
Payment
Date 17/6/2019

Attn

Vehicle No S 2988CD
Vehicle Model : Mercedes Benz E200
Accident on ... 14/6/2019

Not authorized
Reuny Bepain
6 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Rear bumper chrome moulding LH	137.00	10.00	123.30
1.00	Pc	Rear bumper chrome moulding RH	137.00	10.00	123.30
1.00	Pc	Rear bumper	1,698.00	10.00	1,528.20
1.00	Pc	Rear bumper lower garnish	245.00	10.00	220.50
1.00	Pc	Rear bumper inner part (centre)	260.00	10.00	234.00
1.00	Pc	Rear parking sensor inner LH	188.00	10.00	169.20
1.00	Pc	Rear tail lamp LH	718.00	10.00	646.20
1.00	Pc	Rear tail lamp RH	718.00	10.00	646.20
1.00	Pc	Rear bumper lower bracket LH	52.00	10.00	46.80
1.00	Pc	Rear bumper lower bracket RH	52.00	10.00	46.80
1.00	Pc	Rear end panel	1,925.00	10.00	1,732.50
1.00	Pc	Rear end panel trim garnish	135.00	10.00	121.50
1.00	Pc	Rear boot lid	2,850.00	10.00	2,565.00
1.00	Pc	Rear boot lid chrome moulding	120.00	10.00	108.00
1.00	Pc	Rear boot lid E200 emblem	85.00	10.00	76.50
1.00	Pc	Rear boot lid Mercedes logo emblem	50.00	10.00	45.00
1.00	Pc	Rear boot lid 7G Tronic emblem	50.00	10.00	45.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司

LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0022485
Andri Gunawan

Page 2 of 2
Your ref. TP-SLM 1202S ERGO
Job No. 70599
Our ref. 19.06.20
Payment
Date 17/6/2019

Attn

Vehicle No S 2988CD
Vehicle Model : Mercedes Benz E200
Accident on ... 14/6/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		Special nett item:			
			40.00		<i>nu</i> 40.00
1.00	Pc	Rear number plate			
		Labour & Misc:			
			120.00		120.00 ?
1.00		To check/erase fault code			100.00 <i>60</i>
1.00		To apply underbody undercoating	100.00		80.00 <i>4</i>
1.00		To transfer reversing camera + cable, etc	80.00		
1.00		To straighten rear body including cutting and welding, to knock dents on tail lamp panel LH & RH and renew of parts	1,000.00		<i>800</i> 1,000.00
1.00		To spray paint	1,100.00		<i>900</i> 1,100.00

Sub-Total 10,918.00
GST 7.00% 764.26
Total S\$ 11,682.26

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁除外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the su dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced S Deluxe oven heater for re-spraying all motor vehicles."