



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
Chassis No: MRHFC5650JT002418
License No: SMH4398E
Mileage: 2570
Engine No: R16B25502840

Document No: SVO19040010
Printed By: SHNG
Order Date: 24. June 2019
Order Time: 2:30:23 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:ANGELA TAN CHYE YUN OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH: SUPPLEMENTARY LABOUR AND ITEMS						
60261-TBA-A00ZZ	PANELL.FENDER	1	248.90	25	186.67	13.07	199.74
74151-TEA-T00	FENDERL.FR.INNER	1	51.10	25	38.32	2.68	41.00
60263-TBA-A00ZZ	BRACKET AL.FR.FENDER	1	29.40	25	22.05	1.54	23.59
60266-TEM-M00ZZ	STAY, L. FR. FENDER UPPER	1	18.10	25	13.57	0.95	14.52
74155-TEA-T00	ENCLOSUREL.FR.FENDER	1	8.90	25	6.67	0.47	7.14
91501-TR0-003	CLIP,INNER FENDER	22	2.80	25	46.20	3.23	49.43
33150-TEC-306	HEADLIGHT ASSY,L.	1	585.70	25	439.27	30.75	470.02
34350-TET-H01	LIGHT ASSYL.SIDE TURN	1	33.10	25	24.82	1.74	26.56
71101-TEA-T00ZZ	FACEFR.BUMPER	1	579.90	25	434.92	30.44	465.36
71190-TEA-T00	BEAML.FR.BUMPER UPPER	1	26.70	25	20.02	1.40	21.42
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71108-TEA-T00	GARNISHL.FR.BUMPER SIDE	1	18.00	25	13.50	0.95	14.45
91505-TM8-003	CLIP,BUMPER	16	2.30	25	27.60	1.93	29.53
71121-TEA-T01	BASE,FR.GRILLE CHROME	1	73.80	25	55.35	3.87	59.22
75700-TBA-A00	EMBLEM	1	15.00	25	11.25	0.79	12.04
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
51220-TEA-T01	JOINT COMPFR.LOWER BALL	1	47.70	25	35.77	2.50	38.27
33500-TEA-T01	TAILLIGHT ASSYR.	1	261.40	25	196.05	13.72	209.77
75722-TBA-A00	EMBLEM SETRR.	1	11.80	25	8.85	0.62	9.47
75725-TEA-T01	EMBLEMRR.	1	11.00	25	8.25	0.58	8.83
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	36.40	25	27.30	1.91	29.21
71503-TEA-T00	GARNISH R.RR.BUMPER SIDE	1	8.40	25	6.30	0.44	6.74
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	1	2.30	25	1.72	0.12	1.84
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
71103-TEA-T00	GARNISHR.FR.BUMPER SIDE	1	18.00	25	13.50	0.95	14.45
74146-TEA-T00	RUBBERHOOD SEAL	1	27.60	25	20.70	1.45	22.15
71410-TEA-T01	BULKHEAD ASSYFR.	1	525.90	25	394.42	27.61	422.03
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	6	23.20	25	104.40	7.31	111.71
60100-TEA-T00ZZ	HOOD COMPENGINE	1	598.70	25	449.02	31.43	480.45
80050-TG7-000	LABLE AIR CON	1	0.80	25	0.60	0.04	0.64
19043-5AA-E00	LABEL, COOLANT INFORMATION	1	10.00	25	7.50	0.53	8.03
60211-TBA-A00ZZ	PANELLR.FENDER	1	248.90	25	186.67	13.07	199.74
60213-TBA-A00ZZ	BRACKET AR.FR.FENDER	1	29.40	25	22.05	1.54	23.59
90853-SJA-A00	RIVET4.8MM	10	1.90	25	14.25	1.00	15.25
72410-TEA-T01	MOLDING ASSYR.FR.DOOR	1	24.00	25	18.00	1.26	19.26



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer: WZM003 / MSIG INSURANCE
Chassis No: MRHFC5650JT002418
License No: SMH4398E
Mileage: 2570
Engine No: R16B25502840

Document No: SVO19040010
Printed By: SHNG
Order Date: 24. June 2019
Order Time: 2:30:23 PM
Service Advisor: NG SIN HAI

76208-TEA-T02	MIRROR ASSY,R.	1	254.30	25	190.72	13.35	204.07
67050-TEA-T00ZZ	PANEL COMPL.FR.DOOR	1	784.20	25	588.15	41.17	629.32
72465-TBA-A01	MOLDING ASSYL.FR.DOOR SASH	1	26.50	25	19.87	1.39	21.26
72470-TEA-T01	GARNISH ASSYL.FR.DOOR SASH	1	13.70	25	10.27	0.72	10.99
72450-TEA-T01	MOLDING ASSYL.FR.DOOR	1	24.00	25	18.00	1.26	19.26
67510-TEA-T00ZZ	PANELR.RR.DOOR	1	717.50	25	538.12	37.67	575.79
72828-TEA-T01	SEALRR.DOOR LOWER	2	6.20	25	9.30	0.65	9.95
72910-TEA-T01	MOLDING ASSYR.RR.DOOR	1	25.20	25	18.90	1.32	20.22
72925-TEA-T01	MOLDING ASSY,R.RR.DRINNER	1	29.20	25	21.90	1.53	23.43
72930-TEA-T01	GARNISH ASSYR.RR.DOOR SASH	1	28.30	25	21.22	1.49	22.71
04636-TEA-T00ZZ	PANEL SETR.RR.OUTSIDE	1	711.60	25	533.70	37.36	571.06
75450-TEA-T02	OUTLET ASSY,RR.AIR	1	8.20	25	6.15	0.43	6.58
73227-TEA-003	RUBBER CWINDSHIELD DAM	1	17.20	25	12.90	0.90	13.80
91501-S70-003	FASTENER BW/SHIELD	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
91568-TF0-003	CLIP,WINDSHIELD UPPER	2	2.90	25	4.35	0.30	4.65
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
73500-TEA-T01	GLASS ASSYR.QUARTER WINDSHIEL	1	136.60	25	102.45	7.17	109.62
67550-TEA-T00ZZ	PANELL.RR.DOOR	1	717.50	25	538.12	37.67	575.79
60262-TBA-A00ZZ	STAYL.FENDER LOWER	1	17.20	25	12.90	0.90	13.80
72950-TEA-T01	MOLDING ASSY,L.RR.DOOR	1	25.20	25	18.90	1.32	20.22
72965-TEA-T01	MOLDING ASSY,L.RR.DR INNER	1	56.70	25	42.52	2.98	45.50
72970-TEA-T01	GARNISH ASSYL.RR.DOOR SASH	1	28.30	25	21.22	1.49	22.71
72368-TEA-T01	SEALL.FR.DOOR LOWER	1	8.20	25	6.15	0.43	6.58
71850-TEA-T01ZB	GARNISH ASSY,L.SIDE SILL	1	117.80	25	88.35	6.18	94.53
74552-TEA-T00	FENDERR.RR INNER	1	63.00	25	47.25	3.31	50.56
77930-TEA-B21	SENSOR ASSYFR.CRASH	1	71.40	25	53.55	3.75	57.30
17230-5FE-M00	CHAMBER ASSYRESONATOR	1	51.00	25	38.25	2.68	40.93
42700-TEA-T61	DISKALUMINIUM WHEEL	2	297.80	25	446.70	31.27	477.97
32108-TEA-N20	WIRE HARNESS REAR	1	116.80	25	87.60	6.13	93.73
51216-TEA-T10	KNUCKLEL.FR.	1	141.10	25	105.82	7.41	113.23
51360-TEA-T02	ARM COMP,L.FR.LOWER	1	233.90	25	175.42	12.28	187.70
44300-TEA-T51	BEARING ASSYFR.HUB	1	73.90	25	55.42	3.88	59.30
44600-TBC-A00	HUB ASSYFR.	1	73.90	25	55.42	3.88	59.30
33505-TEA-T01	REFLECTOR ASSYR.RR.	1	7.20	25	5.40	0.38	5.78
71504-TBA-A00	COVERR.FINISHER	1	11.90	25	8.92	0.62	9.54
		SUM PARTS:			7,404.08	518.28	7,922.36
BG52R	0701	1	320.00		320.00	22.40	342.40
		REPLACE RR. R QTR GLASS.(N)					
BO-TOW	0701	1	180.00		180.00	12.60	192.60
		TOWING SERVICES (MBBS)(AFTER OFFICE HOUR)					
BOSUN	0701	1	50.00		50.00	3.50	53.50
		SUNDRIES					
BML01I	1438	1	180.00		180.00	12.60	192.60
		INSPECT FR LIGHTING MECHANISMS & FOCUS					
		HEADLIGHTS.(N)					
BMC01D	1438	1	380.00		380.00	26.60	406.60
		REMOVE & INSTALL RADIATOR WITH FITTINGS.					
		PRESSURE TEST COOLING SYSTEM.(N)					



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
Chassis No: MRHFC5650JT002418
License No: SMH4398E
Mileage: 2570
Engine No: R16B25502840

Document No: SVO19040010
Printed By: SHNG
Order Date: 24. June 2019
Order Time: 2:30:23 PM
Service Advisor: NG SIN HAI

BMA01D	1438 REMOVE & INSTALL A/C CONDENSER WITH FITTINGS. VACUUM & RECHARGE A/C GAS.(N)	1	330.00	330.00	23.10	353.10
BMU12R	1438 REMOVE & REPLACE FR UNDERCARRIAGE PARTS.(N)	1	560.00	560.00	39.20	599.20
BKBH01R	1466 REMOVE & RENEW BULKHEAD AND RENEW DAMAGED PARTS INCLUDING FITTING ON ATTACHMENT ITEMS	1	2,240.00	2,240.00	156.80	2,396.80
BP06R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2,250.00	2,250.00	157.50	2,407.50
BG02R	1438 REPLACE RR. WINDSCREEN.(N)	1	560.00	560.00	39.20	599.20
BODAMKIT	1438 WINDSCREEN DAM KIT.	1	100.00	100.00	7.00	107.00
BA02R	1466 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	180.00	12.60	192.60
BOJSE	1718 SEALANT FOR RHR FENDER	1	80.00	80.00	5.60	85.60
BML02I	1438 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00	180.00	12.60	192.60
BMI02D	1438 REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)	1	560.00	560.00	39.20	599.20
BKRP02M	1466 CUT OFF & RENEW RR PANEL. RR FLOOR PAN & RENEW DAMAGE PARTS.	1	4,480.00	4,480.00	313.60	4,793.60
BP06R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) REAR PORTION	1	3,600.00	3,600.00	252.00	3,852.00
BKOT00R	1466 REMOVE AND RENEW TRUNK SPOILER	1	150.00	150.00	10.50	160.50
BKBU01R	1438 REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	480.00	480.00	33.60	513.60
BKBU01R	1438 REMOVE AND RENEW WHEELS/RIMS	1	100.00	100.00	7.00	107.00
BKDR21R	1466 REMOVE & TRANSFER ITEMS TO NEW RR L DR. ADJUST & ALIGN INCLUDING FITTINGS ON ATTACHMENT ITEMS.(N)	1	560.00	560.00	39.20	599.20
BKDR11R	1466 REMOVE & TRANSFER ITEMS TO NEW FR L DR. ADJUST & ALIGN INCLUDING FITTINGS ON ATTACHMENT ITES.(N)	1	560.00	560.00	39.20	599.20
BKDR22R	1466	1	560.00	560.00	39.20	599.20



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	WZM003 / MSIG INSURANCE	Document No:	SVO19040010
Chassis No:	MRHFC565UJT002418	Printed By:	SHNG
License No:	SMH4398E	Order Date:	24. June 2019
Mileage:	2570	Order Time:	2:30:23 PM
Engine No:	R16B25502840	Service Advisor:	NG SIN HAI

REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST & ALIGN INCLUDING FITTINGS ON ATTACHMENT ITEMS.(N)					
BML12R	1466	1	560.00	560.00	39.20 599.20
REMOVE & RENEW WIRE HARNESS. RESET ECU MEMORIES					
			SUM LABOUR:	19,200.00	1,344.00 20,544.00
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS.	1	250.00	250.00	17.50 267.50
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	180.00	12.60 192.60
			SUM EXT SERVICE:	430.00	30.10 460.10
			TOTAL SGD	27,034.08	1,892.38 28,926.46
			Total Payable (SGD)		28,926.46

GST Amount is calculated from individual line(s)