



Hsiao Jony

Section A - Accident Details

|                                    |                       |
|------------------------------------|-----------------------|
| Registration Number                | SHB386G               |
| Case Reference Number              | TAX/06/19/2060        |
| Registration Date                  | 24/10/2014            |
| Company Type                       | SMRT Taxis Pte Ltd    |
| Make                               | TOYOTA                |
| Model                              | PRIUS                 |
| Name of Driver                     | LEONG HAN WAI, JUSTIN |
| Type of Accident                   | Side Swipe            |
| Accident Date and Time             | 15/6/2019 9:55 PM     |
| Accident Reported Date and Time    | 17/6/2019 12:15 PM    |
| Is Surveyor Required?              | Yes                   |
| Survey by                          |                       |
| Vehicle is Towed Back?             | No                    |
| Towed Back Date and Time           |                       |
| Replacement Vehicle issued?        | No                    |
| Job Card Number                    | 24102004              |
| Special Instruction to ARC, if any | TP - AXA              |
| Prepared Date and Time             | 17/6/2019 4:04 PM     |
| Chassis Number                     |                       |
| Mileage                            |                       |
| Work Shop                          |                       |
| Repair Completion Date and Time    |                       |



Toyota Prius

Section B - Summary of Repair Estimates

| Summary of Repair Estimates  |                                |                                     |
|------------------------------|--------------------------------|-------------------------------------|
|                              | Quotation from ARC             | Adjusted by Surveyor, if applicable |
| Total Labour Cost            | \$507.00                       | \$200.00                            |
| Total Spray Cost             | \$756.00                       | \$200.00                            |
| Total Spare Part Cost        | \$2,076.95                     | \$1,025.25                          |
| Total Other Cost             | \$396.00                       | \$60.00                             |
| <b>TOTAL COST</b>            | <b>\$3,735.95</b>              | <b>\$1,485.25</b>                   |
| Lump Sum Total               | \$3,750.00                     | \$1,500.00 (L/S)                    |
| Number of Repair Days        | 4.0                            | 2.0                                 |
| Prepared / Adjusted By       | Kim Ming Chin                  | Hwee Jie (LKK) / AXA                |
| ARC / Surveyor Sign Off Date | 18/06/2019 2:12 PM             | 18/06/2019 1:06 PM                  |
| Signature                    |                                |                                     |
| Remarks                      | L/S REPAIR, PHOTO AFTER PAINT. |                                     |

C/S \$1500/- 2days



## SMRT Accident Vehicle Repair Estimates

|                                                   |
|---------------------------------------------------|
| SMRT Automotive Services Pte Ltd                  |
| 50 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number 63665582                               |
| Estimator Telephone Number 66662623               |
| Accident Reporting Number 66662672                |

Date Generated : 26/05/2019

User ID : PehSuan

## Section C - Quotation and Accident Invoice Details

|                  |              |                |  |
|------------------|--------------|----------------|--|
| Quotation Number | QN-1906-0417 | Invoice Number |  |
| Quotation Date   | 25.06.2019   | Invoice Date   |  |
| Invoice Amount   |              | Prepared Date  |  |

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

| Job Scope                  | Quotation from AR | Adjusted by Surveyor, if applicable |
|----------------------------|-------------------|-------------------------------------|
| TO REPAIR FRONT RH PORTION | \$507.00          | \$200.00                            |
| <b>Total Labour</b>        | <b>\$507.00</b>   | <b>\$200.00</b>                     |

## Part 2 - Spray Painting &amp; Panel Beating Related Works

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO REPSRAY FRONT BUMPER                         | \$378.00           | \$200.00                            |
| TO RESPRAY FRONT FENDER RH                      | \$378.00           | \$0.00                              |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>\$756.00</b>    | <b>\$200.00</b>                     |

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope                               | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-----------------------------------------|--------------------|-------------------------------------|
| TOWING CHARGE                           | \$56.00            | \$40.00                             |
| TO CHECK WIRING AND SYSTEM FUNCTION     | \$80.00            | \$20.00                             |
| TO APPLY RUST-PROOFING ON AFFECTED AREA | \$100.00           | \$0.00                              |
| TO WASH AND VACUUM                      | \$60.00            | \$0.00                              |
| TO REPLACE SUNDRY PARTS                 | \$100.00           | \$0.00                              |
| <b>Total Other Costs</b>                | <b>\$396.00</b>    | <b>\$60.00</b>                      |

## Part 4 - Spare Parts / Material Usage

| Part Number  | Portion       | Stock Number | Part Name                     | Quantity | List Price (\$)   | Discount (%) | Final Price (\$)  | Estimator Approved | Surveyor Approved |
|--------------|---------------|--------------|-------------------------------|----------|-------------------|--------------|-------------------|--------------------|-------------------|
|              |               | 52119-47530  | BUMPER FRT                    | 1.00     | \$482.00          | 25.00        | \$361.50          | Replace            | Replace           |
|              | BODY RH       | 53801-47050  | FENDER FRT/RH                 | 0.00     | \$723.40          | 0.00         | \$0.00            | Replace            | Check X           |
|              | Body          | 75374-47051  | NAME PLATE (HYBRID)           | 0.00     | \$51.90           | 0.00         | \$0.00            | Replace            | Check X           |
|              | UNDERCARRIAGE | 53875-47030  | FENDER LINER FRT/RH           | 0.00     | \$171.70          | 0.00         | \$0.00            | Replace            | Check X           |
|              |               | 52161-16019  | BUMPER CLIPS                  | 10.00    | \$1.61            | 25.00        | \$12.08           | Replace            | Replace           |
|              |               | 52115-47040  | BUMPER SUPPORT FR/RH          | 1.00     | \$76.40           | 25.00        | \$57.30           | Replace            | Replace           |
|              |               | 81511-47050  | LENS & BODY, FR TURN RH       | 0.00     | \$511.80          | 0.00         | \$0.00            | Replace            | Not Given X       |
|              |               | 81519-47060  | BRACKET, FR TURN UPPER RH     | 0.00     | \$58.20           | 0.00         | \$0.00            | Replace            | Not Given X       |
|              |               | 81519-47060  | BRACKET, FR TURN              | 0.00     | \$58.20           | 0.00         | \$0.00            | Replace            | Not Given X       |
|              |               | 81519-47050  | BRACKET, FR TURN LOWER RH     | 0.00     | \$26.00           | 0.00         | \$0.00            | Replace            | Not Given X       |
| 6505437      |               | 81130-47500  | HEAD LAMP RH                  | 1.00     | \$945.20          | 10.00        | \$850.68          | Replace            | Replace           |
|              |               | 53851-47040  | FENDER LINER PAD, FR WHEEL RH | 0.00     | \$49.30           | 0.00         | \$0.00            | Replace            | Not Given X       |
| <b>Total</b> |               |              |                               |          | <b>\$3,155.71</b> |              | <b>\$1,281.56</b> |                    |                   |

DEF

281.56

208

1025.25

200.00

260.00

485.25

45 \$1500