

15/07/2010

INS. CASE OWNER:

CC 4 / LPC1901

LKK:

IDAC:

Surveyor:

KASUL

DOI:

ASSIGNMENT

18/06/19

Date / Time:

18/6/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SBJ 280

Name of Insured:

TAN KIAN HONG

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

14/6/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

19/10/19/1000/01951

Policy No.:

11/10/19/1000/01951

Make / Model:

MITSUBISHI

Place of Accident:

AYE

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJK 8792C

SBJ 280

SLK 5781C



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SLK 5781C - 1

SBJ 280 - 1

STAGE

DATE / PIC

20/06/19

MIS EQUIPMENT. OI INVOLVED IN A

B VEH. C.C.; OI 2ND CAR.

BUTAL LIABILITY CLARIC

24/07/19

PINKETED

TYPE REPORT WHILE PENDING TP LOD

REPORT BONE

ORIGINAL TP LOD IN.

22/08/19

GEEK WARRANT APPROVAL TO LPC

29/08/19

LPC APPROVED WARRANT.

BAND 1ST OFFER TO TP

TP ACCEPTED OFFER.

19/09/19

RECEIVED BY

ALL DOCS IN ORDER

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time: 20/06/19

Sent By: b3

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

PIP

SS 2,884.96

3 days) Reduction:

22

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Confirm by:

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

0%

Repair Cost:

(w/695)

SS 3,086.91

Loss of Rental (LOR)

SS

642.00

(5 days)

x 120

Loss of Use (LOU):

SS

-

(S x days)

Loss of Income (LOI):

SS

-

(S x days)

LOR only ☒LOU only ☐LOR + LOU ☐LOR + LOU ☐

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

3,780.91

Global Sum SS:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Confirm by:

Payee 1:

SS

3,780.91

Name 1:

MOVA AUTOMOTIVE PTB LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400.00



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19010798/R1hb3

Date: 20.06.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLX5781C


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18.06.2019 at the premises of M/s Mova Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	3,717.48
Revised Estimate Amount	: S\$	2,813.56
"Check" Items Amount	: S\$	293.92
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

17/06/2019

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1

Veh # :- SLX5781C

Veh Model :- TOYOTA C-HR HYBRID

Estimate# :- CK419307

Claim # :-

ACC. Date :- 15/06/19

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER <i>de</i>	1	PC 948.60	948.60
2.	BUMPER CLIPS <i>neu</i>	10	PC 5.80	58.00
3.	REAR REFLECTOR GARNISH RH <i>ent</i>	1	PC 145.18	145.18
4.	REAR REFLECTOR RH <i>cha</i>	1	PC 69.80	69.80
5.	REAR BUMPER LOWER GARNISH <i>de</i>	1	PC 396.70	396.70
6.	TOW COVER <i>MIS</i>	1	PC 36.10	36.10
7.	REAR BUMPER SKRU COVER RH <i>MIS</i>	1	PC 97.20	97.20
8.	REAR BUMPER RETAINER RH <i>neu</i>	1	PC 116.30	116.30
9.	REAR TAILLAMP LOWER BRACKET RH <i>? con</i>	1	PC 95.20	95.20
10.	REAR WHEEL ARCH RH <i>cut</i>	1	PC 173.50	173.50
11.	REAR REINFORCEMENT <i>cut</i>	1	PC 376.70	376.70
12.	END PANEL - REAR <i>100</i>	1	PC	
13.	END PANEL TOP GARNISH <i>? X sue</i>	1	PC 296.70	296.70
LIST TOTAL S\$				2,809.98
25% DISCOUNT S\$				-702.50
<i>Parts \$ 2809.98 - 25%</i>				
<i>\$ 2107.48 1884.96</i>				2,107.48
<i>Sn \$ 220</i>				
SPECIAL NET ITEMS :				
1.	REAR PARKING SENSOR <i>MIS</i>	1	PC 250.00	250.00
SPECIAL NET TOTAL S\$				250.00
LABOUR :				
TO REPAIR REAR END PANEL, TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS, TO STRAIGHTEN & REALIGN ON ACCIDENT AFFECTED AREAS				
TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS (PEARL WHITE)				
TO REMOVE & REPLACE REAR PARKING SENSOR				
TO RUST PROOF ON ACCIDENT DAMAGED PARTS				
TO INSPECT REAR TAILLAMP WATER LEAKAGE TEST				
TO REMOVE & REPLACE REAR SIDE TRIM BOARD L+R SPARE TYRE & OTHER ATTACHMENT PARTS				
LABOUR TOTAL S\$				1,360.00

Parts \$ 2809.98 - 25%

\$ 2107.48 1884.96

Sn \$ 220

Labour \$ 780

total P/P \$ 2107.48 3044.5

2884.96

3 days

300 500.00

400 600.00

40 60.00

X 40.00

X 40.00

40 120.00

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

17/06/2019

LONPAC INSURANCE BHD
 300 BEACH ROAD
 #17-04/07 The Concourse
 SINGAPORE 199555.

Attention :- XA025

Page # :- 1 135256
 Veh # :- SLX5781C
 Veh Model :- TOYOTA C-HR HYBRID
 Estimate# :- CK419307
 Claim # :-
 ACC. Date :- 15/06/19
 Terms :- C.O.D Days
 Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O E

NON-TAX AMOUNT-S	
AMOUNT S\$	3,717.48
GST @ 7 %	260.22
AMOUNT DUE S\$	3,977.70

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Resur
Hp 90010568
3 days
P/P
18/66/19 @ 1220
Resy 54 part

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

17/06/2019

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- **XA025**

Page # :- 1

Veh # :- SLX5781C

Veh Model :- TOYOTA C-HR HYBRID

Estimate# :- CK419307

Claim # :-

ACC. Date :- 15/06/19

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER <i>de</i>	1	PC 948.60	948.60
2.	BUMPER CLIPS <i>neu</i>	10	PC 5.80	58.00
3.	REAR REFLECTOR GARNISH RH <i>cut</i>	1	PC 145.18	145.18
4.	REAR REFLECTOR RH <i>coa</i>	1	PC 69.80	69.80
5.	REAR BUMPER LOWER GARNISH <i>de</i>	1	PC 396.70	396.70
6.	TOW COVER <i>MIS</i>	1	PC 36.10	36.10
7.	REAR BUMPER SKRU COVER RH <i>MIS</i>	1	PC 97.20	97.20
8.	REAR BUMPER RETAINER RH <i>neu</i>	1	PC 116.30	116.30
9.	REAR TAILLAMP LOWER BRACKET RH <i>?</i>	1	PC 95.20	95.20
10.	REAR WHEEL ARCH RH <i>cut</i>	1	PC 173.50	173.50
11.	REAR REINFORCEMENT <i>ht</i>	1	PC 376.70	376.70
12.	END PANEL - REAIR	1	PC	
13.	END PANEL TOP GARNISH <i>?</i>	1	PC 296.70	296.70
LIST TOTAL S\$				2,809.98
25% DISCOUNT S\$				-702.50
				2,107.48
SPECIAL NET ITEMS :				
1.	REAR PARKING SENSOR <i>MIS</i>	1	PC 250.00 <i>220</i>	250.00
SPECIAL NET TOTAL S\$				250.00
LABOUR :				
TO REPAIR REAR END PANEL. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS. TO STRAIGHTEN & REALIGN ON ACCIDENT AFFECTED AREAS				<i>300</i> 500.00
TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS (PEARL WHITE)				<i>400</i> 600.00
TO REMOVE & REPLACE REAR PARKING SENSOR				<i>40</i> 60.00
TO RUST PROOF ON ACCIDENT DAMAGED PARTS				X 40.00
TO INSPECT REAR TAILLAMP WATER LEAKAGE TEST				X 40.00
TO REMOVE & REPLACE REAR SIDE TRIM BOARD L+R SPARE TYRE & OTHER ATTACHMENT PARTS				<i>40</i> 120.00
LABOUR TOTAL S\$				1,360.00

Estimate

17/06/2019

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- **XA025**

Page # :- 1 135256
 Veh # :- SLX5781C
 Veh Model :- TOYOTA C-HR HYBRID
 Estimate# :- CK419307
 Claim # :-
 ACC. Date :- 15/06/19
 Terms :- C.O.D Days
 Remarks :-

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel : **(65) 6476 3333**
 Fax : (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel : **(65) 6272 3892**
 Fax : (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S	
AMOUNT S\$	3,717.48
GST @ 7 %	260.22
AMOUNT DUE S\$	3,977.70

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Rasul
Hp 90010068
3 days
P/P
15/6/19 @ 1220
Resy 54 part

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 18 June 2019 11:20 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: FW: TP CLAIMS - SLX5781C AGAINST SBJ28U DOA 14/06/2019 AT AYE NEAR CLEMENTI RD EXIT 9 [External Confidential]
Attachments: RPT.PDF; EST.pdf

11:32am @ 18/6/19
person @ Nivitha
vehicle in
sur @ Resul

Lonpac External - Confidential

Our Ref : 19/19/19/VP00/021951

Dear Nivitha,

Kindly proceed to survey accordingly.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

Lonpac External - Confidential data is for use by authorised external parties only.

From: Nitha [mailto:nitha@mova.com.sg]

Sent: Monday, 17 June, 2019 5:56 PM

To: MT_Claim_SG

Cc: tanyw@mova.com.sg; 'AVRIL HO'

Subject: TP CLAIMS - SLX5781C AGAINST SBJ28U DOA 14/06/2019 AT AYE NEAR CLEMENTI RD EXIT 9

Importance: High

Dear Sir/Madam,

Good day

REF : SBJ28U

Kindly assist revert officer in charge and arrange survey for the above mention case.

Vehicle already at our workshop.

Thank you.

Best Regards,

Nitha

Claims Officer

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314



MOVA

Automotive Pte Ltd



Workshop Address: Blk 1008, Bukit Merah Lane 3
01-04/06/08
Singapore 159722



"WITHOUT PREJUDICE"

Your Ref : 19/19/19/VP00/021951
Our Ref : SLX5781C / T330619

Date : 13 September 2019



LONPAC INSURANCE BERHAD
300 Beach Road
#17-04/07 The Concourse
Singapore 199555.

ATTN : MOTOR CLAIMS DEPT

Dear Sir / Madam,

ACCIDENT INVOLVING SLX5781C & SBJ28U ON 14/06/2019 ALONG NEAR CLEMENNTI ROAD EXIT 9

We refer to the above.

Enclosed herewith are documents for your attention and actions.

Please issue payment in favor of **MOVA AUTOMOTIVE PTE LTD.**

If you have any enquiries, please contact us at 6272 3892 or alternatively:

1. Ms Enny, enny@moval.com.sg for feedback, workshop & claims matters, Lawyer Cases and all Own Damages & Windscreen matters.
2. Ms Suanne Chiu, suann@moval.com.sg for all Third Party matters.

Thank you.

Note: Enclosed tax invoice & discharge voucher.

Yours faithfully
For Claims Manager
Claims Department
Tel: 62723892
Fax: 627083149

*This is a computer generated letter and does not require a signature.

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel : (65) 6272 3892

Fax : (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Performa Invoice

24/07/2019

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Page # :- 1

Veh # :- SLX5781C

Veh Model :- TOYOTA C-HR HYBRID

Performa# :- CK508375

Claim # :- T330619

ACC. Date :- 15/06/19

Terms :- C.O.D Days

Remarks :-

Attention :- XA025

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER	1 PC	948.60	948.60
2.	BUMPER CLIPS	10 PC	5.80	58.00
3.	REAR REFLECTOR GARNISH RH	1 PC	145.18	145.18
4.	REAR REFLECTOR RH	1 PC	69.80	69.80
5.	REAR BUMPER LOWER GARNISH	1 PC	396.70	396.70
6.	TOW COVER	1 PC	36.10	36.10
7.	REAR BUMPER SKRU COVER RH	1 PC	97.20	97.20
8.	REAR BUMPER RETAINER RH	1 PC	116.30	116.30
9.	REAR TAILLAMP LOWER BRACKET RH	1 PC	95.20	95.20
10.	REAR WHEEL ARCH RH	1 PC	173.50	173.50
11.	REAR REINFORCEMENT	1 PC	376.70	376.70
LIST TOTAL S\$				2,513.28
25% DISCOUNT S\$				-628.32
				1,884.96
SPECIAL NET ITEMS :				
1.	REAR PARKING SENSOR	1 PC	220.00	220.00
SPECIAL NET TOTAL S\$				220.00
LABOUR :				
TO REPAIR REAR END PANEL, TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS. TO STRAIGHTEN & REALIGN ON ACCIDENT AFFECTED AREAS				300.00
TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS (PEARL WHITE)				400.00
TO REMOVE & REPLACE REAR PARKING SENSOR				40.00
TO REMOVE & REPLACE REAR SIDE TRIM BOARD L+R SPARE TYRE & OTHER ATTACHMENT PARTS				40.00
LABOUR TOTAL S\$				780.00

Performa Invoice

24/07/2019

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1 135256
Veh # :- SLX5781C
Veh Model :- TOYOTA C-HR HYBRID
Performa# :- CK508375
Claim # :- T330619
ACC. Date :- 15/06/19
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E



NON-TAX AMOUNT S	
AMOUNT S\$	2,884.96
GST @ 7 %	201.95
AMOUNT DUE S\$	3,086.91

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC19010798/R1hb3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 24-09-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBJ 28U	Veh. Inspected	SLX 5781C	
Policy No.	Z/19/VP00/103509	Coverage (\$)	0.00	
Claim No.	19/19/19/VP00/021951	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	18/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA C-HR HYBRID 1.8S	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	ZYX102102923	Colour	WHITE	
Odometer	37083	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	MICHELIN	6 mm	
L/H Front Tyre	215/60 R17	MICHELIN	6 mm	
R/H Rear Tyre	215/60 R17	MICHELIN	6 mm	
L/H Rear Tyre	215/60 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/06/2019	Inspection Date	18/06/2019	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 5781C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	948.60	948.60
10	BUMPER CLIPS @\$5.80	NECESSARY	58.00	58.00
1	REAR REFLECTOR GARNISH RH	CUT	145.18	145.18
1	REAR REFLECTOR RH	CRACKED	69.80	69.80
1	REAR BUMPER LOWER GARNISH	DEFORMED	396.70	396.70
1	TOW COVER	MISSING	36.10	36.10
1	REAR BUMPER SKRU COVER RH	MISSING	97.20	97.20
1	REAR BUMPER RETAINER RH	NECESSARY	116.30	116.30
1	REAR TAILLAMP LOWER BRACKET RH	CRACKED	95.20	95.20
1	REAR WHEEL ARCH RH	CUT	173.50	173.50
1	REAR REINFORCEMENT	BENT	376.70	376.70
1	END PANEL (NPA)	BENT	-	-
1	END PANEL TOP GARNISH	SERVICEABLE	296.70	-
	LESS 25% DISCOUNT		-702.50	-628.32
			2,107.48	1,884.96
SPECIAL NETT ITEMS				
1	REAR PARKING SENSOR (SN)	MISSING	250.00	220.00
			250.00	220.00
LABOUR				
	TO REPAIR REAR END PANEL, TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS. TO STRAIGHTEN & REALIGN ON ACCIDENT AFFECTED AREAS.		500.00	300.00
	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS (PEARL WHITE)		600.00	400.00
	TO REMOVE & REPLACE REAR PARKING SENSOR.		60.00	40.00
	TO RUST PROOF ON ACCIDENT DAMAGED PARTS.	NOT NECESSARY	40.00	-
	TO INSPECT REAR TAILLAMP WATER LEAKAGE TEST.	NOT NECESSARY	40.00	-
	TO REMOVE & REPLACE REAR SIDE TRIM BOARD L+R SPARE TYRE & OTHER ATTACHMENT PARTS.		120.00	40.00
			1,360.00	780.00
GRAND TOTAL			3,717.48	2,884.96



RECOMMENDED COST OF REPAIRS			2,884.96
-----------------------------	--	--	----------

Report Ref No. CC4/LPC19010798/R1hb3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.