

INS. CASE OWNER:

CL

cc 4, Asm 190

10799, Aga32

LKK:

IDAC:

12477

S. No. / Or:

mp

DOI:

ASSIGNMENT

18/6/19

Date / Time:

18/6/2019

Registered in Merimen:

Pre-assign / CCU / FTE

SGL 81840

89m012PS



Insured Vehicle No.:

Claim No.:

Name of Insured:

ONG GAY ENG LIANA

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

14/6/2019

Place of Accident:

Is driver the owner?

(YES NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SGL 81840

SLF 7670X

SJX 43480



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

Green Forest TP



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SLF 7670X - X; SGL 81840 - X

27/10

28/12

28/12

2/3

3/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

4/3

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

12,300.00

(12 days)

Reduction:

13,068.62

% 52

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

100%

Repair Cost:

SS

13,161.00

Loss of Rental (LOR):

SS

()

()

()

()

()

()

()

()

()

()

()

()

()

Loss of Use (LOU):

SS

850.00

()

()

()

()

()

()

()

()

()

()

()

()

Loss of Income (LOI):

SS

()

()

()

()

()

()

()

()

()

()

()

()

()

LOR only

LOU only

LOR + LOU

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

GIA/LTA Search

SS

7.45

Medical:

SS

()

Disbursement:

SS

()

Legal Cost

SS

()

Total:

SS

14,018.45

Global Sum SS:

14,010.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee:

SS

14,010.00

Name 1:

Green Forest Automobile Pte Ltd

Payee 2 (State of P.A.):

SS

()

Name 2:

()

Payee 3 (State of P.A.):

SS

()

Name 3:

()

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLF7670X Yr Regn: 2016, Sept.

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 154898 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Ru11204977

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SR / STD A/Rim or

Tyre Size: F: 215/60R16

R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 18/06/19

Survey held at Green Forest

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Reas N/S, Front

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AXA

L/S \$12,300/- (Red = \$13,068.62 / 527/-)

MV: 65K

PV: 47.6K

Nett: 17.4K

* 12 repair days + 1 PRS + 2 Sunday + 2 Sat = 17 days

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

Survey Fee:

Date:

1)

2)

IN

OUT

Basic & Add.

S + RS SI

Photos

Others

TOTAL

Prel. Report

Final Report

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

CARRO LEASING PTE LTD
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

TRAXA
Acilia

18th JUNE 2019

Accident date: 14th JUNE 2019

Estimated repair cost for vehicle no: SLF7670X HONDA VEZEL 1.5X A '16

S/n	Qty	Items	U/price	Amount
1	1	Front bonnet <i>Distorted</i>		\$950.40 ✓
2	1	Front bonnet lock <i>Jammed</i>		\$188.10 ✓
3	1	bonnet inner insulator <i>New</i>		\$225.20 ✓
4	1	front bonnet inner rubber <i>Wt</i>		\$86.20 ✓
5	2	Front head lamp <i>Cracked</i>	\$1,784.50	\$3,569.00 ✓
6	2	head lamp lower bracket <i>Cracked</i>	\$68.00	\$136.00 ✓
7	2	log lamp chrome <i>Cracked</i>	\$118.20	\$236.40 <i>118.20</i>
8	1	Front bumper <i>Distorted</i>		\$936.70 <i>880</i>
9	2	Front bumper side bracket <i>new</i>	\$68.20	\$136.40 ✓
10	10	Front bumper clips <i>new</i>	\$5.00	\$50.00 <i>30</i>
11	1	Front bumper number plate <i>Best</i>		\$50.00 ✓
12	1	Front bumper reinforcement <i>Best</i>		\$484.00 ✓
13	1	Front center garnish <i>new</i>		\$280.20 ✓
14	1	front centre garnish moulding <i>Delcd</i>		\$138.00 ✓
15	1	Front bumper center lower cover <i>Delcd</i>		\$295.10 ✓
16	1	Front Bumper Towing Cover <i>Missing</i>		\$68.00 ✓
17	1	front windscreen moulding <i>Cracked</i>		\$158.00 ✓
18	1	ERP bracket		\$30.00 ✓
19	1	Front Grille- upper <i>Cracked</i>		\$225.00 ✓
20	1	front grille -lower <i>Cracked</i>		\$385.00 ✓
21	1	Front Grille emble logo <i>new</i>		\$58.00 ✓
22	10	Front Grille clips <i>new</i>	\$5.00	\$50.00 <i>10</i>
23	1	Front support panel <i>Buckled</i>		\$989.00 <i>676</i>
24	2	Front support panel side bracket <i>new</i>	\$55.80	\$111.60 ✓
25	2	Front support panel side cover <i>Delcd</i>	\$187.25	\$374.50 ✓
26	8	Front support panel side cover clips <i>new</i>	\$12.90	\$103.20 <i>30</i>
27	1	Front water tank <i>new</i>		\$225.00 ✓
28	1	Front radiator <i>Distorted</i>		\$960.00 ✓

29	1	radiator fan blade	3 new		\$169.70	+
30	1	radiator fan motor	3 new		\$850.00	+
31	1	Front air-con condenser	Distorted		\$1,020.10	✓
32	1	Front air-con condenser fan motor assy	Crushed		\$381.72	✓
33	1	Front L/H fender	Buckled		\$705.00	✓
34	1	Rear Boot Lid	Dented		\$1,195.00	✓
35	1	Rear Boot Lid damper -LH	new		\$180.00	+
36	1	rear Boot Lid hinges -LH	new		\$168.00	+
37	1	Rear boot lid emble logo	new		\$55.00	+
38	1	Rear boot lid VEZEL logo	3 new		\$38.10	✓
39	1	rear boot lid Emble logo	3 new		\$38.10	✓
40	1	Rear Boot Lid side reflector-LH	ht		\$402.20	✓
41	1	Rear boot lid inner rubber	new		\$237.00	x
42	1	Rear Boot Lid Inner Lock	new		\$284.20	+
43	1	Rear Boot Lid Number Plate	new		\$50.00	+
44	1	rear Boot Lid number Plate top garnish	new		\$110.00	+
45	2	Rear Boot Lid Number Plate Lamp	new	\$61.10	\$122.20	+
46	1	Rear Boot Lid center moulding	new		\$320.80	+
47	10	Rear Boot Lid Inner Trim board clips	3 new	\$5.00	\$50.00	+
48	1	Rear Boot Lid Inner Trim board			\$354.00	+
49	1	Rear tail lamp-LH	new		\$420.00	+
50	1	Rear end panel	Regis		\$420.00	+
51	1	Rear End Panel Top Garnish	new		\$168.00	+
52	1	Rear Bumper	Dented		\$745.30	✓
53	1	Rear bumper top garnish	new		\$226.20	✓
54	2	Rear Bumper Side Bracket	new LH	\$48.00	\$96.00	48
55	1	Rear Bumper reverse sensor	new		\$350.00	+
56	1	Rear side Bumper -LH	Distorted		\$125.00	✓
57	8	Rear bumper clips	new	\$5.00	\$40.00	✓
58	1	Rear Bumper Side Reflector-LH	new		\$68.00	+

Subtotal :- \$20,888.62

14812.62
~~1185009~~

14586.42
 11669.13

Labour charges

To Remove & refix cushion	\$120.00 60
To Remove & refix front windscreen	\$120.00 ✓
Gum	\$50.00 ✓
Remove & refix rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
Tuff kote	\$120.00 80
To remove & re-fix air-con condenser & radiator fan Motor & top up gas	\$280.00 100
WHEEL alignment (computer)	\$120.00 ✓
To remove & install rear reverse sensor	\$120.00 50
Towing charges	\$100.00 60
To Check Wiring System	\$80.00 60
Panel beating	\$1,600.00 ✓
Spray painting	\$1,600.00 800

Subtotal :- \$4,480.00

Total:- \$25,368.62

total: 15369.13

4/s: 12.3k ✓

12 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 5832G

Vehicle Details

Vehicle No.: SLF7670X
Vehicle to be Exported: Yes
Intended Deregistration Date: 10 Jul 2019
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X CVT
Primary Colour: Green
Manufacturing Year: 2016
Engine No.: L15B4404977
Chassis No.: RU11204977
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$21,767.00
Original Registration Date: 08 Sep 2016
First Registration Date: 08 Sep 2016
Transfer Count: 2
Actual ARF Paid: \$12,474.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 07 Sep 2026
PARF Rebate Amount: \$9,355.00

Intended COE Rebate Details

COE Expiry Date: 07 Sep 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$53,000.00
COE Rebate Amount: \$37,943.00
Total Rebate Amount: \$47,298.00

The information contained herein is correct as at 10 Jul 2019

OK

Sketch Plan Pg. 8

6/14/2019

PARF/COE Rebate Enquiry

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	5832G
Vehicle No.:	SLF7670X
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Green
Manufacturing Year:	2016
Engine No.:	L15B4404977
Chassis No.:	RU11204977
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,767.00
Original Registration Date:	08 Sep 2016
First Registration Date:	08 Sep 2016
Transfer Count:	2
Actual ARF Paid:	\$12,474.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Sep 2026
PARF Rebate Amount:	\$9,355.00
COE Expiry Date:	07 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,000.00
COE Rebate Amount:	\$38,328.00
Total Rebate Amount:	\$47,683.00

The information contained herein is correct as at 14 Jun 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5832G
Vehicle Details	
Vehicle No.:	SLF7670X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Green
Manufacturing Year:	2016
Engine No.:	L15B4404977
Chassis No.:	RU11204977
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,767.00
Original Registration Date:	08 Sep 2016
First Registration Date:	08 Sep 2016
Transfer Count:	2
Actual ARF Paid:	\$12,474.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Sep 2026
PARF Rebate Amount:	\$9,355.00
Intended COE Rebate Details	
COE Expiry Date:	07 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,000.00
COE Rebate Amount:	\$38,271.00
Total Rebate Amount:	\$47,626.00

The information contained herein is correct as at 18 Jun 2019

OK

- Liverpool Football Club - 2018/19 season YNWA
- Najib Announce VEP for Spore cars!
- Honda CRV -facelift with 1.5 turbo

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

 Post an Ad  Advertiser Login  Ways of Selling

New 5 Years Renewal Coe Toyota Altis 1.6A

 3.16%P.A \$0 Admin Fees@Gv
Finance.2 Years Warranty.\$1800
Down Monthly From \$488
GV Credit Pte Ltd StarAd

Lake View Credit Pte Ltd view our cars

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category  Save Search  Print » Back (1 2 3 4 5 6) Next » Sort by Date Posted 20 results/page

120 vehicles	Search vezel		Advanced Search		Search	View All		
Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	vezel	Any	Any	2016	Any	Any	Any	Available



☐ **Honda Vezel 1.5A X** \$67,200 \$8,570 /yr 13-Sep-2016 1,496 cc 62,800 km SUV Available

1 Owner, Non-Private Hire Car! Call To Book For Appointment.

 Posted: 01-Jun-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



☐ **Honda Vezel Hybrid 1.5A X** \$73,800 \$9,790 /yr 28-Sep-2016 1,496 cc 58,937 km SUV Available

Fuel Type: Petrol-Electric

Come With 2 Years Third Party Warranty, Easy And Flexible In House Loan And Balloon Scheme Available, No Gimmicks! DVD/Bluetooth, Reverse Camera, Keyless Entry/Start, Paddle Shift, Auto LEDs Headlight...

 Posted: 14-Jun-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



☐ **Honda Vezel 1.5A X** \$71,800 \$9,170 /yr 05-Oct-2016 1,496 cc 76,904 km SUV Available

Benefit Auto Offer Best Deal In Market! Offer Best Price! Offer Best Price For Trade In! Offer Best Interest Rate With Loan! Hurry Arrange Call To Our Sales For Appointment!

Benefit Auto Enterprise Pte Ltd

 Posted: 18-Jun-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



☐ **Honda Vezel 1.5A X** \$67,800 \$8,460 /yr 05-Oct-2016 1,496 cc 45,000 km SUV Available

Graded **A** by **STP**

In-House Available! Beautiful Condition, Like New Car Condition, Professional Evaluation By STP, Professional After Sales Service Assured. Be First To Appreciate This Beauty In Pristine Condition! Cal...

Universe Motoring

 Posted: 16-Jun-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

 Car Buying

 Car Selling

 Car Ownership

 Car Aftermarket

 On The Move

 Lifestyle

TYREPAC

- > Buy Tyres Online!
- > Latest Special Offers from Tyrepac!



☐ **Honda Vezel 1.5A X** \$69,800 \$8,710 /yr 05-Oct-2016 1,496 cc 42,000 km SUV Available

Bank And In House Full Loan Available. Original Paintwork. 100% Accident Free. No Repairs Needed. 6 Months Certified Pre Owned Car Warranty Will Be Provided. Trade In Welcome. Kindly Contact Our Sales...

Imperium Car Motor Pte Ltd

 Posted: 14-Jun-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



☐ **Honda Vezel 1.5A X** \$69,000 \$8,740 /yr 12-Oct-2016 1,496 cc 47,100 km SUV Available

Elegant White SUV, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-house Loan Packages Available.

Prime Motor & Leasing

 Posted: 14-Jun-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



☐ **Honda Vezel 1.5A X** \$73,800 \$9,250 /yr 12-Oct-2016 1,496 cc 68,000 km SUV Available

Please Call To Arrange For A Viewing! Well Maintained, Owner Will Introduce The Workshop To The New Owner, So That The Next Owner Can Check On The Servicing Record, And Buy With A Piece Of Mind That I...

 Posted: 12-May-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Compare 

4pm @ 18/6/19
vehicle in
person @ Chris
sur @ Adrian



Service Request Details

Claim

S9M01QP5

Reference

None

Loss Date

June 14, 2019

Report Date

Jun 17, 2019 12:00:00 AM

Request Date

June 18, 2019

Due Date

June 25, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration

SLF7670X



PROJECT

HONDA

Service Address

Primary Contact/Insured

ONG GAY ENG LIANA
31 JURONG WEST STREET 41, #15-27, 649412, Singapore
90170910
GELICHIN@SINGNET.COM.SG

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: chan pick yuen <chris_chanbebe@hotmail.com>
Sent: Monday, 17 June, 2019 3:46 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: KUMAR Shailendra
Subject: SLF7670X & SGL8184D doa 14/6/19
Attachments: SLF 7670X - Police Report.pdf

Categories: Shekhar

Dear Sir / Mdm ,

Enclosed is our client TP report.

Please let us have your 10 name list of surveyor to survey our clients vehicle: SLF7670X . Thanks

Best Regards

Chris Chan

Green Forest Automobile Pte Ltd

Hp:92712214



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 2/3/2020

Survey Details:

Date of loss	14-Jun-19
Date of appointment	18-Jun-19
Date of survey	18-Jun-19
Location of survey	GREEN FOREST AUTOMOBILE

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SLF7670X
Make and Model	HONDA VEZEL 1.5X CVT
Date of registration	8-Sep-16
Parf Rebate	
Market Value	\$ 65,000.00
Parf Rebate	\$ 47,683.00
Nett Loss	\$ 17,317.00

Repair details:

Initial Estimate	25,368.62
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 11,850.09
Check items (estimate)	\$ -
Labour	\$ 3,580.00
Total	\$ 15,430.09
Lump Sum(if applicable)	\$ 12,300.00

Number of days for repair	12.0
---------------------------	------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

12 REPAIR DAYS + 1PRS + 2SUNDAYS + 2SATURDAYS = 17DAYS

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	13,161.00 W/GST
Loss of use	\$	1,020.00 17 days x \$60
Loss of rental	\$	-
Loss of income	\$	-
LTA search fees	\$	7.45
Others	\$	-
Proposed Total	\$	14,188.45



<MANDATE IA> - S9M01QP5 {ACCIDENT INVOLVING SGL 8184D (OI) & SLF 7670X (TP) ON 14/06/2019}

Type

🔗 Question

Message

LIABILITY: 100% BOLA S28 (OI LAST) - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$14,188.45 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL
02/03/2020

Reply

2017

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

INVOICE

CARRO LEASING PTE LTD
8 Kaki Bukit Avenue 4
#05-25 Premier @ Kaki Bukit
Singapore 415875

Date: 26th FEBRUARY 20

Accident date: 14th JUNE 2019
Final Bill For Vehicle No: SLF7670X Honda Vezel 1.5

Descriptions	AMOUNT
Lump Sum repair cost as recommended by LKK AUTO CONSULTANTS PTE LTD Surveyor : Mr Adrian Ling	\$12,300.00
Total	\$12,300.00
GST 7%	\$861.00
Grand Total	\$13,161.00

S/DLRS: THIRTEEN THOUSAND ONE HUNDRED SIXTY ONE ONLY



**Re:<MANDATE IA> - S9M01QP5 {ACCIDENT
INVOLVING SGL 8184D (OI) & SLF 7670X (TP) ON
14/06/2019}**

Type

🔗 Question

Message

APPROVE

Reply

Cecilia Chong (LKK Auto)

From: chan pick yuen <chris_chanbebe@hotmail.com>
Sent: Wednesday, 26 February 2020 9:21 PM
To: Cecilia Chong (LKK Auto)
Cc: Admin A
Subject: Re: SLF7670X after paint *** LKK REF: CC4/ASM19010799/Aga3
Attachments: GIA.pdf; invoice LOA.pdf; LTA.pdf

Dear Cecilia ,

Please advise AXA OIC email .

I direct liaise with AXA OIC ,less than 1 month can get offer & 2 month receive payment .

Enclosed is the invoice , LOA , LTA & GIA

As request following :

1. RC \$ 13,161.00 (\$12300 +7% GST - AS AGREED)
2. loss of use \$1700 (\$100 X 17days- our client's car under rental company - 12 Days recommend - 3 days waiting PRS - 14/06/19 @ FRIDAY ACCIDENT , waiting Monday then can arrange survey + 2days weekend)
3. Ita fee \$7.45

@ 100% (3 cars chain collision)

TOTAL \$14,868.45

Please let us have your settlement in next 3 weeks . If no heard from your offer , I will direct email & liaise to AXA all OIC . Thanks

Best Regards

Chris Chan

Green Forest Automobile Pte Ltd

Hp:92712214

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Wednesday, July 10, 2019 12:09 PM
To: chan pick yuen <chris_chanbebe@hotmail.com>; Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: SLF7670X after paint *** LKK REF: CC4/ASM19010799/Aga3



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19010799/Aga3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA LOH		Date : 13-03-2020 Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGL 8184D	Veh. Inspected	SLF 7670X
Policy No.	CN827334	Coverage (\$)	0.00
Claim No.	S9M01QP5	Excess (\$)	0.00
Assign From	CYNTHIA LOH	Assign Date	18/06/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11204977	Colour	GREEN
Odometer	154898	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
L/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
R/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm
L/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/06/2019	Inspection Date	18/06/2019
Survey held at	GREEN FOREST AUTOMOBILE 8 KAKI BUKIT AVENUE 4 #05-25 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 7670X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET (CONSISTENT)	DISTORTED	950.40	950.40
1	FRONT BONNET LOCK (CONSISTENT)	JAMMED	188.10	188.10
1	BONNET INNER INSULATOR (CONSISTENT)	NOT NECESSARY	225.20	-
1	FRONT BONNET INNER RUBBER (CONSISTENT)	CUT	86.20	86.20
2	FRONT HEAD LAMP @ \$1784.50 (CONSISTENT)	CRACKED	3,569.00	3,569.00
2	HEAD LAMP LOWER BRACKET @ \$68.00 (CONSISTENT)	CRACKED	136.00	136.00
2	LOG LAMP CHROME @ \$118.20 (CONSISTENT)	N/S CRACKED	236.40	118.20
1	FRONT BUMPER (CONSISTENT)	DISTORTED	936.70	880.00
2	FRONT BUMPER SIDE BRACKET @ \$68.20 (CONSISTENT)	NECESSARY	136.40	136.40
10	FRONT BUMPER CLIPS @ \$5.00 (CONSISTENT)	NECESSARY	50.00	30.00
1	FRONT BUMPER NUMBER PLATE (CONSISTENT)	BENT	50.00	50.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	484.00	484.00
1	FRONT CENTER GARNISH (CONSISTENT)	NOT NECESSARY	280.20	-
1	FRONT CENTRE GARNISH MOULDING (CONSISTENT)	DEFORMED	138.00	138.00
1	FRONT BUMPER CENTER LOWER COVER (CONSISTENT)	DEFORMED	295.10	295.10
1	FRONT BUMPER TOWING COVER (CONSISTENT)	MISSING	68.00	68.00
1	FRONT WINDSCREEN MOULDING (CONSISTENT)	NOT NECESSARY	158.00	-
1	ERP BRACKET (CONSISTENT)	NOT NECESSARY	30.00	-
1	FRONT GRILLE - UPPER (CONSISTENT)	CRACKED	225.00	225.00
1	FRONT GRILLE - LOWER (CONSISTENT)	CRACKED	385.00	385.00
1	FRONT GRILLE EMBLEM LOGO (CONSISTENT)	NECESSARY	58.00	58.00
10	FRONT GRILLE CLIPS @ \$5.00 (CONSISTENT)	NECESSARY	50.00	10.00
1	FRONT SUPPORT PANEL (CONSISTENT)	BUCKLED	989.00	676.00
2	FRONT SUPPORT PANEL SIDE BRACKET @ \$55.80 (CONSISTENT)	NOT NECESSARY	111.60	-
2	FRONT SUPPORT PANEL SIDE COVER @ \$187.25 (CONSISTENT)	DEFORMED	374.50	374.50
8	FRONT SUPPORT PANEL SIDE COVER CLIPS @ \$12.90 (CONSISTENT)	NECESSARY	103.20	30.00
1	FRONT WATER TANK (CONSISTENT)	NOT NECESSARY	225.00	-

Report Ref No. CC4/ASM19010799/Aga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RADIATOR (CONSISTENT)	DISTORTED	960.00	960.00
1	RADIATOR FAN BLADE (CONSISTENT)	NOT NECESSARY	169.70	-
1	RADIATOR FAN MOTOR (CONSISTENT)	NOT NECESSARY	850.00	-
1	FRONT AIR-CON CONDENSER (CONSISTENT)	DISTORTED	1,020.10	1,020.10
1	FRONT AIR-CON CONDENSER FAN MOTOR ASSY (CONSISTENT)	CRACKED	381.72	381.72
1	FRONT L/H FENDER (CONSISTENT)	BUCKLED	705.00	705.00
1	REAR BOOT LID (CONSISTENT)	DENTED	1,195.00	1,195.00
1	REAR BOOT LID DAMPER - LH (CONSISTENT)	NOT NECESSARY	180.00	-
1	REAR BOOT LID HINGES - LH (CONSISTENT)	NOT NECESSARY	168.00	-
1	REAR BOOT LID EMBLEM LOGO (CONSISTENT)	NOT NECESSARY	55.00	-
1	REAR BOOT LID VEZEL LOGO (CONSISTENT)	NECESSARY	38.10	38.10
1	REAR BOOT LID EMBLEM LOGO (CONSISTENT)	NECESSARY	38.10	38.10
1	REAR BOOT LID SIDE REFLECTOR - LH (CONSISTENT)	CUT	402.20	402.20
1	REAR BOOT LID INNER RUBBER (CONSISTENT)	NOT NECESSARY	237.00	-
1	REAR BOOT LID INNER LOCK (CONSISTENT)	NOT NECESSARY	284.20	-
1	REAR BOOT LID NUMBER PLATE (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR BOOT LID NUMBER PLATE TOP GARNISH (CONSISTENT)	NOT NECESSARY	110.00	-
2	REAR BOOT LID NUMBER PLATE LAMP @ \$61.10 (CONSISTENT)	NOT NECESSARY	122.20	-
1	REAR BOOT LID CENTER MOULDING (CONSISTENT)	NOT NECESSARY	320.80	-
10	REAR BOOT LID INNER TRIM BOARD CLIPS @ \$5.00 (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR BOOT LID INNER TRIM BOARD (CONSISTENT)	NOT NECESSARY	354.00	-
1	REAR TAIL LAMP - LH (CONSISTENT)	NOT NECESSARY	420.00	-
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	420.00	-
1	REAR END PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	168.00	-
1	REAR BUMPER (CONSISTENT)	DEFORMED	745.30	745.30
1	REAR BUMPER TOP GARNISH (CONSISTENT)	NOT NECESSARY	226.20	-
2	REAR BUMPER SIDE BRACKET @ \$48.00 (CONSISTENT)	N/S NECESSARY	96.00	48.00
1	REAR BUMPER REVERSE SENSOR (CONSISTENT)	NOT NECESSARY	350.00	-
1	REAR SIDE BUMPER - LH (CONSISTENT)	DISTORTED	125.00	125.00
8	REAR BUMPER CLIPS @ \$5.00 (CONSISTENT)	NECESSARY	40.00	40.00

Report Ref No. CC4/ASM19010799/Aga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER SIDE REFLECTOR - LH (CONSISTENT)	NOT NECESSARY	68.00	-
	LESS 20% DISCOUNT		-	-2,917.29
			20,888.62	11,669.13
	SPECIAL NETT ITEMS			
1	GUM (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	GUM (SN) (CONSISTENT)	NECESSARY	50.00	50.00
			100.00	50.00
	LABOUR			
	TO REMOVE & REFIX CUSHION.		120.00	60.00
	TO REMOVE & REFIX FRONT WINDSCREEN.	NOT NECESSARY	120.00	-
	REMOVE & REFIX REAR WINDSCREEN.		120.00	120.00
	TUFF KOTE.		120.00	80.00
	TO REMOVE & RE-FIX AIR-CON CONDENSER & RADIATOR FAN MOTOR & TOP UP GAS.		280.00	120.00
	WHEEL ALIGNMENT (COMPUTER).	NOT NECESSARY	120.00	-
	TO REMOVE & INSTALL REAR REVERSE SENSOR.		120.00	50.00
	TOWING CHARGES.		100.00	60.00
	TO CHECK WIRING SYSTEM.		80.00	60.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,600.00	1,600.00
	SPRAY PAINTING.		1,600.00	1,500.00
			4,380.00	3,650.00
	GRAND TOTAL		25,368.62	15,369.13
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			12,300.00

Report Ref No. CC4/ASM19010799/Aga3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.