

22/03/2002

ASS. REC. BY:

REF: CS/CI 190108231

Evd352

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Ong Chin Kiat of CI Date/Time: 18.6.19 17.31p.m.

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJK 9859 D Insured: GY 264 R

at Workshop m/s BH Auto Tel: 65598944

of Btk 1 sin ming Industrial Estate sector C #01/111

Policy No: DMCVSN 30743518000 Claim No: SNM19D20279002

Sum Insured: Excess:

Make of Veh: D.O.A. 3.6.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 19.6.19 5.34p.m. Person Contacted: Yiny See Vehicle IN/OUT

Date/Time	Action/Instruction Estimate (✓)
	SJK 9859 D-x
	GY 264 R-x

Steve

ASSIGNMENT

4-5

From: Date: 20-6-2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJK 9859D

at Workshop m/s BH Auto

of BIK 1 sin ming Industrial Estate Sector C

Insured: #01/111

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh: 3.00p.m onvr waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SJK 9859D

Yr Regn: 12/11/08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota AX10

c.c. 1496

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 116113

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: NZE 1416099515

Gen. Cond: Good Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kapsen

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 3/6/19

D.O.I. 20/6/19

Survey held at BH Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11V - 25,000

11V - 13,212

11V - 11,788

RECEIVED 17 JUL 2019

17/7/19 Finalize confirm \$1550, 5 days (Red 6705.04, 819)

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2) 17/7 - typist

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

G + RS, \$

Photos

Others

TOTAL

Report Format:

merimen

Lump Sum / I.B.I. (\$

1550/-

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jun 2019		18 Jun 2019 17:31 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

EVAN LIM & CO PTE LTD, Co. Reg. No.: 198001580H

Main Claimant:

GOH HAN KIAT ALAN, ID: S8023515A

Vehicle Reg. No.:

SJK9859D

Date of Loss:

03/06/2019 17:00 - :59
[129 Months and 22 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / SNM19D202790C02

Policy/Cover Note No.:

DMCVSN30743518000

Vehicle Reg. No. (Insured):

GY264R

Policy No. (Claimant):

MPC18A00278100

Excess:

S\$0.00

Repairer:

BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117, 575636 Sin Ming - Tel: 6559 8944

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]

Claimant's Insurer:

ECICS Limited (HQ) - Tel: 63374779 /6303 0178

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/06/2019]

Driver/Custodian (Insured):

NOEL LESLIE JASWAN (57 / Male), NRIC: S2561711H Email:

Adj Asg. Remarks:

to assign Mr Kenneth Kong for SJE. thank you.

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/06/2019 17:22
Date Of Accident	03/06/2019 17:35
Exact Location Of Accident	ALONG ANGUILLA CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK9859D
Insured/Policyholder	
Name Of Registered Owner	GOH HAN KIAT ALAN
NRIC No	S8023515A
Email Address	ALAN.GOH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97106050
Alternative Phone No	OFFICE-97106050

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA AXIO-1.5 X SPECIAL EDITION (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC18A00278100
Cover Note Number	

Driver

Name of Driver	GOH HAN KIAT ALAN
NRIC No	S8023515A
Date Of Birth	10/08/1980
Occupation	INDOOR
Date Of Driving Pass	01/11/2006
Driving Experience	12 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97106050
Fax Number	
Contact Number	OFFICE-97106050
Email Address	ALAN.GOH@GMAIL.COM

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	LIN SHIMAN SANDRA
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJK9859D
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

on 3rd June 2019, approximately 1740hrs hit floor after
10m. Veh SJK 9859 D was driving when veh A stopped to
reverse into a carpark lot and veh GY364R driven by
Noel Leslie + Jaswan drove and hit my car
The incident happened at Anguilla Park carpark
Passenger was affected and went to the doctor and was
given 3 days MC

I/We declare the foregoing particulars are true in every respect.

[Signature]

Driver's Signature:
(if driver is not the policyholder)
Date & Time:

Centre Personnel
No. 1

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3515A
Vehicle Details	
Vehicle No.:	SJK9859D
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X SPECIAL EDITION A
Primary Colour:	Beige
Manufacturing Year:	2008
Engine No.:	1N2D216586
Chassis No.:	NZE1416099515
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$13,689.00
Original Registration Date:	12 Nov 2008
First Registration Date:	12 Nov 2008
Transfer Count:	2
Actual ARF Paid:	\$13,689.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$15,142.00
COE Rebate Amount:	\$13,212.00
Total Rebate Amount:	\$13,212.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 20 Jun 2019

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Under Agent Warranty, Top Top Condition!



Also Available! Time To Sell!
The Dream Car
Car Empire

PRIME MOTOR & LEASING

JOHNSON YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted 20 results/page

18 vehicles

toyota axio

Advanced Search

Image	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection toyota axio Any Any > 10 year(s) old Any Any Any Available								
	Toyota Corolla Axio 1.5M X (COE till 03/2022)	\$19,998	\$7,340 /yr	12-Mar-2007	1,496 cc	75,801 km	Sedan	Available
Drive With Assurance! 1 Owner! 1 Year Extended Engine & Gearbox Warranty! Genuine And Transparent Deal! Bank/In House Up To 100% Full Loan At Monthly \$722 No Gimmicks! All Our Quality Consignment Cars...								
CarQuotz Singapore								
Posted: 20-Jun-2019 Tags: 2007 Toyota Corolla, 2007 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	Toyota Corolla Axio 1.5A X (COE till 08/2027)	\$43,800	\$5,350 /yr	29-Aug-2007	1,496 cc	146,003 km	Sedan	Available
Genuine Mileage Clocked! Showroom Condition, Accident Free, Low Mileage, Kindly Contact Our Sales Person Directly For Enquiries, Viewing And Testing Immediately!								
Posted: 05-Jun-2019 Tags: 2007 Toyota Corolla, 2007 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	Toyota Corolla Axio 1.5A X (COE till 10/2022)	\$22,800	\$6,800 /yr	26-Oct-2007	1,496 cc	130,000 km	Sedan	Available
Almost New Condition, View To Believe, Nice Number, Call Now!								
Posted: 15-Jun-2019 Tags: 2007 Toyota Corolla, 2007 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	Toyota Corolla Axio 1.5A X (COE till 02/2028)	\$39,800	\$4,590 /yr	18-Feb-2008	1,496 cc	127,138 km	Sedan	Available
Reliable Japanese Sedan Ideally For Daily Drives, Good Fuel Consumption, Annual Depreciation At \$4600 Only, High PQP Value Of \$42,122 Equivalent To Higher Paper Value Than Current PQP For 10 YRS. Well...								
Posted: 11-Jun-2019 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
GET YOUR COE RENEWAL LOAN								
Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.								
	Toyota Corolla Axio 1.5A X (COE till 05/2023)	\$24,800	\$6,280 /yr	03-Jun-2008	1,496 cc	-	Sedan	Available
One Owner, Clean And Neat Interior, New Engine Mounting, New Shock Absorber, New Lower Arm, New Drive Shaft Cover, New Rear Shock Absorber, New Air Con Compressor, New Air Con Cooling Coil, New Tie Rod...								
Posted: 06-May-2019 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	Toyota Corolla Axio 1.5A X (COE till 06/2023)	\$23,800	\$5,920 /yr	27-Jun-2008	1,496 cc	-	Sedan	Available
Only Last Month Sold Units Toyota For Sale At Only \$23800, Monthly \$700plus, WhatsApp For Loan Pre Approval, Open Everyday Including Ph 10.30-6.30pm. We Are Sgcarmart Premium Dealer! We Are Vehicle T...								
88 Motor Trading								
Posted: 13-Jun-2019 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	Toyota Corolla Axio 1.5A X (COE till 07/2028)	\$49,600	\$5,440 /yr	01-Aug-2008	1,496 cc	-	Sedan	Available
Gearbox Filter, Gearbox Cooler, Pan Gasket, Lower Arm, Steering Rack, Tie Rod, Japan Engine Mounting Changed Total \$4K. No Leaking At All.								
Posted: 08-Jun-2019 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	Toyota Corolla Axio 1.5A G (COE till 09/2028)	\$41,800	\$4,520 /yr	17-Sep-2008	1,496 cc	149,294 km	Sedan	Available
Reliable Japanese Sedan Ideally For Daily Drives, One Of Its Kind That Equipped With Push Start & Keyless Entry, Annual Depreciation At \$4500 Only, High PQP Value Of \$32,339 Equivalent To Higher Paper...								
Posted: 17-Jun-2019 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								

Compare

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

China Taiping Insurance (Singapore) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Tel: 63896111 Fax: 6224 7175/7478

E-mail: claimsdept@sg.cntaiping.com

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SJK9859D

MODEL : TOYOTA COROLLA AXIO 1.5X

POLICY NO : MPC18A0078100

CHASSIS NO : NZE1416099515

YEAR OF MANUFACTURE : 2008

DATE / TIME OF ACCIDENT: 03/06/2019 Time: 1735Hrs at ALONG ANGUILLA CARPARK.

THIRD PARTY VEHICLE NO: GY264R

Date: 18/06/2019

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N		Quantity	Unit Price S\$	Condition	Amount S\$
1	Bootlid X R	1	798.50	Dented	798.50 X
2	Bootlid hinge LH X NAI	1	62.80	Bented	62.80 X
3	Bootlid hinge RH X NAI	1	62.80	Bented	62.80 X
4	Bootlid weatherstrip X NAI	1	176.20	Cut	176.20 X
5	Bootlid lock X NAI	1	104.50	Bented	104.50 X
6	Bootlid lock striker X NAI	1	37.24	Bented	37.24 X
7	Bootlid emblem / NPC	1	61.70	Necessary	61.70 /
8	Bootlid lettering "AXIO" / NPC	1	59.80	Necessary	59.80 /
9	Bootlid lettering "X" / NPC	1	48.30	Necessary	48.30 /
10	Rear tail lamp assy LH ? X NAI	1	391.40	Cracked	391.40 X
11	Rear tail lamp assy RH X NAI	1	391.40	Cracked	391.40 X
12	Rear bumper / DD	1	464.20	Torn	786.80 464.20 /
13	Rear bumper side retainer LH / OR	1	97.50	Necessary	229.60 97.50 /
14	Rear bumper side retainer RH X NAI	1	97.50	Necessary	32.80 X
15	Rear bumper clip / NPC	12	3.89	Necessary	30 / 46.68
16	Rear end panel X R	1	493.20	Dented	493.20 X
17	Rear end panel top garnish X NAI	1	180.90	Kinked	180.90 X
18	Rear fender LH X R	1	945.50	Bented	945.50 X
19	Rear fender RH X NAI	1	945.50	Bented	945.50 X
20	Rear fender shield LH X NAI	1	60.70	Cut	60.70 X
21	Rear fender shield RH X NAI	1	60.70	Cut	60.70 X
22	Rear windscreen moulding set X NAI	1	109.70	Necessary	109.70 X

Sub-Total: 6,086.72

Less: 25% discount - 1,521.68

Total Parts after 25% discount: 4,565.04

Special Nett Items

1	Anti-rust coating NPC	1	80.00	30 / 80.00
2	Rear number plate with casing CUT	1	100.00	35 / 100.00
3	Rear windscreen sealant NN	1	120.00	X 120.00
4	Rear end panel seal NPC	1	80.00	50 / 80.00 30 /
				380.00

125

Total Parts: 4,945.04

Labour Charges For Rear Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	500	1,500.00
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	720 600	1,250.00
3	Provide skill labour to disconnect and check electrical wiring	30	60.00
4	Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and or upholstery to facilitate repairs	30	150.00
5	Provide skill labour to remove and refit rear windscreen	X	250.00
6	Dismantle and transfer bootlid fitting and mechanism to new/facilitate repair	X	100.00

Total Labour:

Total Parts & Labour:

GST 7%

Grand Total:

3,310.00

8,255.04

577.85

8,832.89

Estimate Repair Duration

12 days

ACCIDENT VEHICLE OF : SJK9859D

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Steve

Company : LKK

Date : 20/6/19

Time : 3:00pm

Contact No : 8322 8817

Email : Steve.chen@lkkauto.com

with 11/12
5 4 days
L/S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	18 Jun 2019		18 Jun 2019 17:31 Edit Adj Rpt	S\$1,550.00 Edit Estimates	S\$1,550.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	EVAN LIM & CO PTE LTD, Co. Reg. No.: 198001580H		
Main Claimant:	GOH HAN KIAT ALAN, ID: S8023515A		
Vehicle Reg. No.:	SJK9859D	Date of Loss:	03/06/2019 17:00 - :59 [126 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D202790C02	Policy/Cover Note No.:	DMCVSN30743518000
Vehicle Reg. No. (Insured):	GY264R	Policy No. (Claimant):	MPC18A00278100
		Excess:	S\$0.00
Repairer:	BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117, 575636 Sin Ming - Tel: 6559 8944		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Claimant's Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 27/06/2019]		
Driver/Custodian (Insured):	NOEL LESLIE JASWAN (57 / Male), NRIC: S2561711H Email:		
Adj. Asg. Remarks:	to assign Mr Kenneth Kong for SJE. thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***SJK9859D (SNM19D202790C02)**
[GY264R]

TP

GOH HAN KIAT ALAN

Jun 3 2019 5:00PM

[EVAN LIM & CO PTE LTD]

BH Auto Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports

1 per page ☐

No	Finalized On	BH Auto Services Pte Ltd (Sin Ming)	Thumbnail	Print
1	04/06/19 17:44	Accident Statement	Load HTM	
2	17/06/19 12:02	Addendum Sheet	Load JPG ☒	
3	17/06/19 12:02	Accident Statement Addm. #1	Load HTM	

Photos/Images

3 per page ☐

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/06/19 18:28	General View	Load JPG ☒	
2	20/06/19 18:28	General View	Load JPG ☒	
3	20/06/19 18:28	General View	Load JPG ☒	
4	20/06/19 18:28	General View	Load JPG ☒	
5	20/06/19 18:28	General View	Load JPG ☒	
6	20/06/19 18:28	Odometer Reading	Load JPG ☒	
7	20/06/19 18:28	Chassis Number	Load JPG ☒	
8	20/06/19 18:28	General View	Load JPG ☒	
9	20/06/19 18:28	General View	Load JPG ☒	
10	20/06/19 18:28	General View	Load JPG ☒	
11	20/06/19 18:28	General View	Load JPG ☒	
12	20/06/19 18:28	General View	Load JPG ☒	
13	20/06/19 18:28	General View	Load JPG ☒	
14	20/06/19 18:28	General View	Load JPG ☒	
15	20/06/19 18:28	General View	Load JPG ☒	
16	20/06/19 18:28	General View	Load JPG ☒	
17	20/06/19 18:28	General View	Load JPG ☒	
18	20/06/19 18:28	General View	Load JPG ☒	
19	20/06/19 18:28	General View	Load JPG ☒	
20	20/06/19 18:28	General View	Load JPG ☒	
21	20/06/19 18:28	General View	Load JPG ☒	
22	20/06/19 18:28	General View	Load JPG ☒	
23	20/06/19 18:28	General View	Load JPG ☒	
24	20/06/19 18:28	General View	Load JPG ☒	
25	20/06/19 18:28	General View	Load JPG ☒	
26	20/06/19 18:28	General View	Load JPG ☒	
27	20/06/19 18:28	General View	Load JPG ☒	
28	17/07/19 09:44	Reinspection Photo	Load JPG ☒	
29	17/07/19 09:44	Reinspection Photo	Load JPG ☒	
30	17/07/19 09:44	Reinspection Photo	Load JPG ☒	

Assessment Reports			1 per page ▼	✓
No	Finalized On	BH Auto Services Pte Ltd (Sin Ming)	Thumbnail	Print
31	17/07/19 09:44	Reinspection Photo	1 Load JPG	✓
32	17/07/19 09:44	Reinspection Photo	1 Load JPG	✓
33	17/07/19 09:44	Reinspection Photo	1 Load JPG	✓
34	17/07/19 09:44	Reinspection Photo	1 Load JPG	✓
35	17/07/19 09:44	Reinspection Photo	1 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	18/06/19 17:30	INSD GY264R GIA REPORT	1 Load PDF	
2	18/06/19 17:30	PRS	1 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page ▼	✓
No	Finalized On	BH Auto Services Pte Ltd (Sin Ming)	Thumbnail	Print
1	04/06/19 17:44	Accident Statement	1 Load HTM	
2	17/06/19 12:02	Addendum Sheet	1 Load JPG	✓
3	17/06/19 12:02	Accident Statement Addm. #1	1 Load HTM	
4	20/06/19 10:03	Addendum Sheet	1 Load JPG	✓
5	20/06/19 10:03	Accident Statement Addm. #2	1 Load HTM	
Photos/Images			3 per page ▼	✓
No	Finalized On	BH Auto Services Pte Ltd (Sin Ming)	Thumbnail	Print
1	04/06/19 17:39	Identification Card OWNER NRIC & DRIVING LICENCE	1 Load JPG	✓
2	04/06/19 17:39	Accident Photo	1 Load JPG	✓
3	04/06/19 17:39	Accident Photo	1 Load JPG	✓
4	04/06/19 17:39	Accident Photo	1 Load JPG	✓
5	04/06/19 17:39	Accident Photo	1 Load JPG	✓
6	04/06/19 17:39	Accident Photo	1 Load JPG	✓
7	04/06/19 17:39	Accident Photo	1 Load JPG	✓
8	04/06/19 17:44	THIRD PARTY NRIC	1 Load JPG	✓
9	04/06/19 17:44	THIRD PARTY NRIC	1 Load JPG	✓
10	04/06/19 17:44	Accident Photo	1 Load JPG	✓
11	04/06/19 17:44	THIRD PARTY NAME CARD	1 Load JPG	✓
12	20/06/19 10:00	Accident Photo	1 Load JPG	✓
13	20/06/19 10:00	Police Report	1 Load JPG	✓
14	20/06/19 10:00	Police Report	1 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	BH Auto Services Pte Ltd (Sin Ming)	Thumbnail	Print
1	04/06/19 17:37	Individual Statement	1 Load JPG	✓
2	04/06/19 17:37	Individual Statement	1 Load JPG	✓
3	04/06/19 17:37	Accident Sketch Plan	1 Load JPG	✓
4	04/06/19 17:37	Accident Sketch Plan	1 Load JPG	✓
5	04/06/19 17:37	CERTIFICATE OF INSURANCE	1 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:  Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19010823/EVD3S2

Date: 19/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30743518000
Claimant Vehicle No :	SJK9859D	Insured Vehicle No :	GY264R
Date of Loss:	03/06/2019	Nature of Claim:	TP
		Claim No:	SNM19D202790C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK9859D		
Make & Model:	TOYOTA COROLLA AXIO, 1.5 X SPECIAL EDITION (A)	Engine No:	1NZD216586
Reg. Date:	12/11/2008 (Man. Year: 2008)	Chassis No:	NZE1416099515
Colour:	Beige	Odometer:	116113 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	KAPSEN 7 mm	Rear Left Side:	KAPSEN 7 mm
Front Right Side:	KAPSEN 7 mm	Rear Right Side:	KAPSEN 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,865.04	643.62	4,221.42	86.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,390.00	1,310.00	2,080.00	61.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,255.04	1,953.62	6,301.42	76.33
Approved Total (Overridden) (S\$)		1,550.00		
(S\$)	8,255.04	1,550.00	6,705.04	81.22
+ GST 7.00/7.00% (S\$)	577.85	108.50	469.35	81.22
Nett Amount (S\$)	8,832.89	1,658.50	7,174.39	81.22

INSPECTION

Date of Assignment:	18/06/2019	
Date Inspected:	20/06/2019 Inspected At:	BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117 Singapore 575636
Estimated Period of Repair:	5.0 days	

7/19/2019

Adjuster Report

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 19 Jul 2019)

Parts: 143 TOYOTA COROLLA AXIO 1.5 X SPECIAL EDITION (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJK9859D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	798.50 FL	*- FL
2	1		*BOOTLID HINGE LH	Not Necessary	62.80 FL	*- FL
3	1		*BOOTLID HINGE RH	Not Necessary	62.80 FL	*- FL
4	1		*BOOTLID WEATHERSTRIP	Not Necessary	176.20 FL	*- FL
5	1		*BOOTLID LOCK	Not Necessary	104.50 FL	*- FL
6	1		*BOOTLID LOCK STRIKER	Not Necessary	37.24 FL	*- FL
7	1		*BOOTLID EMBLEM	Necessary	61.70 FL	*61.70 FL
8	1		*BOOTLID LETTERING AXIO	Necessary	59.80 FL	*59.80 FL
9	1		*BOOTLID LETTERING X	Necessary	48.30 FL	*48.30 FL
10	1		*REAR TAIL LAMP ASSY LH	Not Necessary	391.40 FL	*- FL
11	1		*REAR TAIL LAMP ASSY RH	Not Necessary	391.40 FL	*- FL
12	1		*REAR BUMPER	Dented	786.80 FL	*464.20 FL
13	1		*REAR BUMPER SIDE RETAINER LH	Broken	229.60 FL	*97.50 FL
14	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	32.80 FL	*- FL
15	1		*REAR END PANEL	Repair	493.20 FL	*- FL
16	1		*REAR END PANEL TOP GARNISH	Not Necessary	180.90 FL	*- FL
17	1		*REAR FENDER LH	Repair	945.50 FL	*- FL
18	1		*REAR FENDER RH	Not Necessary	945.50 FL	*- FL
19	1		*REAR FENDER SHIELD LH	Not Necessary	60.70 FL	*- FL
20	1		*REAR FENDER SHIELD RH	Not Necessary	60.70 FL	*- FL
21	1		*SET REAR WINDSCREEN MOULDING	Not Necessary	109.70 FL	*- FL
22	12		*REAR BUMPER CLIP	Necessary	35.01 FS	*30.00 FS
23	1		*REAR NUMBER PLATE WITH CASING	Cut	100.00 FS	*35.00 FS
24	1		*REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
25	1		*REAR END PANEL SEAL	Necessary	80.00 FS	*30.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	6,375.05	826.50
- List Item Discount on L Items 25.00/25.00% (S\$)	1,510.01	182.88
Total Parts (S\$)	4,865.04	643.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ANTI-RUST COATING	New	80.00	30.00
2	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS,PANEL BEAT,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	1,500.00	500.00
3	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES	New	1,250.00	720.00
4	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	60.00	30.00
5	REMOVE AND REINSTALL CUSHIONS,SEATS,BACKREST,INNER TRIM,GARNISH,ROOF LINING AND OR UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	30.00
6	PROVIDE SKILL LABOUR TO REMOVE AND REFIT REAR WINDSCREEN	New	250.00	0.00
7	DISMANTLE AND TRANSFER BOOTLID FITTING AND MECHANISM TO NEW/FACILITATE REPAIR	New	100.00	0.00
Gross Labour Cost (\$\$)			3,390.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >