

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0761/2019/TG
Date : 18-Jun-19

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Lee Pui Lee
Address : 25 Miltonia Close
#06-12
Singapore 768060
Telephone : 96426011
Type of Claim : Own Damage Claim
Policy No. :
Vehicle No : **SGC 2223 L**
Model Code : Audi Q2 1.4 TFSI COD S TR
Model / Year : 14/11/2018
Engine No : CZE 835657
Chassis No : WAUZZZGA0JA119885
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-Jun-19
Place of Accident : Car Park Of International Plaza

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGC 2223 L

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,400.00	750
3	To remove and reinstall rear bumper.	\$ 600.00	500
5	To respray front bumper, and rhs front fender.	\$ 2,200.00	550
6	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,752.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGC 2223 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPR <i>Deformed</i>	\$ 1,705.00 ✓	1364
2	FRONT BUMPER FIXING PARTS <i>3 New</i>	\$ 314.00 ✗	
3	FRONT BUMPER GRILLE - CENTER	\$ 179.00 ✗	
4	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Deformed</i>	\$ 154.00 ✓	122.80
5	END CAP ? DM	\$ 31.00 ? ✓	24.40
6	SPOILER <i>Deformed</i>	\$ 273.00 ✓	218
7	CLOSING ELEMENT <i>New</i> DEF	\$ 142.00 ✗	113.20
8	WHEEL SPOILER - RH <i>New</i>	\$ 31.00 ✗	
9	ADAPTER - RH <i>New</i>	\$ 38.00 ✗	
10	RADIATOR GRILLE ? NN	\$ 1,301.00 ? ✗	
11	STRIKER PLATE <i>New</i>	\$ 114.00 ✗	
12	FOAM FILLER PIECE ? NN	\$ 71.00 ? ✗	
13	FRONT BUMPER CARRIER ? NN	\$ 625.00 ? ✗	
14	FRONT BUMPER TOP COVER <i>New</i> CRA	\$ 91.00 ✗	72.56
15	GUIDE SECTION - RH <i>New</i>	\$ 32.00 ✗	
16	FRONT FENDER - RH <i>New</i>	\$ 1,047.00 ✗	
17	FRONT FENDER ATTACHMENT PARTS <i>New</i>	\$ 36.00 ✗	
18	BRACKET - RH <i>New</i>	\$ 14.00 ✗	
19	BRACKET - RH <i>New</i>	\$ 43.00 ✗	
20	BRACKET - RH <i>New</i>	\$ 14.00 ✗	
SUB-TOTAL SPARE PARTS		\$ 6,255.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGC 2223 L

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
21	POP RIVET	6 \$	18.00 X
22	BRACE - RH	\$	29.00 X
23	INSULATION FOR WING	\$	69.00 X
24	WHEEL HOUSING LINER - UPPER	\$	33.00 X
25	BRACKET	\$	21.00 X
26	WHEEL HOUSING LINER - RH	\$	183.00 X
27	WHEEL HOUSING ATTACHMENT PARTS	\$	56.00 X
28	CAUTION STICKER	NEC \$	13.00 X ✓ 9.76
29	A/C STICKER	NEC \$	7.00 X ✓ 5.12
30	HEADLIGHT MOUNTING - RH	\$	107.00 X
31	LED HEADLIGHT - RH <i>lit</i>	\$	4,491.00 ✓ 3592.80
32	LIFT CYLINDER - RH ?	NN \$	128.00 ? X
33	AIR GUIDE FOR RADIATOR <i>He new</i>	\$	27.00 X
34	FRONT WHEEL COVER - LH <i>3 new</i>	\$	294.00 ✓ 234.80
35	FRONT WHEEL COVER - RH	\$	294.00 ✓ 234.80
36	REAR BUMPER SPOILER <i>Debond</i>	\$	259.00 ✓ 207.20
37	REAR WHEEL ARCH COVER - LH <i>3 new</i>	\$	156.00 ✓ 124.40
38	REAR WHEEL ARCH COVER - RH	\$	156.00 ✓ 124.40
39	FRONT NO. PLATE <i>He new</i>	S/N \$	40.00 X
40	SUNDRIES ?	NEC \$	300.00 ? ✓ 57
TOTAL SPARE PARTS		:	\$ 12,936.00
TOTAL LABOUR CHARGES		:	\$ 5,752.00
GRAND TOTAL		:	\$ 18,688.00
			20962.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: *Adrian King*
: *18/06/19.*
:
:
:
:
: *Not Authorised, 05 days.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0761/2019/TC

Date

11-Jul-19

Service Advisor

Glory Tan

Pages

1 OF 1

Regn No

SGC 2223 L

Model No

Audi Q2 1.4 TFSI COD S TR

Quantity Description

Unit Price Amount

Parts

1 Rear bumper *um*

\$ 1,074.00 *859.20*

\$ 1,074.00

LABORS

1 To respray rear bumper. *can*

\$ 1,200.00 *550*

TOTAL

\$ 2,274.00

For Premium Automobiles Pte Ltd

Rasul

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following: *12/02/19*

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: