mean	«Cunda cc4/11119010	1 1 1 1 E	LKK IDAC
INS. CASE OWNE	DOE ASSIGN	MENT	Date/Time: (ALB LA -
Pre-assign / CCI Insured Vehicle N Name of Insured Insured Tel No. Excess See II :St Is driver the own	SH 81736 	Claim No. Policy No. Make / Model Place of Accide	HYUNDAT BLO THE LITTE
If NO. Driver No. Driver Te	HNO.: ONA CHEND HIMP:	Of GIA REPOR Insured Liability	T: YES / NO : TP GIA REPORT: YES / NO (:
TRK 6	6>7		
INSRS: WSP: EXC Tel: Liability: RMKS	INSRS: WSP: Tel: Liability: RMKS:	INSRS; WSP: Tel: Liability: RMKS:	INSRS: WSP Tel: Liability: RMKS
Date/ Time	BELLEVILLE WILLIAM TO THE PARTY OF THE	1 2 1 18	STAGE DATE/PIC Non-Reporting br (180)
Z4 6 10 .	3 NEW CC. OID last co.		Nan-Reporting In (2nd): Non-Reporting In (Final): Notification In (if non-pickup): Culf OI:
-11			After call lir to Ol. Documentation Check List: Handler Typist
26819.	Fre -> type morelder		Normannn lir tif non-pickup) After sall lie to OI.
9/1/20m -	Fie of surtime ov		Authorisation To Act Release Voucher:
			Car Rental Invoice Towing Invoice LTA / GIA:
			Medical Bill. PIR. Market //Reject Instruction:
			LOD Payment Breakdown Form:
PRELIMINARY ADVIC	E. Date/Time: Scut By:		Post-Repair Photos:
FINALIZATION	Date/Time: Confirm with:		Others: Confirm by:
Repair Cost	SS days) Reduction:	5	Email Call
FINAL SETTLEMENT Final Liability Repair Cost 5850 @60	Date/Time: 0 2000 Confirm with Ce 16 Agreed / Assessed) BOLA S/N No. :	MIC.	Email Cat If NO & B 28. Ass. Lia
Loss of Rental (LOR): Loss of Use (LOU) Loss of Income (LOI):	\$\$ 120.00 (\$ 50 x\$\frac{days}{days})\$\$ \$\$\$ (\$ x \ days)\$\$		CIPY SENT
LOU on	ly LOR + LOU LOR + LO Tick only	one]	C TITIES III
GIA/LTA Search Medical:	ss ~		1) Claim status: Spal/Reject/Private Settle
Disbursement:	SS (e.g. Tow/ Indepen		2) Report Format: 1 6ω.ω
Legal Cost Total:	88 3337 - 45 Global Sum 88: 33W-U		3) Survey fee 5 600.00
FINAL PAYMENT	Date/Time: Confirm with:		Email Cal
Payor I		e Enterprise P	
Payce 2. (Strike if N.A.)	SS Name 2:	1	
Payce 3: (Strike if N.A.)	SS Name 3:		

Exclusive Enterprise Pte Ltd

8 Kaki Bukit Ave 4, #03-50, Premier @ KB, Singapore 415875

Tel: 62459655 / 9735 6016 (Tony) Fax: 6245 9678

Email: exclusiveenterprise50@gmail.com PAIIINV4018413384

TP INS: III

Veh No. : JRK 6627

Xino Tony

Veh Model: Toyota Innova 2.0E

No.	List items	QTY	Amount
	Bonnet Paris	1	\$739.10 -
	Bonet Lock 2	1	\$93.10
3	Bonnet Outer Chrome Moulding	1	\$267.30
4	Bonnet Rubber Seal	1	\$39.10
5	Bonnet Hinge L/R	2	\$114.20
6	Frt Bumper & C	1	\$573.10 -
	Frt Bumper Side Retainer L/R	2	\$146.20
	Frt Bumper Fog Lamp Garnish L/R Hem-	2	\$178.40
9	Frt Bumper Lower Grille De La	1	\$188.30
10	Frt Bumper Reinforcement	1	\$437.10
	Frt Bumper Bracket	1	\$113.40
12	Frt Grille could	1	\$362.10
13	Frt Grille Logo N=	1	\$48.80
14	Headlamp L/R Cauled	2	\$986.20
15	Support Panel Ry	1	\$519.30
	Brace Panel Bend	1	\$221.90
	Radiator Fue Nu	1	\$939.10 +
18	A/C Condenser	1	\$1,163.90 *.
19	Tailgate Deuted	1	\$1,391.60 /043
	Tailgate Lock Dogle	1	\$476-10 285
	Tailgate W/strip wt	1	\$197.60
22	Tailgate Outer Garnish Net 1964	1	\$119.30 \(\tau \)
23	Tailgate Logo 7	1	\$69.30
24	Emblem " 2.0 "	1	\$53.10
25	Emblem " E "	1	\$48.30
26	Tailgate Glass Moulding L/R	1	\$79.20
		1	\$587.10 -
	Tailgate Inner Trimboard 2	1	\$78.80 +.
	Rear Bumper De-L	1	\$561.90
30	Rear Bumper Side Retainer L/R	2	\$178.60 98
31	Rear Bumper Side Holder L/R	2	\$187.20 +
	Rear Bumper Side Holder L/R Rear Bumper Side Reflector L/R LH Zaul	d 2	\$183.60
			91-80

33 Taillamp L/R Act To 34 End Panel Peyer 35 End Panel Top Garnish 9ch	_d	2 1 1	\$579.20 + \$811.60 7 \$363.70
36 Rear Compartment Board 154	-	1	\$893.60 %
	5272.10	Sub-Total: \$13,990.4 Less 25%: \$3497.60 Total: \$10,492.80	
5/N			
Frt Bumper Clips 2		1Set	\$50-30
Frt Grille Clips		1Set	\$50-20
Coolant we m		1	\$80 <
Frt Number Plate	410	1	\$50
Rear Bumper Clips , www		1Set	\$50.30
Rear W/S Sealant //		1	\$80-60
Tailgate Inner Trim Clips		1	\$50 20
Rear Number Clips , Let ~		1Set	\$50 1
Reverse Sensor		1	\$300 200
		S/N Total : \$760	
Labour			
R&R Front Aircon Condenser & F	Radiator		\$180 -
Top up aircon gas			\$150 -
Wire-Checking (Front)			\$50.30
Labour (Front)			\$1,000 400
Painting (Front)			\$900-400
R&R Rear Windscreen			\$150-120
R&R Reverse Sensor		2370	\$60-50
Wire-Checking (Rear)			\$50 30
R&R Rear Compartment & Trims			\$150 60
Transfer Rear Gate Component	from old to new		\$100 80
Labour (Rear)			\$1,000 600
Painting (Rear)			5900 - 600

Labour Total: \$3790

LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation * Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed . Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company Acknowledged by Repairer

Signature:

Date:

4/s: 5350

Nivitha (LKK Auto)

From:

Motor Claim - III <motorclaim@iii.com.sg>

Sent:

Wednesday, 19 June 2019 9:13 AM

To:

exclusiveenterprise50@gmail.com; 'sur@lkkauto.com'; admin-d@lkkauto.com

Cc:

Sundari Nagarajan - III

Subject:

RE: ACCIDENT INVOLVING JRK 6627 / SH 8873 C

Attachments:

JRK 6627 - MCD.PDF

10:130m@19/6/2019 vehicle In sur@ Nenny

Dear Sir / Mdm.

Please conduct a survey on TP vehicle JRK6627 and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards, Gabriel Wee



64 Cecil Street; #05 - IOB Building Singapore 049711 Tel: 6347 6100, Ext - 248

From: exclusiveenterprise50@gmail.com [mailto:exclusiveenterprise50@gmail.com]

Sent: 18 June, 2019 5:32 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: RE: ACCIDENT INVOLVING JRK 6627 / SH 8873 C

Hi Gabriel,

Please assign LKK Auto Consultants Pte Ltd as the surveyor.

Thank You.

Best regards,

Nenny

Exclusive Enterprise Pte Ltd 8 Kaki Bukit Avenue 4 #03-50 PREMIER@KAKI BUKIT Singapore 415875

Tel: 6245 9655 Fax: 6245 9678

From: Motor Claim - III < motorclaim@iii.com.sg>

Sent: Tuesday, June 18, 2019 5:29 PM To: exclusiveenterprise50@gmail.com

Subject: RE: ACCIDENT INVOLVING JRK 6627 / SH 8873 C

Dear Sir / Mdm,

We acknowledge receipt of your email.

We proprose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards, Gabriel Wee



Singapore 049711 Tel: 6347 6100, Ext – 248

From: exclusiveenterprise50@gmail.com [mailto:exclusiveenterprise50@gmail.com]

Sent: 18 June, 2019 4:07 PM

To: Motor Claim - III < motorclaim@iii.com.sg>

Subject: RE: ACCIDENT INVOLVING JRK 6627 / SH 8873 C

Dear Sir / Mdm,

Please refer to the attached docs. Your prompt reply are highly appreciated. Thank You.

Best regards,

Nenny Exclusive Enterprise Pte Ltd 8 Kaki Bukit Avenue 4 #03-50 PREMIER@KAKI BUKIT Singapore 415875

Tel: 6245 9655 Fax: 6245 9678

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment. India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment. India International Insurance Pte Ltd.

Registration No. 198703792-K

Claim Audit

1	AUDIT TRAIL			
G.	On	Audit	Remarks	Ву
	0010 0000			[A]
1	19 Jun 2019	Clm Dtl Modified	Claimant's Name: ->	Shu
	17:01			Pei
				[A]
	19 Jun 2019			Lau
2	17:01	Clm Veh Model Changed	(206086) ADIVA AD1 200 190cc 3W.	Shu
	47,04			Pei
				[A]
3	19 Jun 2019	22. 23. N. V	Reg No: JRV6627. Acct Date: 2019/06/17. Claim Type: TP. Insurer: India International I	Lau
3	17:01	Clm Created	nsurance Pte Ltd (HQ). Workshop: Exclusive Enterprise Pte Ltd (HQ)	Shu
			CONTROL PACKAGE FINA WE TO THE CONTROL OF THE CONTR	Pei
				[A]
4	19 Jun 2019	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	Lau
4	17:01	Auj co Assigned	EAR PAIN ENGINEERING FAR LINE (1907)	Shu
				Pei
				[A]
5	19 Jun 2019	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/28	Lau
~	17:01		11203.14.01.0103.14.010.02.03.03.03	Shu
				Pel
				[A]
6	19 Jun 2019	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	Shu
	17:01	Device Control of the	SCATEGORY PROGRAMME INSTRUMENT LINES SERVICE AND SCHOOL SERVICE SERVIC	Pei
				[A]
	19 Jun 2019			Lau
7	17:02	Label Added	(30653):Direct Settlement.	Shu
	47.194			Pei
				TAT
44.	19 Jun 2019			Lau
В	17:02	Adj Adjuster Assigned	[None] -> ADRIAN LING	Shu
				Pei
				[A]
9	20 Jun 2019	Cim Dti Modified	Claimant's Name:> TAN SHU CHENG. Claimant's 1D: ->	Lau
3	15:18	Cim Du Flourieu	Claimant's Name> TAIN SHO CHENG, Claimant's 10, -> -	Shu
				Pei
	100 200			[A]
10	20 Jun 2019	Clm Veh Model Changed	(206086) -> (205077) TOYOTA INNOVA 2.0 E AT (A).	Lau
	15:18			Shu
				Pei
	THE STATE OF THE S			[A]
11	24 Jun 2019 09:59	Clm Registration	Reg No:JRV6627->JRK6627.	HSIA
	03:23	Modified	Si contraction de la contracti	TON
				[A]
	24 Jun 2010		Cur Pegi 0.00-BODS Liability: TBA Remarks: 3 vehicles chain collision. BOLA not applicable	A
12	24 Jun 2019 10:02	Adj Mandate Request	Cur.Req:0.00:PODS Liability:TBA Remarks: 3 vehicles chain collision. BOLA not applicable as 2nd car was a Malaysian vehicle. Kindly upload IV video in Merimen for our viewing.	A CONTRACTOR OF THE PARTY OF TH
	40.04		e as and can was a maleysian venicle. Kindly apload 14 video in mention for our viewing.	TONG

Date From		■ ▶ Date To		4 - 1	Audit Type None		▼ Go
CTIVITY							
record							
terimen Billin	g for this case -	Transaction H	istory				
Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2183805	20/06/2019 08:47	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	JRV6627	SH8873C	11.77

Claim Audit

io.	AUDIT TRAIL	Audit	Remarks	By
1	19 Jun 2019 17:01	Clm Dtl Modified	Claimant's Name: ->	[A] Lau Shu Pei
2	19 Jun 2019 17:01	Clm Veh Model Changed	(206086) ADIVA AD1 200 190cc 3W.	[A] Lau Shu Pei
3	19 Jun 2019 17:01	Clm Created	Reg No: JRV6627, Acct Date: 2019/06/17, Claim Type: TP. Insurer: India Internationa i Insurance Pte Ltd (HQ), Workshop: Exclusive Enterprise Pte Ltd (HQ)	[A] Lau Shu Pei
4	19 Jun 2019 17:01	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	(A) Lau Shu Pei
5	19 Jun 2019 17:01	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date: 2019/06/28	[A] Lau Shu Pei
6	19 Jun 2019 17:01	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	(A) Lau Shu Pei
7	19 Jun 2019 17:02	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
8	19 Jun 2019 17:02	Adj Adjuster Assigned	[None] -> ADRIAN LING	(A) Lau Shu Pei
9	20 Jun 2019 15:18	Clm Dtl Modified	Claimant's Name:> TAN SHU CHENG. Claimant's ID: ->	[A] Lau Shu Pel
0	20 Jun 2019 15:18	Clm Veh Model Changed	(206086) -> (205077) TOYOTA INNOVA 2.0 E AT (A).	(A) Lau Shu Pei
11	24 Jun 2019 09:59	Clm Registration Modified	Reg No:JRV6627->JRK6627.	(A) CHEW HSIAO TONG
12	24 Jun 2019 10:02	Adj Mandate Request	Cur,Req:0.00:PODS Liability:TBA Remarks: 3 vehicles chain collision. BOLA not applic able as 2nd car was a Malaysian vehicle. Kindly upload IV video in Merimen for our vie wing.	TONG
13	24 Jun 2019 10:14	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/28. Mandate Remarks: uploaded	[I] Sundari Nagaraja
14	24 Jun 2019 10:14	Adj Mandate Set	Approved:0.00:uploaded	[I] Sundari Nagarajai

Date From

AL	IIVII	Ŧ
		_
- 1		

No record

Bill Ref No	Bill Date	Acc Type	Acc Name	(Branch)	Ref 1	Ref 2	Amount
2183805	20/06/2019 08:47	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	JRV6627	SH8873C	11.77
2186825	24/06/2019 10:11	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	JRK6627	Sundari Nagarajan	301,308
2186848	24/06/2019 10:20	Motor	India International Insurance Pte Ltd (HO)	India International Insurance Pte Ltd (HQ)	JRK6627	Sundari Nagarajan	XX.XX

Hsiao Tong (LKKAuto)

From:

exclusiveenterprise50@gmail.com

Sent:

Friday, 19 July 2019 1:09 PM

To:

Hsiao Tong (LKKAuto)

Subject:

JRK 6627 - LOD

Attachments:

LOD FULL SET.pdf

Hi XiaoTong,

Please see attached for LOD.

Thanks.

Best regards,

Xiang
Exclusive Enterprise Pte Ltd
8 Kaki Bukit Avenue 4 #03-50
PREMIER@KAKI BUKIT
Singapore 415875

Tel: 6245 9655 Fax: 6245 9678

Claim Audit

III.	UDIT TRAIL	Audit	Remarks	By
, :	19 Jun 2019	Clm Dtl Modified	Claimant's Name: ->	[A] Lau Shi Pei
	17:01 19 Jun 2019	CHIMTHIESE CONTROL OF	(206086) ADIVA AD1 200 190cc 3W.	[A] Lau Sh
3	17:01 19 Jun 2019		Reg No: JRV6627. Acct Date: 2019/06/17. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). Workshop: Exclusive Enterprise Pte Ltd (HQ)	(A) Lau Sh
	17:01 19 Jun 2019	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Sh
	17:01 19 Jun 2019	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/28	[A] Lau Sh
	17:01 19 Jun 2019		0.00	(A) Lau Sh
9	17:01 19 Jun 2019	Adj Mandate Set	Approved:0.00.Reinsp:Ad) decides.	Pei [A] Lau Sh
	17:02	Label Added	(30653): Direct Settlement.	Pei [A] Lau Sh
5	19 Jun 2019 17:02	Adj Adjuster Assigned	[None] -> ADRIAN LING	Pei (A) Lau Sh
	20 Jun 2019 15:18	Cim Dtl Modified	Claimant's Name:> TAN SHU CHENG, Claimant's ID: ->	Pei
	20 Jun 2019 15:18	Clm Veh Model Changed	(206086) -> (205077) TOYOTA INNOVA 2.0 E AT (A).	[A] Lau Sh Pei
	24 Jun 2019 09:59	Clm Registration Modified	Reg No:3RV6627->3RK6627-	[A] CHEW HSIAO TON
	24 Jun 2019 10:02	Adj Mandate Request	Cur.Req: 0.00: PODS Liability: TBA Remarks: 3 vehicles chain collision. BOLA not ap plicable as 2nd car was a Malaysian vehicle. Kindly upload IV video in Merimen for our viewing.	[A] CHEW HSIAO TON
	24 Jun 2019 10:14	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/28. Mandate Remarks: uploaded	[1] Sunda: Nagarajar
4	24 Jun 2019 10:14	Adj Mandate Set	Approved:0.00:uploaded	[I] Sunda: Nagarajar
15	11 Jul 2019 08:35	Video Downloaded	Downloaded Video - Accident-IV	(A) CHEW
6	11 Jul 2019 08:36	Video Downloaded	Downloaded Video - Accident-SHD7263X-1stvehicle; SH8873C(III)>JRK6627>SHD 7263X(alsoIII)	[A] CHEW HSIAO TON
7	17 Jul 2019 09:38	Video Downloaded	Downloaded Video - Accident-IV	[A] ADRIA
	17 Jul 2019 09:39	Video Downloaded	Downloaded Video - Accident-SHD7263X-1stvehicle; SH8873C(III)>JRK6627>SHD 7263X(alsoIII)	[A] ADRIA LING
	17 Jul 2019 09:40	Video Downloaded	Dawnloaded Video - Accident-IV	[A] ADRIA LING
	17 Jul 2019 09:40	Video Downloaded	Downloaded Video - Accident-SHD7263X-1stvehicle; SH8873C(III)>JRK6627>SHD 7263X(alsoIII)	[A] ADRIA LING
	17 Jul 2019 09:42	Video Downloaded	Downloaded Video - Accident-IV	[A] ADRIA
12	20 Aug 2019 13:35	Video Downloaded	Downloaded Video - Accident-SHD7263X-1stvehicle; SHB873C(III)>JRK6627>SHD 7263X(alsoIII)	[1] Mekavathar Sarangapa
	20 Aug 2019 13:36	Video Downloaded	Downloaded Video - Accident-IV	[I] Mekavathar Sarangapa [I]
14	20 Aug 2019 13:36	Video Downloaded	Downloaded Video - Accident-IV	Mekavathar Sarangapa
	20 Aug 2019 16:16	Video Downloaded	Downloaded Video - Accident-TV	[1] Sunda Nagarajar
16	20 Aug 2019 16:17	Video Downloaded	Downloaded Video - Accident-SHD7263X-1stvehicle; SH8873C(III)>JRK6627>SHD 7263X(alsoIII)	[1] Sunda Nagaraja
	04 Sep 2019 11:40	Adj Rpt Initiated		[A] JOANN LEE KHAN MIN
	04 Sep 2019 11:40	Clm Dtl Modified	Insured Name: -> -, Insured ID: ->	[A] JOANN LEE KHAN MIN
9	04 Sep 2019 11:40	Clm Dtl Modified	JPJ Reg. Date: -> 2016/03/10.	[A] JOANN LEE KHAN MIN
	04 Sep 2019 11:40	Clm Details Notified		[A] JOANN LEE KHAN MIN
	04 Sep 2019 17:56	Video Downloaded	Downloaded Video - Accident-IV	[1] Sunda Nagaraja
13	04 Sep 2019 17:57	Video Downloaded	Downloaded Video - Accident-SHD7263X-1stvehicle; SH8873C(III)>JRK6627>SHD 7263X(alsoIII)	[1] Sunda Nagaraja
12	17:57 04 Sep 2019 18:03	Video Downloaded	Downloaded Video - Accident-SHD7263X-1stvehicle; SH8873C(III)>JRK6627>SHD 7263X(alsoIII)	[I] Sunda Nagaraja
	04 Sep 2019 18:03	Video Downloaded	Downloaded Video - Accident-IV	[1] Sunda Nagaraja

▼ Go

E AUDIT TRAIL By Remarks Min. [I] Sundari 35 04 Sep 2019 Video Downloaded Downloaded Video - Accident-IV Nagarajan Cur.Req:4447.45:PODS Liability: 80% *Quantum: [(a)CORw/GST: \$5,350.00 + (b)LOU(4days x \$50.00): \$200.00]@80% = 4,440.00 + (c)LTA/GIA search fee: [A] CHEW \$7.45 = Total: \$4,447.45 *Vehicle Model: Toyota Innova (1998cc) *B recommenda HSIAO TONG 36 28 Sep 2019 Adj Mandate Request tion repair days *For

Date	From	400	Date To	4	Audit T	ype None	•	Go
ACTIVITY								
No record								
Merimen Bill	ing for this case	e - Transactio	n History					
			January	Acc Notes			1947.2:	Litymount
	20.1 - 2010	TR Core		LKK Auto	India	2010000	20002222	22.22

			Jan Type	Acc Name				
2183805	20 Jun 2019 08:47:13	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	JRV6627	SH8873C	11.77
2186825	24 Jun 2019 10:11:14	Video Upload	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	3RK6627	Sundari Nagarajan	хх,хх
2186848	24 Jun 2019 10:20:23	Video Upload	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	JRK6627	Sundari Nagarajan	xx.xx
2268966	04 Sep 2019 11:40:15	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	3RK6627	5H8873C	11.77

Print Received Message

This mail is associated with:

*JRK6627 (MCT19060455) [SH8873C] TP TAN SHU CHENG Jun 17 2019 12:00AM

Exclusive Enterprise Pte Ltd

From

India International Insurance Pte Ltd (HQ) (III_SG), sent on 30/09/2019 09:35 AM.

To

LKK_HQ

Subject

Alert - Adj Mandate Approved (S\$2782.45) - JRK6627 - Claim Handler: Sundari Nagarajan

Approved:2782.45:50% liability. As per ID video TP cut into ID's lane

Claim Audit

	UDIT	nieri-rita	Vernarks	By
	Ott.	Audit	Remarks	700
	19 Jun 2019 17:01	Clm Dtl Modified	Claimant's Name: ->	[A] Lau Shi Pei
2	19 Jun 2019 17:01	Cim Veh Model Changed	(206086) ADIVA AD1 200 190cc 3W.	[A] Lau Sh Pei
	19 Jun 2019 17:01	Clm Created	Reg No: JRV6627. Acct Date: 2019/06/17. Claim Type: TP. Insurer: India International Insurance Pte Lt d (HQ). Workshop: Exclusive Enterprise Pte Ltd (HQ)	[A] Lau Sh Pei
1	19 Jun 2019 17:01	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Sh Pei
5		Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/28	[A] Lau Sh Pei
5	19 Jun 2019 17:01	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Sh Pei
7.	19 Jun 2019 17:02	Label Added	(30653):Direct Settlement.	[A] Lau Sh Pei
3	19 Jun 2019 17:02	Adjuster Assigned	[None] -> ADRIAN LING	(A) Lau Sh Pei
9	20 Jun 2019 15:18	Clm Dtl Modified	Claimant's Name:> TAN SHU CHENG. Claimant's ID: ->	[A] Lau Sh Pei
0	20 Jun 2019 15:18	Clm Veh Model Changed	(206086) -> (205077) TOYOTA INNOVA 2.0 E AT (A).	[A] Lau Sh Pei
1	24 Jun 2019 09:59	Clm	Reg No:JRV6627->JRK6627.	[A] CHEW HSIAO TON
2	24 Jun 2019 10:02	Adj Mandate Request	Cur.Req:0.00:PODS Liability:TBA Remarks: 3 vehicles chain collision. BOLA not applicable as 2nd car w as a Malaysian vehicle. Kindly upload IV video in Merimen for our viewing.	[A] CHEW HSIAO TON
3	24 Jun 2019 10:14	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/28. Mandate Remarks: uploaded	[I] Sundar Nagarajar
4	24 Jun 2019 10:14	Adj Mandate Set	Approved:0.00:uploaded	[I] SundarNagarajar
5	11 Jul 2019 08:35	Video Downloaded	Downloaded Video - Accident-IV	[A] CHEW HSIAO TON
6	11 Jul 2019 08:36	Video Downloaded	Downloaded Video - Accident-SHD7263X-1stvehicle; SH8873C(III)>JRK6627>SHD7263X(alsoIII)	[A] CHEW HSIAO TON
7	17 Jul 2019 09:38	Video Downloaded	Downloaded Video - Accident-IV	[A] ADRIA LING
8	17 Jul 2019 09:39	Video Downloaded	Downloaded Video - Accident-SHD7263X-1stvehicle; SH8873C(III)>JRK6627>SHD7263X(alsoIII)	[A] ADRIA LING
g	17 Jul 2019 09:40	Video Downloaded	Downloaded Video - Accident-IV	[A] ADRIA LING
0	17 Jul 2019 09:40	Video Downloaded	Downloaded Video - Accident-SHD7263X-1stvehicle; SH8873C(III)>JRK6627>SHD7263X(alsoIII)	[A] ADRIA LING
1	17 Jul 2019 09:42		Downloaded Video - Accident-IV	[A] ADRIA LING [1]
2	20 Aug 2019 13:35	Downloaded	Downloaded Video - Accident-SHD7263X-1stvehicle; SH8873C(III)>JRK6627>SHD7263X(alsoIII)	Mekavathar Sarangapa [I]
3	20 Aug 2019 13:36	Downloaded	Downloaded Video - Accident-IV	Mekavathar Sarangapa [1]
4	13:36		Downloaded Video - Accident-IV	Mekavathar Sarangapa
5	20 Aug 2019 16:16	Downloaded	Downloaded Video - Accident-IV	[1] Sunda Nagarajar
	20 Aug 2019	Video Downloaded	Downloaded Video - Accident-SHD7263X-1stvehicle; SH8873C(III)>JRK6627>SHD7263X(alsoIII)	[1] Sunda Nagaraja

2019	9		Menmen e-Claims	
AU	DIT	RAIL		By
27 21	4 Sep 019	Adj Rpt Initiated	Remarks	[A] JOANNE LEE KHANG MIN
28 2	1:40 4 Sep 019 1:40	Clm Dti Modified	Insured Name: -> Insured ID: ->	[A] JOANNE LEE KHANG MIN [A] JOANNE
29 2	4 Sep 019 1:40	Clm Dti Modified	JPJ Reg. Date: -> 2016/03/10.	LEE KHANG MIN
30 2 1	1:40	Clm Details Notified		LEE KHANG MIN
31 2	7:56		Downloaded Video - Accident-IV	[I] Sundari Nagarajan
32 2 1	7:57	Downloaded	Downloaded Video - Accident-SHD7263X-1stvehicle; SH8873C(III)>JRK6627>SHD7263X(alsoIII)	[1] Sundari Nagarajan
33 2	8:03	Downloaded	Downloaded Video - Accident-SHD7263X-1stvehicle; SH8873C(III)>JRK6627>SHD7263X(alsoIII)	[I] Sundari Nagarajan
34 2 1	8:03	Downloaded	Downloaded Video - Accident-IV	[1] Sundar Nagarajan
35 2 1	8:03	Downloaded	Downloaded Video - Accident-IV	[1] Sundar Nagarajan
36 2 1	28 Sep 2019 14:04	Mandate Request	Cut.Req:4447.45:PODS Liability: 80% "Quantum: $[(a)CORw/GST: $5,350.00 + (b)LOU(4days \times $50.00): $200.00] \oplus 80\% = 4,440.00 + (c)LTA/GIA search fee: $7.45 = Total: $4,447.45 *Vehicle Model: Toy ota Innova (1998cc) *B recommendation repair days *For$	
37 2 0	30 Sep 2019 39:31	Downloaded	Downloaded Video - Accident-IV	[I] Sundar Nagarajar
38 4	30 Sep 2019 09:32	Video Downloaded	Downloaded Video - Accident-IV	[1] Sundar Nagarajar
39 2	2019 09:35	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/06/28. Mandate Remarks: 50% liability. As per ID video TP cut i nto ID's lane	[1] Sundar Nagarajar
40 2	30 Sep 2019 09:35	Mandate Set	Approved: 2782.45:50% liability. As per ID video TP cut into ID's lane	[I] Sundar Nagarajar
** 1	16:02		Downloaded Video - Accident-IV	Mekavathan Sarangapa [1]
74	16:03		Downloaded Video - Accident-SHD7263X-1stvehicle; SH8873C(III)>JRK6627>SHD7263X(alsoIII)	Mekavathan Sarangapa [1]
*3 /	16:04		Downloaded Video - Accident-SHD7263X-1stvehicle; SH8873C(III)>JRK6627>SHD7263X(alsoIII)	Mekavathan Sarangapa [1]
**	16:04	CONTRACTOR	Downloaded Video - Accident-SHD7263X-1stvehicle; SH8873C(III)>3RK6627>SHD7263X(alsoIII)	Mekayathar Sarangapa [I]
43	16:04		Downloaded Video - Accident-IV	Mekavathar Sarangapa
46 2	06 Dec 2019 17:27	Downloaded	Downloaded Video - Accident-IV	[1] Sunda Nagarajar
7/	17:33		Downloaded Video - Accident-IV	[I] Sunda Nagarajar
48 2	28 Dec 2019 13:42	Mandate Request	Cur,Req:4447,45:3rd party rejected our offer at 50% as it is a chain collision. Kindly review and let us have your further mandate. Thanks.	(A) CHEW

A	c	T	I	٧	Ι	T	Y	

No record

Ni Recha		dell Type	Acc Type	Acc Name	Contracts (Ref L	Ref 2	Amoun
2183805	20 Jun 2019 08:47:13	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	3RV6627	SH8873C	11.77
2186825	24 Jun 2019 10:11:14	Video Upload	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	3RK6627	Sundari Nagarajan	XX.XX
2186848	24 Jun 2019	Video Upload	Motor	India	India	JRK6627	Sundari	XX,XX

Merimen e-Claims

20/20/19	10:20:23			International Insurance Pte Ltd (HQ)	International Insurance Pte Ltd (HQ)		Nagarajan		
2268966	04 Sep 2019 11:40:15	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	JRK6627	SH8873C	11.77	

Print Received Message

This mail is associated with:

*JRK6627 (MCT19060455) [SH8873C] TP TAN SHU CHENG Jun 17 2019 12:00AM

Exclusive Enterprise Pte Ltd

From

India International Insurance Pte Ltd (HQ) (III_SG), sent on 30/12/2019 10:01 AM.

To

LKK_HQ

Subject

Alert - Adj Mandate Approved (S\$3337.45) - JRK6627 - Claim Handler: Sundari Nagarajan

Approved:3337.45:TP cut into ID's lane. Video is clear cut. Just for settlement purpose we may revise liability to 60%

Hsiao Tong (LKKAuto)

From: Sent:	Exclusive Enterprise <exclusiveenterprise50@gmail.com> Monday, 6 January 2020 5:06 PM</exclusiveenterprise50@gmail.com>
To:	Hsiao Tong (LKKAuto)
Subject:	Re: RE: JRK 6627 - LOD //LKK Ref: CC4/III19010871/Apb3
Hi Hsiao Tong ,	
Amount agreed .	
Thanks.	
"May good luck and goo	od fortune always be with you & Happy New Year 2020"
Best Regards,	
ICE	
Exclusive Enterprise 8 Kaki Bukit Avenue 4 #03- PREMIER@KAKI BUKIT Singapore 415875 Tel: 6245 9655 Fax: 6245 9	50
On Fri, 3 Jan 2020 at 17:54, Hs	iao Tong (LKKAuto) < <u>chewht@lkkauto.com</u> > wrote:
Without Prejudice	
(save as to costs)	
Dear Sirs/Mdm,	
bear susy mann,	
Attached is a copy of our insu	ured video for your reference.
Your client had cut into our ir improve offer at a global sum	nsured's lane. For an amicable settlement, we have our principal instruction to of \$3,300.00(all-in).
Please confirm acceptance.	

Note: This video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.
"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.
In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issue of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."
"Wishing you a Happiness and Prosperity New Year"
Best Regards,
Hsiao Tong, Chew (Ms) Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 email: <u>chewht@lkkauto.com</u> fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 S(408933)
From: Exclusive Enterprise <exclusiveenterprise50@gmail.com> Sent: Wednesday, 18 December 2019 2:49 PM To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com> Subject: Re: RE: JRK 6627 - LOD //LKK Ref: CC4/III19010871/Apb3</chewht@lkkauto.com></exclusiveenterprise50@gmail.com>
Hi Hsiao Tong,
Refer to previous email on 15/11/2019. Any update news?

How's the case going on?

Kindly expedite the process to re-advise the liability.
Thank you.
"Best Wishes for Merry Christmas & Happy New Year 2020"
Best Regards,
ICE
Exclusive Enterprise Pte Ltd
8 Kaki Bukit Avenue 4 #03-50
PREMIER@KAKI BUKIT
Singapore 415875
Tel: 6245 9655 Fax: 6245 9678
On Fri, 15 Nov 2019 at 16:58, Exclusive Enterprise < exclusive enterprise 50@gmail.com > wrote:
Hi Hsiao Tong ,
Base on your insured report . it stated there that our client vehicle change lane which did not happen .
And for vehicle damage it can clearly see that our client vehicle had been hit in the center portion of our rear which causes our client to hit the front vehicle .
If you are going to give me 50% liability for this head to rear accident which i think clearly it is unfair .
Please provide evidence showing that our client vehicle is changing lane .

I will not accept that just because your insured wrote in their report that our client change lane to cause the accident will be justify base on your insured report .
So in future if there is any head to rear accident if anyone put in his report front vehicle change lane can be fight to 50% ?
that will not be fair . if your insured said we change lane or have any supporting evidence . Please provide .
Kindly re-advise liability .
Thanks.
Best Regards,
Xiang
Exclusive Enterprise Pte Ltd
8 Kaki Bukit Avenue 4 #03-50
PREMIER@KAKI BUKIT
Singapore 415875
Tel: 6245 9655 Fax: 6245 9678
On Fri, 15 Nov 2019 at 15:14, Hsiao Tong (LKKAuto) < chewht@lkkauto.com > wrote:
Without Prejudice
Dear Sirs/mdm,
Apologised for late response.

Our offer is on 50% basis as our driver reported that your client had switched into his lane, jammed brake and caused our insured driver collided onto your client vehicle's rear portion. Furthermore, your client had hit the front vehicle. Attached is a copy of our driver police report for your necessary action.

Brief Details.

On the 17/6/2019 at about 7.55pm, I was driving on the 3rd lane of the 5 lane road along air boulevard. As such there was a Malaysian vehicle bearing plate number JRK6627 driving all lane and had switched in to my lane. About 1-2 seconds later, the Malaysian vehicle jammed as such I braked and collided on to its rear. I got down and checked that the Malaysian vehicle collided on to the another taxi vehicle bearing plate number SHD7263X which was in front of and ambulance at scene. No injuries at scene. My vehicle has a small dent at the front bump Malaysian vehicle has a small dent at the rear bumper. The taxi vehicle has some dents at the bumper.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108


Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Exclusive Enterprise <exclusiveenterprise50@gmail.com>

Sent: Tuesday, 12 November 2019 5:25 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Re: RE: JRK 6627 - LOD //LKK Ref: CC4/III19010871/Apb3



Best Regards,
ICE
EXCLUSIVE ENTERPRISE PTE LTD
8 Kaki Bukit Avenue 4 #05-50
PREMIER@KAKI BUKIT
Singapore 415875
Tel: 6245 9655 Fax: 6245 9678
From: MotorClaims Sent: Wednesday, October 9, 2019 9:51 AM To: Hsiao Tong (LKKAuto) Subject: RE: JRK 6627 - LOD //LKK Ref: CC4/III19010871/Apb3
Hi Hsiao Tong ,
Please advice why the offered amount is so low .
Thanks.
Best Regards,
XIANG

EXCLUSIVE ENTERPRISE PTE LTD

8 Kaki Bukit Avenue 4 #03-50

PREMIER@KAKI BUKIT

Singapore 415875
Tel: 6245 9655 Fax: 6245 9678
From: Hsiao Tong (LKKAuto) Sent: Tuesday, October 1, 2019 12:52 PM
To: MotorClaims Subject: RE: JRK 6627 - LOD //LKK Ref: CC4/III19010871/Apb3
Without Prejudice
Dear Sirs/Mdm,
Thank you for your patience.
We propose settlement at a global sum of \$2,780.00(all-in).
Please confirm acceptance.
"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed
/ inferred from this negotiation of terms/settlement.
In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Hsiao Tong, Chew Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 email: chewht@lkkauto.com fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 S(408933)
From: MotorClaims < <u>exclusiveenterprise50@gmail.com</u> > Sent: Monday, 16 September 2019 3:05 PM
To: MotorClaims < exclusiveenterprise50@gmail.com >; Hsiao Tong (LKKAuto) < chewht@lkkauto.com > Subject: RE: JRK 6627 - LOD
Importance: High
War - T
Hi Xiao Tong,
We have send out LOD on 25/06/2019 but until now no any news from you all.
We would appreciate your immediate attention and look forward to hearing from you soon.
Thank you very much.
Best Regards,
ICE

Best Regards,

8 Kaki Bukit Avenue 4 #05-50 PREMIER@KAKI BUKIT Singapore 415875 Tel: 6245 9655 Fax: 6245 9678 From: MotorClaims Sent: Wednesday, September 4, 2019 11:39 AM To: chewht@lkkauto.com Subject: RE: JRK 6627 - LOD Importance: High Hi XiaoTong, Refer to below email & advice . Thanks. Best Regards, Xiang EXCLUSIVE ENTERPRISE PTE LTD 8 Kaki Bukit Avenue 4 #03-50 PREMIER@KAKI BUKIT

Singapore 415875

Tel: 6245 9655 Fan: 6245 9678

Sent: Wednesday, August 28, 2019 3:26 PM To: chewht@lkkauto.com Subject: RE: JRK 6627 - LOD Importance: High Hi XiaoTong, It's been one month since I send the LOD to you and haven gotten any replies . Please advise . Thanks. Best Regards, Xiang EXCLUSIVE ENTERPRISE PTE LTD 8 Kaki Bukit Avenue 4 #03-50 PREMIER@KAKI BUKIT Singapore 415875 Tel: 6245 9655 Fax: 6245 9678

From: exclusiveenterprise50@gmail.com

Sent: Friday, July 19, 2019 1:09 PM

To: chewht@lkkauto.com Subject: JRK 6627 - LOD

From: MotorClaims

Hi XiaoTong,

Please see attached for LOD.

Thanks.

Best regards,

Xiang

Exclusive Enterprise Pte Ltd

8 Kaki Bukit Avenue 4 #03-50

PREMIER@KAKI BUKIT

Singapore 415875

Tel: 6245 9655 Fax: 6245 9678

...CLAIM SUBFOLDER...(Pending for Survey Report) Direct Settlement

Case	Notified	Est Submitted	Adj Assigned	Adi Rpt	Adi	Submitted	Ins Auth'ed	Status		
Main	19 Jun 2019 19 Jun 2019			\$\$5,350.00 \$\$5,3		350.00 w Rpt		Pending for Survey Report Cancel Case		
	Main	N R	eference	Claim	Details		Documents		Show All	
CLAIM SU	BFOLDER DE	TAILS				[Created	by adjuster]			
Insured:	COMFORT	TRANSPORTAT	ION PTE LTD, ID	199303821R						
Main Claimant:	TAM SHU	CHENG, ID: -				.,				
Vehicle Reg No.:	JRK662	7		Dat	e of Loss:	17/06/2019 00:00 - :59 [39 Months and 7 Days From LTA Reg Date (Man Yr)]				
Claim Type	TP / MC	T19060455			cy/Cover e No.:	MCOM0015				
Vehicle Reg No. (Insured):	SH8873C	5			cy No. simant):					
A COUNTY OF THE PERSON OF THE				Exc	ess:					
Repairer:	Exclusive	Enterprise Pte I	Ltd (HQ) B KAKI B	AV 4#03-50 PR	EMIEROK	B, 415875 K	aki Bukit - Tel:			
Handling Insurer:	100004705410						lari Nagarajan - 634			
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 67	56-3561 [Ha	ndled by A	DRIAN LIN	G] [Final Rpt d	ue 28/06/20	019]	
ASSOCIAT	TED MAIL RE	CEIVED					View A	II Compos	e Case Ma	
• 111_SG (30/09/2019): 24/06/2019): DCIATED TAS E Priority	Alert - Adj Mand Alert - Adj Mand	late Approved (SS	(2782.45) - JR (0.00) - JRK66	(6627 - C 27 - Clain	laim Handler: 5	er: Sundari Naga er: Sundari Naga Sundari Nagaraj Search Tasks Crea Completed On	te New Task	Complet	

Claim Documents

*JRK6627 (MCT19060455)

[SH8873C]

TP

TAM SHU CHENG

Jun 17 2019 12:00AM

[COMFORT TRANSPORTATION PTE LTD]

Exclusive Enterprise Pte Ltd

Video		1 per	page 🗸	V	
Vo	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Prin
	24/06/19 10:11	Video - Accident-IV	0	Load MP4	
2	24/06/19 10:20	Video - Accident-SHD7263X-1stvehicle;SH8873C(III)>JRK6627>SHD7263X (alsoIII)	0	Load MP4	
Pho	tos/Images		3 per	page 🔻	Ø
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
1	24/06/19 10:00	General View	0	Load 3PG	2
2	24/06/19 10:00	General View	0	Load 3PG	2
3	24/06/19 10:00	Chassis Number	0	Load JPG	Z
4	24/06/19 10:00	General View	8	Load JPG	8
5	24/06/19 10:00	General View	0	Load JPG	100
6	24/06/19 10:00	General View	0	Load IPG	V
7	24/06/19 10:00	General View	0	Load 3PG	2
8	24/06/19 10:00	General View	0	Load JPG	82
9	24/06/19 10:00	General View	0	Load JPG	V
10	24/06/19 10:00	General View	0	Load JPG	M
11	24/06/19 10:00	General View	0	Load IPG	Ø
12	24/06/19 10:00	General View	0	Load JPG	2
13	24/06/19 10:00	General View	0	Load JPG	V
14	24/06/19 10:00	General View	0	Load JPG	2
15	24/06/19 10:00	General View	0	Load JPG	V
16	24/06/19 10:00	General View	0	Load 3PG	N/
17	24/06/19 10:00	General View	0	Load 3PG	Ø
18	24/06/19 10:00	General View	0	Load JPG	8
19	24/06/19 10:00	General View	0	Load JPG	W
20	24/06/19 10:00	General View	0	Load JPG	82
	The succession of the succession	General View	0	Load 3PG	82
21	24/06/19 10:00	General View	0	Load 3PG	82
22	24/06/19 10:00		0	Load JPG	2
23	24/06/19 10:00	General View	0	Load JPG	Z
24	24/06/19 10:00	General View	0	Load JPG	2
25	24/06/19 10:00	General View	0	Load JPG	2
26	24/06/19 10:00	General View			
27	24/06/19 10:00	General View	0	Load 3PG	2
28	24/06/19 10:00	General View	0	Load JPG	M
29	24/06/19 10:00	General View	0	Load JPG	2
30	24/06/19 10:00	General View	0	Load JPG	50
31	24/06/19 10:00	General View	0	Load JPG	₩
32	24/06/19 10:00	General View	0	Load 3PG	82
33	24/06/19 10:00	General View	0	Load JPG	2
34	24/06/19 10:00	General View	0	Load JPG	V
35	24/06/19 10:00	General View	0	Load JPG	M
36	24/06/19 10:00	General View	0	Load JPG	V
37	24/06/19 10:00	General View	0	Load JPG	8
38	24/06/19 10:00	General View	0	Load 3PG	

*****	0		1 per pa		Z
Vo	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnall	
19	24/06/19 10:00	General View	0	Load JPG	K
10	24/06/19 10:00	General View	0	Load JPG	✓
1	24/06/19 10:00	General View	0	Load JPG	V
12	24/06/19 10:00	General View	0	Load JPG	Ø
13	24/06/19 10:00	General View	0	Load JPG	Ø
	24/06/19 10:00	General View	0	Load JPG	V
44		General View	0	Load JPG	Ø
45	24/06/19 10:00	20000000000000	0	Load JPG	Ø
46	24/06/19 10:00	General View	0	Load JPG	R
47	16/07/19 10:03	Reinspection Photo		CONTRACTOR OF THE PARTY OF THE	-
48	16/07/19 10:03	Reinspection Photo	0	Load JPG	V
49	16/07/19 10:03	Reinspection Photo	0	Load JPG	W
50	16/07/19 10:03	Reinspection Photo	0	Load JPG	V
51	16/07/19 10:03	Reinspection Photo	0	Load JPG	2
52	16/07/19 10:03	Reinspection Photo	0	Load JPG	V
53	16/07/19 10:03	Reinspection Photo	0	Load JPG	V
1	PERSONAL PROPERTY OF THE PERSONAL PROPERTY OF	Reinspection Photo	0	Load JPG	V
54	16/07/19 10:03	MENTAL SECTION OF THE	0	Load JPG	82
55	16/07/19 10:03	Reinspection Photo			
56	16/07/19 10:03	Reinspection Photo	0	Load JPG	2
57	16/07/19 10:03	Reinspection Photo	0	Load JPG	2
58	16/07/19 10:03	Reinspection Photo	0	Load JPG	Ø
59	16/07/19 10:03	Reinspection Photo	0	Load JPG	V
60	16/07/19 10:03	Reinspection Photo	0	Load 3PG	Z
61	16/07/19 10:03	Reinspection Photo	8	Load 3PG	2
62	16/07/19 10:03	Reinspection Photo	0	Load JPG	V
63	16/07/19 10:03	Reinspection Photo	0	Load JPG	N.
	- service and a service and a	Or and the Control of Charles Server	Ö	Load JPG	V
64	16/07/19 10:03	Reinspection Photo		110 110 110 110 110	-
65	16/07/19 10:03	Reinspection Photo	0	Load 3PG	82
66	16/07/19 10:03	Reinspection Photo	0	Load JPG	82
67	16/07/19 10:03	Reinspection Photo	0	Load JPG	82
68	16/07/19 10:03	Reinspection Photo	0	Load JPG	V
69	16/07/19 10:03	Reinspection Photo	0	Load 3PG	8
70	16/07/19 10:03	Reinspection Photo	0	Load 3PG	82
71	16/07/19 10:03	Reinspection Photo	0	Load JPG	2
72	16/07/19 10:03	Reinspection Photo	0	Load JPG	V
			0	Load JPG	2
73	16/07/19 10:03	Reinspection Photo			-
74	16/07/19 10:03	Reinspection Photo	0	Load JPG	2
75	16/07/19 10:03	Reinspection Photo	0	Load 3PG	2
76	16/07/19 10:03	Reinspection Photo	0	Load 3PG	82
77	16/07/19 10:03	Reinspection Photo	0	Load JPG	V
78	16/07/19 10:03	Reinspection Photo	0	Load JPG	V
79	16/07/19 10:03	Reinspection Photo	0	Load 3PG	8
80	16/07/19 10:03	Reinspection Photo	0	Load 3PG	8
81	16/07/19 10:03	Reinspection Photo	0	Load JPG	V
82	16/07/19 10:03	Reinspection Photo	0	Load JPG	V
			0	Load JPG	2
83	16/07/19 10:03	Reinspection Photo	0	1000 36.0	1 2
Doc	umentation		1 per pa	oge V	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	+
1	19/06/19 17:02	EMAIL FROM III DD 19062019	0	Load PDF	1
2	19/06/19 17:02	NOTICE & POLICE REPORT	Ŏ	Load PDF	
3	20/06/19 17:26	Malaysia Vehicle Registration Card	0	Load PDF	
4	20/06/19 17:26	INSURANCE CERT	0	Load PDF	
5	24/08/19 12:29	TP_ESTIMATE_MARKED_(FINAL)	0	Load PDF	
6	04/09/19 12:57	WORKSHOP INVOICE	0	Load PDF	-
7	04/09/19 12:57	LTA SEARCH	0	Load PDF	-
8	04/09/19 12:57	LOD	0	Load PDF	-
9	04/02/20 10:28	AUTHORISATION TO ACT FORM		CONTRACT AND DRIVE	

Video		1 per page 🔍	1 2		
No Finalized On India International Insurance Pte Ltd (HQ)		India International Insurance Pte Ltd (HQ)	Thumbna		
-	04/02/20 10:28	GIRO FORM	■ Load PDF		
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnai	-	
1	20/06/19 08:46	Singapore Accident Statement	Load PDF	_	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co Reg No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/III19010871/APS3Q2

Date:

04/02/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No:

JRK6627

Insured Vehicle No: SH8873C

Date of Loss:

17/06/2019

Nature of Claim:

TP

Claim No: MCT19060455

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

JRK6627

Make & Model:

TOYOTA INNOVA, 2.0 E AT (A)

Engine No:

1TR8856072

Reg. Date:

10/03/2016 (Man. Year: 2015)

Chassis No:

PN111NV4018415384

Colour:

Silver

Odometer:

280250 km

Engine Capacity: Market Value/New Car 1998 cc

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size:

205/65 R15

Rear Tyre Size:

205/65 R15

Front Left Side:

Hankook 6 mm

Rear Left Side:

Hankook 6 mm

Front Right Side:

Hankook 6 mm

Rear Right Side:

Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,252.80	4,364.15	6,888.65	61.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,690.00	2,370.00	2,320.00	49.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,942.80	6,734.15	9,208.65	57.76
Approved Total (Overridden) (S\$)		5,350.00		
Nett Amount (S\$)	15,942.80	5,350.00	10,592.80	66.44
+ Loss of Use (4.0 x S\$5	0.00/day) (S\$)	200.00		
	(S\$)	5,550.00		
Liable Amount	(60.00%) (S\$)	3,330.00		
+ Doc/Se	earch Fee (S\$)	7.45		
Net	t Liability (S\$)	3,337.45		
Global Sum Se	ettlement (S\$)	3,300.00		

INSPECTION

Date of Assignment:

19/06/2019

Date Inspected:

19/06/2019 Inspected At:

Exclusive Enterprise Pte Ltd (HQ)

8 KAKI BT AV 4#03-50 PREMIER@KB Singapore 415875

Estimated Period of Repair:

8.0 days

Adjuster Report Page 2 of 5

Adjuster: ADRIAN LING Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Sep 2019)

Parts: M1-MPV TOYOTA INNOVA 2.0 E AT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for JRK6627)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

*BONNET LOCK *BONNET LOCK *BONNET OUTER CHROME MOULDING *BONNET RUBBER SEAL *BONNET HINGE L/R *FRT BUMPER *FRT BUMPER SIDE RETAINER L/R *FRT BUMPER FOG LAMP GARNISH L/R *FRT BUMPER LOWER GRILLE *FRT BUMPER REINFORCEMENT *FRT BUMPER BRACKET	Repair Not Necessary Not Necessary Not Necessary Not Necessary Deformed Necessary Not Necessary Deformed Not Necessary Deformed Not Necessary	739.10 FL 93.10 FL 267.30 FL 39.10 FL 114.20 FL 573.10 FL 146.20 FL 178.40 FL 188.30 FL	*-FL *-FL *-FL *-FL *573.10FL *146.20FL *-FL
*BONNET OUTER CHROME MOULDING *BONNET RUBBER SEAL *BONNET HINGE L/R *FRT BUMPER *FRT BUMPER SIDE RETAINER L/R *FRT BUMPER FOG LAMP GARNISH L/R *FRT BUMPER LOWER GRILLE *FRT BUMPER REINFORCEMENT *FRT BUMPER BRACKET	Not Necessary Not Necessary Not Necessary Deformed Necessary Not Necessary Deformed	267.30 FL 39.10 FL 114.20 FL 573.10 FL 146.20 FL 178.40 FL	*-FL *-FL *-FL *573.10FL *146.20FL
*BONNET RUBBER SEAL *BONNET HINGE L/R *FRT BUMPER *FRT BUMPER SIDE RETAINER L/R *FRT BUMPER FOG LAMP GARNISH L/R *FRT BUMPER LOWER GRILLE *FRT BUMPER REINFORCEMENT *FRT BUMPER BRACKET	Not Necessary Not Necessary Deformed Necessary Not Necessary Deformed	39.10 FL 114.20 FL 573.10 FL 146.20 FL 178.40 FL	*-FL *-FL *573.10FL *146.20FL
*BONNET HINGE L/R *FRT BUMPER *FRT BUMPER SIDE RETAINER L/R *FRT BUMPER FOG LAMP GARNISH L/R *FRT BUMPER LOWER GRILLE *FRT BUMPER REINFORCEMENT *FRT BUMPER BRACKET	Not Necessary Deformed Necessary Not Necessary Deformed	114.20 FL 573.10 FL 146.20 FL 178.40 FL	*- FL *573.10 FL *146.20 FL
*FRT BUMPER *FRT BUMPER SIDE RETAINER L/R *FRT BUMPER FOG LAMP GARNISH L/R *FRT BUMPER LOWER GRILLE *FRT BUMPER REINFORCEMENT *FRT BUMPER BRACKET	Deformed Necessary Not Necessary Deformed	573.10 FL 146.20 FL 178.40 FL	*573.10 FL *146.20 FL
*FRT BUMPER SIDE RETAINER L/R *FRT BUMPER FOG LAMP GARNISH L/R *FRT BUMPER LOWER GRILLE *FRT BUMPER REINFORCEMENT *FRT BUMPER BRACKET	Necessary Not Necessary Deformed	146.20 FL 178.40 FL	*146.20 FL
*FRT BUMPER FOG LAMP GARNISH L/R *FRT BUMPER LOWER GRILLE *FRT BUMPER REINFORCEMENT *FRT BUMPER BRACKET	Not Necessary Deformed	178.40 FL	
*FRT BUMPER LOWER GRILLE *FRT BUMPER REINFORCEMENT *FRT BUMPER BRACKET	Not Necessary Deformed		*-FL
*FRT BUMPER REINFORCEMENT *FRT BUMPER BRACKET		188.30 FL	
*FRT BUMPER BRACKET	Not Necessary		*188.30 FL
	IAUT IAUCGSSUIÀ	437.10 FL	*-FL
	Bent	113.40 FL	*113.40 FL
*FRT GRILLE	Cracked	362.10 FL	*362.10 FL
*FRT GRILLE LOGO	Necessary	48.80 FL	*48.80 FL
*HEADLAMP L/R	Cracked	986.20 FL	*986.20 FL
*SUPPORT PANEL	Repair	519.30 FL	*-FL
*BRACE PANEL	Bent	221.90 FL	*221.90 FL
*RADIATOR	Not Necessary	939.10 FL	*-FL
*A/C CONDENSER	Not Necessary	1,163.90 FL	*-FL
*TAILGATE	Dented	1,391.60 FL	*1,043.00 FL
*TAILGATE LOCK	Damaged	476.10 FL	*285.00 FL
*TAILGATE W/STRIP	Cut	197.60 FL	*197.60 FL
*TAILGATE OUTER GARNISH	Not Necessary	119.30 FL	*-FL
*TAILGATE LOGO	Necessary	69.30 FL	*69.30 FL
*EMBLEM 2.0	Necessary	53.10 FL	*53.10FL
*EMBLEM E	Necessary	48.30 FL	*48.30 FL
*TAILGATE GLASS MOULDING L/R	Necessary	79.20 FL	*79.20FL
*TAILGATE INNER TRIMBOARD	Not Necessary	587.10 FL	*-FL
		78.80 FL	*-FL
			*561.90 FL
			*98.00 FL
	and the second s		*-FL
			*91.80 FL
The state of the s		100-000-000	*-FL
	Deliver the second of the seco		*-FL
	(0,000)	and the state of t	*105.00 FL
	The state of the s		*- FL
		Control Symphotical Community	*30.00FS
	0.000		*20.00FS
			*-FS
	particular and the second seco		*50.00 FS
			*30.00FS
	The state of the s		*60.00FS
and the second control of the second control	- Unique de la lacción de		
TAILGATE INNER TRIM CLIPS	Necessary	50.00 PS	*20.00 FS
	*TAILGATE STOPPER L/R *REAR BUMPER *REAR BUMPER SIDE RETAINER L/R *REAR BUMPER SIDE HOLDER L/R *REAR BUMPER SIDE REFLECTOR L/R *TAILLAMP L/R *END PANEL *END PANEL *END PANEL TOP GARNISH *REAR COMPARTMENT BOARD *SET FRT BUMPER CLIPS *SET FRT GRILLE CLIPS *COOLANT *FRT NUMBER PLATE *SET REAR BUMPER CLIPS *REAR W/S SEALANT *TAILGATE INNER TRIM CLIPS	*REAR BUMPER SIDE RETAINER L/R Necessary *REAR BUMPER SIDE HOLDER L/R Not Necessary *REAR BUMPER SIDE REFLECTOR L/R N/S Cracked *TAILLAMP L/R Not Necessary *END PANEL Repair *END PANEL TOP GARNISH Deformed *REAR COMPARTMENT BOARD Not Necessary *SET FRT BUMPER CLIPS Necessary *SET FRT GRILLE CLIPS Necessary *COOLANT Not Necessary *FRT NUMBER PLATE Bent *SET REAR BUMPER CLIPS Necessary *FRT NUMBER PLATE Necessary *REAR W/S SEALANT Necessary *REAR W/S SEALANT	*REAR BUMPER SIDE RETAINER L/R Necessary 178.60 FL *REAR BUMPER SIDE HOLDER L/R Not Necessary 187.20 FL *REAR BUMPER SIDE REFLECTOR L/R N/S Cracked 183.60 FL *TAILLAMP L/R Not Necessary 579.20 FL *END PANEL Repair 811.60 FL *END PANEL TOP GARNISH Deformed 363.70 FL *REAR COMPARTMENT BOARD Not Necessary 893.60 FL *SET FRT BUMPER CLIPS Necessary 50.00 FS *SET FRT GRILLE CLIPS Necessary 50.00 FS *COOLANT Not Necessary 80.00 FS *COOLANT Not Necessary 80.00 FS *SET REAR BUMPER CLIPS Necessary 50.00 FS *SET REAR BUMPER CLIPS Necessary 80.00 FS *SET REAR BUMPER CLIPS Necessary 50.00 FS *TAILGATE INNER TRIM CLIPS Necessary 50.00 FS

No.	Qty	Part No.	Particulars C	ondition	Repairer's	Amount
44	1		*SET REAR NUMBER CLIPS N	ot Necessary	50.00FS	*-FS
45	1		*REVERSE SENSOR D	amaged	300.00FS	*200.00FS
F=Fn	inchise	part. S=Spct	- List Item Discount on L Items 25.	Sub Total (S\$) 00/25.00% (S\$)	7175. B.	5,682.20 1,318.05
			T	otal Parts (S\$)	11,252.80	4,364.15
			Report was unsubmitted during this	print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Vo	Particulars	Lab.Type	Repairer's	Amount
abo	our Items			
1	R&R FRONT AIRCON CONDENSER & RADIATOR	New	180.00	0.00
2	TOP UP AIRCON GAS	New	150.00	0.00
3	WIRE-CHECKING (FRONT)	New	50.00	30.00
4	LABOUR (FRONT)	New	1,000.00	400.00
5	PAINTING (FRONT)	New	900.00	400.00
3	R&R REAR WINDSCREEN	New	150.00	120.00
7	R&R REVERSE SENSOR	New	60.00	50.00
3	WIRE-CHECKING (REAR)	New	50.00	30.00
9	R&R REAR COMPARTMENT & TRIMS	New	150.00	60.00
10	TRANSFER REAR GATE COMPONENT FROM OLD TO NEW	New	100.00	80.00
11	LABOUR (REAR)	New	1,000.00	600.00
12	PAINTING(REAR)	New	900.00	600.00
	Gross Labo	ur Cost (S\$)	4,690.00	2,370.00

< END OF ESTIMATES >