

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX0729I
POON LEE KIANG LINDA
NO 41 WATTEN HEIGHTS

SINGAPORE 287473
TEL : FAX :
PH : 98009290
ATTN :

ESTIMATE BILL

Number : EB00005189
Date : 18/06/2019
Case No : AD00010495
Vehicle No : SBL9889G
Chassis : WAUZZZ8V6H1068789
Year of Mfr 2017
Policy No
Model : AUDI A3

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	REAR FENDER LH	1.0	1,789.45	0	1,789.45
2	REAR FENDER LAMP LH	1.0	627.25	0	627.25
3	REAR BUMPER	1.0	1,403.55	0	1,403.55
4	REAR BUMPER RETAINER LH	1.0	47.25	0	47.25
5	REVERSE SENSOR	1.0	208.85	0	208.85
6	TAIL LAMP PANEL LH	1.0	149.50	0	149.50
7	REAR FENDER INNER SHIELD LH	1.0	177.25	0	177.25
8	REAR FENDER QUARTER GLASS LH	1.0	402.65	0	402.65
	List Price - Parts Sub Total				4,805.75
9	WINDSCREEN SELANT	2.0	24.00	0	48.00
	Special Nett Price - Parts Sub Total				48.00
	Parts Total				4,853.75
10	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,500.00	0	1,500.00
11	SPRAY PAINT ON THE AFFECTED AREAS	1.0	900.00	0	900.00
12	ANTI-RUST COATING	1.0	200.00	0	200.00
13	WIRING	1.0	40.00	0	40.00
14	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
15	TO REMOVE & REFIT CUSHION & UPHOSTERY	1.0	250.00	0	250.00
16	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
	Labour 1 Sub Total				3,220.00
SINGAPORE DOLLARS : EIGHT THOUSAND SIX HUNDRED THIRTY-EIGHT AND CENTS NINETY-ONE ONLY			Less Excess		0.00
			SUBTOTAL		8,073.75
			GST 7.00%		565.16
			TOTAL		8,638.91

Date of accident : 14/06/2019 02:05 PM. Place : JUNCTION OF ADAM RD AND DUNEARN RD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE