

ASS. REC. BY:

REF: CS/FCI19010919/Ut d3

p2

Special Instruction:

Assigner: Mitrus

ASSIGNMENT (Office)

From (Person): May chunof FCIDate/Time: 5:12pm @ 19/6/19

Estimated Cost:

Bill to:

OD / PP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 4400F

Insured:

SHD 65904

at Workshop m/s

Specialist Motor

Tel:

G7472112

of

Blk 3018A Ubi Road 1 # 01-24-26

Policy No:

Claim No:

D190039SIMF8H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15/06/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

1up)

H.O.D. Endorsement:

Date/Time:

10:32am @ 20/6/19

Person Contacted:

Irene

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate ✓GBE 4400F - XSHD 65904 - CS/FCI19000131/Kcd3n2DOA: 26/12/201825/6/2019 @ 3:33pm - revised via email prev advise.

ASS. REC. BY:

REF: FCI

ASSIGNMENT

From: Date: 04/6/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBF 4400F
at Workshop m/s Specialist Motor
of Blk 30184 Ubi Rd 1 # 01-24/26

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

48

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 1.81 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 1wp 20 AM

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: GBF 4400F Yr Regn: 10 / 16
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: Nissan Cabstar C.C 2953

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 187014 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JNISC2F2420859284

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195-R15

R: 165-R13

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 Rear: 6/6

R/Bal. mm R/Bal. mm

L/Bal. 6 mm L/Bal. 6/6 mm

D.O.A. 18/6/19 D.O.I. 24/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

2/5 Lp.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/8/19 L1A 38278
7/24/6680-11 confirmed with insurance. (Red: 4123 841 3890)

RECEIVED 13 AUG 2019

Date/Time, File Pass to?

☐ Preli. Report
☒ Final Report

1) 13/8 Typist
Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Insp (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Other

TOTAL

Report Forward:

Enter S into 11

TP

6680-11

170

50

50

88

358



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003951MFSH

Date: 25/06/2019

Our Ref: CS/FCI19010919/Utd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. GBF 4400F

Please be informed that we had conducted the inspection of the abovementioned vehicle
24/06/2019 at the premises of M/s Specialist Motor have the following to report: -

Workshop Estimate Amount	: S\$ <u>10,727.45</u>
Revised Estimate Amount	: S\$ <u>6,364.29</u>
"Check" Items Amount	: S\$ <u>892.17</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:
The vehicle sustained damages at the
o/d front portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Marcus
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	17-06-2019	Our Ref No. D19003951MFSH
Accident Date	15-06-2019	Claim Type. Third Party
Insured Vehicle	SHD6590H	Third Party Vehicle. GBF4400F
Survey Location	BLK 3018A UBI ROAD 1 #01-24-26	
Contact Person.	IRENE TING	
Contact No.	67472112/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SPECIALISTS MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 25 June 2019 3:28 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003951MFSH/1
Attachments: PRELI ADVISED GBF 4400F.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **GBF 4400F**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 20 June 2019 10:36 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003951MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 19 June 2019 5:12 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003951MFSH/1

NEW CAR DISCOUNTS & OFFERS

BEST DEAL DAILY!

[VIEW ALL PROMOTIONS](#)

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Years Coe Renewal Toyota Vios 1.5A



3.18%P.A \$0 Admin Fees@GV
Finance.2 Years Warranty.\$1500
Down Monthly From \$448
GV Credit Pte Ltd StarAd

AutoInn
An Inspiration For Car Buyers

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category

Sort by Date Posted 20 results/page

6 vehicles

Cabstar

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Cabstar		Any	Any	2016	Any	Any	Any	Available
	Nissan Cabstar			N.A	26-Nov-2016	2,953 cc	80,865 km	Truck	Available
	Fuel Type: Diesel Auction Closing Time: 1st Jul 2019 at 04:00 PM								
	Posted: 24-Jun-2019 Tags: 2016 Nissan Cabstar, 2016 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan								
	Nissan Cabstar		\$40,999	\$6,240 /yr	19-Jan-2016	2,953 cc	-	Truck	Available
	Fuel Type: Diesel Cheapest In The Market! Seller's Loss Your Gain! Condition Like New! Yet Price Still Negotiable! Only 1 Owner! Low Mileage, Accident Free! 2+1 Front Seating, Optional Rear Canopy! Comes With Full Rear...								
	Net Link Partners Pte Ltd Posted: 22-Jun-2019 Tags: 2016 Nissan Cabstar, 2016 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan								
	Nissan Cabstar		\$49,800	\$7,320 /yr	12-Apr-2016	2,953 cc	55,264 km	Truck	Available
	Fuel Type: Diesel Think One Automobile & Trading								
	Posted: 20-Jun-2019 Tags: 2016 Nissan Cabstar, 2016 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan								
	Nissan Cabstar		\$48,300	\$7,120 /yr	05-Apr-2016	2,953 cc	-	Truck	Available
	Fuel Type: Diesel Think One Automobile & Trading								
	Posted: 19-Jun-2019 Tags: 2016 Nissan Cabstar, 2016 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan								
	Bendix Metal King Front Brake Pad (Mitsubishi Outlander) Front brake pad for Mitsubishi Outlander 2003-2006. Find out more!								
	Nissan Cabstar		\$42,800	\$6,130 /yr	17-Jun-2016	2,953 cc	21,000 km	Truck	Available
	Fuel Type: Diesel Very New, With Half Canopy. See To Believe. Loan Can Be Arrange.								
	Posted: 15-Jun-2019 Tags: 2016 Nissan Cabstar, 2016 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan								
	Nissan Cabstar		\$48,888	\$7,100 /yr	11-May-2016	2,953 cc	-	Truck	Available
	Fuel Type: Diesel 1 Owner Only! Very Well Maintained By Previous Owner, Engine And Gearbox In Perfect Condition. Very Clean Interior! Cabin Height Box Suitable For HDB Parking. 2 Side Sliding Door. Full Loan Can Be Don...								
	Skylink Auto Pte Ltd Posted: 06-May-2019 Tags: 2016 Nissan Cabstar, 2016 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan								

[Compare](#)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 2047M

Vehicle Details

Vehicle No.: GBF4400Y

Vehicle to be Exported: No

Intended Deregistration Date: 24 Jun 2019

Vehicle Make: NISSAN

Vehicle Model: CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5

Primary Colour: White

Manufacturing Year: 2016

Engine No.: ZD30015417N

Chassis No.: JN1SC2F24Z0859284

Maximum Power Output: -

Open Market Value: \$24,942.00

Original Registration Date: 31 Oct 2016

First Registration Date: 31 Oct 2016

Transfer Count: 1

Actual ARF Paid: \$1,248.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Oct 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$48,001.00

COE Rebate Amount: \$35,278.00

Total Rebate Amount: \$35,278.00

The information contained herein is correct as at 24 Jun 2019

OK

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GBF4400Y/1906083

18th June 2019

The Manager
Motor Claim Department
MS First Capital Insurance Ltd
36 Robinson Rd
#16-01 City House
Singapore 068877

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No in-painting/modification(s) is allowed
- Supplemental work (item(s)) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Ackd
Hm
7 day
Theft & Acc rep.
24/6/19
P/P \$ 6680.11

Date of Accident : 15th June 2019
Location : Kaki Bukit Ave 3
Third Party Claim Vehicle No : SHD 6590 H
Repair Cost For Vehicle No : GBF 4400 Y Nissan Cabstar

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Headlamp assy RH (net)	510 1	473.40	\$ 473.40 ✓
2	Headlamp end panel RH (net) / over	510 1	75.00	\$ 75.00 ✓
3	Front grille (net)	cu 1	438.40	\$ 438.40 ✓
4	Front grille emblem (logo) (net)	21 1	58.20	\$ 58.20 ✓
5	Front bumper fascia (net) 945.10	D.S 1	1,039.50	\$ 1,039.50 ✓
6	Front bumper bracket RH (net)	51 1	30.00	\$ 30.00 ✓
7	Front corner panel RH (net)	D.S 1	392.20	\$ 392.20 ✓
8	Front door assy RH (net)	510 1	1,396.50	\$ 1,396.50 ✓
9	Front door hinge (top) RH (net) 61.10	510 / 1	61.70	\$ 61.70 ✓
10	Front door hinge (bottom) RH (net) 61.10	510 / 1	61.70	\$ 61.70 ✓
11	Front door lamp RH (net)	51 1	48.50	\$ 48.50 ✓
12	Front door regulator gear RH (net)	510 / 1	127.00	\$ 127.00 ✓
13	Front door power window motor RH (net)	11 1	524.40	\$ 524.40 X
14	Front door arch panel RH	11 1	1,943.00	\$ 1,943.00 X
15	Front step garnish RH (net)	310 1	139.40	\$ 139.40 ✓
16	Front body w/strip RH (net)	21 1	95.00	\$ 95.00 ✓
17	Front wheel arch garnish RH (net)	21 1	95.00	\$ 95.00 ✓
18	Front wheel arch garnish clips RH (net)	11 1	10.00	\$ 10.00 X
19	Front door w/strip RH (net)	21 1	137.00	\$ 137.00 ✓
20	Front door board RH (net)	11 1	750.00	\$ 750.00 X
21	Accelerator pedal (net)	11 1	35.00	\$ 35.00 X
				\$ 7,930.90

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GBF4400Y/1906083

18th June 2019

No.	Particulars	Qty	Price	Amounts
	Balance b/f			\$ 7,930.90
22	Accelerator linkage (net)	11 1	179.60	\$ 179.60
	wiper washer tank one			\$ 8,110.50
		Less	10%	\$ 811.05
				\$ 7,299.45
23	Front door sticker (s/net)	1	28.00	\$ 28.00
				\$ 7,327.45

Labour Charges :-

	Amounts
Cut out, renew, knocking & welding front corner panel RH, front door pillar RH, front wheel arch panel RH, front door assy RH, remove & install all damage parts, straighten & re-align body	\$ 1,480.00 1200
Remove & install front door glass, board, lock & etc	\$ 120.00 60
Remove & install seats, carpets & etc	\$ 230.00 100
Tuff-kote on damage parts	\$ 160.00 80
Spray painting on damage parts	\$ 1,280.00 900
Check all lighting after repairs	\$ 30.00 20
Body lettering on front door	net \$ 100.00

Labour Charge

\$ 3,400.00

Total Amount

\$10,727.45

GST will be reflected in the final bills.

10803.95

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

P- 4657.90
10%
P- 492.11
S.N- 28.00
L - 2460.00
6680.11

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GBF4400Y/1906083

18th June 2019

The Manager
Motor Claim Department
MS First Capital Insurance Ltd
36 Robinson Rd
#16-01 City House
Singapore 068877

Date of Accident : 15th June 2019
Location : Kaki Bukit Ave 3
Third Party Claim Vehicle No : SHD 6590 H
Repair Cost For Vehicle No : GBF 4400 Y Nissan Cabstar

Supplementary Supply of Parts

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Washer tank	1	85.00	\$ 85.00
				\$ 85.00
		Less	10%	\$ 8.50
				\$ 76.50

GST will be reflected in the final bills.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19010919/Utd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-08-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6590H	Veh. Inspected	GBF 4400Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003951MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	19/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN CABSTAR (M)	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JN1SC2F24Z0859284	Colour	WHITE	
Odometer	187014	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	165 R13 (D)	BRIDGESTONE	6/6 mm	
L/H Rear Tyre	165 R13 (D)	BRIDGESTONE	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/06/2019	Inspection Date	24/06/2019	
Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 4400Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HEADLAMP ASSY RH (N)	BROKEN	473.40	473.40
1	HEADLAMP END PANEL RH LOWER (N)	BROKEN	75.00	75.00
1	FRONT GRILLE (N)	CUT	438.40	438.40
1	FRONT GRILLE EMBLEM (LOGO)(N)	NECESSARY	58.20	58.20
1	FRONT BUMPER FASCIA (N)	DISTORTED	1,039.50	945.10
1	FRONT BUMPER BRACKET RH (N)	BENT	30.00	30.00
1	FRONT CORNER PANEL RH (N)	DISTORTED	392.20	392.20
1	FRONT DOOR ASSY RH (N)	BADLY DENTED	1,396.50	1,396.50
1	FRONT DOOR HINGE (TOP) RH (N)	BENT / TWISTED	61.70	61.10
1	FRONT DOOR HINGE (BOTTOM) RH (N)	BENT / TWISTED	61.70	61.10
1	FRONT DOOR LAMP RH (N)	SCRATCHED	48.50	48.50
1	FRONT DOOR REGULATOR GEAR RH (N)	BENT / JAMMED	127.00	127.00
1	FRONT DOOR POWER WINDOW MOTOR RH (N)	NOT NECESSARY	524.40	-
1	FRONT DOOR ARCH PANEL RH (N)	TO REPAIR SEE LABOUR	1,943.00	-
1	FRONT STEP GARNISH RH (N)	BROKEN	139.40	139.40
1	FRONT BODY W/STRIP RH (N)	NECESSARY	95.00	95.00
1	FRONT WHEEL ARCH GARNISH RH (N)	DEFORMED	95.00	95.00
1	FRONT WHEEL ARCH GARNISH CLIPS RH (N)	NOT NECESSARY	10.00	-
1	FRONT DOOR W/STRIP RH (N)	NECESSARY	137.00	137.00
1	FRONT DOOR BOARD RH (N)	NOT NECESSARY	750.00	-
1	ACCELERATOR PEDAL (N)	NOT NECESSARY	35.00	-
1	ACCELERATOR LINKAGE (N)	NOT NECESSARY	179.60	-
1	WASHER TANK (ADDITIONAL)(N)	CRACKED	85.00	85.00
	LESS 10% DISCOUNT		-819.55	-465.79
			7,375.95	4,192.11
SPECIAL NETT ITEMS				
1	FRONT DOOR STICKER (SN)	NECESSARY	28.00	28.00
			28.00	28.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	CUT OUT,RENEW,KNOCKING & WELDING FRONT CORNER PANEL RH,FRONT DOOR PILLAR RH,FRONT WHEEL ARCH PANEL RH,FRONT DOOR ASSY RH,REMOVE & INSTALL ALL DAMAGE PARTS,STRAIGHTEN & RE-ALIGN BODY.INCLUSIVE OF THE REPAIR OF FRONT DOOR ARCH PANEL RH.		1,480.00	1,200.00
	REMOVE & INSTALL FRONT DOOR GLASS,BOARD,LOCK & ETC.		120.00	60.00
	REMOVE & INSTALL SEATS,CARPETS & ETC.		230.00	100.00
	TUFF-KOTE ON DAMAGE PARTS.		160.00	80.00
	SPRAY PAINTING ON DAMAGE PARTS.		1,280.00	900.00
	CHECK ALL LIGHTING AFTER REPAIRS.		30.00	20.00
	BODY LETTERING ON FRONT DOOR.		100.00	100.00
			3,400.00	2,460.00
	GRAND TOTAL		10,803.95	6,680.11
RECOMMENDED COST OF REPAIRS				6,680.11

Report Ref No. CS/FCI19010919/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.