

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0273/2019
DATE : 22-JUN-2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 63387288
FAX : 68804838/ 3382522
MS LINA EXT: 824

OWNER'S NAME : MEHTA SHEKHAR
ADDRESS : 185 TANJONG RHU ROAD
#04-01
S(436924)
TELEPHONE NO :

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : GA466859/1
VEHICLE NO : SLW6178T
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YC55581
CHASSIS NO : JF1SJ5KC5JG104369
MILEAGE : 20595 KM
DATE IN : 22/06/2019
LIABILITY : 0.00
EXCESS CLAUSE : 1100.00
ESTIMATE BY : MOHAMED ISMAN BIN MOHAMED HEPBUN**
ACCIDENT DATE : 18/06/2019

Print Date : 13/07/2019
Print Time : 14:03:42

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLW6178T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ODCLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM) AGAINST SLW6178T - AXA INSURED		
2	TOWACC	VEHICLE TOWED TO MOTOR IMAGE DUE TO ACCIDENT	180.00	180.00
3	ZZ/001	CONDCUT OD CLAIM DATE:18/06/2019 TIME:1000HRS LOCATION:SANCTUARY GREEN CONDO BASEMENT CARPARK		
4	ZZ/002	REPAIR/REPLACE FORNT BUMPER,RH FRONT FENDER & BONNET	1680.00	1680.00
5	ZZ/003	RESPRAY FRONT BUMPER,RH FRT FENDER,RH FRT DOOR & BONNET	1680.00	1680.00
6	ZZ/004	FAULT DIAGNOSTIC	280.00	280.00
7	ZZ/005	TO CONDUCT FRONT LIGHTING TEST	50.00	50.00
8	ZZ/006	REMOVE/REFIX FRT HAEDLAMP WASHER & PIPING	150.00	150.00
TOTAL LABOUR CHARGES			4020.00	4020.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLW6178T

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	CASE-AIR CLNR UPR	46052AG070	108.00			OK
2	CASE-AIR CLNR LWR	46052SG000	36.00			OK
3	WHEEL APR FF C RPRH	51610SG1209P	172.80			OK
4	RAD PNL COMPL SDR	53029SG0509P	45.00			X
5	FRT FENDER RH (W/O SIGNAL LP)	57120SG0209P	270.00			OK
6	EXT FENDER F CP RH (SUPP)	57160SG0009P	25.20			X
7	HOOD F CPL	57229SG0009P	882.00			OK
8	HINGE COMPL F HD RH	57260SG0009P	43.20			OK
9	HINGE COMPL F HD LH	57260SG0109P	43.20			OK
10	BRKT CORNER F RH	57707SG000	36.00			OK
11	BRKT SD F RH	57707SG020	12.60			OK
12	MOLDING BMRP F PDI PARTS	57708SG000A	43.20			OK
13	FRT BUMPER	57709SG030A	594.00			OK
14	BACK BEAM CPL F	57711SG0009P	288.00			OK
15	ENERGY ABSOR F	57722SG020	126.00			OK
16	WSTR OUT DR F RH (SUPP)	61280SG020			100.80	X
17	LAMP ASSY HEAD EOF	84002SG222	2380.00			OK
18	BRKT F FOG ASSY RH PDI PARTS	84927SG020A	19.80			OK
19	NOZZLE COVER ASSY RH PDI PARTS	86636SG380A	54.00			OK
SUB TOTAL			5108.80	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			1021.76	0.00	0.00	0.00
GRAND TOTAL			4087.04	0.00	0.00	0.00
OVERALL TOTAL			4087.04			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLW6178T

NETT ITEM	5108.80
LESS 20 %	-1021.76
NETT AMOUNT	4087.04
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	0.00
S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00
TOTAL LABOUR CHARGES	4020.00
TOTAL SPARE PARTS CHARGES	4087.04
TOTAL CHARGES	8107.04
LESS EXCESS	1100.00
TOTAL	7007.04
ADD 7 % GST	490.49
GRAND TOTAL	7497.53