



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CC4/EGI19010944/Kha3q2		
5 TEMASEK BOULEVARD #04-05 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 08-05-2020		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YN 1305U	Veh. Inspected	SHD 5291C
	Policy No.	DMCG18002599	Coverage (\$)	0.00
	Claim No.	YN1305U/SL/jc	Excess (\$)	0.00
	Assign From	JEANNIE	Assign Date	20/06/2019
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTDKB3FU903078743	Colour	METALLIC WHITE / RED
	Odometer	41222	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	YOKOHAMA	8 mm
	L/H Front Tyre	195/65 R15	YOKOHAMA	8 mm
	R/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm
	L/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	18/06/2019	Inspection Date	20/06/2019
	Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	