

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 24 Jun 2019

Preliminary Advice

Vehicle No	: SGM3813A	Accident Date	: 06/06/2019
Make	: MITSUBISHI LANCER EVOLUTION IX	Policy No.	: DMPCSN1760351801
Assignment Date	: 21/06/2019	Excess	: S\$1,000.00
Date of Inspection	: 21/06/2019	Est. Duration of Repair	: 24 days
Inspection At	: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, and parts claimed are consistent to the accident. The undercarriage & body structure affected due to collision.

Repairer's Estimate (Gross)	:S\$	35,409.65
Revised Amount	:S\$	27,011.15
Check Items (Estimated)	:S\$	8,264.50
Total	:S\$	35,275.65

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	32,060.00
Salvage Value	:S\$	
Margin for Repair	:S\$	49,940.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :