

TUNED PERFORMANCE PTE LTD

C/O REG: 201905120W

AIG INSURANCE
78 SHENTON WAY #07-16
SINGAPORE 079120

D.O.A: 17-06-2019
VEHICLE NUMBER: SKZ4043H
MAKE/MODEL: TOYOTA HARRIER
CHASSIS NUMBER: ZSU600062596

QTY	PARTICULARS	UNIT PRICE-SGD
<u>PARTS REPLACEMENT- LIST ITEMS</u>		
1	REAR BUMPER <i>distorted (upper & lower)</i>	1720.00 ✓
2	REAR BUMPER SIDE RETAINER <i>HN</i>	125.00 X
1	REAR BUMPER REINFORCEMENT <i>HF</i>	700.00 X
2	REAR BUMPER REFLECTOR <i>HN</i>	375.00 X
1	REAR EXHAUST PIPE <i>HN</i>	950.00 X
1	REAR BUMPER SPONGE <i>turn</i>	135.00 ✓
4	REAR REVERSE SENSOR <i>replaced</i>	880.00 X
1	END PANEL <i>ray</i>	1220.00 X
1	END PANEL TOP GARNISH <i>HN</i>	570.00 X
1	TAILGATE <i>Dented</i>	1715.00 ✓
1	TAILGATE EMBLEM <i>Hec</i>	85.00 ✓
1	TAILGATE EMBLEM HARRIER <i>Hec</i>	135.00 ✓
1	TAILGATE LOCK <i>HN</i>	385.00 X
1	TAILGATE LOCK CATCH <i>HN</i>	180.00 X
1	TAILGATE RUBBER <i>Hec</i>	375.00 ✓
1	TAILGATE GLASS MOULDING <i>Hec</i>	175.00 ✓
	<i>LHR Tail lamp crack</i>	<i>533.70</i> ✓
		9725.00
	LESS 25%	2431.25
	SUBTOTAL	7293.75
	BALANCE C/F	7293.25
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	BALANCE B/F	7293.25
1SET	REAR BUMPER CLIP <i>Hec</i>	<i>50 30/-</i>
1SET	REAR REVERSE SENSOR <i>Dam</i>	<i>400 220/-</i>
1	JOINT SEALANT <i>HN</i>	150 X
1	WINDSCREEN SEALANT <i>Hec</i>	<i>150 40/-</i>
		290.00
	SUBTOTAL	750
	BALANCE C/F	8043.25

S/NO	LABOUR AND MISCELLANEOUS CHARGES	
	BALANCE B/F	8043.25
1	CHECK REAR WIRING AND LIGHTING SYSTEM	60 30/-
2	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	200 80/-
3	REMOVE AND RENEW REAR REVERSE SENSOR	150 40/-
4	REMOVE AND STRAIGHTEN REAR EXHAUST	150 ru
5	REMOVE AND REFIT REAR WINScreen	150 120/-
6	TRANSFER PARTS, ATTACHMENT FROM OLD TO NEW TAILGATE	200 60/-
7	PANEL BEATING ON AFFECTED AREAS	1200 700/-
8	SPRAY PAINTING ON AFFECTED AREAS	1400 700/-
9	APPLY ANTI RUST ON AFFECTED AREAS	150 40/-
	SUBTOTAL	3660
	GRAND TOTAL	11703.25

5715.27

20/06/2019 @ 1030am

L/S 4500/-

NA Amount

L/Sum

6000/-

yan

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: