

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Yap, Weijoe

Date: 28 Jun 2019

Preliminary Advice

Vehicle No	: SKM8225S	Accident Date	: 20/06/2019
Make	: AUDI Q7	Policy No.	: 2100483999
Assignment Date	: 21/06/2019	Excess	: S\$500.00
Date of Inspection	: 21/06/2019	Est. Duration of Repair	: 3 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	33,793.00 (inclusive supp)
Revised Amount	:S\$	9,296.00 (inclusive supp)
Check Items (Estimated)	:S\$	10,635.00
Total	:S\$	19,931.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	195,000.00
COE / PARF Rebate	:S\$	98,998.00
Salvage Value	:S\$	
Margin for Repair	:S\$	96,002.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 903.00