	Adrian	ASSIGNM	ENT (Office)	
From (Person)	Ivy Rahlla	of	AGI	Dute/Time: 24.6.19 3.51 P
Estimated Con	E		Bill to:	
To Inspect Ve	hicle No: SIK 19	12	CS	Insured: SER 63734
	als SM Automob			Tel:
of I EQU	BURST AVE 6 B	It ( #01-4		
Policy No:			Claim No:	C10003539 12W
Sum Insured:			Excess:	
Make of Veh: (Client's Record				D.O.A. 24.6 2017
CA / REV /	REP. / REV 24 HRS	Person Contacted	sury	Vehicle IN LOUT
Date/Time	Action/instruction (	) Estimat	P	
				sna she know Adrian is on
	Lears mon a			
	Slk 19172 1/			
	Continue de	1		D-0-A:15 05 100 16

LUMBURG

#### Nivitha (LKK Auto)

From:

Ivy Ratilla <ivy.r@budgetdirect.com.sg>

Sent:

Monday, 24 June 2019 3:51 PM

To:

Admin-D (LKKAuto) SUR; Justin Wong

Cc: Subject:

TPPD Survey: Claim ref:C10003339/JW || OI- SGR6373G (Red) TP- SLK1917Z ||

Est:0.00 || SM Automotive

Attachments:

SLK1917Z PRI.pdf

Hi Team,

We would like to arrange TP PRS for SLK1917Z. Please see below email for reference.

They have chosen Mr. Mohamad Taufihk

Kindly confirm.

Regards,

Ivy

Admin Executive, Claims

T +65 6540 2185 F +65 6725 0853

E ivy.r@budgetdirect.com.sg



Trusted Service Award

Claims +65 6221 2111 Claims +65 6221 2199 Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01 Singapore Shopping Centre Singapore 239924 budgetdirect.com.sq

# auto 🗟 general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as <u>Budget</u> <u>Direct Insurance</u>.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: sm automotive <sm automotive@hotmail.com>

Sent: Monday, 24 June 2019 2:59 PM

To: Ivy Ratilla <ivy.r@budgetdirect.com.sg>; Claims <claims@budgetdirect.com.sg>

Cc: Justin Wong <justin.wong@budgetdirect.com.sg>

Subject: Re: SLK1917Z CLAIMING AGAINST SGR6373G DOA:24.06.19 | C10003339/JW

Without Prejudice

Hi Ivy

Please arrange :-

Mohamad Taufihk LKK Auto Consultants Pte Ltd

Regards,

# Sukyi Chong SM AUTOMOTIVE

1 Kaki Bukit Ave 6 Blk C #01-43 Singapore 417883

Tel: 6747 9241 Fax: 6741 7276

From: sm automotive <sm automotive@hotmail.com>

Sent: Monday, 24 June 2019 12:52 PM To: Claims <claims@budgetdirect.com.sg>

Subject: SLK1917Z CLAIMING AGAINST SGR6373G DOA:24.06.19

Without Prejudice

Hi Motor Claim Dept

Please send us your surveyor list, thanks.

Regards,

# Sukyi Chong SM AUTOMOTIVE

1 Kaki Bukit Ave 6 Blk C #01-43 Singapore 417883

Tel: 6747 9241 Fax: 6741 7276

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the

stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.



#### Vezel Used Vehicle List (20 vehicles)

Car Model Price Depreciation Reg Date Eng Cap Mileage Company Availability Honda Vezel 1.5A S \$75,800 \$9,000 /yr 01-Jan-2017 1,496 cc 24,899 km Dickson Automobile Available

Low Interest Rate From 1.99%! In-house Loan Available! Full Accessories Equipped! Like Brand New! An Economical, Stylish And Powerful SUV That Would Appeal To Both Urbanites And Rugged Prospects. Buy ...

Office No. - 68447667

Tank Ong - 85265670 | Beatrice Teo - 81287619 | Eric Lee - 91827304

Honda Vezel 1.5A X \$71,800 \$8,700 /yr 04-Jan-2017 1,496 cc 20.329 km Wheeler Dealers 2018 Pte Available

Driven By Only 1 Mature Owner Since Day 1! Premium High Grade Leathers Seats! Perfect Glossy Blue Paintwork In Showroom Condition! Interior In Its Neat And Clean Look! No Different From New! Viewing L.,

Office No. - 67435323

Sam Tan - 93860913 | Yong - 90078000 | Jacky - 92972176

Available Honda Vezel 1.5A X \$71,800 \$8,730 AT 06-Jan-2017 1,496 cc 55,000 km Bliss Auto

1st Owner Unit! Premium Pearl White Honda Vezel 1.5A For Sale! (This 1s Not A P/H Carl.) Genuine Low Mileage Of 55000km Done Only! Very Mint Condition! Interior & Exterior Looks Like New! Drives Like A ...

Office No. - 67542808 James Phua - 97657171

Honda Vezel Hybrid 1.5A RS \$88,888 \$11,470 /vr 10-Jan-2017 1.496 cc 47,002 km Available Honda Sensing (Petrol-Electric)

Shelterad Car Park Everyd Ay. Only Hand Wash By Owner And No One Else. Car Exterior Shinny Even Without Wax Or Clear Coat Because 1 Use Sonax. Products For Washing. Average Petrol Consumption = 16.6Km/...

Office No. - -

Lim Yi Long - 90094424

Honda Vezel Hybrid 1.5A \$80,000 \$10,250 /yr 20-Jan-2017 1,496 cc 64,153 km Prem Roy Motoring Available

X (Petrol-Electric)

I Owner Only! Low Mileage Done! Not A Private Hirer Unit, Very Well Kept In Rare Condition. View And Believe, Buy It From Us With A Peace Of Mind, Discover The Greatness Of This Car. Consignment Unit!...

Office No. - 66028046

Zin - 90025579 ( Mark - 98896985

Honda Vezel 1.5A X \$70,800 \$8,670 /yr 25-Jan-2017 1,496 cc Prime Motor & Leasing Available

Elegant Silver SUV, One Owner Only, Low Maintenance Cost, Comes With Warranty, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available.

Office No. - 64440088

Connie - 91130008 | Andy - 91086443 | Mark - 84995146 | Pauline - 97810269

Honda Vezel Hybrid 1.5A X \$79,800 \$10,200 /yr 26-Jan-2017 1,496 cc 53,800 km Republic Auto Available

Honda Sensing (Petrol-Electric)

Most Popular SUV With Honda Sensing. Enjoy Exclusive Interest Rates At 2.48%, Please Call/SMS/Whatsapp Now For Enquiries And Viewing Appointment.

Office No. - 65672000 Edmund Lee - 84886999

Honda Vezel 1.5A X \$72,800 \$8,840 Art 10-Feb-2017 1,496 cc 25,000 km Laxis Available

100% Loan Available, We Are Full Loan Specialist, 1 Owner, Accident Free Unit, Act Now To Test Drive Now!

Jack - 84306433 | Catherine Lee - 90019707 | Kervin Chia - 88113768

Honda Vezel Hybrid 1.5A \$76,800 \$9,680 /yr. 03-Mar-2017 1,496 cc Presto Expat Motoring Available

X (Petrol-Electric) Services Pte Ltd

Well Maintained By Lady Expat Owner. Rejuctant Sale. Consignment Unit, Viewing By Appointment Only.

Office No. - 67327737

Chin - 96857377

Honda Vezel 1.5A X \$73,800 \$8,840 /yr 03-Mar-2017 1,496 cc 30,000 km Available "One Year In-House Warranty", High Loan Available, Price Stated Above Is Actual Selling Price, Bank And In-House Loan Available, Purchase Comes With Official Warranty Certificate For A Peace Of Mind, ...

Office No. - 68440777

Peter Quek - 84840777 | Tanisha - 88665777 | Addy Ho - 88330777

Honda Vezel 1.5A X

\$76,800

\$9,130 /yr

07-Mar-2017

1,496 cc

41,000 km

Motorist Pte Ltd

Available

Non PHV Unit! Low Depreciation With Regular Servicing, Well Maintained Unit. Loan Available From Interest Rates From 2.28%. Call Now To Book An Appointment To View This Beauty. Viewing Strictly Appoin...

Office No. - 65898800

Kanthan - 90225037 | Benedictine - 81813664

Honda Vezel Hybrid 1.5A X (Petrol-Electric)

\$80,200

\$10,100 /yr

10-Mar-2017

1,496 cc

4,900 km

Prime Motor & Leasing

Available

3 Years On 100000Km Warranty, High Trade In.

Office No. - 68984488

Eliz - 88680011 | Larry - 96861029 | Jack - 91096509

Honda Vezel 1.5A X

\$77,888

\$9,190 /yr

16-Mar-2017

1,496 cc

37,000 km Motorist Pte Ltd

Available

Low Mileage, \$3k Worth Of Lipgraded Audio System To Go With The Car. Still Linder Warranty, Road Tax Renewed. High Leans Up To 80% Of The Car Price With Lowest Interest Rates From 2.28%. Trade In Welcom...

Office No. - 65898800

Lionel - 93697866 | Kanthan - 90225037

Honda Vezel 1.5A X

\$75,800

\$9,010 /VT

16-Mar-2017 1,496 cc

40,000 km Oscars Auto

Available

(Flexible Loan) 1 Owner, Well Maintained, 100% Accident Free, Sheltered Parking, No Further Repairs Needed, Clean And Neat Interior, Showroom Conditions, High And Bank Loan Available! Call Us For More...

Office No. - 67488616 Allan Ching - 97396913

Honda Vezel 1.5A X

\$72,800

\$8,800 /yr

20-Mar-2017

1,496 cc

27.000 km Taxis Available

100% Loan Available, We Are Full Loan Specialist, 1 Owner, Accident Free Unit, Act Now To Test Drive Now.

Office No. - -

Jack - 84306433 | Catherine Lee - 90019707 | Kervin Chia - 88113768

Honda Vezel Hybrid 1.5A X Honda Sensing (Petrol-Electric) \$81,800

\$10,260 /vr

23-Mar-2017 1,496 cc

18,000 km

Available Creative Auto

1. Owner And Only 18k km Mileage. Most Popular SUV With Honda Sensing. Condition Is As Good As New, It Has Been In Extremely Good Care Of Owner. Always Parked In Shelter, Warranty Till Mar 2020, Why Bu ...

Office No. - -

Jeff Huang - 88180344 | Alex Tan - 97556887 | Terence Leow - 90290899

Honda Vezel 1.5A X

\$71,800

\$8,570 /VT

31-Mar-2017 1,496 cc

Prime Motor & Leasing

Available

Elegant White SUV, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-house Loan Packages Available.

Office No. - 64440088

Andy - 91086443 | Jordan - 91168032 | Mark - 84995146 | Pauline - 97810269

Honda Vezel 1.5A X

\$72,000

\$8,580 Art

06-Apr-2017 1,496 cc

Prime Motor & Leasing

Available

Elegant White SUV, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-house Loan Packages Available.

Office No. - 68723113

Larry - 96861029 | Eliz - 88680011 | Jack Ng - 91096509

Honda Vezel Hybrid 1.5A

RS (Petral-Electric)

\$89,600

\$11,210 /yr

07-Apr-2017

1,496 cc

49,000 km Monster Motors Pte Ltd

Available

100% Accident Free. 5 Years Warranty With Optima Werks. Turied By Honda Hybrid Specialist. Full Car Sound Proof Worth \$3000, Pioneer 5850, Original Leather Seats With Alcantara Foctures, V-Kool Solar F...

Office No. - -

Rachel - 88082170 | Jerome - 92369056

Honda Vezel 1.5A X

\$72,800

\$8,650 /yr

20-Apr-2017 1,496 cc

36,665 km Prime Car Traders Pte Ltd Available

Excellent Condition, Very Well Maintained By Previous Owner, 1 Owner Only Unit, Low Mileage, View To Believe, Bank Loan/Loan/In House Loan Available! Trade In Most Welcome! Call/SMS/WhatsApp Our Frien...

Office No. - 63166000

#### > Back to OneMotoring

#### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 5955F

Vehicle Details

Vehicle No.: SLK1917Z

Vehicle to be Exported: No

Intended Deregistration Date: 24 Jun 2019
Vehicle Make: HONDA

Vehicle Model: VEZEL 1.5X CVT

Primary Colour: Red Manufacturing Year: 2016

 Engine No.:
 L15B4403117

 Chassis No.:
 RU11203117

 Maximum Power Output:
 96.0 kW (128 bhp)

 Open Market Value:
 \$21.532.00

 Original Registration Date:
 09 Jan 2017

 First Registration Date:
 09 Jan 2017

Transfer Count: 0

Actual ARF Paid: \$12.145.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 08 Jan 2027 PARF Rebate Amount: \$9,108.00

Intended COE Rebate Details

COE Expiry Date: 08 Jan 2027

COE Category: A - Car up to 1600cc & 97kW

(130bhp)

COE Period(Years): 10

QP Paid: \$50,101.00
COE Rebate Amount: \$37,777.00
Total Rebate Amount: \$46,885.00

The information contained herein is correct as at 24 Jun 2019

OK

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT	
Date Of Report	24/06/2019 12:24	
Date Of Accident	24/06/2019 09:45	
Exact Location Of Accident BKE (PIE) BEFORE PIE (CHANGI EXIT)		
Country/State of Loss SINGAPORE		

	DETAILS OF OWN VEHICLE	
/ehicle Registration Number	SLK1917Z	

Vehicle Registration Number

Insured/Policyholder

Name Of Registered Owner

NRIC No Email Address

Mobile Phone No Alternative Phone No RUDY HERIANTO S8685955F

NOEMAIL (LOCAL) +65-86422180

OFFICE-86422180

Vehicle Particulars

Manufacturer

Model

Exact Purpose for which vehicle was being used at time of accident

VEZEL-1.5 (A) PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

HONDA

If No. Please state action to be taken

THIRD PARTY PRIVATE CAR

Insurance Company

Vehicle Category

Name of Insurance Company

DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD

COMPREHENSIVE Type Of Coverage

NO Fleet Policy

MT/00574713 Policy Number

Cover Note Number

Driver

RUDY HERIANTO Name of Driver

S8685955F NRIC No 22/10/1986 Date Of Birth INDOOR Occupation 27/11/2010 Date Of Driving Pass

8 YEARS AND 6 MONTHS Driving Experience

Gender

(LOCAL) +65-86422180 Mobile Number

Fax Number

OFFICE-86422180 Contact Number

NOEMAIL EMail Address

Address

54 CHOA CHU KANG NORTH 7 #06-36

Postcode

689529

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

20

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

YES

Foreign Vehicle Registration Number

JNQ6994 (PRIVATE CAR)

Number of vehicles (including own vehicle)

involved in the accident

5

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

25

**Details of Police Action** 

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

TRAFFIC POLICE DIVISION HQ

Police Station Address

ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

PLEASE REFER TO POLICE REPORT NO.T/20190624/7006

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SGR6373G

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

YP2075R

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

COMMERCIAL VEHICLE

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

JNQ6994

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### **DETAILS OF OTHER VEHICLE PROPERTY 4**

Vehicle Registration Number

SFK3012S

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

B SEKSOISS

E SEKSOISS

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Plea le	refer	to	bolice	report	7/2019	0624/7006
						1
						161
		_				
		_			y to the server	
		_				
		_				

DECLARATION

L/We declare the foregoing particulars are true in every respect.

Policyhelder's Signature

Oriver's Signature (if diwer a not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: NRIC/FIN No.:



#### SKLICH PLAN

# IMPORTANT NOTICE

- 1. Charter report particilly the details of the accident to speed up the city on process
- the first result to completed by the Policyhelder and/or the Authorised Driver
- information provided must be as givibble and according to possible. Any will descript exercision or withholding of material facts may alice neverter companies to remailists making liability
- 4. The insue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5 Any lake reporting may be referred to the Palice for investigation
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for architing and that copies of this report will for a fee be made available upon application by
- ? By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to cooles of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (POPA)

Lunderstand, acknowledge, agree and consent that

- (x) My insures, my workshop and the General Insurance Association of Singapore ("GLA") may/are permitted to collect, use. disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lewyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) ef :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims:
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packagesic and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/low firms), which may be slied outside of Singapore, for one or more of the showe Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detaction. investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing traud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (iii) for complying with requirements under any regulations, laws or court orders.

Driver's Signature (If driver is het the policyholder)

DIME & TIME!

Reporting Centre Personnel's Signature

NINC/FIN No.

CANADA TANGAMARKAN VI





Police Station Of Origin: Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

1 of 3 Report No. T/20190624/7006

DEDODT OF	A TOACEI	ACCIDENT
REPORT OF	AIRAFFIL	ALLIDENI

Date/Time Report Made: 24/06/2019 10:51		Made:	Vide Report No.:	Station Diary No.:	
Informa	nt's Partic	ulars			
Name of Informant: RUDY HERIANTO			Address: 54 CHOA CHU KANG NORTH 7 #06-36 SINGAPORE 689529		
ID Type / ID No.: NRIC NO / S8685955F			Contact No.: Home/Office: Mobile: 86422180		
Nationali INDONE	ty: SIAN		Email: rudyherianto@gmail.com		
Sex: Age: Date of Birth: Male 32 22/10/1986			Type of Informant: Driver		
Race: Chinese			Language: Institution / School Name English		
Occupation: ENGINEER			Driving Licence Information: Class: Date of Expiry:		

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 24/06/2019 09:45	Type of Location Straight Road	
Location: BUKIT TIMAH Weather: Clear	EXPRESSWAY	Road Surface:		Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control:		Traffic Volume: Moderate	
Type of Collis CHAIN COLL	ion: ISION HEAD TO REAR			Anyone conveyed by ambulance: No	

Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
JNQ6994	Car					0
SFK3012S	Car					0
SGR6373G	Car					0
SLK1917Z	Car	HONDA	VEZEL 1.5X	Red		0
YP2075R	Lorry					0





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865

10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

2 of 3 Report No. T/20190624/7006

Details of Vehicle Insurance					
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date	
SLK1917Z	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	MT/00574713	09/01/2019	08/01/2020	

Any Pedestrian I	nvolved: No				
No. of Pedestriar	s Injured: NIL	Use of Pedestrian Crossing: NA			ing: NA
Driver	EL CONTROL SON CONTROL SON CONTROL SON	AND SERVICE AND SE	A PROPERTY	18X3419	LOSSOF MINERAL LATER OF THE PARTY OF THE PAR
Name	RUDY HERIANTO		ID No		S8685955F
Related Vehicle	SLK1917Z (Car)		Conta	ct No.	86422180
Hospital/Clinic	NIL		Class Drivin Licen Expin	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Disc	charge	NIL	
No. of Days gran	ted Medical Leave NIL	Degree o			

#### Brief Details.

I was driving SLK1917Z travelling straight along BKE(PIE) before PIE(Changi) Exit on the second lane out of three lanes.

Front vehicle "E" (SFK3012S) braked his vehicle, I followed suit and stopped.

Suddenly, I felt a strong impact, vehicle B (SGR6373E) had hit onto the rear portion of my vehicle. The strong impact caused my vehicle to surge forward and hit onto Vehicle "E" (SFK3012S).

After the accident, I alighted and realised it was a 5 car chain collision involving

Vehicle A - SLK1917Z Vehicle B - SGR6373G Vehicle C - YP2075R Vehicle D - JNQ6994 Vehicle E - SFK3012S





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

3 of 3 Report No. T/20190624/7006

CONTINUATION OF REPORT

	14-1	4 - 4-	-	an
-	K O	ton	-	on.

NP168

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 24/06/2019 10:51
Officer In Charge Of Case: TP / TPIB / ANG YI TING, STEPHANIE Contact No.: 65476414	Classification Of Case:
Authentication Stamp	

# SM &UTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883 Email: SM\_AUTOMOTIVE@HOTMAIL.COM Fax: (65) 6741 7276 Tel: (65) 6747 9241

RCB No.: 53231488C

24/06/2019

RUDY HERIANTO Blk 1 Kaki Bukit Ave 6 # 01-43 Singapore 417883

TP Budget Direct

Accident date: 24/06/2019

Estimated repair cost for vehicle no: SLK1917Z HONDA VEZEL 1.5X A '17

		CHASSIS: RU11203117	U/price	Amount
S/n	Qty	Items		\$892.30
1	1	Front Bonnet Best	\$48.50	\$97.00
2	2	Front Bonnet Hinge Bevt		\$97.80 ~
3	1	Front Bonnet Lock Deg		\$122.30
4	1	Front Bonnet Insulator He me	\$6.50	\$52.00
5	8	Front Bonnet Insulator Clip > ~ ~	\$37.50	\$75.00 ×
6	2	Front Bonnet Inner Side Rubber KM New	\$23.00	\$46.00 -
7	2	Front Bonnet Inner Centre Rubber > H	\$1,820.90	\$3,641.80
8	2	Front Head Lamp Conclud	\$35.00	\$70.00
9	2	Front Head Lamp Lower Bracket Zoulcd	<b>433.00</b>	\$801.70
10	1	Front Bumper Distorted	\$6.50	\$65.00
11	10	Front Bumper Clip AL	\$27.10	\$54.20
12	2	Front Bumper Side Retainer	<b>J27.12</b>	\$50.00
13	1	Front Bumper Number Plate and d		\$96.80
14	1	Front Bumper Centre Lower Garnish Deld		\$321.00
15	1	Front Bumper Reinforcement 3ext	\$24.20	\$48.40
16	2	react Bumper Reinforcement 100 Cover		\$26.00
17	4	Front Bumper Reinforcement Top Cover Clip 344	\$0.50	\$15.70
18	1	Front Bumper Towing Cover		\$351.00
19	1		\$327.70	\$655.40
20	2	Front Bumper Fog Lamp	\$45.00	\$90.00
21	2	Front Bumper Fog Lamp Cover Zouleed	<b>V</b> .13.00	\$465.00
22	1			\$351.80
23	1	Front Grille Inner Child		\$38.70
24	1			\$75.00
25	1	Front Grille Chrome NL M	\$6.50	\$52:00
26	8	Front Grille Clip New	<b>\$5.50</b>	\$576.20
27	į.	1 Front Support Panel Buckled		\$85.30
28		1 Front Support Panel Top Cover Deformed		Ç03.50

1.0				
29	10	Front Support Panel Top Cover Clip New	\$6.50	\$65:00 22
30	2	Front Support Panel Side Air Duct Cover NH M		\$77.50 *
31	8	Front Support Panel Side Air Duct Cover Clip 14 ~	\$6.50	\$52.00 +
32	1	Front Air-Con Condenser Deutco		\$750.10
33	1	Front Radiator Deuted		\$1,250.60
34	1	Front Radiator Fan Motor Assy Tanda		\$480.90 2
35	1	Rear Boot Lid Peuted		\$1,100.90
36	2	Rear Boot Lid Hinges 744 Man	\$68.10	\$136.20 *
37	2	Rear Boot Lid Shock Absorbers > > - >	\$180.90	\$361.80 *
38	1	Rear Boot Lid Emblem Logo Add Mar		\$45.10 +
39	1	Rear Boot Lid Vezel Logo		\$56.30 -
40	1	Rear Boot Lid Camera (Special Nett) Hem		\$550.00 }-
41	1	Rear Boot Lid Number Plate ** 1-		\$50.00+
42	2	Rear Boot Lid Number Plate Lamp > ~ ~	\$38.50	\$77.00 +
43	2	Rear Boot Lid Side Reflector Lut	\$284.60	\$569.20
44	1	Rear Boot Lid Inner Lock Dange		\$185.60
45	1	Rear Boot Lid Inner Rubber 64		\$135.25
46	1	Rear Boot Lid Inner Trim Board Trulell		\$355.75
47	1	Rear Boot Lid Inner Trim Board Side Handle Cover &	et co	\$55.80 ~
48	1	Rear Boot Lid Windscreen Seal Zun		\$151.70 -
49	2	Rear Boot Lid Windscreen Side Moulding	\$75.00	\$150.00
50	2	Rear Tail Lamp Let	\$474.60	\$949.20
51	2	Rear Tail Lamp Panel 245	\$135.70	\$271.40 +
52	4	Rear Tail Lamp Clips	\$8.00	\$32.00
53	2	Rear Tail Lamp Lower Bracket New	\$18.10	\$36.20
54	2	Rear Tail Lamp Lower Cover The d	\$198.70	\$397.40
55	1	Rear Bumper Distarted	West (1972 - 20072)	\$801.70 ~
56	2	Rear Bumper Side Retainer	\$29.20	\$58.40
57	2	Rear Bumper Side Reflector	\$148.40	\$296.80
58	1	Rear Bumper Reverse Sensor (Special Nett)		\$350.00-2 00
59	1	Rear End Panel Distorted		\$595.60
60	1	Rear End Panel Top Garnish 24		\$122.30
51	1	Rear End Panel Antenna		\$98.10
62	1	Rear End Panel Buzzer PHCA-		\$85.50 *.
63	2	Rear Fender Russ	\$931.80	\$1,863.60 *
64	2	Rear Fender Protector	\$150.20	\$300.40
65	2	Rear Fender Cowling Ht could	\$105.30	\$210.60
66	12	Rear Fender Cowling Clip NC ~	\$6.50	\$78.00
67	2	Rear Fender Inner Trim Board	\$325.25	\$650.50
68	16	Rear Fender Inner Trim Board Clip 744	\$6.50	\$104:00 6
69	1	Rear Spare Tyre Panel Distorted		\$662.20
70	2	Rear Spare Tyre Side Panel	\$125.70	\$251.40 /
71	1	Rear Spare Tyre Panel Top Cover Delan		\$306.65

72	1	Rear Spare Tyre Panel Lower Cover Deld		\$190.90
73	1	Rear Spare Tyre Panel Foam Tool Box De lond		\$226.70
74	1	Rear Spare Tyre Under Cover Percented		\$190.90 +
75	8	Rear Spare Tyre Under Cover Clips Her	\$6.50	\$52,00 30
76	1	Rear Exhaust But		\$868.00 2
77	1	Rear Center Exhaust / >>		\$986.00 *
78	4	Rear Exhaust Mounting MM	\$25.60	\$102.40 &
79	1	Rear Exhaust Aluminum Cover Pisto-led		\$105.00 \$
		,		

20564.75 S.N.200 16451-80 Subtotal:-\$27,213.95

# Labour charges

To remove & refit cu	shion		\$280,00 80
To remove & refit air & top up gas	r-con condenser, radiator, fan motor		\$380.00 125
To remove & refit re	verse sensor		\$100,00 50
To remove & refit re	ar & center exhaust		\$380.00 80
To remove & refit re	ar camera		\$180.00 50
To remove & refit re	ar windscreen	4630	\$120.00
Gum NEC	LKK Auto Consultants hence notify the Repairer of the following:		\$50.00
To check wiring	To resurvey before latter spray painting To display damaged partial during resurvey Parts prices are subject to continuation.		\$190.00 60
Tuff kote	Third party survey is on a "Wimout Prejudice" basis No illegal modification is allowed. Supplementary remiss must be resurveyed and is subject to final approval from insurance Company.		\$150.00 60
Towing fee	Acknowledged by Repairer Signature:		\$150.00 60
Panel beating	Adrian L		\$3,500.00 2300
Spray painting	Adrian L.	9.	\$2,800.00 1600
	1 S Days	Subtotal :-	\$8,190.00

\$35,403.95



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to	Federation	Internationale Des	Experts En	Automobile
---------------	------------	--------------------	------------	------------

AUTO & GENERAL INSURANCE (S) PL

Ref: CS/AGI19011091/Atd3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE

Date: 01-08-2019



			Code: AGI	
1.		Policy Partic	culars :- THIRD PARTY CLA	IM
	Insured Veh.	SGR 6373G	Veh. Inspected	SLK 1917Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10003339/JW	Excess (\$)	0.00
	Assign From	IVY RATILLA	Assign Date	24/06/2019
2.		Vehicle	Particulars & Condition	
	Make & Model	HONDA VEZEL	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	RU11203117	Colour	RED
	Odometer	64279	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.			Conditions of Tyres	Carried to the
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	DUNLOP	6 mm
	L/H Front Tyre	215/60 R16	DUNLOP	6 mm
	R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
	L/H Rear Tyre	215/60 R16	DUNLOP	6 mm
4.		Des	scription of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT T	THE FRONT AND REAR PORTIO	ON.
	DAMAGES SEE D	ETAILS.		
5.	30 43	G	General Information	
	Accident Date	24/06/2019	Inspection Date	26/06/2019
	Survey held at	SM AUTOMOTIVE		
		BLK C, 1 KAKI BUKIT AV	VENUE 6 #01-43 SINGAPORE 4	17883
5a.			Remarks	
			N A"WITHOUT PREJUDICE" BAS ONS, WE HAVE NOT AUTHORI	
5b.	To the second second		stimate Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAI	R: 15 Working D	avs



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

# ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 1917Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	BENT	892.30	892.30
2	FRONT BONNET HINGE @\$48.50	BENT	97.00	97.00
1	FRONT BONNET LOCK	DAMAGED	97.80	97.80
1	FRONT BONNET INSULATOR	NOT NECESSARY	122.30	
8	FRONT BONNET INSULATOR CLIP @\$6.50	NOT NECESSARY	52.00	
2	FRONT BONNET INNER SIDE RUBBER @\$37.50	NOT NECESSARY	75.00	
2	FRONT BONNET INNER CENTRE RUBBER @\$23.00	NOT NECESSARY	46.00	
2	FRONT HEAD LAMP @\$1820.90	CRACKED	3,641.80	3,641.80
2	FRONT HEAD LAMP LOWER BRACKET @\$35.00	CRACKED	70.00	70.00
1	FRONT BUMPER	DISTORTED	801.70	801.70
10	FRONT BUMPER CLIP @\$6.50	NECESSARY	65.00	30.00
2	FRONT BUMPER SIDE RETAINER @\$27.10	NECESSARY	54.20	54.20
1	FRONT BUMPER NUMBER PLATE	CRACKED	50.00	50.00
1	FRONT BUMPER CENTRE LOWER GARNISH	DEFORMED	96.80	96.8
1	FRONT BUMPER REINFORCEMENT	BENT	321.00	321.00
2	FRONT BUMPER REINFORCEMENT TOP COVER @\$2	4.20 NOT NECESSARY	48.40	
	FRONT BUMPER REINFORCEMENT TOP COVER CLIP @\$6.50		26.00	
1	FRONT BUMPER TOWING COVER	DEFORMED	15.70	15.70
1	FRONT BUMPER LOWER SPOILER	DEFORMED	351.00	351.0
2	FRONT BUMPER FOG LAMP @\$327.70	CRACKED	655,40	655.4
2	FRONT BUMPER FOG LAMP COVER @\$45.00	CRACKED	90.00	90.0
1	FRONT GRILLE OUTER GARNISH	CRACKED	465.00	465.0
1	FRONT GRILLE INNER	CRACKED	351.80	351.8
1	FRONT GRILLE TOP BRACKET	CRACKED	38.70	38.70
1	FRONT GRILLE CHROME	NOT NECESSARY	75.00	
8	FRONT GRILLE CLIP @\$6.50	NECESSARY	52.00	20.0
1	FRONT SUPPORT PANEL	BUCKLED	576.20	576.2
1	FRONT SUPPORT PANEL TOP COVER	DEFORMED	85.30	85.3
10	FRONT SUPPORT PANEL TOP COVER CLIP @\$6.50	NECESSARY	65.00	20.0
2	FRONT SUPPORT PANEL SIDE AIR DUCT COVER	NOT NECESSARY	77.50	
8	FRONT SUPPORT PANEL SIDE AIR DUCT COVER CLI @\$6.50	P NOT NECESSARY	52.00	
1	FRONT AIR-CON CONDENSER	DENTED	750.10	750.1

Report Ref No. CS/AGI19011091/Atd3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RADIATOR	DENTED	1,250.60	1,250.60
1	FRONT RADIATOR FAN MOTOR ASSY	CRACKED	480.90	480.90
1	REAR BOOT LID	DENTED	1,100.90	1,100.90
2	REAR BOOT LID HINGES @\$68.10	NOT NECESSARY	136.20	
2	REAR BOOT LID SHOCK ABSORBERS @\$180.90	NOT NECESSARY	361.80	
1	REAR BOOT LID EMBLEM LOGO	NOT NECESSARY	45.10	
1	REAR BOOT LID VEZEL LOGO	NECESSARY	56.30	56.30
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	
2	REAR BOOT LID NUMBER PLATE LAMP @\$38.50	NOT NECESSARY	77.00	
2	REAR BOOT LID SIDE REFLECTOR @\$284.60	CUT	569.20	569.20
1	REAR BOOT LID INNER LOCK	DAMAGED	185.60	185.60
1	REAR BOOT LID INNER RUBBER	CUT	135.25	135.25
1	REAR BOOT LID INNER TRIM BOARD	CRACKED	355.75	355.75
1	REAR BOOT LID INNER TRIM BOARD SIDE HANDLE COVER	NOT NECESSARY	55.80	
1	REAR BOOT LID WINDSCREEN SEAL	NECESSARY	151.70	151.70
2	REAR BOOT LID WINDSCREEN SIDE MOULDING @\$75.00	NECESSARY	150.00	150.00
2	REAR TAIL LAMP @\$474.60	CUT	949.20	949.20
2	REAR TAIL LAMP PANEL @\$135.70	TO REPAIR SEE LABOUR	271.40	
4	REAR TAIL LAMP CLIPS @\$8.00	NECESSARY	32.00	32.00
2	REAR TAIL LAMP LOWER BRACKET @\$18.10	NOT NECESSARY	36.20	
2	REAR TAIL LAMP LOWER COVER @\$198.70	DEFORMED	397.40	397.40
1	REAR BUMPER	DISTORTED	801.70	801.70
2	REAR BUMPER SIDE RETAINER @\$29.20	NECESSARY	58.40	58.40
2	REAR BUMPER SIDE REFLECTOR @\$148.40	CRACKED	296.80	296.80
1	REAR END PANEL	DISTORTED	595.60	595.60
1	REAR END PANEL TOP GARNISH	DEFORMED	122.30	122.30
1	REAR END PANEL ANTENNA	CRACKED	98.10	98.10
1	REAR END PANEL BUZZER	NOT NECESSARY	85.50	
2	REAR FENDER @\$931.80	TO REPAIR SEE LABOUR	1,863.60	
2	REAR FENDER PROTECTOR @\$150.20	NOT NECESSARY	300.40	
2	REAR FENDER COWLING @\$105.30	N/S CRACKED	210.60	105.30
12	REAR FENDER COWLING CLIP @\$6.50	NOT NECESSARY	78.00	
2	REAR FENDER INNER TRIM BOARD @\$325.25	CRACKED	650.50	650.50
16	REAR FENDER INNER TRIM BOARD CLIP @\$6.50	NECESSARY	104.00	60.00

Report Ref No. CS/AGI19011091/Atd3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SPARE TYRE PANEL	DISTORTED	662.20	662.20
2	REAR SPARE TYRE SIDE PANEL @\$125.70	TO REPAIR SEE LABOUR	251.40	
1	REAR SPARE TYRE PANEL TOP COVER	DEFORMED	306.65	306.65
1	REAR SPARE TYRE PANEL LOWER COVER	DEFORMED	190.90	190.90
1	REAR SPARE TYRE PANEL FOAM TOOL BOX	DEFORMED	226.70	226.70
1	REAR SPARE TYRE UNDER COVER	REPEATED	190.90	
8	REAR SPARE TYRE UNDER COVER CLIPS @\$6.50	NECESSARY	52.00	30.00
1	REAR EXHAUST	BENT	868.00	868.00
1	REAR CENTER EXHAUST	NOT NECESSARY	986.00	
4	REAR EXHAUST MOUNTING @\$25.60	NOT NECESSARY	102.40	
1	REAR EXHAUST ALUMINUM COVER	DISTORTED 662.20 TO REPAIR SEE LABOUR DEFORMED 306.66 DEFORMED 190.90 DEFORMED 190.90 REPEATED 190.90 NECESSARY 52.00 BENT 868.00 NOT NECESSARY 986.00 NOT NECESSARY 102.40 DISTORTED 105.00  26,313.90 NOT NECESSARY 550.00 380.00 380.00 180.00 150.00 150.00 150.00 150.00	105.00	
	LESS 20% DISCOUNT		5.0	-4,112.95
		26,313.95	16,451.80	
	SPECIAL NETT ITEMS			
1	REAR BOOT LID CAMERA (SN)	NOT NECESSARY	550.00	
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
1	GUM (SN)	NECESSARY	50.00	50.00
		N .	950.00	250.00
	LABOUR			
	TO REMOVE & REFIT CUSHION.		280.00	80.00
	TO REMOVE & REFIT AIR-CON CONDENSER, RADIATOR, FAN MOTOR & TOP UP GAS.		380.00	120.00
	TO REMOVE & REFIT REVERSE SENSOR.		100.00	50.00
1 1 1	TO REMOVE & REFIT REAR & CENTER EXHAUST.		380.00	80.00
	TO REMOVE & REFIT REAR CAMERA.		180.00	50.00
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00
	TO CHECK WIRING.		100.00	60.00
	TUFF KOTE.		150.00	60.00
	TOWING FEE.		150.00	60.00
	PANEL BEATING INCLUSIVE OF THE REPAIR OF REAR TAIL LAMP PANEL, REAR FENDER AND REAR SPARE TYRE SIDE PANEL.		3,500.00	2,300.00
	SPRAY PAINTING.		2,800.00	1,600.00
	LABOUR TO REMOVE & REFIT CUSHION. TO REMOVE & REFIT AIR-CON CONDENSER, RADIATOR, FAN MOTOR & TOP UP GAS. TO REMOVE & REFIT REVERSE SENSOR. TO REMOVE & REFIT REAR & CENTER EXHAUST. TO REMOVE & REFIT REAR CAMERA. TO REMOVE & REFIT REAR WINDSCREEN. TO CHECK WIRING, TUFF KOTE. TOWING FEE. PANEL BEATING, INCLUSIVE OF THE REPAIR OF REAR TAIL LAMP PANEL, REAR FENDER AND REAR SPARE TYRE SIDE PANEL. SPRAY PAINTING.	8,140.00	4,580.00	
	GRAND TOTAL		35,403.95	21,281.80

Report Ref No. CS/AGI19011091/Atd3n2



Page No.:4 of 4

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	17,000.00
--	-----------

Report Ref No. CS/AGI19011091/Atd3n2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whetevever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.