

154200

INS. CASE OWNER:

CC 4 / AIG1901

1092, B dls

LKK:

IDAC:

Surveyor:

MR Lim

DOI:

ASSIGNMENT

24/6/19

Date / Time:

24/6/19

Registered in Meritum:

24/6/19

Pre-assign / CCU / FTE

SUP 6935L



Insured Vehicle No.:

LAU SIEW TEE

Claim No.:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

Place of Accident:

Is driver the owner?

(YES) (NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SGZ 3217C

INSRS:
WSP:
Tel:
Liability:
RMKS:

Team Antopro

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

30/10/19

FILE PAS TO TYPE MANDATE

12/3/2020

FILE PAS TO LSL TO CLIVE

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 9/3/2020

Confirm with Ade

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

22-

If NO or B 28, Ass. Lia

Repair Cost:

SS 8350.00

Loss of Rental (LOR):

SS 1100.00

(11 days) x \$100

Loss of Use (LOU):

SS -

(\$ x days)

Loss of Income (LOI):

SS -

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

SS 7.45

Medical:

SS -

Disbursement:

SS 90.00

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS 9547.45

Global Sum SS: 9350.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 9350.00

Name 1:

Team Antopro Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
12/3/2020

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SGZ 3217C**
Model : Honda Jazz
Year : _____
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Tailgate	1	\$ 903.60	\$ 830.60 903.60	DDV
2	Tailgate logo	1	\$ 48.10	\$ 22.00 48.10	NEC
3	Tailgate emblem 'Jazz'	1	\$ 42.80	\$ 38.00 42.80	BT
4	Tailgate inner lock	1	\$ 288.60	\$ 168.50 288.60	BT
5	Tailgate striker	1	\$ 48.90	\$ 48.90 48.90	BT
6	Tailgate weatherstrip	1	\$ 165.60	\$ 152.40 165.60	BT
7	Tailgate inner trim board	1	\$ 296.30	\$ 194.40 296.30	BR
8	Tailgate inner handle	1	\$ 36.00	\$ 36.00 36.00	BR
9	Tailgate outer garnish	1	\$ 118.50	\$ 118.50 118.50	BR
10	Tailgate no plate lamp	2	\$ 88.50	\$ 177.00 177.00	BR
11	Tailgate solenoid switch	1	\$ 235.00	\$ 235.00 235.00	NNX
12	Tailgate windscreen	1	\$ 980.00	\$ 675.50 980.00	BR
13	Tailgate windscreen moulding	1	\$ 90.50	\$ 90.50 90.50	NEC
14	Tailgate windscreen wiper arm	1	\$ 93.20	\$ 93.20 93.20	NNX
15	Tailgate windscreen wiper motor	1	\$ 269.60	\$ 269.60 269.60	NNX
16	Tailgate windscreen wiper garnish	1	\$ 45.50	\$ 45.50 45.50	MIS
17	Tailgate third brake lamp	1	\$ 268.70	\$ 268.70 268.70	NNX
18	Rear bumper	1	\$ 680.90	\$ 520.80 680.90	BR
19	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00	NEC
20	Rear bumper side retainer	2	\$ 48.60	\$ 97.20 97.20	NEC
21	Rear bumper bracket	2	\$ 39.60	\$ 79.20 79.20	BT
22	Rear end panel	1	\$ 525.60	\$ 365.30 525.60	DDV
23	Rear end panel top garnish	1	\$ 124.80	\$ 124.80 124.80	DLV
24	Rear end panel top garnish clips	1	\$ 50.00	\$ 30.00 50.00	NEC
25	Spare tyre panel	1	\$ 881.70	\$ 781.60 881.70	DIS
26	Spare tyre panel top board	1	\$ 250.00	\$ 238.50 250.00	DIS
27	Spare tyre panel insulator	1	\$ 188.60	\$ 150.00 188.60	NEC
28	Taillamp rh	1	\$ 386.00	\$ 386.00 386.00	BR
29	Taillamp clips rh	1	\$ 50.00	\$ 30.00 50.00	NEC
30	Taillamp lower bracket rh	1	\$ 48.40	\$ 37.00 48.40	BR
31	Taillamp base panel rh	1	\$ 138.00	\$ 138.00 138.00	BT
32	Taillamp lh	1	\$ 386.00	\$ 386.00 386.00	BR
33	Taillamp clips lh	1	\$ 50.00	\$ 30.00 50.00	NEC
34	Taillamp bracket lh	1	\$ 48.40	\$ 37.00 48.40	BR
35	Taillamp panel lh	1	\$ 138.00	\$ 138.00 138.00	DDV
36	Rear fender rh	1	\$ 648.40	\$ 648.40 648.40	DDV
37	Rear fender inner trim rh	1	\$ 350.00	\$ 350.00 350.00	BR
38	Rear fender inner cowl	1	\$ 115.90	\$ 115.90 115.90	NNX
39	Rear fender quarter glass moulding	1	\$ 88.00	\$ 88.00 88.00	NEC
40	Rear fender lh	1	\$ 648.40	\$ 648.40 648.40	NNX
41	Rear fender inner trim lh	1	\$ 350.00	\$ 350.00 350.00	BR
42	Exhaust pipe	1	\$ 728.20	\$ 552.80 728.20	BT
43	Exhaust pipe mounting	2	\$ 38.20	\$ 76.40 76.40	NEC

44	Exhaust pipe heat shield	1	\$	156.00	\$ 60.00	156.00	DDV
45	Rear door lock assy rh	1	\$	268.90	\$	268.90	JAMV
Parts Sub Total :					\$ 8591.70	11,710.90	
20% Discount					\$ 1718.34	2,342.18	
PARTS TOTAL :					\$ 6873.36	9,368.72	

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$	60.00	\$ -60.00 NNX
2	Tailgate inner trim board clips	1	\$	50.00	\$ 30.00 50.00
3	Tailgate outer garnish clips	1	\$	50.00	\$ 30.00 50.00
4	Tailgate windscreen clips	1	\$	50.00	\$ 30.00 50.00
5	Tailgate primer and cleaner	1	\$	80.00	\$ 80.00 NNX
6	Tailgate windscreen sealant	1	\$	100.00	\$ 60.00 100.00
7	Rear no plate with cover	1	\$	80.00	\$ 50.00 80.00
8	Rear bumper reverse sensor	2	\$	200.00	\$ 200.00 400.00
9	Rear end panel sealant	1	\$	100.00	\$ 60.00 100.00
10	Taillamp inner seal	2	\$	80.00	\$ 160.00
11	Rear fender inner trim clips rh	1	\$	50.00	\$ 30.00 50.00
12	Rear fender inner trim clips Lh	1	\$	50.00	\$ 30.00 50.00
13	Rear fender inner cowling clips rh	1	\$	50.00	\$ 30.00 50.00
14	Rear fender sealant rh	1	\$	100.00	\$ 60.00 200.00
15	Spare tyre panel sealant	1	\$	100.00	\$ 60.00 100.00
16	Rear fender quarter glass clips	1	\$	50.00	\$ 30.00 100.00
SPECIAL NETT TOTAL :					\$ 900.00 1,680.00

Nos.	LABOUR	S\$	
1	R&R tailgate component	\$ 50.00	100.00
2	R&R rear windscreen	\$ 120.00	250.00
3	R&R upholstery	\$ 100.00	180.00
4	R&R exhaust pipe assy	\$ 120.00	250.00
5	R&R fuel tank	\$	100.00
6	R&R rear fender quarter glass Lh and RH	\$ 60.00	150.00
7	R&R reverse sensor	\$ 60.00	80.00
8	Mount bench work	\$ 100.00	350.00
9	Rear Chasis alignment	\$	300.00
10	Disconnect wire harness to facilitate repair, reconnect and check function	\$ 50.00	80.00
11	Panel beat	\$ 1200.00	1,800.00
12	Rust proofing	\$ 60.00	150.00
13	Spray painting	\$ 1000.00	1,800.00
LABOUR TOTAL :		\$ 2920.00	5,590.00

PARTS TOTAL :	\$	9,368.72
SPECIAL NETT TOTAL :	\$	1,680.00
LABOUR TOTAL :	\$	5,590.00
GRAND TOTAL :	\$	16,638.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurvey on
25/6/19

Lump Sum Repairs

Repair days 9

Parts 6873.36

SN 700.00

Labour 2920.00

10493.36

@ 20% 2098.67

8394.69

L/S 8,350/2

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6372E
Vehicle Details	
Vehicle No.:	SGZ3217C
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.4A
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	L13A54002995
Chassis No.:	JHMGD185075228434
Maximum Power Output:	60.0 kW (80 bhp)
Open Market Value:	\$13,611.00
Original Registration Date:	25 Oct 2007
First Registration Date:	25 Oct 2007
Transfer Count:	2
Actual ARF Paid:	\$14,973.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Oct 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$21,282.00
COE Rebate Amount:	\$14,167.00
Total Rebate Amount:	\$14,167.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 Jun 2019

OK

Dep 7,900/yr
658/mth

MV 25,000/2
PV 14,167/2
NV 10,833/2

TC Lim
25/4/19

Email: sm@idac.com.sg

Tel no: 6555 6888 Fax no: 6454 3279

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 22/06/19 (dd/mm/yy) Time of Accident: 22 : 05 (24-HR-FORMAT)

Vehicle No.: S6Z 3217C Vehicle Make & Model: HONDA JAZZ

Exact location of Accident: PIE TUNAS EXIT 26A

Policyholder's Name / IC No.: NG CHOR JOO / S1776372E

Driver's Name / IC No.: AARON SEE ZHEN JIE / S9139241J (As Above) ☐

Driver's Contact No.: 9685 6566 Company Contact No:

Driver's Address: APT BLK 402 ANG MO KIO AVE 10 #25-615 (S560402)

Insurance Company: Direct Asia Email address (if any):

Relationship between Owner & Driver:

or Others specify:

What do you wish to claim? (Please TICK one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

Exact purpose for which the vehicle was being used at time of accident?

Occupation (nature of job) ☒ Indoor / ☐ Outdoor

☒ Private use / ☐ Work purpose

No. of Passengers (Including Driver): 03

Passenger Name: NG CHOR JOO

Gender: F

Passenger Name: ALOYSIOUS LOW MUN TUCK

Gender: M

Weather condition & Road conditions? (On the day of accident)

☐ Clear & Dry / ☐ Raining & Wet / ☒ After-Rain & Wet / ☐ Drizzling & Wet / Others:

Was there any video captured by your Car Camera? ☐ Yes / ☐ No

Any Injuries: ☒ Yes / ☐ No (If YES) Injured Person's Name: ALOYSIOUS LOW MUN TUCK / AARON SEE ZHEN JIE / NG CHOR JOO

Injuries Sustain: Injured Person in Which Vehicle:

Police Report filed: ☒ Yes / ☐ No (If YES) Which Police Station: online.

The Other Party(s) Details:

1. Driver's Name / IC No: Vehicle No: SLP 6935L

Driver's Contact No: Insurance Company (If any):

2. Driver's Name / IC No: Vehicle No:


Driver's Contact No: Insurance Company (If any):

*Independent Witness (If Any): Contact No:

Preferred Workshop Name: Contact No:

*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

SKETCH PLAN



A - SGZ 3217C

B - SLP 6935L

PIE TUAS EXIT 26A
SLIP ROAD

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the stated date and time I vehicle 'A'
was travelling at my designated lane on SLIP Road of PIE
TUAS Exit 26, as the car in front of me slowed down
and I followed, after awhile I felt a huge impact from
the rear of my vehicle that push my vehicle forward,
I then stopped my car and realised that vehicle 'B'
collided onto the rear of my vehicle. That all.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Rear Portion

NAC	INC	Item	CON	ACQ	BY
1137	993626	Rear Number Plate	BT	✓	
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish	BR	✓	
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	BR	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket	BT	✓	
1148	993068	Rear Bumper Side Retainer	NEC	✓	
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Rear Sensor			
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	DL	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	AR	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel	DD	✓	
1166	995116	Rear RH Taillamp	BR	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel	DD	✓	
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD	✓	
1182	991328	Tailgate Emblem	NEC	✓	2
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm	assembly	✓	
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass	BR	✓	
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NEC	✓	
1196	994607	Tailgate Glass Sealant	NEC	✓	
1197	994629	Tailgate Lock	assembly	✓	
1198	994651	Tailgate Rubber	cut	✓	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board	BR	✓	

No of Items: 33

Assessor: T. G. Lin

25/6/19

Vehicle No:

547 3217C

NAC	INC	Item	CON	ACQ
1202	993784	Spare Tyre Board	DA	✓
1203	994328	Spare Tyre Panel	DD	✓
1204	995065	Spare Tyre		
1205	994326	Spare Tyre Lock Screw		
1206	993787	Spare Tyre Cover		
1207	995323	Triangle Breakdown Sign		
1208	990507	CD Changer Assy		
1209	990164	Antenna		
1210	990534	Centre Exhaust Pipe Assy		
1211	990532	Centre Exhaust Mounting		
1212	993364	Rear Exhaust Pipe	BT	✓
1213	993357	Rear Exhaust Chrome Pipe		
1214	993361	Rear Exhaust Mounting	NEC	✓
1215	993358	Rear Exhaust Heat Shield	DD	✓
1216	995223	Rear LH Chassis Member		
1217	993165	Rear RH Chassis Member		
1218	993436	Rear LH Fender		
1219	993449	Rear LH Fender Protector		
1220	993420	Rear LH Fender Inner Panel		
1221	993431	Rear LH Fender Inner Trim		
1222	993415	Rear LH Fender Inner Garnish		
1223	993425	Rear LH Fender Inner Shield		
1224	993621	Rear LH Mudflap		
1225	993933	Rear LH Wheel Rim		
1226	994025	Rear LH Rim Cover		
1227	995065	Rear LH Tyre		
1228	993456	Rear RH Fender	DD	✓
1229	993450	Rear RH Fender Protector		
1230	993420	Rear RH Fender Inner Panel		
1231	993431	Rear RH Fender Inner Trim	BR	✓
1232	993415	Rear RH Fender Inner Garnish		
1233	993425	Rear RH Fender Inner Shield		
1234	993622	Rear RH Mudflap		
1235	993934	Rear RH Wheel Rim		
1236	994025	Rear RH Rim Cover		
1237	995065	Rear RH Tyre		
1238	995162	Rear Fender Extension Panel LH		
1239	993401	Rear Fender Extension Panel RH		
1240	993430	Rear Fender Inner Top Garnish		
1241	993673	Rear Fender 1/4 Glass		
1242	993452	Rear Fender 1/4 Glass Rubber	RUNEC	✓
1243	993453	Rear Fender 1/4 Glass Sealant	RUNEC	✓
1244	993949	Rear Windscreen Glass		
1245	993976	Rear Windscreen Rubber		
1246	993961	Rear Windscreen Moulding		
1247	993955	Rear Windscreen Sealant		
1248	994729	Third Brake Light		
1249	993385	Rear Fender Air Grille		
1250	992167	Fuel Lid		
1251	992168	Fuel Neck		
1252	992179	Fuel Tank		
1253	992184	Fuel Tank Bracket		
1254	992191	Fuel Tank Float		
1255	990247	Sticker		
		Spare tyre panel insulator	NEC	✓
		Tail lamp lower bracket RH	BR	✓
		Tail lamp lower bracket LH	BR	✓



Beautiful Pearl Yellow Honda Jazz 1.4L Auto. Small And Mighty! Excellent Fuel Savings. Very Easy To Drive And Easy Parking. Low Maintenance Cost. Reliable Ride. Road Tax Till November'19. Loan/Trade-in...

Posted: 19-May-2019 Tags: 2008 Honda Jazz, 2008 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda



Honda Jazz 1.3M (COE till 04/2023) **\$20,500** **\$5,330 /yr** **05-May-2008** **1,339 cc** **140,000 km** **Hatchback** **Available**

Call Now!

Posted: 24-Jun-2019 Tags: 2008 Honda Jazz, 2008 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda



Honda Jazz 1.3A (COE till 03/2023) **-** **N.A** **08-Mar-2008** **1,339 cc** **-** **Hatchback** **SOLD**

Drive With Assurance! All Our Quality Pre-Owned Cars Are Selling At The Most Reasonable Price With A Peace Of Mind! STA/VICOM Inspection Welcome! Most Reliable And Economical Choice! Easy Maintained! ...

CarQuartz Singapore

Posted: 17-Jun-2019 Tags: 2008 Honda Jazz, 2008 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda



Honda Jazz 1.3A (COE till 10/2022) **-** **N.A** **25-Oct-2007** **1,339 cc** **-** **Hatchback** **SOLD**

Text For More Info.

DIRECT OWNER

Posted: 21-May-2019 Tags: 2007 Honda Jazz, 2007 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda



Audio Upgrade for Any Budget

Want more than what your stock in-car entertainment system can offer? With 400 head units choose from, you'll definitely find "the one" that suits your needs. Prices from just \$170!

Find out more!



Honda Jazz 1.3A (COE till 10/2022) **-** **N.A** **18-Oct-2007** **1,339 cc** **-** **Hatchback** **SOLD**

Complete Car With 2 Working Keys And Owner Reference Manual. Clean Interior, Strictly Family Use Only, Meticulous Maintained. In Full Running Condition, No Repairs Required. SGZ (3 Digits) License Pla...

DIRECT OWNER

Posted: 16-May-2019 Tags: 2007 Honda Jazz, 2007 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda



Honda Jazz 1.3A (COE till 10/2022) **-** **N.A** **03-Oct-2007** **1,339 cc** **-** **Hatchback** **SOLD**

Tip Top Condition Inside Out! No Repairs Needed As No Under Carriage Sound Whatsoever. Regularly Maintenance Done Up With Very Low Mileage Clocks As I Am A Frequent Flyer. From Cosmetic To Engine All...

DIRECT OWNER

Posted: 31-May-2019 Tags: 2007 Honda Jazz, 2007 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda



Honda Jazz 1.3A (COE till 07/2022) **-** **N.A** **03-Oct-2007** **1,339 cc** **-** **Hatchback** **SOLD**

Beautiful 1 And Only Hot Hatchback With Pearl White Paintwork Done Up! Upgraded Lightweight Rims To Go Well With Car Body Color! Excellent Tip Top Condition As Car Is Lightly Used To Ferry Kids Only A...

DIRECT OWNER

Posted: 08-May-2019 Tags: 2007 Honda Jazz, 2007 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda



Honda Jazz 1.3A (COE till 09/2022) **-** **N.A** **24-Sep-2007** **1,339 cc** **-** **Hatchback** **SOLD**

Depreciation Only At Less Than \$450/Month, \$15/Day. Cheaper Than Renting A Car. Priced Low For Quick Sale! Only 1 Owner Till Date! Fully Serviced And Maintained By Agent (Kah Motor). Always Prompt Ser...

Posted: 30-May-2019 Tags: 2007 Honda Jazz, 2007 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda



Honda Jazz 1.3A (COE till 05/2022) **-** **N.A** **29-May-2007** **1,339 cc** **-** **Hatchback** **SOLD**

Suitable Usage For Short Term, Contact Sale Person, Many Thanks!

Henly Enterprises Co

Posted: 24-May-2019 Tags: 2007 Honda Jazz, 2007 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda



Honda Jazz 1.3A (COE till 04/2022) **\$22,500** **\$7,900 /yr** **14-May-2007** **1,339 cc** **211,000 km** **Hatchback** **Available**

Most Popular Honda Hatchback For Your Family And Daily Usage. Very Clean Interior And Own By Non Smoker. Fuel Saving Yet Powerful Drive.Best Short Term Usage And For New Driver! Road Tax Till Nov 2019...

Quality Motor Trading Enterprise

Posted: 01-Jun-2019 Tags: 2007 Honda Jazz, 2007 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda

Honda Jazz 1.3A (COE till 03/2022) **-** **N.A** **04-Apr-2007** **1,339 cc** **-** **Hatchback** **SOLD**

High Loan Applicable Here Must Call For Discussions, Cash Deal Welcome, Trade In Available, Hurry, Call For Availability Or Viewing Appointment

PRE-REPAIR INSPECTION REQUEST – SGZ3217C vs SLP6935L (OI) on D.O.A.: 22/06/2019

From: Hor Yinnui
To: 'assignments@kkauts.com', Admin A (admin-a@kkauts.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim; Noor Mariesa; Azlan; Syszairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh; Ashweenjeetkaur; Subramaniam; Divyashni; Tor
Sent: 6/24/2019 10:56:57 AM
Attachments:  3217 PRS SLP6935L.pdf

Hi,

Please refer to the enclosed request from **Team AutoPro Pte Ltd**.
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thanks & Regards,

Hor Yinn Rui (Viviane)
AIG
Claim Adjuster II, Singapore FNOCL Claims Operations – Auto
Yinnui.Hor@aig.com | www.aig.sg

12.01pm @ 24/6/19
vehicle in
sur @ Mr. Lim

From: TeamAutoPro North [mailto:teamautopl@gmail.com]
Sent: Monday, June 24, 2019 10:31 AM
To: AIG SGP, Claims-Survey; Chan, Yoke Shi; Chin, Lee-Ying; Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Md Ishak, Mohd Imran; Abu Kassim, Noor Mariesa; Supramaniam, Darshene; Tan, Lily (AIG)
Subject: [EXTERNAL] 2 Days Notice: SGZ 3217 C (Our Ref) and SLP 6935 L (Your Ref) Dated 22nd June 2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Madam,
Road Traffic Accident Involving SGZ 3217 C (Our Ref) and SLP 6935 L (Your Ref)
Dated 22nd June 2019, Time around 22:05
@ PIE TUAS EXIT 26A

We represent our client; NG CHOR JOO, to notify you of the aforesaid road traffic accident involving our client's vehicle registration number: SGZ 3217 C and your insured's vehicle registration number: SLP 6935 L.

Enclosed herewith a copy of our 2 Days Notice Letter and the relevant Singapore Accident Statement filed for your reference.

For efficiency purpose, we are agreeable with the appointment of **Mr Lim - LKK** as the SJE for subject claim. Please let us know within **2 working days** from today your agreeing to the above otherwise kindly send us your list of at least **ten (10) motor surveyors**, via email to the following personnel:-

Contact Person	Alan Koh	9092 7279
	Frederick Lim	9674 6635
Email Address	teamautopl@gmail.com	
Survey Address	160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722	

Thank you for your attention to this email and we look forward to your earliest reply.

The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Chern,
Prach Ang
Team AutoPro Pte Ltd
Tel: 6258 1953
Fax: 6258 1956

385 Sin Ming Drive
#01-02 Vicom Inspection Centre
Singapore 575718

IMPORTANT NOTICE:
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)
Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jun 2019 Edit Reg		24 Jun 2019 00:00 Edit Adj Rpt	S\$8,350.00 Edit Estimates	S\$8,350.00 View Rpt		Pending for Survey Report Cancel Case

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LAU SIEW TEE, ID: S0015102E		
Main Claimant:	NG CHOR JOO, ID: S1776372E		
Vehicle Reg. No.:	SGZ3217C	Date of Loss:	22/06/2019 00:00 - :59 [139 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4619852848SG	Policy/Cover Note No.:	1700017054 (Comprehensive)
Vehicle Reg. No. (Insured):	SLP6935L	Policy No. (Claimant):	
		Excess:	
Repairer:	Team Autopro Pte Ltd (KAKI BUKIT) No.8 Kaki Bukit Avenue 4, #06-21 Premier@ Kaki Bukit (Gate 2), 415875 Kaki Bukit - Tel: 90927279		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com		
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 03/07/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (03/03/2020): Alert - Adj Mandate Maintained - SGZ3217C - Claim Handler: Tan, Bennie-WZ
- AIG_SG_EXPRESS (08/01/2020): Alert - Adj Mandate Approved (S\$9350.00) - SGZ3217C - Claim Handler: Tan, Bennie...
- AIG_SG_EXPRESS (30/12/2019): Alert - Adj Mandate Maintained - SGZ3217C - Claim Handler: Tan, Bennie-WZ

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGZ3217C (4619852848SG)
[SLP6935L]
TP
NG CHOR JOO
Jun 22 2019 12:00AM
[LAU SIEW TEE]
Team Autopro Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Video											1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)									Thumbnail	Print
1	30/12/19 12:01	OI Video - Accident										Load MP4
Letters/Correspondences											1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown										Edit
Photos/Images											3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print
1	25/11/19 12:16	General View										Load JPG ☒
2	25/11/19 12:16	General View										Load JPG ☒
3	25/11/19 12:16	General View										Load JPG ☒
4	25/11/19 12:16	Odometer Reading										Load JPG ☒
5	25/11/19 12:16	Chassis Number										Load JPG ☒
6	25/11/19 12:16	General View										Load JPG ☒
7	25/11/19 12:16	General View										Load JPG ☒
8	25/11/19 12:16	General View										Load JPG ☒
9	25/11/19 12:16	General View										Load JPG ☒
10	25/11/19 12:16	General View										Load JPG ☒
11	25/11/19 12:16	General View										Load JPG ☒
12	25/11/19 12:16	General View										Load JPG ☒
13	25/11/19 12:16	General View										Load JPG ☒
14	25/11/19 12:16	General View										Load JPG ☒
15	25/11/19 12:16	General View										Load JPG ☒
16	25/11/19 12:16	General View										Load JPG ☒
17	25/11/19 12:16	General View										Load JPG ☒
18	25/11/19 12:16	General View										Load JPG ☒
19	25/11/19 12:16	General View										Load JPG ☒
20	25/11/19 12:16	General View										Load JPG ☒
21	25/11/19 12:16	General View										Load JPG ☒
22	25/11/19 12:16	General View										Load JPG ☒
23	25/11/19 12:16	General View										Load JPG ☒
24	25/11/19 12:16	General View										Load JPG ☒
25	25/11/19 12:16	General View										Load JPG ☒
26	25/11/19 12:16	General View										Load JPG ☒
27	25/11/19 12:16	General View										Load JPG ☒
28	25/11/19 12:16	General View										Load JPG ☒
29	25/11/19 12:16	General View										Load JPG ☒
30	25/11/19 12:16	General View										Load JPG ☒
31	25/11/19 12:16	General View										Load JPG ☒
32	25/11/19 12:16	General View										Load JPG ☒
33	25/11/19 12:16	General View										Load JPG ☒
34	25/11/19 12:16	General View										Load JPG ☒
35	25/11/19 12:16	General View										Load JPG ☒
36	25/11/19 12:16	General View										Load JPG ☒

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
37	25/11/19 12:16	General View	 Load JPG	☒
38	25/11/19 12:16	General View	 Load JPG	☒
39	25/11/19 12:16	General View	 Load JPG	☒
40	25/11/19 12:16	General View	 Load JPG	☒
41	25/11/19 12:16	General View	 Load JPG	☒
42	25/11/19 12:16	General View	 Load JPG	☒
43	25/11/19 12:16	General View	 Load JPG	☒
44	25/11/19 12:16	General View	 Load JPG	☒
45	25/11/19 12:16	General View	 Load JPG	☒
46	25/11/19 12:16	General View	 Load JPG	☒
47	25/11/19 12:16	General View	 Load JPG	☒
48	25/11/19 12:16	General View	 Load JPG	☒
49	25/11/19 12:16	General View	 Load JPG	☒
50	25/11/19 12:16	General View	 Load JPG	☒
51	25/11/19 12:16	General View	 Load JPG	☒
52	25/11/19 12:16	General View	 Load JPG	☒
53	25/11/19 12:16	General View	 Load JPG	☒
54	25/11/19 12:16	General View	 Load JPG	☒
55	25/11/19 12:16	General View	 Load JPG	☒
56	25/11/19 12:16	General View	 Load JPG	☒
57	25/11/19 12:16	General View	 Load JPG	☒
58	25/11/19 12:16	General View	 Load JPG	☒
59	25/11/19 12:16	General View	 Load JPG	☒
60	25/11/19 12:16	General View	 Load JPG	☒
61	25/11/19 12:16	General View	 Load JPG	☒
62	25/11/19 12:16	General View	 Load JPG	☒
63	25/11/19 12:16	General View	 Load JPG	☒
64	25/11/19 12:16	General View	 Load JPG	☒
65	25/11/19 12:16	General View	 Load JPG	☒
66	25/11/19 12:16	General View	 Load JPG	☒
67	25/11/19 12:16	General View	 Load JPG	☒
68	25/11/19 12:16	General View	 Load JPG	☒
69	25/11/19 12:16	General View	 Load JPG	☒
70	25/11/19 12:16	General View	 Load JPG	☒
71	25/11/19 12:16	General View	 Load JPG	☒
72	25/11/19 12:16	General View	 Load JPG	☒
73	25/11/19 12:16	General View	 Load JPG	☒
74	25/11/19 12:16	General View	 Load JPG	☒
75	25/11/19 12:16	General View	 Load JPG	☒
76	25/11/19 12:16	General View	 Load JPG	☒
77	25/11/19 12:16	General View	 Load JPG	☒
78	25/11/19 12:16	General View	 Load JPG	☒
79	25/11/19 12:16	General View	 Load JPG	☒
80	25/11/19 12:16	General View	 Load JPG	☒
81	25/11/19 12:16	General View	 Load JPG	☒
82	25/11/19 12:16	General View	 Load JPG	☒
83	25/11/19 12:16	General View	 Load JPG	☒
84	25/11/19 12:16	General View	 Load JPG	☒
85	25/11/19 12:16	General View	 Load JPG	☒
86	25/11/19 12:16	General View	 Load JPG	☒
87	25/11/19 12:16	General View	 Load JPG	☒
88	25/11/19 12:16	General View	 Load JPG	☒
89	25/11/19 12:16	General View	 Load JPG	☒
90	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
91	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
92	25/11/19 12:20	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
93	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
94	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
95	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
96	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
97	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
98	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
99	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
100	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
101	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
102	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
103	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
104	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
105	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
106	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
107	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
108	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
109	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
110	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
111	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
112	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
113	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
114	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
115	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
116	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
117	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
118	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
119	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
120	25/11/19 12:20	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/06/19 16:39	EMAIL FROM AIG DD 24062019	 Load PDF	
2	24/06/19 16:39	NOTICE & GIA REPORT	 Load PDF	
3	27/06/19 08:41	TP ESTIMATE- MARKED	 Load PDF	
4	22/11/19 09:19	LETTER TO OI	 Load PDF	
5	22/11/19 09:19	LOD	 Load PDF	
6	22/11/19 09:19	LTA SEARCH	 Load PDF	
7	22/11/19 09:19	RENTAL RECEIPT	 Load PDF	
8	22/11/19 09:19	TOWING FEE	 Load PDF	
9	17/03/20 10:25	AUTHORISATION TO ACT FORM	 Load PDF	
10	17/03/20 10:25	Release Voucher	 Load PDF	
11	17/03/20 10:32	WORKSHOP INVOICE	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	25/06/19 09:50	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)

Vehicle No:	SLP6935L (Insd veh)	Model:	HONDA JAZZ 1.4 (A)
	SGZ3217C (TP veh)		
Date of Accident:	22/06/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	16,638.72
Final Repair Cost	:	\$	9,350.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	11 days
LTA / GIA Search Fee	:	\$	
Others:Towing Fee	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	9,350.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> : Agreed Liability _____100_____(%)			
B) For <u>GIA Registered Workshop</u> : BOLA Applicable: Yes/ No BOLA Scenario No: _____			
BOLA Liability: _____(%) Assessed Liability (*): _____(%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Team Autopro Pte Ltd	:	\$ 9,350.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

17 Mar
2020
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19011092/BDS3Q2

Date: 17/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700017054
 Claimant Vehicle No : SGZ3217C Insured Vehicle No : SLP6935L
 Date of Loss: 22/06/2019 Nature of Claim: TP Claim No: 4619852848SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGZ3217C Engine No: L13A54002995
 Make & Model: HONDA JAZZ, 1.4 (A) Chassis No: JHMGD18507S228434
 Reg. Date: 25/10/2007 (Man. Year: 2007) Odometer: 0 km
 Colour: White
 Engine Capacity: 1339 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
 Front Left Side: Nexen 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Nexen 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,048.72	7,573.36	3,475.36	31.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,590.00	2,920.00	2,670.00	47.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,638.72	10,493.36	6,145.36	36.93
Approved Total (Overridden) (S\$)		8,350.00		
Nett Amount (S\$)	16,638.72	8,350.00	8,288.72	49.82
+ Car Rental (11.0 x S\$100.00/day) (S\$)		1,100.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		90.00		
Nett Liability (S\$)		9,547.45		
Global Sum Settlement (S\$)		9,350.00		

INSPECTION

Date of Assignment: 24/06/2019
 Date Inspected: 24/06/2019 Inspected At: 160 Sin Ming Dr #01-14 Sin Ming
 AutoCity Singapore 575722
 Repairer: Team Autopro Pte Ltd (KAKI BUKIT)
 Estimated Period of Repair: 9.0 days

Adjuster: Lim Teow Guan**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	903.60 FL	*830.60 FL
2	1		*TAILGATE LOGO	Necessary	48.10 FL	*22.00 FL
3	1		*TAILGATE EMBLEM JAZZ	Necessary	42.80 FL	*38.00 FL
4	1		*TAILGATE INNER LOCK	Bent	288.60 FL	*168.50 FL
5	1		*TAILGATE STRIKER	Bent	48.90 FL	*48.90 FL
6	1		*TAILGATE WEATHERSTRIP	Cut	165.60 FL	*152.40 FL
7	1		*TAILGATE INNER TRIM BOARD	Broken	296.30 FL	*194.40 FL
8	1		*TAILGATE INNER HANDLE	Broken	36.00 FL	*36.00 FL
9	1		*TAILGATE OUTER GARNISH	Broken	118.50 FL	*118.50 FL
10	2		*TAILGATE NO PLATE LAMP	Broken	177.00 FL	*177.00 FL
11	1		*TAILGATE SOLENOID SWITCH	Not Necessary	235.00 FL	*- FL
12	1		*TAILGATE WINDSCREEN	Broken	980.00 FL	*675.50 FL
13	1		*TAILGATE WINDSCREEN MOULDING	Necessary	90.50 FL	*90.50 FL
14	1		*TAILGATE WINDSCREEN WIPER ARM	Not Necessary	93.20 FL	*- FL
15	1		*TAILGATE WINDSCREEN WIPER MOTOR	Not Necessary	269.60 FL	*- FL
16	1		*TAILGATE WINDSCREEN WIPER GARNISH	Missing	45.50 FL	*45.50 FL
17	1		*TAILGATE THIRD BRAKE LAMP	Not Necessary	268.70 FL	*- FL
18	1		*REAR BUMPER	Broken	680.90 FL	*520.80 FL
19	1		*REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
20	2		*REAR BUMPER SIDE RETAINER	Necessary	97.20 FL	*97.20 FL
21	2		*REAR BUMPER BRACKET	Bent	79.20 FL	*79.20 FL
22	1		*REAR END PANEL	Dented	525.60 FL	*365.30 FL
23	1		*REAR END PANEL TOP GARNISH	Dislodged	124.80 FL	*124.80 FL
24	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FL	*30.00 FL
25	1		*SPARE TYRE PANEL	Distorted	881.70 FL	*781.60 FL
26	1		*SPARE TYRE PANEL TOP BOARD	Distorted	250.00 FL	*238.50 FL
27	1		*SPARE TYRE PANEL INSULATOR	Necessary	188.60 FL	*150.00 FL
28	1		*TAILLAMP RH	Broken	386.00 FL	*386.00 FL
29	1		*TAILLAMP CLIPS RH	Necessary	50.00 FL	*30.00 FL
30	1		*TAILLAMP LOWER BRACKET RH	Broken	48.40 FL	*37.00 FL
31	1		*TAILLAMP BASE PANEL RH	Bent	138.00 FL	*138.00 FL
32	1		*TAILLAMP LH	Broken	386.00 FL	*386.00 FL
33	1		*TAILLAMP CLIPS LH	Necessary	50.00 FL	*30.00 FL
34	1		*TAILLAMP BRACKET LH	Broken	48.40 FL	*37.00 FL
35	1		*TAILLAMP PANEL LH	Dented	138.00 FL	*138.00 FL
36	1		*REAR FENDER RH	Dented	648.40 FL	*648.40 FL
37	1		*REAR FENDER INNER TRIM RH	Broken	350.00 FL	*350.00 FL
38	1		*REAR FENDER INNER COWLING	Not Necessary	115.90 FL	*- FL
39	1		*REAR FENDER QUARTER GLASS MOULDING	Necessary	88.00 FL	*88.00 FL
40	1		*REAR FENDER RH	Not Necessary	648.40 FL	*- FL
41	1		*REAR FENDER INNER TRIM LH	Broken	350.00 FL	*350.00 FL
42	1		*EXHAUST PIPE	Bent	728.20 FL	*552.80 FL
43	2		*EXHAUST PIPE MOUNTING	Necessary	76.40 FL	*76.40 FL
44	1		*EXHAUST PIPE HEAT SHIELD	Dented	156.00 FL	*60.00 FL
45	1		*REAR DOOR LOCK ASSY RH	Jammed	268.90 FL	*268.90 FL
46	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
47	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
48	1		*TAILGATE OUTER GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
49	1		*TAILGATE WINDSCREEN CLIPS	Necessary	50.00 FS	*30.00 FS
50	1		*TAILGATE PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS
51	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*REAR NO PLATE WITH COVER	Broken	80.00 FS	*50.00 FS
53	2		*REAR BUMPER REVERSE SENSOR	Cut	400.00 FS	*200.00 FS
54	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
55	2		*TAILLAMP INNER SEAL	Not Necessary	160.00 FS	*- FS
56	1		*REAR FENDER INNER TRIM CLIPS RH	Necessary	50.00 FS	*30.00 FS
57	1		*REAR FENDER INNER TRIM CLIPS LH	Necessary	50.00 FS	*30.00 FS
58	1		*REAR FENDER INNER COWLING CLIPS RH	Necessary	50.00 FS	*30.00 FS
59	2		*REAR FENDER SEALANT RH	Necessary (1 PCS ONLY)	200.00 FS	*60.00 FS
60	1		*SPARE TYRE PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
61	2		*REAR FENDER QUARTER GLASS CLIPS	Necessary (1 PCS ONLY)	100.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,390.90	9,291.70
- List Item Discount on L Items 20.00/20.00% (S\$)	2,342.18	1,718.34
Total Parts (S\$)	11,048.72	7,573.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R TAILGATE COMPONENT	New	100.00	50.00
2	R&R REAR WINDSCREEN	New	250.00	120.00
3	R&R UPHOLSTERY	New	180.00	100.00
4	R&R EXHAUST PIPE ASSY	New	250.00	120.00
5	R&R FUEL TANK	New	100.00	0.00
6	R&R REAR FENDER QUARTER GLASS RH	New	150.00	60.00
7	R&R REVERSE SENSOR	New	80.00	60.00
8	MOUNT BENCH WORK	New	350.00	100.00
9	REAR CHASIS ALIGNMENT	New	300.00	0.00
10	DISCONNECT WIRE HARNESS TO FACILITATE REPAIR ,RECONNECT AND CHECK FUNCTION	New	80.00	50.00
11	PANEL BEAT	New	1,800.00	1,200.00
12	RUST PROOFING	New	150.00	60.00
13	SPRAY PAINTING	New	1,800.00	1,000.00
Gross Labour Cost (S\$)			5,590.00	2,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >