



VAC AUTO CENTRE PTE LTD

UEN: 200210945Z

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883

Tel: 8618 8008 | Fax: 6636 5355 | Email: vacauto@singnet.com.sg

Page1

Regn No : SJT8650Y

Vehicle Make & Model : Honda Jazz 1.5 LA

ITEM NO	DESCRIPTION OF ITEMS	QUANTITY (Piece/Set)	UNIT PRICE (S\$)	AMOUNT (S\$)
List Price:				
1	Front door RH	1	\$ 841.60	\$ 841.60 X
2	Front door mirror assembly RH 421.20	1	\$ 481.90	\$ 481.90 ✓
3	Front fender RH	1	\$ 426.30	\$ 426.30 X
4	Front headlamp RH	1	\$ 561.90	\$ 561.90 X
Sub-total				\$ 2,311.70
Less 20%				\$ 462.34
List Price Total				\$ 1,849.36

Labour Charge Items:				
1	To check electrical wiring systems		\$ 40.00	X
2	To spray undercoating		\$ 60.00	X
3	To respray painting & etc		\$ 800.00/300	
4	Panel beating, cut, weld, remove and replacing above parts		\$ 800.00/150	
Labour Charge Total			\$ 1,700.00	

Overall Estimate Parts & Labour

Grand total \$ 3,549.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not paid
2/5 \$600/
28/6/19
2/5