



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:KHOR SAW THENG

Ref: CC4/ASM19011165/Jga3q2
Date: 08/11/2021
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLU 5681Z	Veh. Inspected	FBP 612B
Policy No.	P2039994	Coverage (\$)	0.00
Claim No.	S9M01QST	Excess (\$)	0.00
Assign From		Assign Date	24/06/2019

2. Vehicle Particulars & Condition

Make & Model	YAMAHA GDR155A	c.c	155
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MH3SG4640KJ049080	Colour	BLACK
Odometer	2118 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	110/80-14	MAXXIS	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70-14	MAXXIS	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/06/2019	Inspection Date	25/06/2019
Survey held at	SOON HIN MOTOR PTE LTD BLK 1018, YISHUN INDUSTRIAL PARK A, #01-342, SINGAPORE 768760		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**