

ASS. REC. BY:

Sunayr: Rasul

REF: CS/CT1901173/Ata322

Special Instruction:

ASSIGNMENT (Office)

From (Person): chong Boon Sen of CTI

Date/Time: 25/6/19 @ 9.52am

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLV 19312

Insured: GBE 6389P

at Workshop m/s Kah Motor

Tel: 86680608

of GA Mandai estate

Policy No: DMCVSN16084619033

Claim No: SNM19D202910C02

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 20/06/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.47am @ 25/6/19

Person Contacted: Anikka

Vehicle IN/OUT

Date/Time

Action/Instruction

Shangli ✓

GBE 6389P: /

SLV 19312: /

Part by Part \$2,436.07 (Red: PH732, 27%)



## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Tuesday, 25 June 2019 9:52 AM  
**To:** Ivan Teo  
**Cc:** assignments  
**Subject:** RE: OUR REF: SNM19D202910/CHONGBS - ARRANGE FOR 3RD PARTY PRI SURVEY SLV1931Z AGAINST GBE6389P (CHINA) DOA 20/06/2019

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

### Chong Boon Sen

Claims Executive  
Department

### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平狮城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Ivan Teo [mailto:[ivanteo@honda.com.sg](mailto:ivanteo@honda.com.sg)]

**Sent:** Tuesday, 25 June, 2019 9:21 AM

**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

**Subject:** RE: OUR REF: SNM19D202910/CHONGBS - ARRANGE FOR 3RD PARTY PRI SURVEY SLV1931Z AGAINST GBE6389P (CHINA) DOA 20/06/2019

Dear Boon Sen,

Kindly appoint Kelvin Ang as the surveyor.  
Please advise liability on direct settlement.

Thank you

Warmest Regards

Ivan Teo  
Kah Motor Co. Sdn Bhd  
6A Mandai Estate  
Singapore 729903  
DID : 86680608

Email: [ivanteo@honda.com.sg](mailto:ivanteo@honda.com.sg)

**From:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

**Sent:** Tuesday, 25 June, 2019 9:16 AM

**To:** Ivan Teo <[ivanteo@honda.com.sg](mailto:ivanteo@honda.com.sg)>

**Subject:** RE: OUR REF: SNM19D202910/CHONGBS - ARRANGE FOR 3RD PARTY PRI SURVEY SLV1931Z AGAINST GBE6389P (CHINA) DOA 20/06/2019

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

---

**From:** Lim Shu Min  
**Sent:** Monday, 24 June, 2019 11:54 AM  
**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>; [ivanteo@honda.com.sg](mailto:ivanteo@honda.com.sg)  
**Subject:** OUR REF: SNM19D202910/CHONGBS - ARRANGE FOR 3RD PARTY PRI SURVEY SLV1931Z AGAINST GBE6389P (CHINA) DOA 20/06/2019

Dear Boon Sen,

Please conduct PRS – SLV1931Z soonest possible.

File with Officer-In-Charge – Chong Boon Sen – 63896171

Thank you

**Lim Shu Min**  
Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 63896156 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Ivan Teo [<mailto:ivanteo@honda.com.sg>]  
**Sent:** Monday, 24 June, 2019 8:41 AM  
**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>  
**Subject:** ARRANGE FOR 3RD PARTY PRI SURVEY SLV1931Z AGAINST GBE6389P (CHINA) DOA 20/06/2019


Dear Motor Claims,

Kindly arrange for 3<sup>rd</sup> party PRI survey and advise on direct settlement liability.

Thank you

Warmest Regards

Ivan Teo  
Kah Motor Co. Sdn Bhd  
6A Mandai Estate  
Singapore 729903  
DID : 86680608  
Email: [ivanteo@honda.com.sg](mailto:ivanteo@honda.com.sg)



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/06/2019 13:36
Date Of Accident	20/06/2019 16:40
Exact Location Of Accident	49 HINDHEDE WALK SPRINGDALE CONDO OPEN CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV1931Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	AZHAR BIN MOHAMED NOOR
NRIC No	S7037432C
Email Address	BRADERAZA@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92707494
Alternative Phone No	OFFICE-92707494

### Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V00054/VPC2/R00
Cover Note Number	

### Driver

Name of Driver	AZHAR BIN MOHAMED NOOR
NRIC No	S7037432C
Date Of Birth	20/10/1970
Occupation	INDOOR
Date Of Driving Pass	19/01/1989
Driving Experience	30 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92707494
Fax Number	
Contact Number	OFFICE-92707494
EMail Address	BRADERAZA@GMAIL.COM

Address -  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 0

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name WOODLANDS EAST N.P.C  
 Police Station Address ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER POLICE REPORT

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number GBE6389P  
 Vehicle Make/Model/Colour  
 Details Of Properties VEH B  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





**SINGAPORE  
POLICE FORCE**



L/20190621/2021

2 of 2

POLICE REPORT (NP299)


CONTINUATION OF REPORT

Report No. L/20190621/2021

passenger door was dented and a deep scratch about 30cm long. I checked around the vehicle and no contact or details were being left behind. Subsequently, I checked through the vehicle built-in camera. From the camera footage on 20/06/2019 at about 1639hrs one white pick-up vehicle (GBE6389P) with a company name SNG TEC Development Pte Ltd tried to parked at the right side empty space of my vehicle. After the pick-up lorry reverse, the pick-up lorry then left the vicinity. I suspect that it was during the process when the pick-up lorry reverse, the pick-up lorry hit onto the rear right passenger door.

I wish to state that I do not wish to pursue the driver of the pick-up lorry or the company concerning this matter. I am lodging this report for my own follow-up and insurance claim only.

Signature Of Officer Recording The Report: L / Sr Staff Sgt POH JIANYU 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 21/06/2019 09:48
Officer In-Charge Of Case: L / Woodlands Police Divisional Investigation Branch / Insp MUHAMMAD TAJUDDIN BIN MOHAMED TAMRIN Contact No.: 63647559	Classification Of Case:
Authentication Stamp	





# QUOTATION

**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

<b>Customer</b>	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	<b>Document No.</b>	: SQT19002733	<b>Page</b>	1
<b>Registration No</b>	: SLV1931Z	<b>Date</b>	: 21. Jun 2019	<b>Customer No.</b>	: WZC008
<b>Chassis No</b>	: MRHFC5650HT000568	<b>Svc Advisor</b>	: IVAN TEO BOON KIAT	<b>Engine No</b>	: R16B22000984
<b>Model</b>	: CIVIC 1.6 VTI YM2017	<b>Date   Time</b>	: 21. Jun 2019 4:44:28 PM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: AZHAR BIN MOHAMED NOOR	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 20/6/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: AZHAR BIN MOHAMED NOOR OWNER INSURER: LIBERTY INSURANCE ACC DATE: 20/06/2019 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: GBE6389P						
67510-TEA-T00ZZ	PANEL.RR.DOOR <i>bl /</i>	1	717.50	5	681.62	47.71	729.33
72828-TEA-T01	SEALRR.DOOR LOWER <i>rec -</i>	1	6.20	5	5.89	0.41	6.30
72930-TEA-T01	GARNISH ASSYR.RR.DOOR SASH <i>rec -</i>	1	28.30	5	26.88	1.88	28.76
72721-TEA-T01	GARNISHR.RR.DOOR QUARTER OUT <i>X rec</i>	1	23.50	5	22.32	1.56	23.88
72925-TEA-T01	MOLDING ASSY,R.RR.DRINNER <i>rec -</i>	1	29.20	5	27.74	1.94	29.68
72910-TEA-T01	MOLDING ASSYR.RR.DOOR <i>rec -</i>	1	25.20	5	23.94	1.68	25.62
	<b>Sum Item</b>				<b>788.39</b>	<b>55.18</b>	<b>843.57</b>
BOSUN	SUNDRIES	1	<del>100.00</del> <i>70</i>		100.00	7.00	107.00
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	<del>450.00</del> <i>300</i>		450.00	31.50	481.50
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR.	1	<del>560.00</del> <i>280</i>		560.00	39.20	599.20
BPBODY	LABOUR TO INSTALL NEW DOOR AND REALIGN	1	560.00		560.00	39.20	599.20
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)	1	<del>675.00</del> <i>450</i>		675.00	47.25	722.25
BOBC	BODY UNDERSIDE COATING (N)	1	<del>250.00</del> <i>50</i>		250.00	17.50	267.50
	<b>Sum Labor</b>				<b>2595.00</b>	<b>181.65</b>	<b>2,776.65</b>

Survey By	<i>RASUL - Hp 90010068</i>							
Date & Time	<i>01/07/19 @ 1720</i>	<i>3 days</i>			<b>Total Amount</b>	3,383.39	236.83	3,620.22
	<i>Repy before paint</i>							

Printed on 21/6/2019 5:17:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**Customer** : CHINA TAIPING INSURANCE (S'PORE) PTE  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
**Registration No** : SLV1931Z  
**Chassis No** : MRHFC5650HT000568  
**Model** : CIVIC 1.6 VTI YM2017  
**Owner's Name** : AZHAR BIN MOHAMED NOOR  
**Ins Policy No.** :  
**Date of Accident** : 20/6/2019

**Document No.** : SQT19002733 **Page** 2  
**Date** : 21. Jun 2019  
**Customer No.** : WZC008  
**Svc Advisor** : IVAN TEO BOON KIAT  
**Engine No** : R16B22000984  
**Date | Time** : 21. Jun 2019 4:44:28 PM  
**Surveyor Name** :  
**Survey Date** :  
**Authorisation Date** :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Excess							Total (Inclusive of GST) <u>3,620.22</u>

Status \_\_\_\_\_  
Signature 

  
27/6/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Printed on 21/6/2019 5:17:01 PM

This is a computer generated invoice. No signature is required.  
Part prices are subjected to change without notice.  
The above estimated cost of repair do not include any unforeseen damages.  
GST Amount is calculated from individual line(s).  
An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.  
However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.



Dense

# QUOTATION

**KAH MOTOR CO. SDN. BHD.**  
 (A Member of the Oriental Holdings Berhad)  
 Service and Body Repair  
 Tel: +65 6841 3838 Website: www.honda.com.sg  
 For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223  
 Company Ref. No.: S60FC1380G

<b>Customer</b>	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	<b>Document No.</b>	: SQT19002733	<b>Page</b>	1
<b>Registration No</b>	: SLV1931Z	<b>Date</b>	: 21. Jun 2019	<b>Customer No.</b>	: WZC008
<b>Chassis No</b>	: MRHFC5650HT000568	<b>Svc Advisor</b>	: IVAN TEO BOON KIAT	<b>Engine No</b>	: R16B22000984
<b>Model</b>	: CIVIC 1.6 VTI YM2017	<b>Date   Time</b>	: 21. Jun 2019 4:44:28 PM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: AZHAR BIN MOHAMED NOOR	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 20/6/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: AZHAR BIN MOHAMED NOOR OWNER INSURER: LIBERTY INSURANCE ACC DATE: 20/06/2019 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: GBE6389P						
67510-TEA-T00ZZ	PANELR.RR.DOOR <i>bl /</i>	1	717.50	5	681.62	47.71	729.33
72828-TEA-T01	SEALRR.DOOR LOWER <i>acc /</i>	1	6.20	5	5.89	0.41	6.30
72930-TEA-T01	GARNISH ASSYR.RR.DOOR SASH <i>acc /</i>	1	28.30	5	26.88	1.88	28.76
72721-TEA-T01	GARNISHR.RR.DOOR QUARTER OUT <i>XAN</i>	1	23.50	5	22.32	1.56	23.88
72925-TEA-T01	MOLDING ASSY,R.RR.DRINNER <i>acc /</i>	1	29.20	5	27.74	1.94	29.68
72910-TEA-T01	MOLDING ASSYR.RR.DOOR <i>acc /</i>	1	25.20	5	23.94	1.68	25.62
	<b>Sum Item</b>				<b>788.39</b>	<b>55.18</b>	<b>843.57</b>
BOSUN	SUNDRIES	1	<del>100.00</del> <i>30</i>		100.00	7.00	107.00
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	<del>450.00</del> <i>300</i>		450.00	31.50	481.50
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR.	1	<del>560.00</del> <i>280</i>		560.00	39.20	599.20
BPBODY	LABOUR TO INSTALL NEW DOOR AND REALIGN	1	560.00		560.00	39.20	599.20
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)	1	<del>675.00</del> <i>450</i>		675.00	47.25	722.25
BOBC	BODY UNDERSIDE COATING (N)	1	<del>250.00</del> <i>50</i>		250.00	17.50	267.50
	<b>Sum Labor</b>				<b>2595.00</b>	<b>181.65</b>	<b>2,776.65</b>

Survey By: RASUL - Hp 90010068  
 Date & Time: 01/07/19 @ 1720 *3 days Rem before paint*  
 Total Amount: 3,383.39    236.83    3,620.22

Printed on 21/6/2019 5:17:01 PM  
 This is a computer generated invoice. No signature is required.  
 Part prices are subjected to change without notice.  
 The above estimated cost of repair do not include any unforeseen damages.  
 GST Amount is calculated from individual line(s)  
 An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.  
 However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



# SERVICE PRE-INVOICE

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

**Customer:** WZC008 / CHINA TAIPING  
**Chassis No:** MRHFC5650HT000568  
**License No:** SLV1931Z  
**Mileage:** 32884  
**Engine No:** R16B22000984

**Document No:** SVO19040919  
**Printed By:** IVANTEO  
**Order Date:** 27. June 2019  
**Order Time:** 2:19:02 PM  
**Service Advisor:** IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: AZHAR BIN MOHAMED NOOR OWNER INSURER: LIBERTY INSURANCE ACC DATE: 20/06/2019 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: GBE6389P						
67510-TEA-T00ZZ	PANLRR.RR.DOOR	1	717.50 ✓	5	681.62	47.71	729.33
72828-TEA-T01	SEALRR.DOOR LOWER	1	6.20 ✓	5	5.89	0.41	6.30
72930-TEA-T01	GARNISH ASSYR.RR.DOOR SASH	1	28.30 ✓	5	26.88	1.88	28.76
72925-TEA-T01	MOLDING ASSY,R.RR.DRINNER	1	29.20 ✓	5	27.74	1.94	29.68
72910-TEA-T01	MOLDING ASSYR.RR.DOOR	1	25.20 ✓	5	23.94	1.68	25.62
	<b>SUM PARTS:</b>				<b>766.07</b>	<b>53.62</b>	<b>819.69</b>
BOSUN		1	30.00 ✓		30.00	2.10	32.10
	SUNDRIES						
BC012R	0669 RESET VEHICLE SMART ENTRY SYSTEM	1	300.00 ✓		300.00	21.00	321.00
BKDR22R	0669 REMOVE & TRANSFER ITEMS TO NEW RR R DR. & ALIGN INCLUDING FITTINGS ON ATTACHMENT ITEMS.(N)	1	280.00 ✓		280.00	19.60	299.60
BPBODY	0669 LABOUR TO INSTALL NEW DOOR AND REALIGN	1	560.00 ✓		560.00	39.20	599.20
BP01R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(1P)	1	450.00 ✓		450.00	31.50	481.50
BOBC	1610 BODY UNDERSIDE COATING (N)	1	50.00 ✓		50.00	3.50	53.50
	<b>SUM LABOUR:</b>				<b>1,670.00</b>	<b>116.90</b>	<b>1,786.90</b>
	<b>TOTAL SGD</b>				<b>2,436.07</b>	<b>170.52</b>	<b>2,606.59</b>
	<b>Total Payable (SGD)</b>						<b>2,606.59</b>

GST Amount is calculated from individual line(s)

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Jun 2019		27 Jun 2019 14:48 <a href="#">Edit Adj Rpt</a>	<b>S\$2,436.07</b> <a href="#">Edit Estimates</a>	<b>S\$2,436.07</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>SING TEC CONSTRUCTION PTE LTD</b> , Co. Reg. No.: 199804598M								
Vehicle Reg. No.:	<b>SLV1931Z</b>	Date of Loss:	20/06/2019 17:00 - :59 [17 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D202910C02</b>	Policy/Cover Note No.:	DMCVSN16084619033						
Vehicle Reg. No. (Insured):	<b>GBE6389P</b>	Policy No. (Claimant):	DMCVSN1608461903						
		Excess:	S\$0.00						
Repairer:	<b>Kah Motor Co Sdn Bhd (Mandai)</b> 8 Mandai Estate, CBODY REPAIR AND PAINT CENTRE, 729905 Mandai - Tel: 90721767								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... <b>[Final Rpt due 08/07/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>			<a href="#">View All</a>	<a href="#">Search Tasks</a>					
			<a href="#">Create New Task</a>	<a href="#">Complete</a>					
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SLV1931Z (SNM19D202910C02)  
[GBE6389P]  
TP  
SING TEC CONSTRUCTION PTE LTD  
Jun 20 2019 5:00PM  
[-]  
Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
<b>Assessment Reports</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)						Thumbnail	Print		
1	21/06/19 17:00	<b>Accident Statement</b>						Load HTM			
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)						Thumbnail	Print		
1	21/06/19 16:59	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
2	21/06/19 16:59	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
3	21/06/19 16:59	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
4	21/06/19 16:59	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
5	21/06/19 16:59	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	02/08/19 16:50	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
2	02/08/19 16:50	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
3	02/08/19 16:50	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
4	02/08/19 16:50	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
5	02/08/19 16:50	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
6	02/08/19 16:50	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
7	02/08/19 16:50	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
8	02/08/19 16:50	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
9	02/08/19 16:50	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
10	02/08/19 16:50	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
11	02/08/19 16:50	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
12	02/08/19 16:50	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
13	02/08/19 16:50	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
14	02/08/19 16:50	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
15	02/08/19 16:50	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
16	02/08/19 16:50	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
17	02/08/19 16:50	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
18	02/08/19 16:51	<b>Reinspection Photo</b>						Load JPG	<input checked="" type="checkbox"/>		
19	02/08/19 16:51	<b>Reinspection Photo</b>						Load JPG	<input checked="" type="checkbox"/>		
20	02/08/19 16:51	<b>Reinspection Photo</b>						Load JPG	<input checked="" type="checkbox"/>		
21	02/08/19 16:51	<b>Reinspection Photo</b>						Load JPG	<input checked="" type="checkbox"/>		
22	02/08/19 16:51	<b>Reinspection Photo</b>						Load JPG	<input checked="" type="checkbox"/>		
23	02/08/19 16:51	<b>Reinspection Photo</b>						Load JPG	<input checked="" type="checkbox"/>		
24	02/08/19 16:51	<b>Reinspection Photo</b>						Load JPG	<input checked="" type="checkbox"/>		
25	02/08/19 16:51	<b>Reinspection Photo</b>						Load JPG	<input checked="" type="checkbox"/>		
26	02/08/19 16:51	<b>Reinspection Photo</b>						Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
27	02/08/19 16:51	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) <b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
28	02/08/19 16:51	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
29	02/08/19 16:51	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	27/06/19 14:49	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) <b>PRI CONTACT</b>	Load PDF	
1	21/06/19 16:58	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) <b>Sketch Plan</b> <small>[Linked Accident Report Documents]</small>	Load TIF	
2	21/06/19 17:00	<b>IC,DL</b> <small>[Linked Accident Report Documents]</small>	Load TIF	

### Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	21/06/19 17:00	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) <b>Accident Statement</b>	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	21/06/19 16:59	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) <b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
2	21/06/19 16:59	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
3	21/06/19 16:59	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
4	21/06/19 16:59	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
5	21/06/19 16:59	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	21/06/19 16:58	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) <b>Sketch Plan</b>	Load TIF	
2	21/06/19 17:00	<b>IC,DL</b>	Load TIF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI19011173/R1TD3E2

**Date:** 21/08/2019

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN16084619033	
Claimant Vehicle No: SLV1931Z	Insured Vehicle No: GBE6389P	
Date of Loss: 20/06/2019	Nature of Claim: TP	Claim No: SNM19D202910C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>SLV1931Z</b>	Engine No: R16B22000984
Make & Model: HONDA CIVIC, 1.6 (A)	Chassis No: MRHFC5650HT000568
Reg. Date: 26/12/2017 (Man. Year: 2017)	Odometer: 35039 km
Colour: Grey	
Engine Capacity: 1597 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): <b>Market Value/New Car Price</b>	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size: 225/45 R17	Rear Tyre Size: 225/45 R17
Front Left Side: Pirelli 6 mm	Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm	Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	888.39	796.07	92.32	10.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,495.00	1,640.00	855.00	34.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,383.39</b>	<b>2,436.07</b>	<b>947.32</b>	<b>28.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>236.84</b>	<b>170.52</b>	<b>66.32</b>	<b>28.00</b>
<b>Nett Amount (S\$)</b>	<b>3,620.23</b>	<b>2,606.59</b>	<b>1,013.64</b>	<b>28.00</b>

#### INSPECTION

Date of Assignment: 27/06/2019		
Date Inspected: 01/07/2019	Inspected At:	Kah Motor Co Sdn Bhd (Mandai) 6A MANDAI ESTATE SINGAPORE 729903
Estimated Period of Repair: 3.0 days		

**Adjuster:** MOHD RASUL

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS**

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 21 Aug 2019)
<b>Parts:</b> 143	HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLV1931Z)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANELR.RR.DOOR	Bent	681.62 FS	*681.62 FS
2	1		*SEALRR.DOOR LOWER	Necessary	5.89 FS	*5.89 FS
3	1		*GARNISH ASSYR.RR.DOOR SASH	Necessary	26.88 FS	*26.88 FS
4	1		*GARNISHR.RR.DOOR QUARTER OUT	Not Necessary	22.32 FS	*- FS
5	1		*MOLDING ASSY, R.RR.DRINNER	Necessary	27.74 FS	*27.74 FS
6	1		*MOLDING ASSYR.RR.DOOR	Necessary	23.94 FS	*23.94 FS
7	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
<b>Total Parts (S\$)</b>					<b>888.39</b>	<b>796.07</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RESET VEHICLE SMART ENTRY SYSTEM	New	450.00	300.00
2	REMOVE & TRANSFER ITEMS TO NEW RR R DR	New	560.00	280.00
3	LABOUR TO INSTALL NEW DOOR AND REALIGN	New	560.00	560.00
4	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (1P)	New	675.00	450.00
5	BODY UNDERSIDE COATING	New	250.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,495.00</b>	<b>1,640.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >