



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Ref: CS/INC19011187/R1sd3e2

Date: 04-07-2019



ATTN : ERIC TANG

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 1528C	Veh. Inspected	FZ 6005P
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1050061-002	Excess (\$)	0.00
Assign From		Assign Date	25/06/2019

2. Vehicle Particulars & Condition

Make & Model	YAMAHA SUPREME X-1	c.c	111
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	5YW034684	Colour	RED
Odometer	31125 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	70/90-17	MAXXIS	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90-17	MAXXIS	3 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/06/2019	Inspect Date / Time	25/06/2019 (01:49 PM)
Survey held at	HKL LIM TEAM MOTORSPORT BLK 1008 #01-24 BUKIT MERAH LANE 3 SINGAPORE 159722.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------