

**CAS GARAGE PTE LTD**

(Reg No. 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

Jimmy

VEHICLE REPAIR ESTIMATE

Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD

Address: 64, CECIL STREET, #04-05
IOB BUILDING, S(049711)

Xiao Tony.

Telephone: 63476100 Fax: 62244174

Email: insure@iii.com.sg

Make/ Model : HYUNDAI AVANTE

Date: 25.06.2019

Chassis No : KMHD841CMKU891227

Vehicle No: SCH108X

Date/Time of Accid: 29-01-1903 0:00

Date of reg: 17.06.2019

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	FINAL PRICE \$
1	BOOTLID <i>3 ne</i>	1	\$ 1,853.70	\$ 1,853.70 <i>+</i>
2	BOOTLID REFLECTOR LH <i>ne</i>	1	\$ 405.60	\$ 405.60 <i>+</i>
3	REAR BUMPER <i>Deformed</i>	1	\$ 654.30	\$ 654.30 <i>✓</i>
4	REAR BUMPER LOWER COVER LH <i>Rnr</i>	1	\$ 195.80	\$ 195.80 <i>+</i>
5	REAR BUMPER LOWER (GLOSS BLACK) <i>ML</i>	1	\$ 496.30	\$ 496.30 <i>+</i>
6	REAR BUMPER SIDE RETAINERS <i>ne</i>	2	\$ 85.90	\$ 171.80 <i>✓</i>
7	REAR BUMPER REFLECTOR LH <i>ut</i>	1	\$ 305.70	\$ 305.70 <i>✓</i>
8	REAR TAILAMP LH <i>ne m</i>	1	\$ 546.90	\$ 546.90 <i>+</i>
9	REAR MUDGUARD LH <i>ne m</i>	1	\$ 95.60	\$ 95.60 <i>+</i>

Total List Price Cost**\$ 4,083.20**

1131.80 PARTS DISCOUNT 20%

\$ 3,266.56

905.44

SPECIAL NETT ITE	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR NUMBER PLATE WITH CASING <i>ne</i>	1SET	\$ 50.00	\$ 50.00 <i>+</i>
2	REAR BUMPER CLIPS <i>ne</i>	1 SET	\$ 30.00	\$ 30.00 <i>✓</i>
3	REAR BUMPER UNDERCOVER CLIPS <i>ne</i>	1 SET	\$ 30.00	\$ 30.00 <i>+</i>
4	REAR SENSORS <i>ne</i>	1 SET	\$ 280.00	\$ 280.00 <i>+</i>

Total Special Nett Items**\$ 390.00**

30

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE,BEAT ,WELD , REALIGN AND ALIGNE	\$ 800.00 20
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,000.00 20
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 200.00 2
TO REMOVE/ REFIT WIRING CHECKS	\$ 120.00 30
TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTLING	\$ 150.00 50
Total Others Cost	\$ 470.00
GRAND TOTAL	\$ 5,926.56 480

CAS GARAGE PTE LTD
 UEN 201828067M
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
 SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
 Direct Contact: +65 8782 7171
 Email: allangoh.cas@gmail.com
 Fax: +65 6509 9501

Adrian Lj
 1/s 26/06/19
 03 days

total: 1415.44
 1/s: 1.1k

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: