

DATE:

ASS. REC. BY:

REF:

01/TPD19011268/Pg

Special Instructions

ASSIGNMENT (Office)

Surveyor:

From (Person): Kamaliah Kamie

at

SPF

Date/Time: 20/6/2019

Estimated Cost:

Bill to:

OD+TP+WS+TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: GAB 5F39K

Insured:

at Workshop m/s

Tel:

of

Policy No: MHASPP06000020127

Claim No:

TP/IP/33089/2019

Sum Insured:

Excess:

D.O.A. 25/5/2019

Make of Veh:
(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate	
	GAB 5F39K-X	Awaiting Repair & Brake test.

Key in (AIS)
Round. Notes

Sherwin Beh (LKK Auto)

From: Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>
Sent: Thursday, 20 June, 2019 6:00 PM
To: Sherwin Beh (LKK Auto); Naz (LKKAuto)
Cc: Bryan Ang (LKKAuto); SPF-TP FAIT; Muhammad Afiq RAHMAT (SPF); Yus Mastari I KHAZALI (SPF); Nor Hidayu ABDUL SAMAD (SPF); Junxiang MA (SPF); Norashikin DAUD (SPF)
Subject: Mechanical Inspection Report Request

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the 30 vehicles below: [The ones marked in RED are deemed to be URGENT hence please EXPEDITE ON THESE REQUESTS]

- a) Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle, FBK6016J (TP/IP/25861/2019)
- b) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Car, SKE2457X (TP/IP/25861/2019)

On 19 April 2019 at about 11.45 pm, the deceased was riding motorcycle FBK 6016 J on lane 1 of 6 lanes along CTE towards City when car driver of motor car SKE 2457 X lost control of her vehicle collided onto 3 other vehicle before encroaching onto the path of the deceased resulting in the deceased motorcycle to collide onto the motor car. The deceased was pronounced dead at the scene.

Vehicles to be inspected: FBK6016J - Rider (Deceased)
SKE2457X - Defendant

IO In-Charge: SIO Mohd Yazid

- c) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Bus, CB6563G (TP/IP/31357/2019)

On 15 May 2019 at about 6.07 pm, the driver of motor bus CB 6563 G was travelling along Tuas Road towards Tuas Basin on lane 2 of 3 lanes when the driver collided onto a pedestrian (Deceased) who was running from the driver's left to right. The deceased succumbed to his injuries on the same day in hospital.

Vehicle to be inspected: CB6563G - Defendant

IO In-Charge: SIO Mohd Yazid

- d) Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle VCN9549 (TP/IP/32821/2019)

On 24/05/2019 at about 3.36 am, the Deceased was riding motor cycle VCN9549 along PIE (AP) when he lost control and collided onto the centre divider railing. The Deceased sustained fatal injuries and passed away at the accident scene.

Vehicles to be inspected: VCN9549 - Rider (Deceased)

IO In-Charge: SIO Farhan

- e) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Lorry, G8B5739K (TP/IP/33089/2019)

urgent
↑

(EI)

On 25 May 2019, sometime before 4.33 p.m., the Involved Party (GBB5739K) was travelling along Sheares Avenue towards Central Boulevard and at the junction of Marina Boulevard. B1 saw a red light and B1 changed to lower gear but the clutch did not release back. He also tried to brake but the brake was also faulty. B1 passed the junction and A1 came from his right side. A1's front collided into his right side.

Vehicles to be inspected: GBB5739K - Involved Party (GI)

IO In-Charge: IO Afiq

- f) Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle, FBG6864Z (TP/IP/12743/2019)
- g) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Trailer, BJQ6562 (TP/IP/12743/2019)

On 04 March 2019 (Monday) at or about 7.54 p.m., the Deceased was riding his motor cycle along BKE towards the direction of Woodlands, on Lane 1 of 3 lanes, when he lost control of the vehicle and skidded. The Deceased then fell underneath the moving trailer which was travelling abreast on Lane 2. As a result, the Deceased was caught in between the 2 rear right wheels of the trailer and he was dragged for a short distance before the trailer came to a stop. The Deceased suffered fatal injuries and was pronounced dead at scene by SCDF Paramedic at 8.22 p.m. on the same day.

Vehicles to be inspected: FBG6864Z - Rider (Deceased)
BJQ6562 - Involved Party

IO In-Charge: SIO Saleha

- h) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Car, SLT9282X (TP/IP/22305/2019)

On 1 April 2019 at about 9.58pm, motor car was travelling along lane 1 of the 2 lanes road of Hougang Ave 8 towards Hougang Ave 10, when its front left portion collided onto a pedestrian. The pedestrian was crossing the road from the left to right side of the motor car. The pedestrian was conveyed to Tan Tock Seng Hospital and was pronounced dead by Dr Su Jun, on 2 April 2019 at 4.38pm.

Vehicles to be inspected: SLT9282X - Defendant

IO In-Charge: SIO Saleha

- i) Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle, JMB7792 (TP/IP/23475/2019)
- j) Case IAFP-IB-20190614 - Mechanical Inspection of Pickup, GX820R (TP/IP/23475/2019)

On 07 April 2019 at or about 8.33 a.m., a case of Road Traffic Accident had occurred along Mandai Ave towards Yishun Ave 1, L/P 70 involving one Malaysian motor cycle, JMB7792 and one Singapore motor pick up. The driver of the motor pick up informed that he was travelling along Mandai Ave towards Yishun Ave 1 on the centre of 3 lanes road and his vehicle came to a stop due to heavy traffic ahead. As the driver was stationary, approximately 5-6 seconds later, he suddenly felt an impact from the rear and realized that the rider (deceased) had collided onto his vehicle right rear portion. As a result of the collision, the rider suffered severe head injuries and multiple fractures on his body and was conveyed to Khoo Teck Phuat Hospital by ambulance. The rider succumbed to his injuries and was pronounced dead on 10 April 2019 at 4.05pm by Dr Stacey Goh.

Vehicles to be inspected: JMB7792 - Rider (Deceased)
GX820R - Involved Party

IO In-Charge: SIO Saleha