

REF: CITD19011286/Pc Special Instructions: _____
 ASS. REC. BY: _____
 Surveyor: _____
 From (Person): Kamali Kani of SPF Date/Time: 20/6/2019
 Estimated Cost: _____ Bill to: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SHA 1206S Insured: _____
 at Workshop in/s _____ Tel: _____
 of _____
 Policy No: MHASPF06000020127 Claim No: TP/IP/33067/2019
 Sum Insured: _____ Excess: _____
 Make of Vch: _____ D.O.A. 25/5/2019
 (Client's Record)
 CA / REV / REP. / REV 24 HRS
 Date/Time: _____ Person Contacted: _____ Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	SHA 1206S - X

500/19

45D
05

- k) Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle, FBD2381S (TP/IP/25947/2019)
l) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Lorry, XB8413U (TP/IP/25947/2019)

On 21 April 2019 (Sunday) at about 2 pm., the Deceased was riding his motorcycle together with his pillion, on Lane 4 of 6 lanes along Marina Coastal Expressway (MCE) towards Kallang Paya Lebar Expressway (KPE). Somewhere before the exit of Marina Gardens Drive (0.2km mark), the Deceased did not realise that there was a breakdown lorry ahead of him on Lane 4 and collided head-on onto the said stationary lorry. Driver informed that he had already been stationary at scene, for about 10 minutes, due to a punctured front right tyre when he felt an impact from the rear of his motor lorry. As a result of the accident, the Deceased sustained head injuries and multiple fractures. He was pronounced dead at scene by Paramedic Sgt Kumar at 2.15pm

Vehicles to be inspected: FBD2381S - Rider (Deceased)
XB8413U - Involved Party

IO In-Charge: SIO Saleha

- m) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Taxi, SHA1206S (TP/IP/33067/2019)
n) Case IAFP-IB-20190614 - Mechanical Inspection of PMD (TP/IP/33067/2019)

On 25 May 2019, sometime before 10.49 p.m., the Involved Party driving taxi (SHA1206S) was travelling along Punggol Way towards Seletar North Link and at the junction of Punggol Central, involved party collided with PMD rider who was approaching from taxi's right to left. As a result of the RTA, the PMD rider was conveyed unconscious to KTPH.

Vehicles to be inspected: SHA1206S - Involved Party
PMD - Defendant

IO In-Charge: SIO Yus Mastari

- o) Case IAFP-IB-20190612 - Mechanical Inspection of Motorcar, SLA1567C (TP/IP/35751/2019)

On 5 June 2019 (Wednesday) at about 8.51 p.m., the Potential Defendant was driving his motor car on lane 2 of the 2 lanes of Jurong East Avenue 1 towards Toh Guan Road when the Deceased ran across the signalised pedestrian crossing, from his right to left. The traffic light signal was green for the Potential Defendant at the time. The Potential Defendant was unable to brake in time and collided onto the Deceased. As a result of the accident, the Deceased was conveyed by ambulance to the Ng Teng Fong General Hospital however, he succumbed to his injuries and was pronounced dead in hospital on the same day, at 10.44 p.m. by Dr Leon.

Vehicles to be inspected: SLA1567C (Potential Defendant)

IO In-Charge: SIO Clarence Lim

- p) Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle, FBG3955P (TP/IP/26131/2019)

On 22 April 2019 at about 1.01pm, the Deceased was riding his motorcycle on the left lane of 2 lanes, along Hougang Avenue 9 towards Yio Chu Kang Road, when B1 ran across the road from his right to left. As B1 was crossing halfway, the Deceased collided onto B1 before landing on the left kerb. The Deceased was conveyed to Tan Tock Seng Hospital and was pronounced dead at 1.55 pm by Dr Praseetha.