

ASS. REC. BY:

REF:

CS/INC19011296/R1v03

Special Instruction:

Surveyor: Rusu

ASSIGNMENT (Office)

From (Person): Theresa Vimala of INCDate/Time: 26/6/19 @ 9:17am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: _____

SLJ 8914RInsured: GBD 8552 B

at Workshop in/s _____

Thiam Hong StreetTel: 826 36245

of _____

176 Bin Ming Drive # 05-1496391626 Jenny

Policy No: _____

Claim No: _____

MT/1049959-002

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. _____

20/6/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 9:41am 26/6/19

Person Contacted: _____

StevenVehicle IN OUT

Date/Time

Action/Instruction

3/26/19 ✓SLJ 8914R-XAfter repair: 4/7/2019Recovery: 3/7/201930/7 12:45pm Jenny will email estimate and QA to us.

ASSIGNMENT

From: Date: *27-2019*

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: *SLJ 8914R*at Workshop m/s *Thiam Hong Huat*
of *176 Sin Ming Drive #05-14*

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *rep*

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: *SLJ 8914R* Yr Regn: *16*Type: (M) Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *M420A 3* c.c. *1496*Colour: *Grey* A/C: Insured / Std / NI / NASp. Reading: *88760* T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: *JM 6BN 22A 8401 29108*Gen. Cond: Good (F) / Poor / BurntSteering: (F) Inorder / Jammed / Leaked / Burnt orBrake: (F) Inorder / Jammed / Leaked / Burnt orModi: Nil / (F) S/Rim / STD A/Rim orTyre Size: F: *205/60R16*

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *HUN LONH*

Front

Rear

R/Bal. *6* mm R/Bal. *6* mmL/Bal. *6* mm L/Bal. *6* mm

D.O.A.

D.O.I.

Survey held at

Thiam Hong Huat 2.54pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/8/19 LS \$750 confirmed by email (Ref 5415.80, 8890)

RECEIVED 15 AUG 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) *15/8 - typist*Report Format: *TP*Lump Sum / I.B.I. (\$ *750/2*)Days Of Repair: *2*Resurvey No. of Trip: *2*Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

250

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Thursday, 27 June 2019 8:25 AM
To: Admin-D (LKKAuto); assignments
Cc: SUR
Subject: RE: TP CASES FARMED OUT TO LKK ON 26/06/2019

Dear Nivitha

Details of OIC, etc, Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 26 June 2019 2:34 PM
To: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>; assignments <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 26/06/2019

Dear Theresa,

Thank you for the assignment.

Please be informed that SLJ 8914R and SJJ 808R (THIAM HENG HUAT) is not in the workshop) repairer will arrange.

Kindly assist to resend with full details.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Theresa Vimala D/O Balagangadharan [mailto:thrsvim.bala@income.com.sg]

Sent: Wednesday, 26 June 2019 9:17 AM

To: assignments <assignments@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>

Subject: FW: TP CASES FARMED OUT TO LKK ON 26/06/2019

:

Dear LKK,

Please assist to survey the following vehicles as per Clarence's instruction :- Thank you.

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Jared	MT/1050511-001	26/6/2019	SLF7216A	MOTOR IMAGE ENTERPRISES PTE LTD	19 LORONG 8 TOA PAYOH SINGAPORE 319255	Sayedinaah Ali / 92992693		Sjw4678d	24/6	
2	David phua	MT/1050251-002	26/6/2019	SJH08R	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		Slk9j66m	22/6	
3	Muhd airwan	MT/1049959-002	26/6/2019	SLJ8914R	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		Gbd8552b	20/6	

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg

income

more different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 15 August 2019 5:35 PM
To: Thiam Heng Huat; SUR
Subject: RE: Estimate for SLJ8914R

Dear Steven,

Noted with thanks.

Kindly send Final invoice and all supporting documents directly to NTUC INCOME

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Thiam Heng Huat <thh176@yahoo.com>
Sent: Thursday, 15 August 2019 4:46 PM
To: SUR <sur@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: Re: Estimate for SLJ8914R

Dear Veron,

We confirm Lump Sum \$750 @ 2 working days.

Warmest regards,
Steven
Thiam Heng Huat Pte Ltd
82636295

On Wednesday, 14 August 2019, 03:27:54 pm GMT+8, Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Steven,

WITHOUT PREJUDICE

Offer Lump Sum \$750 @ 2 working days.

PARTS-\$626 (less 20%)=\$500.80

LABOUR-\$440

TOTAL-\$940.80 (less 20%)=\$752.64

Please check and confirm

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Thiam Heng Huat <thh176@yahoo.com>

Sent: Thursday, 8 August 2019 10:01 AM

To: SUR <sur@lkkauto.com>

Subject: Estimate for SLJ8914R

Dear Survey Team,

Please see attached estimate.

Warmest regards,

Steven

Thiam Heng Huat Pte Ltd

82636295

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	311G
Vehicle Details	
Vehicle No.:	SLJ8914R
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jul 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP6EAT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	P520413926
Chassis No.:	JM6BN22A8H0129108
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$16,726.00
Original Registration Date:	29 Dec 2016
First Registration Date:	29 Dec 2016
Transfer Count:	2
Actual ARF Paid:	\$11,726.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2026
PARF Rebate Amount:	\$8,794.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,507.00
COE Rebate Amount:	\$38,159.00
Total Rebate Amount:	\$46,953.00

The information contained herein is correct as at 30 Jul 2019

OK

ESTIMATE

VEHICLE NO : SLJ 8914 R
MARK & MODEL : Mazda

YEAR : 2019

NO	DESCRIPTION	QTY	AMOUNT (\$)
	Parts		
1	Front Bonnet X	1	\$ 966.80
2	Front Bumper X	1	\$ 880.00
3	Front Bumper retainer X	1	\$ 70.00
4	Front Bumper rivets X	10	\$ 40.00
5	Front Bumper Clip (1 set) X	1	\$ 38.00
6	Front Bumper RHS Foglamp X	1	\$ 300.00
7	Front Bumper RHS Foglamp Cover X	1	\$ 80.00
8	Front Bumper RHS Foglamp Cover extension X	1	\$ 50.00
9	Front Bumper Lower grille side cover X	1	\$ 35.00
10	Front Headlamp RHS X	1	\$ 1,050.00
11	Front Fender RHS 5f ✓	1	\$ 398.00
12	Front Fender Splash shield RHS c-4 ✓	1	\$ 188.00
13	Front Fender Splash shield Clip (1 set) m ✓	1	\$ 40.00
	Adjust computer wheel alignment X m		\$ 80.00
	Check wiring and lighting system X m		\$ 150.00
	Panel beating on affected areas		\$ 800.00 200
	Spray painting on affected areas		\$ 800.00 200
	Rust proofing		\$ 200.00 40
			6165.80



Signature
14/8/19 Rasul
Hp 90010068

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2 days
4/8
02/07/19 @ 1455
Resurvey after repair



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19011296/R1vd3n2
73 BRAS BASAH ROAD Date: 19-08-2019
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556



ATTN: MUHD AIRWAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 8552B	Veh. Inspected	SLJ 8914R
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1049959-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	26/06/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JM6BN22A8H0129108	Colour	GREY
Odometer	88710 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	LING LONG	6 mm
L/H Front Tyre	205/60 R16	LING LONG	6 mm
R/H Rear Tyre	205/60 R16	LING LONG	6 mm
L/H Rear Tyre	205/60 R16	LING LONG	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/06/2019	Inspect Date / Time	02/07/2019 (02:54 PM)
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 8914R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	NOT NECESSARY	966.80	-
1	FRONT BUMPER	NOT NECESSARY	880.00	-
1	FRONT BUMPER RETAINER	NOT NECESSARY	70.00	-
10	FRONT BUMPER RIVETS	NOT NECESSARY	40.00	-
1	SET FRONT BUMPER CLIP	NOT NECESSARY	38.00	-
1	FRONT BUMPER RHS FOGLAMP	NOT NECESSARY	300.00	-
1	FRONT BUMPER RHS FOGLAMP COVER	NOT NECESSARY	80.00	-
1	FRONT BUMPER RHS FOGLAMP COVER EXTENSION	NOT NECESSARY	50.00	-
1	FRONT BUMPER LOWER GRILLE SIDE COVER	NOT NECESSARY	35.00	-
1	FRONT HEADLAMP RHS	NOT NECESSARY	1,050.00	-
1	FRONT FENDER RHS	BENT	398.00	398.00
1	FRONT FENDER SPLASH SHIELD RHS	CUT	188.00	188.00
1	SET FRONT FENDER SPLASH SHIELD CLIP	NECESSARY	40.00	40.00
	LESS 20% DISCOUNT		-	-125.20
			4,135.80	500.80
LABOUR				
	ADJUST COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	CHECK WIRING AND LIGHTING SYSTEM.	NOT NECESSARY	150.00	-
	PANEL BEATING ON AFFECTED AREAS.		800.00	200.00
	SPRAY PAINTING ON AFFECTED AREAS.		800.00	200.00
	RUST PROOFING		200.00	40.00
			2,030.00	440.00
GRAND TOTAL			6,165.80	940.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				750.00

Report Ref No. CS/INC19011296/R1vd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.